

Wulff Enterprises

07/29/2010

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner 2212	157324	262	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	
Gestetner DSC224	150895	120	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830) 114k FAX(TYPE 1232) E(PT290)	Offcolor panels; color = 7k; B/W =
Gestetner DSC232	147966	281	ST() RADF(DF75) PC(TYPE 1232)	Registration off on copies; color = 10k; B/W = 272k
Gestetner DSM415	156631	19		Error code SC547 (zero cross problem); broken feed tray
Gestetner DSM415	156632	56		Error code SC541 (fuser lamp); broken feed tray
Gestetner DSM618D	157317	94	ST() RADF(DF79)	Yellowed RADF panels
Gestetner DSM620D	155493	87	ST() RADF(DF79) FAX(TYPE 2018)	
Gestetner DSM622	156634	205	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	
Gestetner DSM622	156635	103	ST() RADF(DF75)	Bypass will not feed; yellowed RADF panels
Gestetner DSM627	152919	171	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR790) FAX(TYPE 2027)	
Gestetner DSM627	156670	299	ST() RADF(DF75) PC(TYPE 2027) FN(SR790)	
Gestetner DSM635	157300	573	ST() PU(TYPE 1045) PC(TYPE 2045E) P(RT45) FN(SR880)	Duplex jams; offcolor panels
Gestetner DSM645	156608	458	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E) E(PT330)	
Gestetner 3227	157075	96	ST() RADF(DF69) FAX(TYPE 270) B(TYPE 270)	Yellowed panels
Gestetner DSC424	132333	81	ST() FAX(TYPE 3232)	Side-side registration is off on copies; color = 19k; B/W = 63k
Gestetner DSC424	140347	104	ST()	Cracked front door; broken access door C at pivot pin; color = 22k; B/W = 83k
Gestetner DSC428	154415	426	ST() PU(TYPE 2238) FN(SR950) FAX(TYPE	Color = 100k; B/W = 326k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			3245) E(PT460)	
Gestetner DSC428	157144	263 ST()	FN(SR950) FAX(TYPE 3245)	Missing hard drive- unable to fully test machine; shows error code SC819; missing finisher interlock actuator on door R3 (unable to test finisher); color = 11k; B/W = 252k
Gestetner DSC460	153657	N/A PS(TYPE 3260)	PC(TYPE 3260)	Machine will not come to ready- can't test
Gestetner 3235E	157325	573 ST()	RADF(DF67) PC(TYPE 450E) NIC(TYPE	Error code SC329-00 (laser beam pitch error); offcolor panels
Gestetner DSM716	150827	134 FAX(TYPE 2000)	ADF(DF2000)	
Gestetner DSM416	156618	30		
Gestetner DSM721D	149073	70 ST()	RADF(DF2010)	
Gestetner DSM721D	156063	103 ST()	RADF(DF2010)	
Gestetner DSM725E	153353	162 RADF(DF83)	PED(PS490) PC(TYPE 3010) FAX(TYPE 3030)	Broken bypass tray
Gestetner DSM735E	156264	156 ST()	FN(SR790) FAX(TYPE 3045)	
Gestetner DSM745E	154948	199 PED(PS530)	PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	Fax board inoperable- machine will not allow access (shows no privileges)
Gestetner DSC530	148400	426 PED(PB3000)	FN(SR790)	Color = 272k; B/W = 154k
Gestetner DSC530	150824	393 ST()	FN(SR3000)	
Gestetner DSC530	151411	342 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000)	Finisher jamming at R5 when in staple mode; color = 55k; B/W = 288k
Gestetner DSC535	153196	248 PED(PB3000)	FN(SR790)	Color = 110k; B/W = 139k
Gestetner DSC545	150524	395 PED(PB3000)	FN(SR3020)	Has E-5000 external Fiery controller; color = 225k; B/W = 170k
Gestetner DSC545	156645	436 PED(PB3000)	FN(SR790)	Color = 142k; B/W = 294k
Gestetner DSC545	157203	N/A PED(PB3000)	FN(SR3030) FAX(TYPE MPC4500)	Touch screen inoperable- cannot test machine; finisher in error code SC529 (function gate #1 motor sensor) due to missing entrance guide

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.