

Wulff Enterprises

07/29/2010

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C2230	156957	623	RADF(DP-621) PED(PF-621) FN(DF-626) DX(DU-621)	Bent finisher tray mount (still works); color = 557k; B/W = 66k
Copystar CS-1820	155043	64	FAX(K) ADF(DP-100)	
Copystar CS-1820	155044	117	FAX(K) ADF(DP-100)	
Kyocera KM-2550	152179	409	ST() RADF(DP-410) FAX(L)	Cracked RADF panel; machine will not detect paper in bypass
Kyocera KM-2550	152542	184	ST() RADF(DP-410) FN(DF-410) DX(DU-410)	
Copystar CS-2550	152991	67	ST() RADF(DP-410) DX(DU-410)	RADF has a bad hinge & will not stay open
Copystar CS-2550	156015	155	ST() SCAN(F) RADF(DP-410) DX(DU-410)	Yellowed panels
Copystar CS-3050	152992	290	ST() RADF(DP-700) FN(DF-710)	
Kyocera KM-4050	150769	1211	ST() RADF(DP-700) PU(PH-5A) FN(DF-710)	
Kyocera KM-4050	150771	1077	ST() RADF(DP-700) PU(PH-5A) FN(DF-730)	
Kyocera KM-4050	157358	466	RADF(DP-700) PED(PF-750) FN(DF-710)	LCT jams- inop
Kyocera KM-5050	156595	387	RADF(DP-700) PED(PF-750) FN(DF-730)	
Kyocera KM-5050	156598	1517	RADF(DP-700) PED(PF-750) FN(DF-730)	Finisher tray switches are sticking causing trays to not move- inop
Kyocera KM-5050	157369	265	RADF(DP-700) PED(PF-750) FN(DF-710)	
Kyocera KM-6030	156589	419	FN(DF-650)	
Kyocera KM-6030	157291	1790	PU(PH-4) FN(DF-650)	Blurs and streaks in copies
Copystar CS-C2520	149432	289	ST() RADF(DP-710)	Ran fine, now touch screen is locked up; Black meter = 227k; color meter = 63k
Kyocera KM-C2520	153611	144	RADF(DP-710) PED(PF-710) FAX(N)	Color = 34k; B/W = 10k; *electronic meter does not match
Kyocera KM-C2520	153612	94	RADF(DP-710) PED(PF-710) FAX(N)	Smashed upper left side corner of machine; color = 35k; B/W = 60k
Kyocera KM-C2520	153613	48	RADF(DP-710) FAX(N)	Missing pickup roller in bypass unit- inop; color copies jam every try at fuser and are 100% cyan; color = 19k; B/W = 29k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C2520	153614	161	RADF(DP-710) PED(PF-710) FAX(N)	Color = 44k; B/W = 118k
Kyocera KM-C2520	153616	62	RADF(DP-710) PED(PF-710) FAX(N)	Control panel loose on right side; color = 41k; B/W = 22k
Kyocera KM-C2520	153617	19	RADF(DP-710) PED(PF-710) FAX(N)	Cracked bypass panel; color = 15k; BW = 4k
Kyocera KM-C2520	153618	35	RADF(DP-710) PED(PF-710) FAX(N)	Color = 9k; B/W = 2k; *electronic meter does not match
Kyocera KM-C2520	153620	83	RADF(DP-710) PED(PF-710) FAX(N)	Error code SC-C7101 (bad black toner concentration sensor or DV unit or engine PCB); color = 3k; B/W = 81k
Kyocera KM-C2520	153621	90	RADF(DP-710) PED(PF-710) FAX(N)	Color = 25k; B/W = 17k; *electronic meter does not match
Kyocera KM-C2520	153623	140	RADF(DP-710) PED(PF-710) FAX(N)	Color = 33k; B/W = 12k; electronic meter does not match
Kyocera KM-C2630D-A	145793	669	RADF(SRDF-2) FAX(H)	Dented back panel; missing left side exit tray; bypass will not stay closed; color = 154k; B/W = 54k
Kyocera KM-C2630D-A	150533	143	RADF(SRDF-2)	Copies not seeming to fully fuse; missing left side exit tray; color = 18k; B/W = 125k
Kyocera KM-C2630D-B	145591	1060	RADF(SRDF-2) FAX(H)	Color = 167k; B/W = 395k
Kyocera KM-C3225	155694	503	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710) E(JS-710)	RADF shows constant reset originals- will not clear (inop); machine will not allow finisher or be selected (says cannot combine modes); scanner error light is on; color = 218k; B/W = 286k
Kyocera KM-C3225	155695	96	RADF(DP-710)	Has a DF-710 pedestal (works OK); color = 44k; B/W = 53k
Kyocera KM-C3225	155697	542	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710) E(JS-710)	Color = 40k; B/W = 502k
Kyocera KM-C3225	155698	313	RADF(DP-710) PED(PF-750) FN(DF-710) E(JS-710)	Unable to test finisher- shows cannot combine functions; Color = 117k; B/W = 196k
Kyocera KM-C3225	156889	N/A	ST() RADF(DP-710)	Touch screen inoperable- cannot fully test machine; makes a grinding noise when cycling; missing toner cartridges
Kyocera KM-C3225	156919	146	ST() RADF(DP-710) FAX(N) E(JS-710)	Color = 39k; B/W = 107k
Copystar CS-C3225	157073	300		Back left corner panel out of alignment; color = 162k; B/W = 139k
Mita KM-C2030	156599	744	ST() RADF(DP-620) PC(FIERY X3E 31) DX(DU-620)	Duplex jams- inop; color = 68k; B/W = 677k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita KM-C3130	156493	418 ST()	RADF(DP-620) PC(FIERY X3E 31) DX(DU-620)	Has finisher brackets - missing finisher; PC cable insulation torn; black meter = 233k; color meter = 186k
Mita AI 1515	157074	N/A	ADF(STDF-2)	Scanner is off track and cables unwound causing error code C31 (scan home sensor); yellowed panels
Mita AI 3010	150737	473 ST()	RADF(SRDF-1) DX(AD-60) B()	Cracked right side of control panel; broken bypass door; offcolor panels
Mita KM-2030	154563	53 ST()	RADF(SRDF-1) PC(K) DX(AD-61)	Needs toner to test
Copystar CS-3035	152129	136 ST()	RADF(SRDF-2) FN(DF-73)	
Copystar CS-3035	152134	143	RADF(SRDF-2) PED(PF-75) FN(DF-73)	
Mita KM-3035	152216	209	RADF(SRDF-2) PED(PF-70) FN(DF-71U)	
Mita KM-3035	152543	176 ST()	RADF(SRDF-2) FN(DF-78)	Finisher in false jam code- inop
Mita KM-3035	155701	123 ST()	RADF(SRDF-2)	Dented & bent back panel
Copystar CS-3035	156341	222 ST()	RADF(SRDF-2) FN(DF-71U)	Stapler inop- shows functions cannot be combined; broken finisher interlock switch cover
Mita KM-3035	156517	315 ST()	RADF(SRDF-2)	Back panel dented
Mita KM-3035	157271	21 ST()	RADF(SRDF-2)	
Mita KM-3530	141477	245 ST()	RADF(SRDF-2) FN(DF-78) DX(AD-63)	Scratched & dented back panel; broken RADF plug socket
Mita KM-3530	150410	746	RADF(SRDF-2) PED(PF-70) FN(DF-71U) DX(AD-63)	
Royal RI-4030	143946	437 ST()	RADF(SRDF-2) FN(DF-78) DX(AD-63)	Cracked RADF panel; broken RADF plug socket; dented & bent lower back panle; unable to test stapler (functions cannot be combined); missing fax board (Has fax count of 63,344); broken end cap on finisher tray
Mita KM-4035	156331	89	RADF(SRDF-2) PED(PF-70) FN(DF-71U) FAX(J)	Missing toner cartridge- tested with another; broken RADF plug socket; broken finisher interlock cover; noisy machine when running
Mita KM-4035	156350	178 ST()	RADF(SRDF-2)	Dirty panels
Copystar CS-4530	147316	2543	FN(DF-600)	Finisher socket broken; yellow panels; cassette #1 inop - not tested; does not staple
Copystar CS-4530	156467	237	PC(Q)	Front door actuator broken; has finisher brackets - missing finisher; Error code C5110 - transfer separator

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita KM-5530	157263	403	SCAN(D) PU(PH-3) PC(Q) FN(DF-610)	corona; back panel dented Finisher entrance guide all bent up- unable to test; missing finisher trays; duplex jams; offcolor & dirty panels

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.