

# Wulff Enterprises

02/10/2012

## GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier 5515	181724	349	ST() RADF(DF72) FAX(TYPE 1018)	Yellow and dirty panels
Ricoh AFICIO 1027	190796	266	ST() RADF(DF75) PC(TYPE 1027[S]) NIC(TYPE 1027) FN(SR820) FAX(TYPE 1027) DX(AD420) B(TYPE	Error code SC793 - interchange error or SBCU board - not tested, yellow panels, bypass tray missing
Savin 2535	182851	433	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720)	Error code SC726 - finisher shift tray 1, lift motor error - not tested, off color panels
Savin 2535	190660	558	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720) FAX(TYPE 1045)	Off color panels. void lines on copies
Ricoh AFICIO 1045	190661	315	RADF(DF70) PED(PS360) FN(SR720)	Hard-drive removed after testing, yellow panels, finisher will not latch , error code SC726 - finisher shift/lift motor - finisher not tested, jamming in RADF, void lines in copies
Ricoh AFICIO 1045	191511	1560	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720) FAX(TYPE 1045)	Error code SC726 - finisher shift tray/lift motor error - finisher not tested, toner spilled in cassette #2, off color
Ricoh AFICIO 1055	191765	1946	PU(TYPE 850) PC(TYPE 1055) NIC(TYPE 450-E) FN(SR870)	RADF plug socket broken
Gestetner DSM415	176986	46		Off color panels
Ricoh AFICIO 1515	192215	43		Off color panels
Ricoh AFICIO 1515M	174542	246	ST()	Off color panels
Lanier LD015SPF	174547	278		
Lanier LD015SPF	174548	149		Off color; Jamming in RADF
Ricoh AFICIO 1515M	174557	180		Off color panels
Savin 3515MF	176004	230		Off color panels
Savin 3515MF	181081	199		Very dirt - toner spilled on machine, yellow panels
Savin 3515MF	183385	77		RADF yellow, toner spilled in cassettes
Ricoh AFICIO 1515M	187150	127		Toner bomb

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 1515M	188015	103		Toner spilled throughout machine, off color panels
Ricoh AFICIO 1515M	188878	165		
Savin 3515MF	188895	141		
Gestetner DSM415PF	189422	192		
Gestetner DSM415PF	189423	103		Off color panels
Gestetner DSM415PF	189424	117		Off color panels
Gestetner DSM415PF	189425	158		ADF not turning on - not tested, off color panels
Gestetner DSM415PF	189426	135		Off color panels
Gestetner DSM415PF	189427	220		Error code SC670 - engine startup error, off color panels
Gestetner DSM415PF	189428	244		
Gestetner DSM415PF	189429	72		Off color panels
Lanier LD015SPF	189727	43		Cassette paper sensor broken - not tested (ran through bypass only)
Savin 3515MF	190443	19		
Ricoh AFICIO 2016	177891	163	ST() PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Yellowed panels
Savin 8016	188779	10	ST() ADF(DF78)	Jams at fuer every copy; missing small access panel on left side; broken back panel on right side
Ricoh AFICIO 2016	191991	59	ST()	
Savin 4018D	186771	142	ST() RADF(DF79)	Off color panels
Savin 8020	184397	247	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Wireless PC card, has ADF DF2000
Savin 8020	184402	105	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Has wireless PC LAN card, exit tray broken
Savin 8020	184403	288	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Has ADF DF2000; ADF top access panel dented
Savin 8020	184404	352	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340) ADF(DF78)	Has wireless PC card, has ADF DF2000
Savin 8020	184406	178	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Has ADF DF2000, has wireless card
Ricoh AFICIO 2020	188389	123	ST() ADF(DF78)	Void lines in copies
Gestetner DSM620	189158	49	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340) ADF(DF78)	Cassette #2 front panel broken
Gestetner DSM620	189159	28	ST() FAX(TYPE 2018) E(PT340) ADF(DF78)	Wireless PC card

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM620	189166	60	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340) ADF(DF78)	
Ricoh AFICIO 2020D	183170	467	ST() RADF(DF79)	RADf yellow, control panel contrast light, bypass tray paper sensor missing - not tested
Savin 8020D	190615	81	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE	
Savin 8020D	192710	144	RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018)	Ground in dirt
Savin 4022	187974	1054	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	Jamming at registration rollers - not tested, toner spilled throughout machine, off color panels, duplexer will not latch
Ricoh AFICIO 2022	188164	336	ST() RADF(DF75) FN(SR820) FAX(TYPE 2027) E(PT280)	
Lanier LD122	190653	288	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	
Ricoh AFICIO 2022	190840	460	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE 2027) E(PT280)	Front door broken & smashed - interlock broken, bypass tray broken off, back panel smashed in on left side, duplexer unit badly scratched, off color panels
Ricoh AFICIO 2022	190841	241	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	Back panel broken, scratched, bypass tray broken, error code C320 - laser polygon motor problem, off color panels
Ricoh AFICIO 2022	190843	239	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	Bottom cassette jammed in machine & will not open - not tested, front door broken in half, deeply scratched panels all over, bypass tray broken off & wiring damaged
Ricoh AFICIO 2027	186085	460	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR790)	Yellow panels, scan button not working
Savin 4027	190397	608	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	RADF yellow, void lines on copies
Ricoh AFICIO 2027	192216	50	SS(TYPE 1027) RADF(DF75) PED(PS490) PC(TYPE 2027) FAX(TYPE 2027)	
Ricoh AFICIO 2027	192217	94	RADF(DF75) PED(PS490) PC(TYPE 2027) FAX(TYPE 2027)	RADF yellow, off color panels
Ricoh AFICIO 2045E	191118	351	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Finisher frame bent at entrance side-finisher not tested - jamming in finisher, off color
Savin 4045E	191224	175	ST() PC(TYPE 2045E) FN(SR790) FAX(TYPE	Yellow panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			2045E)	
Ricoh AFICIO 2045E	191229	201	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	Yellow panels, Has punch unit but cannot be selected
Ricoh AFICIO 2045E	191918	706	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	yellow panels, toner all over copies
Ricoh AFICIO 2051	191722	1766	FN(SR850)	
Ricoh AFICIO 2060	191001	1266	PU(TYPE 1075) PC(TYPE 2075) FN(SR850)	
Savin 4075	187553	1142	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	Front door magnet bracket broken, finisher tray broken
Ricoh AFICIO 2075	191928	3175	PC(TYPE 2075) FN(SR850)	Error code SC557 - fusing thermistor error - not tested, toner spilled in machine
Toshiba E-STUDIO900	183110	862	FN(MJ-1026)	Jamming in duplexer
Toshiba E-STUDIO900	184999	712	PC(TYPE 2105)	Has SR880 finisher with interposer MJ-7002, finisher throat frame bent - finisher not tested, finisher trays missing, monitor mounting arm broken
Ricoh AFICIO 2090	188913	3956	PU(TYPE 1075) P(RT46) FN(SR860)	Machine scans and shows "copying" but never copies- can't resolve or test; finisher in error code SC740 (stapler problem); off color panels
Toshiba E-STUDIO900	192609	1353	PC(TYPE 2105) P(MP-4501L) FN(MJ-1026)	Lower finisher tray broken, finisher expansion cover missing, RADF exit tray broken, missing ecopy tower - has monitor and keyboard
Ricoh AFICIO 2232C	187588	402	PED(PS550) FN(SR920) FAX(TYPE 2238) E(PT460)	Yellow panels, black meter = 232k, color meter = 170k
Gestetner DSC332	187715	659	PED(PS540) FN(SR920) FAX(TYPE 2238) E(PT460)	Off color panels, black meter = 571k, color meter = 88k
Savin C3224	187869	416	PED(PS540) FN(SR910) FAX(TYPE 2238) E(PT460)	Yellow panels, trim panel below bypass tray missing, black meter = 326k, color meter = 90k
Savin C3224	187870	288	PED(PS540) FN(SR910) FAX(TYPE 2238) E(PT460)	Finisher front access door broken below finisher entrance guide, yellow panels, black meter = 109k, color meter = 179k
Gestetner DSC332	192622	53	ST() E(PT460)	Not feeding paper - not tested, off color panels, black meter = 36k, color meter = 17k
Savin C3828	180353	436	PED(PS540) FN(SR910)	Yellow panels, black meter = 308k, color meter = 128k
Lanier LD238C	181455	967	PED(PS550) E(PT460)	Exit tray broken, off color, yellow, black meter = 782k, color meter = 186k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD238C	186400	348	PED(PS550) FN(SR920) FAX(TYPE 2238) E(PT460)	Off color panels, right side corner cover panel broken, cover below bypass tray missing, black meter - 278k, color meter = 71k
Ricoh AFICIO 2238C	190200	605	PED(PS560) FAX(TYPE 2238)	FN- SR960 finisher, Black meter = 549k, color meter = 56k, PED door interlock broken, jamming out of PED - not tested, yellow panels
Ricoh AFICIO 2238C	191502	273	PED(PS550) E(PT460)	Yellow panels
Savin 8025	177910	131	ST()	Off color panels
Gestetner DSM725	179671	76	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030)	Yellow, jamming at fuser - not tested
Ricoh AFICIO 3025	182061	107	ST() RADF(DF83)	Bypass tray broken
Savin 8025	182217	153	ST() RADF(DF83)	Off color panels
Ricoh AFICIO 3025	182386	300	ST() RADF(DF83) PC(TYPE 3030) FAX(TYPE	RADF yellow
Ricoh AFICIO 3025	182431	165	ST() RADF(DF83)	Yellow panels
Gestetner DSM725	183149	313	ST() RADF(DF83) PC(TYPE 3030 (S))	Bypass tray broken - not tested
Savin 8025	184754	77	ST() SS(TYPE 1027) RADF(DF83) FAX(TYPE 3030)	
Gestetner DSM725	184813	232	ST() RADF(DF83)	
Gestetner DSM725	185339	372	ST() RADF(DF83) PC(TYPE 3030 (S))	
Ricoh AFICIO 3025	185883	159	SS(TYPE 1027) PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030) E(PT280)	Touch screen not responding - not fully tested, yellow panels
Savin 8025	187871	97	ST() RADF(DF83) PC(TYPE 3030)	Off color panels
Gestetner DSM725	188375	97	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	
Gestetner DSM725	188376	168	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	Yellowed RADF panels
Ricoh AFICIO 3025	190231	306	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790)	
Ricoh AFICIO 3025	190232	337	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Finisher off color
Ricoh AFICIO 3025	191002	46	ST() RADF(DF83) PC(TYPE 3030 (S))	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8025	191058	193	ST() RADF(DF83) PC(TYPE 3030 (S))	
Ricoh AFICIO 3025	192261	90	ST() RADF(DF83)	Bypass tray broken - not tested
Gestetner DSM725	192339	361	ST() RADF(DF83) PC(TYPE 3030) FAX(TYPE 3030) E(PT280)	
Gestetner DSM725	192674	83	ST() RADF(DF83) PC(TYPE 3030 (S))	
Gestetner DSM730	179259	251	ST() RADF(DF83) PC(TYPE 3030 (S))	Error code SC501 - cassette #1 out of order - not tested, yellow
Ricoh AFICIO 3030	182086	122	ST()	Top cassette not recognizing paper - not tested
Ricoh AFICIO 3030	182088	123	ST()	
Ricoh AFICIO 3030	182090	513	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790)	Finisher off color
Ricoh AFICIO 3030	183122	132	ST() RADF(DF83) PC(TYPE 3030)	Bypass tray broken- jamming in bypass, missing PC (SD card)
Ricoh AFICIO 3030	185879	121	ST() RADF(DF83)	Jamming out of bypass tray
Savin 8030	187166	310	ST() RADF(DF83) PC(TYPE 3030 (S))	Error code SC411 - separataion bias, HCT or discharge plate - not tested, off color panels
Ricoh AFICIO 3030	190066	124	RADF(DF83) PED(PS490) FN(SR790)	RADF and finisher yellow
Gestetner DSM730	190195	248	RADF(DF83) PED(PS490) PC(TYPE 3030)	
Savin 8035	179593	484	ST() FAX(TYPE 3045)	Off color panels
Gestetner DSM735	179714	268	PED(PS530) FN(SR790)	Yellow panels
Savin 8035	184025	517	ST() FN(SR790) FAX(TYPE 3045) E(PT330)	
Savin 8035	185007	184	ST() FN(SR790)	
Gestetner DSM735	185646	593	ST() PC(TYPE 3045) FAX(TYPE 3045) E(PT330)	Stand off color
Ricoh AFICIO 3035	185884	570	ST() PC(TYPE 3045)	
Ricoh AFICIO 3035	186714	444	ST() PC(TYPE 3045) FN(SR890) FAX(TYPE 3045)	
Ricoh AFICIO 3035	187825	121	ST() FN(SR790)	Finisher yellow
Ricoh AFICIO 3035	188137	362	ST()	Off color panels
Gestetner DSM735	188530	194	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Broken bypass tray; yellowed panels
Gestetner DSM735	189161	219	PED(PS530) PC(TYPE 3045) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(TYPE 3045)	
Ricoh AFICIO 3035	190064	404	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Jamming in machine - not fully tested
Gestetner DSM735	190196	816	PED(PS530) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO 3035	190236	678	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Jamming in stapler - not tested
Ricoh AFICIO 3035	190240	577	PED(PS530) PC(TYPE 3045) FN(SR790)	
Savin 8035	190612	595	ST() FN(SR790)	Lower right side access door missing- tested with another; off color panels; void streaks in copies
Ricoh AFICIO 3035	190665	51	ST() FN(SR790)	Jamming in stapler jogger - stapler not tested, off color panels
Ricoh AFICIO 3035	191291	532	ST() PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Touch screen not responding - not fully tested, hard-drive removed, off color and dirty
Ricoh AFICIO 3035	191723	738	ST() FN(SR790)	Off color panels
Gestetner DSM735	192690	312	ST()	
Ricoh AFICIO 3045	188387	335	PED(PS530) P(RT45) FN(SR790) FAX(TYPE 3045)	Yellow panels, cassette #3 will not close - not tested
Ricoh AFICIO 3045	189190	1074	ST() PC(TYPE 3045) P(RT45) FN(SR790)	Off color panels
Ricoh AFICIO 3045	190234	1080	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Yellow panels
Ricoh AFICIO 3045	190666	171	PU(TYPE 1045) PED(PS530) FN(SR880)	hard-drive failed - removed hard-drive to test machine - not fully tested
Gestetner DSC424	126842	190	ST()	
Savin C2410	186494	232	ST()	Front door interlock switch not working - not tested, hole in front door, fuser oil spilled all throughout machine from being on its back, off color panels, black meter = 194k,
Gestetner DSC428	182232	636	PU(TYPE 2238) PED(PS580) FN(SR950) FAX(TYPE 3245) E(PT460)	Error code SC542- fuser heat roller temp too low - not tested, off color panels, black meter = 321k, color meter = 315k
Savin C2824	188793	253	ST() FN(SR960) FAX(TYPE 3245) E(PT460)	Finisher jams & grinds- inop; cannot access fax option; yellowed & very dirty panels; color = 48k; B/W = 206k
Gestetner DSC435	181464	254	ST() FAX(TYPE 3245) E(PT460)	Error code 440-02 - color drum motor error - not tested, off color, black meter - 219k, color meter = 35k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3235C	184232	410	PED(PS580) FN(SR960) FAX(TYPE 3245)	Error code SC733 - Tray two lift motor error - finisher not tested, black meter = 167k, color meter = 243k, RADF and bypass tray yellow
Savin C3528	187173	442	PED(PS580) FAX(TYPE 3245) E(PT460)	Error code SC820 - CPU, firmware or controller error - not tested, black meter = 358k, color meter = 84k, yellow panels
Gestetner DSC435	187460	553	PED(PS580) FAX(TYPE 3245)	Machine would not copy - not fully tested (does not show an error code), black meter = 227k, color meter = 327k
Ricoh AFICIO 3235C	187668	481	PU(TYPE 1045) PED(PS590) FN(SR960) FAX(TYPE 3245)	Control cover panels dented, Finisher disconnected - tray does not see upper limit sensor, black meter = 425k, color meter = 56k
Ricoh AFICIO 3235C	187770	912	PED(PS580) FN(SR960) FAX(TYPE 3245) E(PT460)	Off color panels, error code SC542- fuser temp too low - not tested
Gestetner DSC435	191743	665	PED(PS590) FAX(TYPE 3245) E(PT460)	Black meter = 373k, color meter = 293k
Ricoh AFICIO 3235C	191990	133	ST() FN(SR960) FAX(TYPE 3245)	Black meter = 75k, color meter = 59k
Ricoh AFICIO 3245C	184226	448	PED(PS590) E(PT460)	Exit tray broken, missing hard-drive - not fully tested, counter in development mode
Gestetner DSC445	187461	562	PED(PS590) FN(SR950)	False door indicator in finisher - not tested, error code SC391 - black charge AC output error - not tested, off color panels, black meter = 131k, color meter = 431k
Savin C4535	190055	493	PED(PS590) FN(SR950) FAX(TYPE 3245)	Jamming in duplexer - not tested, yellow panels, Finisher rail top panel cracked, black meter= 233k, color meter = 261k
Ricoh AFICIO 3260C	175700	427	FN(SR970)	Bent & broken; finisher entrance guide; Color = 325k; B/W = 103k
Toshiba E-STUDIO4500	178841	436	PC(TYPE 3260)	Came in with wrong finisher, black meter = 277k, color meter = 160k
Lanier LD160C	179207	1503	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Color = 367k; B/W = 1136k
Lanier LD160C	179731	1377	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	Has inverter type 3260, black meter - 112k, color meter = 1265k
Toshiba E-STUDIO4500	180054	662	FN(SR970)	Has external HP PC with windows XP pro, black mter = 569k, color meter = 93k
Ricoh AFICIO 3260C	180110	681	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Black meter = 547k, color meter = 138k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C6045	180827	81	PC(TYPE 3260) E()	Black meter = 7k, color meter = 75k
Gestetner DSC460	180964	1465	PU(TYPE 3260) PC(TYPE 3260) FN(SR980)	Color = 23k; B/W = 1442k
Gestetner DSC460	180967	2080	PU(TYPE 1075) PC(TYPE 3260) FN(SR841)	Color = 244k; B/W = 1837k
Gestetner DSC460	181165	1577	PU(TYPE 3260) PC(TYPE 3260) FN(SR4000)	Jamming in finisher - not tested, error code SC760 - finisher punch motor, sensor, motor drive or main board, black meter = 1010k, color meter = 567k
Savin C6045	181336	1917	FN(SR4000)	Black meter = 1710k, color meter = 207k, has inverter type 3260
Gestetner DSC460	183167	1067	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Finisher off color. black meter = 975k, color meter = 92k
Savin C6045	183379	1594	PC(FIERY E-7000) FN(SR980)	Needs toner to test; color = 1534k; B/W = 61k
Toshiba E-STUDIO4500	185025	305	PC(FIERY E-7000) FN(SR4000)	Front door broken, right side access door bent - does not latch, lower finisher tray support bent - not tested, black meter = 197k, color meter = 108k
Lanier LD160C	185630	821	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	
Gestetner DSC460	185872	224	PC(FIERY E-7000) E()	Black meter = 27k, color meter = 197k
Gestetner DSC460	185873	329	PC(FIERY E-7000) E()	Black meter = 41k, color meter = 289k
Savin C6045	185930	422	PU(TYPE 3260) PC(TYPE 3260) FN(SR4000)	Has cover interposer 3260, off color panels, black meter = 269k, color meter = 154k
Ricoh AFICIO 3260C	186379	580	PC(TYPE 3260) FN(SR970)	Black meter = 281k, color meter = 300k
Ricoh AFICIO 3260C	187256	1269	PU(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	Black meter = 1102k, color meter = 168k
Savin C6045	187554	275	PU(TYPE 3260) PC(FIERY E-7000) FN(SR970)	Black meter = 85k, color meter = 190k
Gestetner DSC460	187894	906	PU(TYPE 3260) FN(SR980)	Black meter = 276k, color meter = 631k
Ricoh AFICIO 3260C	188436	306	PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Black meter = 225k, color meter = 81k
Savin C6045	189179	965	FN(SR4000)	Missing PC has PC fiery decal on copier, black meter = 251k, color meter = 714k
Toshiba E-STUDIO4500	189561	222	PC(TYPE 3260) E()	Black meter = 64k, color meter = 158k
Ricoh AFICIO 5560	177783	507	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Black meter = 214k; color meter = 273k, jamming at duplexer - not fully tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO5500	180055	331		Has external HP PC with windows XP pro. occassional jamming at fuser, black meter = 265k, color meter = 66k
Gestetner CS555	180068	724	PU(TYPE 3260) PC(FIERY E-7000) FN(SR4000)	Black meter = 597k, color meter = 127k
Gestetner CS555	183323	978	PU(TYPE 3260) PC(FIERY E-7000) FN(SR4000)	Black meter = 635k, color meter = 343k
Ricoh AFICIO 5560	188598	501	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Missing doc server button; color = 125k; B/W = 376k
Gestetner CS555	189421	563	PU(TYPE 3260) PC(FIERY E-7000) FN(SR970)	Black meter = 414k, color meter = 150k
Toshiba E-STUDIO5500	190230	179	PC(FIERY E-7000)	Has SR 4010 finisher, toner spilled throughout machine, Missing PC crossover cable - PC not tested, Jamming in finisher throat - finisher not tested, black meter = 32k, color meter = 147k
Ricoh AFICIO MP 13	187590	5768	PC(TYPE 1350) FN(SR5000)	Constant jam in fuser - not tesetd, missing LCT, very dirty and off color panels
Lanier LD1135	188380	2560	P(RT5000) FN(SR5000)	Machine will not come to ready- shows "please wait" and will not go beyond; broken lower right access door; off color panels
Lanier LD316	189958	11	ADF(DF2000)	ADF yellow
Lanier LD016	192675	15		
Ricoh AFICIO MP 16	192233	25	PFU(PS480)	
Lanier LD016SPF	192683	274		Jamming in fuser when duplexing, front door broken at left hinge
Lanier LD016SPF	192684	229		
Ricoh AFICIO MP 17	191184	25		
Ricoh AFICIO MP 20	179849	11	ST() RADF(DF2010)	Off color and yellow panels
Ricoh AFICIO MP 20	181440	71	ST() RADF(DF2010)	RADF off color
Gestetner DSM721D	181730	55	ST() RADF(DF2010) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	182378	254	ST() FAX(TYPE 2000) ADF(DF2000)	ADF yellow
Ricoh AFICIO MP 20	182391	58	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Stand front door missing, front panel bent from machine frame
Lanier LD320D	183113	37	RADF(DF2010)	
Ricoh AFICIO MP 20	183461	48	ST() RADF(DF2010)	
Lanier LD320D	183671	28	ST() RADF(DF2010)	Cassette #1, bypass not feeding - not tested, RADF yellow, ground in dirt

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD320D	185438	487	RADF(DF2010) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	Right side access door broken, off color
Lanier LD320D	186582	55	ST() ADF(DF2000)	
Ricoh AFICIO MP 20	187866	51	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Very dirty, Cassette #2 front paper guide broken - cassette not tested, front door broken
Lanier LD320D	187944	27	ST() RADF(DF2010) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	190676	138	ST() RADF(DF2010) PC(TYPE 2000)	Off color and dirty panels
Ricoh AFICIO MP 20	191187	116	RADF(DF2010) FAX(TYPE 2000)	Jamming in bypass - not tested
Ricoh AFICIO MP 20	191285	144	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	191286	126	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Error code SC500 - main motor lock
Ricoh AFICIO MP 20	191287	38	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Lanier LD320D	191498	116	ST() RADF(DF2010)	
Lanier LD320D	191499	163	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	191500	58	ST() RADF(DF2010) PFU(PS460)	
Ricoh AFICIO MP 20	191737	5	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Lanier LD320D	192672	46	ST() RADF(DF2010)	
Savin 7025	178865	139	ST() RADF(DF3020) PC(TYPE 2500NA) E(BN3020)	Off color panels, jamming in duplexer - not tested
Ricoh AFICIO MP 25	181874	124	ST() RADF(DF3020)	Error code SC391 - development bias leak - not tested
Ricoh AFICIO MP 25	182983	283	FN(SR3010) FAX(TYPE 2500) E(BN3020)	Black meter = 265k, color meter = 18k
Ricoh AFICIO MP 25	184238	52	ST() RADF(DF3020) FAX(TYPE 2500)	Void lines in copies
Savin 7025	186565	36	ST() RADF(DF3020)	
Ricoh AFICIO MP 25	187821	277	ST() RADF(DF3020) PC(TYPE 2500) FN(SR3010) E(BN3020)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 25	192231	134	ST() RADF(DF3020) PC(TYPE 2500) FAX(TYPE 2500) E(BN3020)	
Savin 8025E	177635	185	ST() RADF(DF83) FAX(TYPE 3030)	Off color panels
Savin 8025E	179294	309	ST() RADF(DF83)	Off color and very dirty, jamming in duplexer - not tested
Ricoh AFICIO MP 25	179857	143	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Ricoh AFICIO MP 25	179858	106	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Gestetner DSM725E	180932	142	ST() RADF(DF83)	
Ricoh AFICIO MP 25	181869	365	ST() RADF(DF83)	RADF yellow
Ricoh AFICIO MP 25	183775	422	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Touch screen not responding - not fully tested
Lanier LD325	183899	428	ST() RADF(DF83)	Jamming out of bypass tray - not tested, RADF panels yellow, Has PC and NIC
Savin 8025E	184398	385	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	Wireless PC card, front door scratched
Ricoh AFICIO MP 25	184910	267	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030) E(PT280)	Finisher shift tray frame bent - finisher not tested, toner spilled in machine. touch panel not holding calibration
Ricoh AFICIO MP 25	185430	175	ST() RADF(DF83) PC(TYPE 3010)	Missing hard-drive - not fully tested, off color paenls
Ricoh AFICIO MP 25	185431	81	ST() RADF(DF83) PC(TYPE 3010)	Jamming in duplexer, RADF socket broken, off color panels. back panel cracked
Ricoh AFICIO MP 25	185621	160	ST() RADF(DF83) PC(TYPE 3010)	RADF off color
Savin 8025E	186615	178	ST() RADF(DF83) PC(TYPE 3010)	Bypass tray not detecting paper - not tested
Ricoh AFICIO MP 25	187146	144	RADF(DF83) PED(PS490) PC(TYPE 3010) FAX(TYPE 3030)	
Gestetner DSM725E	187878	161	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Toner spilled in top cassette
Ricoh AFICIO MP 25	188906	280	ST() SS(TYPE 1027) RADF(DF83) FAX(TYPE 3030) E(PT280)	Broken rear paper guide in tray #1; off color & dirty panels
Ricoh AFICIO MP 25	189022	165	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	Jamming at finisher throat - not tested, RADF spring cover missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD325	189329	56	ST() RADF(DF83) FAX(TYPE 3030)	
Lanier LD325	189865	91	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	
Ricoh AFICIO MP 25	189959	175	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Lanier LD325	190239	259	ST() RADF(DF83)	Bypass not feeding - not tested
Savin 8025E	190445	52	ST() RADF(DF83)	
Savin 8025E	190613	44	ST() RADF(DF83)	Yellowed RADF panels
Savin 8025E	190637	133	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	RADF yellow
Savin 8025E	190638	185	ST() RADF(DF83)	Touch screen not responding -not fully tested, RADF yellow
Ricoh AFICIO MP 25	191281	118	ST() RADF(DF83)	Bypass tray missing, RADF and control panel yellow
Ricoh AFICIO MP 25	191288	233	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Back panel smashed in, off color panels
Ricoh AFICIO MP 25	191289	177	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	
Ricoh AFICIO MP 25	191290	113	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	jamming in bypass - not tested
Ricoh AFICIO MP 25	191793	96	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	Touch screen not responding - not fully tested
Ricoh AFICIO MP 25	192667	144	ST() SS(TYPE 1027) RADF(DF83)	Touch screen not responding - not fully teted
Ricoh AFICIO MP 25	172427	142	RADF(DF3030) PED(PS500) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Off color and dirty panels
Savin 9025	176046	52	ST() RADF(DF3030) FN(SR790) E(BN3030)	
Ricoh AFICIO MP 25	177573	219	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 25	177632	147	ST() FAX(TYPE 3350) E(BN3030)	
Savin 9025	180062	208	ST() SCAN(TYPE 3350) E(BN3030)	
Savin 9025	180579	105	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	Error code SC792 - finisher problem - not tested, yellow control panel
Ricoh AFICIO MP 25	180675	113	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Very dirty

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			E(BN3030)	
Savin 9025	180920	115	ST() RADF(DF3030) PC(TYPE 3350 (S)) E(BN3030)	
Lanier LD425	180954	186	ST() RADF(DF3030)	
Ricoh AFICIO MP 25	181341	76	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	181343	102	ST() RADF(DF3030) PC(TYPE 3350) E(BN3030)	
Savin 9025	181453	757	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350)	Error code SC876-05 - hard-drive defective, hard-drive removed, duplexer internal parts missing, error code sc672 - controller to operation communication error, transfer roller falling apart
Lanier LD425	182104	205	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	182440	228	RADF(DF3030) FN(SR790) E(BN3030)	
Ricoh AFICIO MP 25	182444	15	ST() RADF(DF3030) E(BN3030)	
Ricoh AFICIO MP 25	182982	218	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	183132	406	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Partially blank image
Ricoh AFICIO MP 25	183133	473	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	183134	334	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	184197	158	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	Jamming in stapler - not tested
Savin 9025	184701	56	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 25	184730	210	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Paper feed assembly missing from RADF - not tested, scanner lenses off track - not tested, very dirty

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 25	184751	348	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Error code SC798-08 finisher lift tray bound up - not tested, touch screen scratched, exit tray missing
Ricoh AFICIO MP 25	185413	164	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350)	Cassette #1 does not recognize paper - not tested, jamming in bypass, off color panels
Savin 9025	185877	238	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050)	
Savin 9025	185878	211	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050)	Finisher top access door interlock broken - finisher not tested, needs toner - not fully tested,
Ricoh AFICIO MP 25	186769	42	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	
Ricoh AFICIO MP 25	187659	87	ST() RADF(DF3030) FN(SR3050) FAX(TYPE 3350)	
Lanier LD425	187771	12	ST() RADF(DF3030)	
Ricoh AFICIO MP 25	187991	171	ST() RADF(DF3030) FAX(TYPE 3350)	Permanent marker on duplex panels
Lanier LD425	190395	211	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 25	191769	176	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S))	Toner spilled in cassette #1, jamming out of cassette #1 - not tested,
Ricoh AFICIO MP 25	191979	178	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Scan slit glass broken
Lanier LD425	192332	191	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	192333	151	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	192334	311	ST() RADF(DF3030) FAX(TYPE 3350)	
Lanier LD425	192335	112	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	192677	239	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 30	185620	389	ST() RADF(DF83) PC(TYPE 3010)	RADF off color

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 30	191282	347	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Jamming in duplexer - not tested, very dirty and yellow
Savin 8030E	191720	264	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Ricoh AFICIO MP 33	178656	138	RADF(DF3030) PED(PB3030) FN(SR3050) FAX(TYPE 3350)	
Lanier LD433	180326	690	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	Top finisher guide broken. lower finisher tray broken, jamming in stapler
Lanier LD433	180931	434	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 33	181342	245	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350) E(BN3030)	Blank image at bottom half
Ricoh AFICIO MP 33	182069	130	ST() RADF(DF3030) FN(SR790) E(BN3030)	Finisher tray bracket bent - finisher not tested
Ricoh AFICIO MP 33	182080	34	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) E(BN3030)	Finisher frame bent at bottom tray mount
Ricoh AFICIO MP 33	183129	346	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350) E(BN3030)	Will not fuse copies, yellow panesl, jamming out of RADF
Ricoh AFICIO MP 33	183235	199	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 33	183460	96	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 33	183475	258	ST() RADF(DF3030) PC(TYPE 3350 (S)) E(BN3030)	
Ricoh AFICIO MP 33	184200	268	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	
Ricoh AFICIO MP 33	184233	N/A	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Touch screen not responding - not fully tested, hard-drive removed

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 33	185201	421	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Wrinkling copies
Ricoh AFICIO MP 33	185871	288	ST() RADF(DF3030) E(BN3030)	Jamming in fuser, off color
Ricoh AFICIO MP 33	187259	382	RADF(DF3030) PED(PB3030) FN(SR790)	Whining noise in machine, jamming occasionally throughout machine
Ricoh AFICIO MP 33	189247	124	ST() RADF(DF3030) FN(SR3050)	
Ricoh AFICIO MP 33	190680	354	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 33	191986	86	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	Error code SC672 - controller to operation panel communication error - not fully tested
Lanier LD433	192678	143	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050)	
Lanier LD433	192679	57	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Lanier LD433	192680	231	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790)	
Ricoh AFICIO MP 35	174965	222	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Finisher rail bent
Ricoh AFICIO MP 35	177623	67	FN(SR790)	Error code SC329 - laser beam pitch error - not fully tested
Savin 8035E	178113	12	PED(PS530) FN(SR790) FAX(TYPE 3045)	Touch screen not responding - not fully tested, hard-drive removed
Lanier LD335	181781	526	ST()	
Lanier LD335	183592	530	ST() PC(TYPE 4500) FAX(TYPE 3045)	Jamming in RADF
Lanier LD335	183597	696	ST() PC(TYPE 4500) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	183615	193	ST() PC(TYPE 4500) FAX(TYPE 3045)	Jamming in RADF
Gestetner DSM735E	184408	279	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	Off color panels
Savin 8035E	184756	80	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	184911	325	ST() PC(TYPE 4500)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8035E	185083	142	ST() PC(TYPE 4500) FAX(TYPE 3045)	Jamming in fuser, jams in duplexer
Savin 8035E	185084	492	ST() PC(TYPE 4500) FAX(TYPE 3045)	
Savin 8035E	186040	302	ST() PU(TYPE 1045) FN(SR880)	Off color panels
Gestetner DSM735E	187467	292	ST() PC(TYPE 4500) FAX(TYPE 3045)	
Gestetner DSM735E	187468	377	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	188491	401	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	
Gestetner DSM735E	190192	278	PED(PS530) PC(TYPE 4500) E(PT330)	
Ricoh AFICIO MP 35	190226	1014	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Off color and very dirty, toner spilled in back of machine
Savin 8035E	190614	369	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO MP 35	190683	421	ST() PC(TYPE 4500)	Off color and dirty panels
Ricoh AFICIO MP 35	191122	224	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO MP 35	191292	432	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045)	Missing finisher - has hardware, off color panels
Ricoh AFICIO MP 35	191293	383	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Fuser knob broken, off color panels
Ricoh AFICIO MP 35	191294	479	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Yellow panels
Ricoh AFICIO MP 35	191297	349	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Bypass tray broken, top panel broken by bypass tray
Ricoh AFICIO MP 35	191718	152	ST() PC(TYPE 4500) E(PT330)	
Ricoh AFICIO MP 35	191988	210	ST() PC(TYPE 4500)	PC does not have scan feature
Ricoh AFICIO MP 35	192658	221	ST() PS(TYPE 4500) PC(TYPE 4500)	Does not have scan feature
Savin 8035E	192711	625	ST() PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 40	175285	82	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 40	177387	249	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030)	Off color panels; jamming in punch unit - not tested
Ricoh AFICIO MP 40	179049	445	ST()	
Lanier LD040	179261	475	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3020) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	179272	335	PED(PB3040) PC(TYPE 5000 (S)) E(BN3040)	
Ricoh AFICIO MP 40	180322	264	PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	180908	241	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 40	180914	614	PED(PB3040)	
Lanier LD040	180930	95	PED(PB3040) PC(TYPE 5000 (S))	
Ricoh AFICIO MP 40	180984	218	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Lanier LD040	181456	184	ST() PC(TYPE 5000 (S)) FN(SR790)	Jamming in stapler - not tested, left side panel cracked
Ricoh AFICIO MP 40	181954	353	ST()	Ground in dirt
Ricoh AFICIO MP 40	181958	328	ST() PU(TYPE 3260) PC(TYPE 5000 (S)) FN(SR3030)	
Ricoh AFICIO MP 40	182079	137	ST() PC(TYPE 5000 (S)) FN(SR790)	
Savin 9040	182407	308	PED(PB3040) FN(SR790)	
Lanier LD040	182427	517	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 40	182696	276	ST() PC(TYPE 5000 (S))	
Ricoh AFICIO MP 40	182697	304	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Lanier LD040	184556	642	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Finisher tray bent - not tested, jamming in bypass tray
Savin 9040	184734	519	ST() PC(TYPE 5000 (S))	
Ricoh AFICIO MP 40	184909	195	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 40	185408	69	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Scanner right side panel cracked
Ricoh AFICIO MP 40	185416	210	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	Bypass tray broken
Ricoh AFICIO MP 40	187769	589	ST() PC(TYPE 5000 (S)) FN(SR790)	
Savin 9040	188391	237	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Lanier LD040	188551	341	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	RADF jams when duplexing
Ricoh AFICIO MP 40	189080	72	PED(PB3040) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	189471	357	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 40	190033	417	PED(PB3040) PC(TYPE 5000 (S))	
Ricoh AFICIO MP 40	190208	155	ST() PS(TYPE 5000) PC(TYPE 5000 (S))	
Ricoh AFICIO MP 40	190405	680	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	
Ricoh AFICIO MP 40	190407	235	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Hard-drive removed before arriving
Ricoh AFICIO MP 40	190793	714	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	190794	917	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Savin 9040	191719	318	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	191768	302	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	192238	460	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Does not recognize toner installed - not tested; broken top finisher access door
Lanier LD040	192671	650	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 45	179270	420	ST()	PC board missing, No power to control panel - not tested
Ricoh AFICIO MP 45	180903	561	ST() FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8045E	180924	327	ST() PC(TYPE 4500) FN(SR880)	
Ricoh AFICIO MP 45	181952	557	ST() FN(SR790)	Jamming in finisher entrance - not tested, front door scratched, bypass tray broken
Lanier LD345	183614	815	ST() PC(TYPE 4500) FAX(TYPE 3045)	Toner spilled in back of machine
Ricoh AFICIO MP 45	184941	292	ST() PC(TYPE 4500) FAX(TYPE 3045)	Center filter tray broken
Ricoh AFICIO MP 45	186797	755	PED(PS530) FN(SR790)	Error code SC865 - hard-drive failure - not fully tested, off color and yellow panels
Lanier LD345	187138	688	ST() PC(TYPE 4500) FAX(TYPE 3045)	Fuser knob broken, toner spilled in machine, off color
Ricoh AFICIO MP 45	187147	435	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	
Ricoh AFICIO MP 45	187920	524	ST() PC(TYPE 4500) FAX(TYPE 3045)	Missing finisher - has hardware; off color panels
Ricoh AFICIO MP 45	188374	391	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045)	Touch screen not responding - not fully tested, off color, void lines on copies
Ricoh AFICIO MP 45	188388	390	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880)	Yellow panels
Savin 8045E	188591	237	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	Missing lower right side access door - unable to test tray #2; off color panels
Ricoh AFICIO MP 45	190191	165	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Off color panels
Gestetner DSM745E	190241	154	ST() PC(TYPE 4500) P(RT45) FN(SR880) FAX(TYPE 3045)	
Ricoh AFICIO MP 45	190388	227	PED(PS530) PC(TYPE 4500) FN(SR790)	Off color panels
Savin 8045E	190436	388	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Savin 8045E	190446	429	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Savin 8045E	190611	256	ST() PU(TYPE 1045) FN(SR880)	Yellowed panels
Lanier LD345	191999	729	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD345	192331	298	PED(PS530) FAX(TYPE 3045)	
Savin 8045E	192615	234	PED(PS530) PC(TYPE 4500) FN(SR790)	
Ricoh AFICIO MP 50	176257	321	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	176259	186	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Off color panels
Ricoh AFICIO MP 50	176879	412	PED(PB3040) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 50	178378	310	PED(PB3040)	Missing finisher - has brackets
Ricoh AFICIO MP 50	178379	622	PED(PB3040)	Missing finisher - has hardware
Ricoh AFICIO MP 50	178657	282	PED(PB3040) FN(SR790)	
Ricoh AFICIO MP 50	178757	587	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	179712	215	PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR790) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 50	179787	631	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Jamming in stapler - not tested
Lanier LD050	180344	301	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	
Lanier LD050	180345	309	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	180910	654	PED(PB3050) FN(SR790)	Needs new cleaning web, touch screen yellow
Ricoh AFICIO MP 50	180911	108	PED(PB3040) FN(SR790)	Control panel yellow
Ricoh AFICIO MP 50	180912	554	PED(PB3040) FN(SR790)	Cassette #1 not lifting paper - not tested
Ricoh AFICIO MP 50	180913	411	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	180915	302	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	Finisher panels yellow
Ricoh AFICIO MP 50	181450	732	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Error code SC792 - finisher connector or cable - missing finisher
Ricoh AFICIO MP 50	181452	536	PED(PB3040) FN(SR790)	
Ricoh AFICIO MP 50	181815	280	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 50	181864	143	ST() PC(TYPE 5000 (S)) FN(SR3020)	Finisher thout and cross brace bent- finsher not tested
Ricoh AFICIO MP 50	181953	252	ST() E(BN3040)	
Savin 9050	182918	708	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	183017	279	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	183125	541	PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	184731	786	ST() PC(TYPE 5000 (S)) FN(SR790) E(BN3040)	RADF hinge bent; finisher in error code SC750 - finisher tray lift motor
Ricoh AFICIO MP 50	184792	455	ST() FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 50	185410	450	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Savin 9050	186397	854	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Top finisher panel interlock broken, jamming in stapler
Ricoh AFICIO MP 50	187257	309	PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 50	189085	301	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Finisher top access door broken
Savin 9050	189248	441	PED(PB3040) PC(TYPE 5000 (S)) FN(SR3020)	Not fusing copies
Savin 8055	187872	1096	PU(TYPE 3260) FN(SR970)	Has NIC but no PC enablers
Ricoh AFICIO MP 55	191977	334	PC(TYPE 7500)	Missing finisher, missing paper deck - has hardware
Ricoh AFICIO MP 55	192620	1569	PU(TYPE 3260) PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	Error code SC672 - controller startup error - no tested, removed hard-drive
Lanier LD260	187868	547	PU(TYPE 3260) P(RT43) FN(SR970)	
Ricoh AFICIO MP 60	191948	1032	PU(TYPE 3260) PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	
Lanier LD260	192330	239	FN(SR970)	
Savin 8065	189151	399	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Touch screen working intermittedly - not fully tested
Lanier LD265	189170	628	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Jamming in finisher when punching and stapling

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 65	189635	2817	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Error code SC860 - hard-drive error - not fully tested, jamming in finisher - not tested disconnected
Ricoh AFICIO MP 65	191283	906	FN(SR970) FAX(TYPE 7500)	RADF platen clover broken
Savin 8065	191919	526	PU(TYPE 3260) PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	Front door has deep scratch
Lanier LD265	191997	997	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Stapler not recognizing staples - not tested
Ricoh AFICIO MP 75	189579	221	PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	Jamming at finisher entrance - not tested, control panel yellow
Ricoh AFICIO MP 75	190923	516	PU(TYPE 3260) PC(TYPE 7500) P(RT43) FN(SR970)	
Savin 8080	191183	1331	PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	
Ricoh AFICIO MP 80	192568	35	PU(TYPE 3260) FN(SR970)	
Ricoh AFICIO MP 90	187260	1878	PU(PU5000) PS(TYPE 1350) PC(TYPE 1350) FN(SR5000)	Front door scratched, finisher plug broken - finisher not tested, off color panels
Ricoh AFICIO MP 90	189862	808	PU(PU5000) P(RT5000) FN(SR5000)	Error code SC-860 - hard-drive error; error code SC-872 software error & SC-925 - netfile error, will not come to ready
Ricoh AFICIO MP 90	191298	2411	PU(PU5000) PC(TYPE 1350) FN(SR5000)	Jamming in RADF - not tested, yellow panels
Ricoh AFICIO MP 90	191509	1579	PU(PU5000) PC(TYPE 1350) FN(SR5000)	Missing paperdeck - has hardware
Ricoh AFICIO MP 90	187436	705	PC(TYPE 9001) P(RT43) FN(SR4030)	Missing hard-drive - not tesetd, Has LCT but no hardware to connect to machine
Ricoh AFICIO MP 90	187438	941	PC(TYPE 9001) P(RT43) FN(SR4030)	Missing hard drive- unable to fully test; RT43 was never set up for this machine and is missing mounting hardware
Ricoh AFICIO MP 90	189073	1596	PC(TYPE 9001) FN(SR4030)	Missing hard-drive not fully tested
Ricoh AFICIO MP C2	176270	68	ST()	Touch screen inoperable- cannot fully test; removed hard drive; missing fax board (port cover missing); off color panels; color = 16k; B/W = 52k
Ricoh AFICIO MP C2	180364	80	ST()	Black meter = 36k, color meter = 45k
Ricoh AFICIO MP C2	180503	98	ST() PU(PU3000) FN(SR3000) E(BN3000)	Finsher throat and finisher bent - finisher not tested, black meter = 64k, color meter = 35k
Ricoh AFICIO MP C2	181433	98	ST() E(BN3000)	Black meter = 39k, color meter = 60k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C2	181870	160	ST() FN(SR3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 62k, color meter = 98k
Ricoh AFICIO MP C2	183372	238	ST() FAX(TYPE MPC3000) E(BN3000)	Black meter = 219k, color meter = 19k
Ricoh AFICIO MP C2	184076	229	ST() PU(PU3000) PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	Error code SC764 - paper position slide motor error - finisher not tested, bypass tray scratched, black meter = 135k, color meter 94k
Ricoh AFICIO MP C2	185903	198	ST() FAX(TYPE MPC3000)	Black meter = 190k, color meter = 8k
Lanier LD420C	186074	117	ST() FAX(TYPE MPC3000)	Black meter = 80k, color meter = 38k
Ricoh AFICIO MP C2	186564	104	ST() FAX(TYPE MPC3000) E(BN3000)	Black meter = 66k, color meter = 38k
Ricoh AFICIO MP C2	186587	194	ST() PU(PU3000) FN(SR3000) FAX(TYPE MPC3000)	Black meter = 95k, color meter = 100k
Ricoh AFICIO MP C2	176643	91	ST() FAX(TYPE C2550)	Front door missing - not tested, right side of RADF bent, stand back panel dented, stand front door missing, yellow panels, black meter - 91k; color meter = 1k
Ricoh AFICIO MP C2	179852	52	ST() FAX(TYPE C2550) E(BN3060)	Jamming in fuser during duplexing, dirty and off color panels, black meter = 41k, color meter = 1k
Ricoh AFICIO MP C2	182394	161	PED(PB3070) FAX(TYPE C2550) E(BN3060)	Black meter = 139k, color meter = 23k
Savin C9020	183546	27	ST()	Needs toner - not tested, black meter = 7k, color meter = 20k
Ricoh AFICIO MP C2	192665	195	ST() FAX(TYPE C2550)	Black meter = 92k, color meter = 103k
Savin C2525	183466	181	PED(PB3000) FN(SR790) E(BN3000)	Black meter = 178k, color meter = 3k
Gestetner DSC525	183900	157	ST() FN(SR790)	Error code SC750 - tray lift motor error - finisher not tested, black meter = 68k, color meter = 90k
Ricoh AFICIO MP C2	184237	264	ST()	Black meter = 237k, color meter = 27k
Savin C2525	184750	253	ST() FN(SR790) FAX(TYPE MPC3000)	Jamming in stapler - not tested, off color and dirty panels, black meter = 193k, color meter 60k
Ricoh AFICIO MP C2	184790	198	ST() SS(SH3000) E(BN3000)	Black meter = 116k, color meter = 82k
Gestetner DSC525	184814	290	PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 214k, color meter= 77k
Gestetner DSC525	185880	170	ST() FN(SR3010)	Finisher top panel yellow, black meter = 132k, color meter = 39k
Ricoh AFICIO MP C2	185983	109	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 92k, color meter = 17k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C2525	186391	212	PED(PB3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Jamming in stapler- not tested, hole in finisher shift tray, black meter = 148k, color meter = 65k
Ricoh AFICIO MP C2	186661	227	ST() SS(SH3000) FAX(TYPE MPC3000)	Black meter = 162k, color meter = 66k
Ricoh AFICIO MP C2	187308	296	ST() FN(SR790)	Black meter = 105k, color meter = 192k
Ricoh AFICIO MP C2	187475	201	ST() FAX(TYPE MPC3000)	Right side stand door broken, black meter = 173k, color meter = 29k
Savin C2525	187688	247	ST() FAX(TYPE MPC3000)	Black meter = 175k, color meter = 72k
Savin C2525	187776	261	PED(PB3000) FN(SR3010) FAX(TYPE MPC3000)	Color = 79k; B/W = 182k
Savin C2525	188117	156	ST()	Black meter = 78k, color meter = 78k
Ricoh AFICIO MP C2	188122	156	PED(PB3000) FAX(TYPE MPC3000)	Mising finisher has bridge unit installed, black meter = 138k, color meter = 19k
Ricoh AFICIO MP C2	188138	276	PED(PB3000) FN(SR790)	Black meter = 162k, color meter = 114k
Ricoh AFICIO MP C2	188139	274	ST() PED(PB3010) FAX(TYPE MPC3000)	Left side vent broken, black meter = 195k, color meter = 79k
Savin C2525	188141	267	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 206k, color meter = 61k, finisher panels yellow
Ricoh AFICIO MP C2	188163	234	ST() FAX(TYPE MPC3000) E(BN3000)	Black meter = 163k, color meter = 71k
Ricoh AFICIO MP C2	188523	228	ST() SS(SH3000) FAX(TYPE MPC3000) E(BN3000)	Color = 47k; B/W = 182k
Ricoh AFICIO MP C2	188898	671	PED(PB3000) FN(SR3010)	Color = 190k; B/W = 482k
Ricoh AFICIO MP C2	188900	242	ST()	Color = 18k; B/W = 225k
Lanier LD425C	189078	145	PED(PB3000)	Has external fiery - missing cables - not tested, black meter = 83k, color meter = 63k
Ricoh AFICIO MP C2	189728	234	ST() FAX(TYPE MPC3000)	Black meter = 227k, color meter = 8k, error code SC290 - shutter sensor time over error
Ricoh AFICIO MP C2	189786	N/A	ST() FN(SR790) FAX(TYPE MPC3000)	Touch screen not responding - not tested, Does not recognize used toner bottle
Ricoh AFICIO MP C2	189945	166	PED(PB3000) FAX(TYPE MPC3000)	Waste toner door will not latch, black meter = 110k, color meter = 56k
Ricoh AFICIO MP C2	190225	128	ST()	Front door broken, black mter = 116k, color meter = 13k
Ricoh AFICIO MP C2	190681	112	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 108k, color meter - 5k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C2	190778	N/A	ST()	Error code SC860 - hard-drive error - missing hard-drive - not tested, missing finisher - has bridge and mounting brackets, machine will not come to ready
Ricoh AFICIO MP C2	190782	286	ST() PS(TYPE C3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 219k, color meter = 68k
Ricoh AFICIO MP C2	190804	264	ST() FAX(TYPE MPC3000)	Wireless card antenna broken, black meter = 235k, color meter = 30k
Ricoh AFICIO MP C2	191223	N/A	ST() PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Touch screen not responding - not fully tested, removed hard-drive
Ricoh AFICIO MP C2	191510	135	PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Lower finisher mount badly bent - finisher not tested, black mter = 122k, color meter = 14k
Ricoh AFICIO MP C2	191741	411	PED(PB3000) FAX(TYPE MPC3000)	Black meter = 348k, color meter = 64k
Ricoh AFICIO MP C2	191974	214	PED(PB3000) FAX(TYPE MPC3000)	Missing finisher - has bridge unit, black meter = 146k, color meter = 68k
Ricoh AFICIO MP C2	191976	246	PED(PB3000) FAX(TYPE MPC3000)	Missing finisher - has bridge unit, black meter = 136k, color meter = 111k
Gestetner DSC525	192681	N/A	ST() FAX(TYPE MPC3000)	Touch screen not responding - not fully tested; hard drive removed
Ricoh AFICIO MP C2	174972	226	ST() FN(TYPE C2550) FAX(TYPE C2550)	Off color and dirty panels; black meter = 193k; color meter = 34k
Ricoh AFICIO MP C2	176640	238	ST() FAX(TYPE C2550) E(BN3060)	Black meter = 223k; color meter = 16k
Ricoh AFICIO MP C2	182704	211	PU(PU3010NA) PED(PB3030) FN(TYPE C2550) FAX(TYPE C2550)	Jamming in duplexer, finisher tray bracket broken, black meter = 187k, color meter = 25k
Ricoh AFICIO MP C2	185424	86	ST() FAX(TYPE C2550)	Void lines in copies, black meter = 83k, color meter = 3k
Ricoh AFICIO MP C2	185425	84	ST() FAX(TYPE C2550)	Black meter = 77k, color meter = 8k
Ricoh AFICIO MP C2	190031	174	PED(PB3030) FN(TYPE C2550) FAX(TYPE C2550)	Black meter = 52k, color meter = 123k
Ricoh AFICIO MP C2	190399	110	PED(PB3030)	Came in with wrong finisher (SR3000) - not tested, black meter = 37k, color meter = 74k
Ricoh AFICIO MP C3	180577	149	ST() FN(SR790) E(BN3000)	Black meter = 95k, color meter = 54k
Ricoh AFICIO MP C3	181054	168	PED(PB3000) FN(SR790)	Finisher yellow, black meter = 37k, color meter = 131k
Savin C3030	181401	275	ST() FAX(TYPE MPC3000) E(BN3000)	Black meter = 247k, color meter = 29k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C3030	181458	505 ST()	E(BN3000)	Black meter - 363k, color meter - 143k
Gestetner DSC530	181493	264 ST()	PS(TYPE C3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Black meter = 207k, color meter = 58k
Ricoh AFICIO MP C3	181866	393 ST()	SS(SH3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 388k, color meter = 5k
Ricoh AFICIO MP C3	182177	328 PS(TYPE C3000)	PED(PB3000) FAX(TYPE MPC3000)	Black meter = 122k, color meter = 207k
Ricoh AFICIO MP C3	182695	206 ST()	FAX(TYPE MPC3000) E(BN3000)	Black meter = 162k, color meter = 44k
Ricoh AFICIO MP C3	184908	482 ST()	PU(PU3000) PS(TYPE C3000) FN(SR3000)	Black meter = 147k, color meter = 436k
Gestetner DSC530	184915	244 ST()	FN(SR3010) FAX(TYPE MPC3000)	Control panel yellow, black meter = 191k, color meter = 53k
Gestetner DSC530	184916	295 ST()	FN(SR3010) FAX(TYPE MPC3000)	Black meter = 154k, color meter = 141k
Gestetner DSC530	184917	265 ST()	FN(SR3010) FAX(TYPE MPC3000)	Black meter = 123k, color meter = 142k
Ricoh AFICIO MP C3	187137	678 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000)	Off color panels, power plug socket broken, black meter = 419k, color meter = 260k
Ricoh AFICIO MP C3	190656	25 ST()	FN(SR3010)	Black meter = 10k, color meter = 15k
Ricoh AFICIO MP C3	190901	421 PED(PB3000)	FN(SR3010) FAX(TYPE MPC3000)	Black meter = 252k, color meter = 169k
Ricoh AFICIO MP C3	190902	471 PED(PB3000)	FN(SR3010) FAX(TYPE MPC3000)	Color = 129k; B/W = 343k
Ricoh AFICIO MP C3	190903	314 PED(PB3000)	FN(SR3010) FAX(TYPE MPC3000)	Blurry copies, black meter = 121k, color meter = 193k
Ricoh AFICIO MP C3	190904	422 PED(PB3000)	FN(SR3010) FAX(TYPE MPC3000)	Grinding in finisher (Still works), black meter = 283k, color meter = 140k
Ricoh AFICIO MP C3	191221	224 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000)	Black meter = 100k, color meter = 125k
Ricoh AFICIO MP C3	191512	541 ST()		Black meter = 46k, color meter = 496k
Gestetner DSC530	192336	667 ST()		Missing toner bottles- tested with others, Black meter = 616k, color meter = 52k
Ricoh AFICIO MP C3	185415	639 ST()	PU(TYPE 3260) FN(SR3020) FAX(TYPE MPC4500)	Front door scratched, black meter = 523k, color meter = 117k
Gestetner DSC535	185617	816 PS(TYPE C4500)	PED(PB3000) FN(SR3030)	Bypass tray broken, black meter= 515k, color meter = 301k
Ricoh AFICIO MP C3	187324	410 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Black meter = 141k, color meter = 269k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C3	187574	251	ST() FN(SR790) FAX(TYPE MPC4500)	Black meter = 168k, color meter = 83k
Lanier LD435C	188039	551	PED(PB3000) FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Black meter = 432k, color meter = 119k
Ricoh AFICIO MP C3	189079	436	PU(TYPE 3260) PED(PB3010) FN(SR3030)	Bracket below bypass tray bent, jamming at stapler, black meter = 346k, color meter = 91k
Savin C3535	189197	539	PU(PU3000) PED(PB3000) FN(SR3030)	Jamming in punch unit, black meter = 415k, color meter = 125k
Savin C3535	189249	499	PED(PB3000) FN(SR790)	Black meter = 261k, color meter = 238k
Ricoh AFICIO MP C3	189562	189	PU(TYPE 3260) PED(PB3010) FN(SR3020) FAX(TYPE MPC4500)	Error code SC549 - ferrite core rotation error - not fully tested, black meter = 157k, color meter = 32k
Ricoh AFICIO MP C3	189580	290	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Yellow panels, black meter = 123k, color meter = 167k
Ricoh AFICIO MP C3	189581	376	PS(TYPE C4500) PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Control panel yellow, black meter = 159k, color meter = 217k
Ricoh AFICIO MP C3	189789	539	PU(TYPE 3260) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 445k, color meter = 95k
Ricoh AFICIO MP C3	190911	294	PU(TYPE 3260) PS(TYPE C4500) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 214k, color meter = 81k
Ricoh AFICIO MP C3	191295	308	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 206k, color meter = 102k
Ricoh AFICIO MP C3	191744	237	ST() FAX(TYPE MPC4500)	Error code SC860 - hard-drive connection problem - not fully tested, missing finisher - has bridge unit & hardware, black meter = 216k, color meter = 32k
Lanier LD435C	191844	581	PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Jamming in punch unit - not tested, black meter = 378k, color meter = 204k
Lanier LD435C	191845	305	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 263k, color meter = 43k
Lanier LD435C	191936	23	ST()	RADF plug socket broken, black meter = 12k, color meter = 12k
Ricoh AFICIO MP C4	187401	430	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Lower finisher tray mount badly bent causing error code SC750 - shift tray motor or sensor, yellow control panel, black meter = 400k, color meter = 31k
Savin C4040	189198	827	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Has USB/SD card reader, jamming in stapler, black meter = 424k, color meter = 404k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C4040	189201	457	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Has USB/SD card reader, black meter= 264k, color meter = 194k
Ricoh AFICIO MP C4	190679	217	PED(PB3050) FN(SR790) FAX(TYPE C5000)	Could not get into sp mode - hard-drive removed -not fully tested, black meter = 197k, color meter = 20k
Ricoh AFICIO MP C4	190779	475	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Black meter = 327k, color meter = 148k
Ricoh AFICIO MP C4	191733	280	PED(PB3040) FN(SR790)	Black meter = 221k, color meter = 59k
Ricoh AFICIO MP C4	183764	313	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 302k, color meter = 11k
Ricoh AFICIO MP C4	183765	315	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Error code SC750 - tray lift motor - finisher not tested, black meter = 299k, color meter = 17k
Ricoh AFICIO MP C4	183767	612	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	RADF off color, black meter = 305k, color meter = 308k
Ricoh AFICIO MP C4	183768	691	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 433k, color meter = 259k
Ricoh AFICIO MP C4	183769	355	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Jamming in stapler - not tested, black meter = 295k, color meter = 61k
Ricoh AFICIO MP C4	184239	575	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 520k, color meter = 56k
Gestetner DSC545	185442	323	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	RADF jamming when reversing, jamming in punch unit, black meter = 258k, color meter = 65k
Savin C4540	185641	403	PS(TYPE C4500) PED(PB3000) FN(SR3020)	Black meter = 243k, color meter = 161k, off color panels
Gestetner DSC545	186580	330	PU(TYPE 3260) PS(TYPE C4500) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 159k, color meter = 171k
Ricoh AFICIO MP C4	186645	561	PS(TYPE C4500) PED(PB3000)	Right side filter cover missing, black meter - 187k, color meter = 374k
Gestetner DSC545	186658	566	PU(TYPE 3260) PED(PB3000) FN(SR3030)	Black meter = 482k, color meter = 85k
Ricoh AFICIO MP C4	186884	417	ST() PS(TYPE C4500) FAX(TYPE MPC4500)	Color copies are password protected, black meter = 376k, color meter = 42k
Ricoh AFICIO MP C4	187143	297	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	PC and Scan does not come to ready - not tested, black meter = 141k, color meter = 157k
Gestetner DSC545	187775	1090	PU(TYPE 3260) PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Jamming in bypass, jamming in duplexer, jamming in stapler, black meter = 631k, color meter = 460k
Savin C4540	188589	764	PU(PU3000) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Color = 114k; B/W = 650k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD445C	189163	293	ST() FN(SR790) FAX(TYPE MPC4500)	Black meter = 265k, color meter = 29k
Ricoh AFICIO MP C4	189582	184	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Yellow control panel cover, black meter = 64k, color meter = 121k, most of image missing on copies
Ricoh AFICIO MP C4	190032	868	PU(TYPE 3260) PS(TYPE C4500) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 621k, color meter = 247k, error code SC750 - tray lift motor error - lower finisher tray clicking - finisher not tested, black meter = 621k, color meter - 247k
Ricoh AFICIO MP C4	190662	201	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Color copies blurry, black meter = 92k, color meter = 110k
Ricoh AFICIO MP C4	190677	211	PED(PB3010) FAX(TYPE MPC4500) E(BN3010)	Black meter = 156k, color meter = 56k
Ricoh AFICIO MP C4	190678	304	PED(PB3010)	Color on black copies, black meter = 231k, color meter = 74k
Savin C4540	191920	298	PU(PU3000) PS(TYPE C4500) PED(PB3010) FN(SR3020) FAX(TYPE MPC4500)	Color meter - 182k, black meter = 116k
Gestetner DSC545	191921	697	PU(TYPE 3260) PED(PB3000) FN(SR3020)	Error code SC547 - zero cross error, fuser relay, 24 volt fuse on PSU, , cassette #3 will not close, black meter = 536k, color meter = 162k
Ricoh AFICIO MP C4	191922	837	PU(TYPE 3260) PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Jamming at second finisher tray- tray mount panel broken (finisher not tested), black meter = 425k, color meter = 413k
Ricoh AFICIO MP C4	191978	284	PU(TYPE 3260) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Left side panel dented and scratched in front corner, black meter = 156k, color meter = 128k
Gestetner DSC545	192208	601	PED(PB3010) FN(SR3020)	Jamming in finisher - not tested, black meter = 530k, color meter = 72k
Gestetner DSC545	192585	377	ST() PU(TYPE 3260) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 317k, color meter = 60k
Ricoh AFICIO MP C5	176642	228	PED(PB3050) FAX(TYPE C5000)	Black meter = 227k; color meter = 1k
Ricoh AFICIO MP C5	182067	232	ST() FN(SR790)	Finisher throat cross support bent - not tested, black meter = 171k, color meter = 61k
Ricoh AFICIO MP C5	185334	344	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Black meter = 263k, color meter = 81k
Ricoh AFICIO MP C5	190781	407	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Error code SC860 - hard-drive error - hard-drive missing - not fully tested, lower finisher tray mount bent - finisher not tested, black meter = 328k, color meter = 80k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C6	164495	515	PU(TYPE 3260) P(RT43) FN(SR4010) FAX(TYPE C7500)	Paper deck inop - not tested; Front door scratched
Ricoh AFICIO MP C6	176260	651	FN(SR4010) FAX(TYPE C7500)	Blurred areas on prints (sporadic); color = 155k; B/W = 496k
Ricoh AFICIO MP C6	176261	462	FN(SR4010) FAX(TYPE C7500)	Color = 103k; B/W = 360k
Savin C6055	176364	362	FN(SR4010) FAX(TYPE C7500)	Missing black toner bottle - not tested, black meter = 201k; color meter = 162k
Ricoh AFICIO MP C6	184207	1431	FN(SR4020)	Black meter = 1379k, color meter = 53k
Ricoh AFICIO MP C6	184427	586	PU(TYPE 3260) PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Color = 33k; B/W = 554k
Lanier LD260C	192670	487	PU(TYPE 3260) FN(SR4020)	Missing finisher entrance guide- tested with another; Black meter = 298k, color meter = 190k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.  
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.  
Please call our sales team for current availability.