

Wulff Enterprises

02/10/2012

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2513	192776	126	ADF(DF74)	Off color panels
Gestetner 3502	191355	1613	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) P(RT36) NIC(TYPE 1045) FN(SR720) FAX(TYPE 1045)	Jammin in stapler - not tested, yellow panels
Ricoh AFICIO 1035	191964	213	ST() RADF(DF70) PC(TYPE 1045[S])	Blank copies
Gestetner 4502	191360	973	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR760) FAX(TYPE 1045)	Bypass tray broken, yellow panels
Ricoh AFICIO 1045	191965	614	RADF(DF70) PED(PS360) PC(TYPE 1045) NIC(TYPE 1045)	
Gestetner 6002	191363	1102	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Error code SC542 - fuser temp to olow - not tested, Cassette #3 - not tested - partition missing
Ricoh AFICIO 1060	191959	1759	PC(TYPE 1075[S]) FN(SR850)	Off color and dirty panels, RADF plug socket broken
Ricoh AFICIO 1060	191960	1877	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	
Ricoh AFICIO 1060	191961	2678	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	RADF plug socket loose
Lanier LD060	192034	3116	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Cassette #2 not feeding - not tested, jamming in stapler jogger - stapler not tested
Lanier LD060	192145	875	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Hard-drive error - hard-drive missing - not fully tested
Savin 2560	192777	1163	PU(TYPE 1045) PC(TYPE 1075) P(RT43) FN(SR850)	Very dirty panels, control panel quit functioning during testing - not fully tested
Gestetner 7502	191367	1419	PU(TYPE 1075) PC(TYPE 1075[S])	Has SR861 finisher (works OK)
Gestetner 7502	191403	1614	PC(TYPE 1075[S]) FN(SR850)	
Ricoh AFICIO 1075	191958	1275	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Not recognizing staples - stapler not tested, slit glass frame cracked
Ricoh AFICIO 1224C	185616	198	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830)	RADF yellow, bypass tray mount broken, black meter = 133k, color meter = 66k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 1515	183211	78		Yellow RADF and duplexer deflector cover
Ricoh AFICIO 1515	189035	121		ADF feed tray broken
Ricoh AFICIO 1515	189036	64		ADF feed tray broken, back panel dented and bent
Gestetner DSM415	190454	98		ADF tray broken, ADF yellow
Ricoh AFICIO 1515	191396	205		Accessory cover panel cracked, ADF feed tray missing, ozone fan loud
Savin 3515	192504	35		Error code SC120 - scanner home problem - not tested
Savin 3515	192505	25		
Savin 3515	192506	14		RADF feed tray broken
Ricoh AFICIO 1515F	184169	29		RADF yellow, jamming in duplexer, jamming in fuser
Ricoh AFICIO 1515F	188205	148		
Ricoh AFICIO 1515F	192362	76 ST()	PC(TYPE 1515)	ADF yellow, ADF feed tray broken
Ricoh AFICIO 1515M	182019	961		
Ricoh AFICIO 1515M	182025	150		Missing cassette, paper feed unit broken, RADF tray broken, yellow, right side panel broken, missing fuser - not tested
Ricoh AFICIO 1515M	182028	44		Dirty inside machine, yellow
Ricoh AFICIO 1515M	182029	791		Jams in fuser - not tested, very dirty
Ricoh AFICIO 1515M	182030	40		ADF off color, dirty inside machine
Ricoh AFICIO 1515M	182032	1261		Yellow, toner in cassette, bypass switch out of place - not tested
Ricoh AFICIO 1515M	182034	33		
Ricoh AFICIO 1515M	182035	154 ST()	PS(TYPE 2018) PFU(PS480)	
Ricoh AFICIO 1515M	182631	909 ST()		Yellow panels
Ricoh AFICIO 1515M	182637	559		ADF feed tray broken
Ricoh AFICIO 1515M	182639	501		
Ricoh AFICIO 1515M	190254	50		Toner spilled throughout machine, could not test cassette, double image on copies, yellow & dirty panels
Lanier LD015SPF	190588	210 PFU(PS480)		
Ricoh AFICIO 2015	181927	76 ST()		
Ricoh AFICIO 2015	181928	105 ST()		
Savin 4015	189505	70 ST()	PFU(PS450) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Yellowed panels; missing stand door

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8016	179990	142	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Yellow panels
Ricoh AFICIO 2016	185387	51	ST() ADF(DF78)	RADF yellow
Ricoh AFICIO 2016	191432	43	ST() FAX(TYPE 2018) ADF(DF78)	RADF off color
Ricoh AFICIO 2016	191544	27	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Cassette #2 not feeding - not tested
Ricoh AFICIO 2018D	185240	505	ST() RADF(DF79)	RADF yellow
Gestetner DSM618D	191381	173	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018)	Jamming in duplexer
Gestetner DSM618D	191408	135	ST() RADF(DF79)	RADF yellow
Ricoh AFICIO 2018D	191411	349	ST() RADF(DF79) PC(TYPE 2018)	
Ricoh AFICIO 2018D	191429	116	RADF(DF79) FAX(TYPE 2018)	Yellow panels
Ricoh AFICIO 2020	188197	67	ST() ADF(DF78)	Yellow ADF panels
Ricoh AFICIO 2020	188204	112	ST() ADF(DF78)	Jamming at drum unit - not tested
Lanier LD120	191550	174	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018)	Has ARDF - DF2010
Savin 8020	191682	55	ST()	Has ADF- DF2000
Ricoh AFICIO 2020D	190738	191	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	
Ricoh AFICIO 2020D	190742	178	ST() RADF(DF79) PC(TYPE 2018)	RADF yellow
Ricoh AFICIO 2020D	190882	339	ST() RADF(DF79) PFU(PS450) PC(TYPE 2018)	off color and dirty panels, top right side panel below RADF cracked
Gestetner DSM620D	191105	469	ST() RADF(DF79) PFU(PS460) PC(TYPE 2018)	Yellow panels, PFU connector cover missing
Gestetner DSM620D	191106	291	ST() RADF(DF79) PC(TYPE 2018)	RADF off color
Gestetner DSM620D	191394	317	ST() RADF(DF79) PC(TYPE 2018)	
Ricoh AFICIO 2020D	191405	274	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Yellow panels
Ricoh AFICIO 2020D	191407	151	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018)	
Ricoh AFICIO 2020D	191431	66	ST() RADF(DF79) FAX(TYPE 2018)	RADF off color

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8020D	191597	382	ST() PC(TYPE 2018) FAX(TYPE 2018)	Has ARDF DF2010
Ricoh AFICIO 2020D	192782	171	ST() RADF(DF79) PC(TYPE 2018)	
Ricoh AFICIO 2022	183220	529	ST() RADF(DF75) PC(TYPE 2027)	Bypass tray broken
Ricoh AFICIO 2022	183750	262	ST() RADF(DF75) PC(TYPE 2027) FN(SR790) FAX(TYPE 2027)	Bypass tray broken - not tested, error code SC870 - Hard-drive or software - missing hard-drive
Savin 4022	183921	75	ST() RADF(DF75) FAX(TYPE 2027)	
Ricoh AFICIO 2022	189058	205	ST() RADF(DF75)	Yellow panels
Ricoh AFICIO 2022	190743	295	ST() SS(TYPE 1027) RADF(DF75)	Control panel function buttons missing
Ricoh AFICIO 2022	191424	319	RADF(DF75) PED(PS490) PC(TYPE 2027) FAX(TYPE 2027)	Yellow panels
Lanier LD127	183097	254	ST() RADF(DF75) PC(TYPE 2027)	Off color panels
Ricoh AFICIO 2027	183958	364	ST() RADF(DF75)	Dirty, RADF yellow
Ricoh AFICIO 2027	189059	280	SS(TYPE 1027) RADF(DF75) PED(PS490) PC(TYPE 2027) FAX(TYPE 2027)	Cassette #2 feed tires broken - not tested
Lanier LD127	190582	43	RADF(DF75) PED(PS500) PC(TYPE 2027) FAX(TYPE 2027)	Bypass tray broken - not tested, has bridge unit - missing finisher, bridge unit socket broken
Ricoh AFICIO 2027	190625	393	ST() RADF(DF75) PC(TYPE 2027) FN(SR820) FAX(TYPE 2027)	Stand front door broken, RADF yellow
Ricoh AFICIO 2027	190626	63	ST() RADF(DF75) FN(SR820) FAX(TYPE 2027)	Error code SC731 - output tray error - finisher not tested, bypass tray broken & will not lower - not tested
Ricoh AFICIO 2027	190690	364	RADF(DF75) PC(TYPE 2027)	Off color panels, dirty
Ricoh AFICIO 2027	190744	642	ST() RADF(DF75) PC(TYPE 2027) FN(SR820) FAX(TYPE 2027)	Off color, toner handle broken
Gestetner DSM627	191401	538	ST() RADF(DF75) PC(TYPE 2027) FN(SR790) FAX(TYPE 2027)	Off color panels
Ricoh AFICIO 2027	191406	824	ST() RADF(DF75) PC(TYPE 2027) FN(SR790) FAX(TYPE 2027)	Off color and dirty, right side access door broken
Ricoh AFICIO 2027	191666	231	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE 2027)	Yellow panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4035E	192146	391	ST() FN(SR790)	Off color panels
Savin 4035E	192147	419	ST() FN(SR790)	Off color panels
Gestetner DSM635	192476	236	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	Yellow panels
Ricoh AFICIO 2045	191409	298	ST()	
Ricoh AFICIO 2051	182041	4134	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	182131	2815	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Machine dirty, toner spilled in machine, off color
Ricoh AFICIO 2051	182132	2588	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	182133	3932	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Ground in dirt
Ricoh AFICIO 2051	182134	2151	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Toner spilled in machine, off color and dirty
Ricoh AFICIO 2051	182135	173	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Off color and dirty
Ricoh AFICIO 2051	182136	813	PS(TYPE 2075) PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Off color and dirty
Ricoh AFICIO 2051	182641	2841	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; RADF outlet broken, off color and dirty
Ricoh AFICIO 2051	182642	1427	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Off color and very dirty
Ricoh AFICIO 2051	182643	1052	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	182648	669	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	182649	1432	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	182650	2136	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	182651	2565	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	182652	1170	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Needs new staple cartridge - borrowed to test stapler functionality
Ricoh AFICIO 2051	182653	3336	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Tandem tray #1 will not raise - not tested,
Ricoh AFICIO 2051	182654	3381	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Toner spilled in machine, jamming in duplexer - not tested
Ricoh AFICIO 2051	182655	414	PS(TYPE 2075) PC(TYPE 2075) FN(SR850)	Hard drive removed after testing
Ricoh AFICIO 2051	189180	3584	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; yellowed panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM651	190485	3916	PC(TYPE 2075) E()	Missing tandem tray left side paper fence; broken fuser unit release handle; missing serial tag; exit overflow actuator displaced
Ricoh AFICIO 2060	182656	3322	PC(TYPE 2075) FN(SR850)	Hard drive removed after testing; Broken front side fence of tandem tray; off color & very dirty panels
Ricoh AFICIO 2060	192502	1011	PC(TYPE 2075) FN(SR850)	Error code SC860 - hard-drive error - removed PC sd card and hard-drive to test
Ricoh AFICIO 2090	190707	10279	PS(TYPE 2105) PC(TYPE 2105) FN(SR840)	Cassettes #2,3 not feeding - not tested, ground in dirt, off color panels
Ricoh AFICIO 2090	190708	9820	PU(TYPE 1075) PS(TYPE 2105) PC(TYPE 2105) P(RT46) FN(SR840)	Cassettes #2,3 not feeding - not tested
Lanier 5222	162295	310	ST() RADF(RADF-527) DX(ADM-527)	Yellowed panels
Ricoh AFICIO 220	182987	316	SS(TYPE 270) RADF(DF69) PED(PS420)	Ground in dirt, yellow panels, toner spilled in cassettes
Ricoh AFICIO 2228C	192623	360	ST()	Yellow panels, duplexer exit tray missing, bypass trim panel missing, black meter = 298k, color meter = 63k
Savin C3224	186162	443	PED(PS550) FAX(TYPE 2238) E(PT460)	Bent controller box; front door interlock out of alignment; missing fax button; yellowed panels; color = 195k; B/W = 249k
Lanier LD232C	190186	567	PED(PS540) FAX(TYPE 2238) E(PT460)	Yellow panels, black meter = 414k, color meter = 154k
Lanier LD232C	192046	261	ST() E(PT460)	Yellow panels, Back panel dented, frame dented on left side, black meter = 185k, color meter = 76k
Gestetner DSC338	189975	384	PED(PS550) FN(SR920) FAX(TYPE 2238)	Yellow panels, black meter = 365k, color meter = 19k
Savin 8025	179038	276	ST() RADF(DF83) PC(TYPE 3030 (S))	RADF and finsher yellow
Ricoh AFICIO 3025	181307	127	PED(PS490) PC(TYPE 3030 (S))	Glass is raised 1 inch, bypass tray broken
Ricoh AFICIO 3025	181308	153	PED(PS490) PC(TYPE 3030 (S))	Glass raised 1 inch
Ricoh AFICIO 3025	181309	161	PED(PS490) PC(TYPE 3030 (S))	Scan glass raised 1 inch
Lanier LD225	181843	212	ST() RADF(DF83) PC(TYPE 3030 (S))	Cassette #1 will not lift - error code SC501 - not tested
Gestetner DSM725	182569	209	ST() RADF(DF83) FAX(TYPE 3030)	RADF yellow
Ricoh AFICIO 3025	182661	147	ST() RADF(DF83)	Hard drive removed after testing;

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Yellow panels, finisher top access door broken, missing finisher tray, very dirty
Ricoh AFICIO 3025	182662	153	ST() RADF(DF83) PS(TYPE 3030) PC(TYPE 3030 (S)) FAX(TYPE 3030)	Removed hard drive after testing; Yellow and dirty
Ricoh AFICIO 3025	182663	142	ST() RADF(DF83) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Hard drive removed after testing; Dirty, Off color, RADF and finisher yellow, toner spilled in machine
Ricoh AFICIO 3025	183002	217	ST() RADF(DF83)	Touch screen locked up- cannot fully test; yellowed RADF panels
Savin 8025	183075	625	RADF(DF83) PED(PS490) PC(TYPE 3030 (S))	Copies not fusing
Gestetner DSM725	183195	248	ST() RADF(DF83) PC(TYPE 3030 (S))	RADF and control panel yellow
Ricoh AFICIO 3025	183216	313	ST() RADF(DF83) PC(TYPE 3030) FN(SR790) - not tested, yellow finisher panels	Finisher stapler not recognizing paper
Ricoh AFICIO 3025	183972	129	ST() RADF(DF83)	
Savin 8025	185108	399	ST() RADF(DF83) PC(TYPE 3030 (S))	Jamming in bypass - not tested
Gestetner DSM725	186900	157	ST() RADF(DF83) FN(SR820)	Does not recognize staples in stapler - not tested, RADF yellow
Ricoh AFICIO 3025	187371	184	ST() RADF(DF83)	
Savin 8025	188934	568	ST() RADF(DF83) PC(TYPE 3030 (S)) FAX(TYPE 3030) E(PT280)	
Gestetner DSM725	189054	292	ST() RADF(DF83)	Yellow control panel, RADF yellow
Ricoh AFICIO 3025	189116	410	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Broken byass tray; dirty & off color panels
Gestetner DSM725	190214	928	ST() RADF(DF83) PC(TYPE 3030 (S))	Toner spilled in cassettes, bypass tray broken, RADF off color
Ricoh AFICIO 3025	190487	414	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030) E(PT280)	Off color panels
Lanier LD225	190589	490	ST() RADF(DF83) PC(TYPE 3030 (S)) FAX(TYPE 3030) E(PT280)	RADF yellow, off color panels, bypass tray broken
Ricoh AFICIO 3025	191387	440	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	
Gestetner DSM725	191391	82	ST() RADF(DF83) FAX(TYPE 3030)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8025	191691	218	ST() RADF(DF83) PC(TYPE 3030 (S))	Cassette #2 not recognizing paper = not tested, bypass tray hinges broken
Lanier LD230	180399	393	ST() RADF(DF83)	Missing Doc server, printer and scan features - has buttons
Ricoh AFICIO 3030	182047	525	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030)	Hard drive removed after testing; Yellow panels
Ricoh AFICIO 3030	182048	217	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Hard drive removed after testing
Ricoh AFICIO 3030	182049	571	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Hard drive removed after testing; Toner spilled in cassettes
Ricoh AFICIO 3030	182050	439	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Hard drive removed after testing; RADF yellow
Ricoh AFICIO 3030	182139	319	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Removed hard drive after testing; Jamming in stapler - not tested, bypass tray broken
Savin 8030	182574	262	ST() RADF(DF83) PC(TYPE 3030 (S))	RADF yellow and finisher
Ricoh AFICIO 3030	182657	143	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030)	Removed hard drive after testing; Missing finisher - has brackets, bypass tray broken
Ricoh AFICIO 3030	182658	741	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Removed hard drive after testing; Very dirty, yellow, jamming in bypass - not tested, jams in stapler, bypas tray broken
Ricoh AFICIO 3030	182659	273	ST() RADF(DF83) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE	Removed hard drive after testing; Finisher deflector broken, bypass tray broken
Ricoh AFICIO 3030	182660	588	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030)	Removed hard drive after testing; Registration off, jamming at conveyer in finisher, yellow panels
Ricoh AFICIO 3030	185386	216	ST() RADF(DF83) PC(TYPE 3030) FAX(TYPE 3030) E(PT280)	Error code SC542- fuser temp too low - not tested, RADF yellow
Savin 8030	186734	310	ST() RADF(DF83) PC(TYPE 3030 (S))	Front door actuator broken, off color panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8030	188511	250	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR820) FAX(TYPE 3030) E(PT280)	Missing cassette #1, right side access door broken, jamming in finisher - not tested, Yellow panels, broken bypass tray
Savin 8030	188512	455	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR820) FAX(TYPE 3030) E(PT280)	RADF yellow, jamming in duplexer
Savin 8030	190357	730	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030)	Missing finisher - has bridge unit and mount screws
Savin 8030	192213	457	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030) E(PT280)	Off color and dirty panels
Gestetner DSM735	186874	59	ST()	
Ricoh AFICIO 3035	187515	389	PED(PS530) FN(SR790) FAX(TYPE 3045)	Yellow, finisher stapler spring - not tested
Ricoh AFICIO 3035	189761	103	ST() PC(TYPE 3045)	Yellow panels
Ricoh AFICIO 3035	190766	438	ST() PS(TYPE 3045) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Error code SC992 - software error code - not tested
Gestetner DSM735	190833	259	ST() PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Error code SC819 - control board, system program or optional board - appeared after testing
Gestetner DSM735	191108	154	ST() PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO 3035	191359	1075	PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	Yellow panels
Gestetner DSM735	191532	361	PU(TYPE 1045) PED(PS530) FN(SR880)	Finisher tray cracked, very dirty and off color
Gestetner DSM735	191533	293	PU(TYPE 1045) PED(PS530) FN(SR880)	Off color and dirty
Gestetner DSM735	191963	488	ST()	Yellow and dirty panels
Ricoh AFICIO 3035	192052	190	ST() PC(TYPE 3045) FAX(TYPE 3045)	Off color panels
Savin 8035	192465	95	PED(PS530) PC(TYPE 3045) FAX(TYPE 3045)	Off color panels
Ricoh AFICIO 3045	182051	438	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3045	182052	1681	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing
Ricoh AFICIO 3045	182053	487	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Finisher top access door broken, yellow panels
Ricoh AFICIO 3045	182054	867	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Toner spilled in machine, off color
Ricoh AFICIO 3045	182055	1520	PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Yellow panels, toner spilled in cassettes, jamming at paper deflector in duplexer - not tested
Ricoh AFICIO 3045	182056	355	PED(PS530) PC(TYPE 3045) FN(SR790)	Hard drive removed after testing
Ricoh AFICIO 3045	182071	594	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Toner spilled in cassettes
Ricoh AFICIO 3045	182072	862	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Toner spilled in cassettes, touch screen not responding - not fully tested
Ricoh AFICIO 3045	182073	688	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Error code SC322 - laser/ synch problem - not tested, toner spilled in
Ricoh AFICIO 3045	182076	158	PS(TYPE 3045) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing
Ricoh AFICIO 3045	182140	1693	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Yellow panels
Ricoh AFICIO 3045	182665	1270	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Off color panels, transfer belt handle broken
Ricoh AFICIO 3045	182666	902	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing
Ricoh AFICIO 3045	182667	697	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Finisher yellow, jamming in fuser - not tested
Ricoh AFICIO 3045	182668	1488	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Hard drive removed after testing; Toner spilled in cassettes, error code SC725 - finisher stack feed out motor or sensor - stapler not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8045	183059	167	PED(PS530) PC(TYPE 3045) FN(SR790)	
Ricoh AFICIO 3045	188852	193	PED(PS530) FN(SR790) FAX(TYPE 3045)	Off color panels
Savin 8045	188933	154	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Error code SC870 - address book data error - hard-drive failure, looks like hard-drive was scrubbed, unable to fully test machine, hard-drive removed, off color, finisher yellow
Lanier LD245	190590	629	PED(PS530) FN(SR790)	
Gestetner DSM745	190784	299	PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Gestetner DSM745	190785	233	PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Gestetner DSM745	190786	304	PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Ricoh AFICIO 3045	190866	368	PU(TYPE 1045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	Missing hard-drive - not fully tested, off color panels, bottom finisher tray cracked
Ricoh AFICIO 3045	191661	417	PED(PS530)	Yellow panels
Ricoh AFICIO 3045	191962	601	ST()	Yellow and dirty panels
Savin 8045	192301	585	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Lower right side access panel missing, touch screen not responding - not fully tested
Ricoh AFICIO 3045	192704	198	ST() PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Finisher deflector missing spring - finisher not tested, off color and dirty panels
Savin 8045	192846	473	ST() FN(SR790)	Error code SC995 - machine type information error - not tested, very dirty, yellow
Lanier LD124C	183865	57	ST() FAX(TYPE 3232)	Jamming out of cassette #2, black meter = 49k, color meter = 9k
Savin C2410	184861	431	ST()	Black meter = 263k, color meter = 168k
Ricoh AFICIO 3224C	190168	80	ST() FN(SR830)	Touch screen not responding - not fully tested, yellow panels, finisher jogger arm broken, black meter = 20k, color meter = 61k
Ricoh AFICIO 3228C	182645	320	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Hard drives removed after testing; Yellow panels, black meter = 113k, color meter = 208k
Gestetner DSC428	186875	90	PED(PS590) FAX(TYPE 3245) E(PT460)	Needs black toner - not tested, black meter = 67k, color meter = 24k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3228C	190169	343	PS(TYPE 3245) FN(SR960) FAX(TYPE 3245) E(PT460)	Lower finisher tray missing, right side scanner cover scratched, yellow panels, exit tray broken
Ricoh AFICIO 3228C	190170	169	ST() PS(TYPE 3245) FN(SR960) E(PT460)	Yellow and dirty panels, jamming in duplexer, fax panel dented, black meter= 131k, color meter = 39k
Ricoh AFICIO 3228C	190171	204	ST() FN(SR960) E(PT460)	RADF socket frame broken, slit glass cracked, yellow and dirty panels, black meter= 157k, color meter = 48k
Ricoh AFICIO 3228C	190172	286	PS(TYPE 3245) PED(PS590) FN(SR960) E(PT460)	Yellow panels, black meter = 250k, color meter - 37k
Ricoh AFICIO 3228C	190326	198	ST() PS(TYPE 3245) FN(SR960)	Error code SC733 - finisher lower stack height sensor or tray 2 lift motor, lower finisher tray will not stay up - not tested, dirty and off color panels, black meter = 164k, color meter = 35k
Ricoh AFICIO 3228C	190327	555	PS(TYPE 3245) PED(PS590) FN(SR960) E(PT460)	RADF jamming when reversing, yellow panels, finisher tray cracked, black meter = 506k, color meter = 49k
Ricoh AFICIO 3228C	190328	423	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Front door broken, Jamming in duplexer, Error code SC385 - Image density sensor dirty, ID sensor, por connection or bad ID sensor, Very yellow, top finisher tray cracked
Ricoh AFICIO 3228C	190329	79	PS(TYPE 3245) PED(PS600) FN(SR960) E(PT460)	Finisher bracket guide pin broken, very yellow, PED not recognizing paper - not tested
Ricoh AFICIO 3228C	190330	244	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Jamming in RADF - not tested, very yellow, bottom finisher tray cracked, black meter = 20k, color meter =
Ricoh AFICIO 3228C	190553	113	PS(TYPE 3245) PED(PS590) FN(SR960)	PED frame bent - cassette #4 will not close, error code SC622 - connector BCU or main board of unit - PED not tested, finisher trays will not lift - not tested, stapler cartridge missing, very yellow, black meter = 97k, color meter = 17k
Ricoh AFICIO 3228C	190554	480	PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Error code SC-560 - zero cross error - not tested, black meter = 297k, color meter = 184k
Ricoh AFICIO 3228C	190565	147	PED(PS590) FN(SR960) E(PT460)	Yellow panels, finisher tray cracked, bottom right side access door broken, bypass lower trim panel missing, jamming in RADF - not tested, jamming in duplexer - not tested, grinding noise in fuser, error code sc471 - home position error for transfer belt - not fully tested, black meter = 129k, color meter = 18k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3228C	190881	333	PED(PS580) FAX(TYPE 3245) E(PT460)	Yellow panels, missing finisher - has brackets, black emter = 271k, color meter = 63k
Gestetner DSC428	191110	521	PS(TYPE 3245) PED(PS580) FN(SR960) FAX(TYPE 3245) E(PT460)	Off color panels, black meter = 313k, color meter = 208k
Ricoh AFICIO 3235C	182646	350	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Removed hard drives after testing; Black meter = 204k, color meter = 146k, yellow panels, jamming in machine
Ricoh AFICIO 3235C	182647	660	PS(TYPE 3245) PED(PS590) FAX(TYPE 3245) E(PT460)	Hard drives removed after testing; Has SR920 finisher, yellow finisher and cassettes, black meter = 478k, color meter = 182k
Ricoh AFICIO 3235C	190555	380	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Yellow and dirty panels, finisher trays broken, black meter = 361k, color meter = 20k
Ricoh AFICIO 3235C	190556	420	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245)	Yellow panels, Exit tray missing, RADF skewing copies - not tested, black meter = 327k, color meter = 94k
Ricoh AFICIO 3245C	180837	1027	PU(TYPE 1045) PED(PS590) FN(SR960)	Finisher exit area bent - finisher not tested, yellow and dirty, bypass missing paper guide. black meter = 1014k, color meter = 14k
Gestetner DSC445	181253	1117	PED(PS580) E(PT460)	Yellowed panels; color = 541k; B/W = 577k
Ricoh AFICIO 3245C	183973	602	PED(PS590) FAX(TYPE 3245) E(PT460)	Error code SC672 (controller to op panel communication error); yellowed panels; missing toner cartridges; color = 13k; B/W = 589k
Gestetner DSC445	188706	240	ST() PU(TYPE 2238) FN(SR960) FAX(TYPE 3245) E(PT460)	Jams in area Z1 every try- can't test; off color & dirty panels
Ricoh AFICIO 3245C	189509	1432	PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Missing print controller; touch screen inop; color = 517k; B/W = 915k; yellowed panels
Ricoh AFICIO 3245C	190079	339	PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Off color panels, black meter = 194k, color meter = 146k
Ricoh AFICIO 3245C	190173	341	PU(TYPE 1045) PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Grinding in finisher, cassette #1 not recognizing paper - not tested, front door interlock broken, will not latch, yellow panels, black meter = 257k, color meter= 84k
Ricoh AFICIO 3245C	190174	1084	PS(TYPE 3245) PED(PS600) FN(SR960) E(PT460)	Yellow panels, Bottom cassette not recognizing paper - not tested, black mter = 887k, color meter = 197k
Ricoh AFICIO 3245C	190178	194	PS(TYPE 3245) PED(PS590) FN(SR960) E(PT460)	Yellow panels, black mter = 87k, color meter = 107k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3245C	190306	768	PS(TYPE 3245) PED(PS590) FN(SR960) E(PT460)	Yellow panels, finisher throat bent, finisher access door handle broken, black meter = 688k, color meter = 81k
Ricoh AFICIO 3245C	190307	1120	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Error code SC733 - tray 2 shift motor error - finisher not tested, missing lower finisher tray, black meter = 703k, color meter = 417k
Ricoh AFICIO 3245C	190308	350	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Very yellow, jamming in fuser -not tested, knocking noise in machine, black meter = 264k, color meter = 86k
Ricoh AFICIO 3245C	190312	920	PU(TYPE 1045) PS(TYPE 3245) PED(PS600) FN(SR960) E(PT460)	Yellow panels, black meter = 490k, color meter = 431k
Ricoh AFICIO 3245C	190313	968	PS(TYPE 3245) PED(PS590) FN(SR960) E(PT460)	Yellow panels, black meter = 418k, color meter = 551k
Ricoh AFICIO 3245C	190314	838	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Finisher bracket pin broken, yellow panels, black meter = 465k, color meter = 373k
Ricoh AFICIO 3245C	190315	463	PS(TYPE 3245) PED(PS600) FN(SR960) E(PT460)	Black meter = 309k, color meter = 155k, yellow panels
Ricoh AFICIO 3245C	190316	825	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Finisher bracket guide pin broken, yellow panels, error code SC440 - Color drum motor error, defective PCU, drum motor or drum CPU position sensor - not tsted, black meter = 298k, color meter = 528k
Ricoh AFICIO 3245C	190319	599	PS(TYPE 3245) PED(PS600) FN(SR960) E(PT460)	Yellow panels, error code SC385 - ID sensor VSG error - not fully tested, top finisher tray cracked, black meter = 434k, color meter = 166k
Ricoh AFICIO 3245C	190320	921	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Yellow panels, jamming in bypass -not tested, jamming in stapler - not tested, finisher skewing copies, bottom finisher tray cracked, black meter = 671k, color meter = 251k
Ricoh AFICIO 3245C	190322	538	PU(TYPE 1045) PS(TYPE 3245) PED(PS590) FN(SR960) E(PT460)	Yellow panels, bypass not feeding paper - not tested, black meter = 479k, color meter = 60k
Ricoh AFICIO 3245C	190323	606	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Yellow and dirty panels, black meter = 523k, color meter = 83k
Ricoh AFICIO 3245C	190331	559	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Finisher bracket guide pin broken, yellow panels. top finisher tray missing, bottom finisher tray cracked, toner spilled in cassettes, black meter = 450k, color meter = 109k
Ricoh AFICIO 3245C	190332	1252	PS(TYPE 3245) PED(PS600) FN(SR960)	Very yellow panels, black meter = 1107k, color meter = 146k, does not

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(TYPE 3245) E(PT460)	recognize bottom cassette closed - not tested
Ricoh AFICIO 3245C	190335	394	PU(TYPE 1045) PS(TYPE 3245) PED(PS590) FN(SR960)	Exit tray missing, black meter = 258k, color meter = 137k, back panel has deep scratch
Ricoh AFICIO 3245C	190557	661	PS(TYPE 3245) PED(PS600) FN(SR960)	Off color panels, exit tray missing, black meter = 481k, color meter = 181k
Ricoh AFICIO 3245C	190558	704	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Very yellow panels, knocking noise in machine, black meter = 415k, color meter = 289k
Ricoh AFICIO 3245C	190559	856	PU(TYPE 1045) PS(TYPE 3245) PED(PS590) FN(SR960) E(PT460)	Bypass tray broken, black meter = 381k, color meter = 475k
Ricoh AFICIO 3245C	190560	260	ST() PS(TYPE 3245) FN(SR960)	Yellow panels, black meter - 253k, color meter = 7k
Savin C4535	190850	418	PS(TYPE 3245) PED(PS600) FAX(TYPE 3245)	Missing finisher -has brackets, duplexer exit tray missing, yellow panels, black meter = 230k, color meter = 188k
Lanier LD160C	172965	3655	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Unable to clear login code- ran in SP mode; color = 286k; B/W = 3369k; blurred color copies
Savin C6045	175378	685	PU(TYPE 3260) FN(SR970)	Black meter = 466k; color meter = 220k, finisher tray yellow
Ricoh AFICIO 3260C	178786	2049	PU(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	Yellow finisher trays and control panel cover, black meter = 2006k, color meter = 43k
Gestetner DSC460	179904	510	PU(TYPE 3260) FN(SR4000)	Black meter = 291k, color meter = 220k
Ricoh AFICIO 3260C	180889	1144	PC(TYPE 3260) P(RT43) FN(SR4000)	Has cover imposer type 3260, finisher tray yellow, paper deck not tested - jamming and gears slipping, does not staple - not tested, black meter = 1086k, color meter = 59k
Ricoh AFICIO 3260C	181313	1092	FN(SR970)	Black meter = 970k, color meter = 122k
Toshiba E-STUDIO4500	181675	244	PC(FIERY E-7000) FN(SR841)	Error code SC723 - finisher feed out error -stapler not tested, stacker feed out belt broken, has GBS stream punch III, has punch assembly, black meter = 52k, color meter = 193k
Toshiba E-STUDIO4500	181676	805	PC(FIERY E-7000) P(RT43) FN(SR4000)	Bottom finisher tray yellow. black meter = 587k, color meter = 218k
Lanier LD160C	181851	627	PC(FIERY E-7000) FN(SR980)	Black meter = 115k, color meter = 513k
Toshiba E-STUDIO4500	182495	508	PC(FIERY E-7000) P(RT43) FN(SR4000)	Color = 473k; B/W = 36k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3260C	182794	941	FN(SR980)	Error code SC520 - fuser, exit motor error - not tested, chunks of roller missing from fuser
Lanier LD160C	182863	836	PU(TYPE 1075) PC(TYPE 3260) FN(SR970)	Finisher tray off color, black meter = 409k, color meter = 427k
Ricoh AFICIO 3260C	183278	504	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Black meter = 270k, color meter = 234k
Ricoh AFICIO 3260C	183738	959	PS(TYPE 3260) PC(TYPE 3260)	Missing toner cartridges- tested with others; color = 326k; B/W = 633k; scraped front door
Ricoh AFICIO 3260C	183947	227	PS(TYPE 3260) PC(TYPE 3260)	Has SR850 finisher with punch unit, black meter = 119k, color meter = 109k
Ricoh AFICIO 3260C	185228	818	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Screw holding lever B4 in machine, black meter = 704k, color meter = 114k
Ricoh AFICIO 3260C	187571	720	PC(TYPE 3260) FN(SR4000)	Jamming out of cassette #3, black meter = 428k, color meter = 293k
Ricoh AFICIO 3260C	187972	182	PS(TYPE 3260) PC(TYPE 3260) E()	Black meter = 67k, color meter = 115k
Toshiba E-STUDIO4500	188272	1114	PU(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	Jamming at finisher exit rollers - finisher not tested, knockout missing at right side access door interlock switch, black meter = 973k, color meter = 142k
Savin C6045	189393	719	PC(TYPE 3260)	Came in with wrong finisher
Toshiba E-STUDIO4500	191235	448	PC(TYPE 3260) FN(SR970)	Black meter = 330k, color meter = 119k
Gestetner DSC460	191393	1163	PU(TYPE 3260) PC(FIERY E-7000) FN(SR4000)	No magenta or yellow on color copies, black meter = 135k, color meter = 1029k
Toshiba E-STUDIO4500	191690	1425	PC(TYPE 3260) FN(SR4000)	Finisher exit tray yellow, black meter = 790k, color meter = 636k
Ricoh AFICIO 3260C	192367	332	PS(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR970)	Black meter = 314k, color meter = 18k
Savin 2055 DP	191849	7087	FN(SR740)	Left side top cover cracked, yellow panels, has PC button - missing PC
Ricoh AFICIO 5560	177860	643	PU(TYPE 3260) PC(FIERY E-7000) FN(SR970)	Black meter = 505k, color meter = 139k
Toshiba E-STUDIO5500	178317	963	PS(TYPE 3260) PC(TYPE 3260) P(RT43)	Has SR842 finisher, black meter = 770k, color meter = 194k
Ricoh AFICIO 5560	182837	566	PC(TYPE 3260) FN(SR4000)	Black meter = 290k, color meter = 277k
Ricoh AFICIO 5560	182838	738	PU(TYPE 3260) FN(SR970)	Has interposer 3260, fuser belt torn causing jam in fuser, Missing SD card

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				for PC, black meter = 221k, color meter = 717k
Ricoh AFICIO 5560	182969	509	PU(TYPE 1075) PC(FIERY E-7000) FN(SR841)	Lower finisher tray out of alignment, PC does not ome to ready, PC front panel broken, finisher top panel broken
Ricoh AFICIO 5560	189273	1117	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Black meter = 559k, color meter = 558k
Ricoh AFICIO 5560	190790	298	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR4000)	Black meter = 200k, color meter = 98k, has cover interposer type 3260
Lanier LC155	191392	890	PC(TYPE 3260) FN(SR970)	Lower finisher tray yellow, black meter = 855k, color meter = 36k
Toshiba E-STUDIO5500	191820	423	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Toner spilled inside machine, black meter = 157k, color meter = 267k
Savin SGC 1506	191519	77		Has stand and 1C PFU, black meter = 46k, color meter = 32k, does not recognize toner installed - not tested, yellow panels
Ricoh AFICIO MP 11	190376	4937	PU(PU5000) PS(TYPE 1350) PC(TYPE 1350) P(RT5010) FN(SR5000) B(BY5000)	Requires 30A, 220V line - not tested, Has cover interposer CI5000, power cord plug removed, control panel disassembled
Ricoh AFICIO MP 11	190377	6542	PU(PU5000) PS(TYPE 1350) PC(TYPE 1350) P(RT5010) FN(SR5000) B(BY5000)	Requires 30A 220V power source, touch screen disassembled - not tested, has cover interposer CI5000
Ricoh AFICIO MP 11	190378	6637	PU(PU5000) PS(TYPE 1350) PC(TYPE 1350) P(RT5010) FN(SR5000) B(BY5000)	Has cover interposer needs 30Amp 220V power source - not tested, touch screen disassembled, finisher jogging arm broken
Ricoh AFICIO MP 16	181647	155	ST() PFU(PS460) PC(TYPE 2000) FAX(TYPE 2000)	Error code SC302 - charge roller problem or HVT problem - not tested, yellow panels
Savin 9016	182945	24	PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	
Savin 9016	182947	30	ST() PC(TYPE 2000) ADF(DF2000)	
Savin 9016	182948	28	ST() PC(TYPE 2000) ADF(DF2000)	Yellowed ADF panels
Savin 9016	182953	119	ST() ADF(DF2000)	
Ricoh AFICIO MP 16	183153	13	ADF(DF2000)	
Ricoh AFICIO MP 16	184835	4	ST()	
Ricoh AFICIO MP 16	184836	36	ST()	
Ricoh AFICIO MP 16	184837	20		

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 16	185404	73	PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	ADF off color
Ricoh AFICIO MP 16	188693	313	ST() PS(TYPE 2000) PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	
Ricoh AFICIO MP 16	189124	76	ST() PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	Yellowed ADF panels
Ricoh AFICIO MP 16	189138	34	ST() ADF(DF2000)	
Ricoh AFICIO MP 16	189506	121	ST() ADF(DF2000)	Cracked paper tray handle; yellowed RADF panels; missing stand door
Ricoh AFICIO MP 16	191635	85	ST() PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	
Ricoh AFICIO MP 16	192451	32	PFU(PS460) PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	
Ricoh AFICIO MP 16	183223	240		
Savin 816F	186272	125		
Ricoh AFICIO MP 16	189056	159		Bypass not feeding paper - not tested
Savin 816F	192514	29		
Ricoh AFICIO MP 16	190887	113		Front door broken at left hinge
Lanier LD016SPF	191383	128		
Lanier LD117SPF	192036	95		
Lanier LD117SPF	192037	67		
Ricoh AFICIO MP 20	178784	72	ST() RADF(DF2010) FAX(TYPE 2000)	Yellow panels
Savin 9021D	180203	26	ST() RADF(DF2010)	Dirty inside machine
Ricoh AFICIO MP 20	181319	47	ST() RADF(DF2010) PFU(PS460)	
Lanier LD320D	181335	266	ST() RADF(DF2010)	
Savin 9021D	182924	55	RADF(DF2010) PS(TYPE 2000) PC(TYPE 2000) FAX(TYPE 2000)	PFU harness broken, left side panel broken, jamming in duplexer, jamming out of cassette #2
Savin 9021D	182925	133	RADF(DF2010) PS(TYPE 2000) PC(TYPE 2000) FAX(TYPE 2000)	Lower right side access door out of alignment causing lower tray to jam; toner spilled in paper trays; yellowed RADF panels
Ricoh AFICIO MP 20	184752	36	ST() RADF(DF2010) FAX(TYPE 2000)	Jamming in RADF, RADF front frame bent - RADF not tested, jamming in duplexer - not tested, error code sc 121 - scanner home position or scanner drive motor or BICU board - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 20	184846	62	ST() RADF(DF2010) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	185218	35	ST()	
Ricoh AFICIO MP 20	185229	6	ST() ADF(DF2000)	RADF top access panel cracked, RADF yellow, back panel cracked
Lanier LD320D	185778	106	ST() RADF(DF2010) FAX(TYPE 2000)	
Savin 9021D	186275	59	RADF(DF2010) PFU(PS450) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	187189	76	ST() RADF(DF2010) FAX(TYPE 2000)	RADF yellow
Ricoh AFICIO MP 20	188623	344	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Duplex jams
Ricoh AFICIO MP 20	189057	194	ST() RADF(DF2010) PS(TYPE 2000) PC(TYPE 2000)	Thumping noise in machine, RADF yellow
Savin 9021D	190374	317	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Skewing paper in RADF, right side panels yellow
Ricoh AFICIO MP 20	190740	220	ST() RADF(DF2010) PC(TYPE 2000)	Could not print config pages
Ricoh AFICIO MP 20	190751	204	ST() RADF(DF2010) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	190762	205	ST() RADF(DF2010)	Missing functions buttons on control panel
Ricoh AFICIO MP 20	191560	15	ADF(DF2000)	
Ricoh AFICIO MP 20	191641	178	ST() RADF(DF2010) PFU(PS460) PC(TYPE 2000) FAX(TYPE 2000)	Has internal exit tray
Savin 9021D	191660	210	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Lanier LD320D	192086	84	ST() RADF(DF2010) FAX(TYPE 2000)	Registration off on copies
Lanier LD320D	192474	184	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	192489	378	ST() RADF(DF2010) PS(TYPE 2000) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	Cassette #1 handle cracked
Ricoh AFICIO MP 20	192490	86	ST() RADF(DF2010) PS(TYPE 2000) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	Very dirty panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 20	192491	200	ST() RADF(DF2010) PS(TYPE 2000) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	Off color and very dirty
Ricoh AFICIO MP 20	192492	155	ST() RADF(DF2010) PS(TYPE 2000) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	
Ricoh AFICIO MP 20	192493	165	ST() RADF(DF2010) PS(TYPE 2000) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	Yellow and dirty panels
Ricoh AFICIO MP 20	192692	107	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Lanier LD320D	192779	55	ST() RADF(DF2010) FAX(TYPE 2000)	
Ricoh AFICIO MP 25	176794	54	ST() RADF(DF3020) PC(TYPE 2500) FAX(TYPE 2500) E(BN3020)	Yellow panels
Ricoh AFICIO MP 25	177209	137	ST() RADF(DF3020) PC(TYPE 2500) FN(SR3010) FAX(TYPE 2500) E(BN3020)	Error code SC500 - main motor lock - replaced drum and developer to test, finisher exit assembly broken - finisher not tested,
Lanier LD125	181841	27	ST() RADF(DF3020) FN(SR3010)	
Ricoh AFICIO MP 25	182014	82	ST() RADF(DF3020) PC(TYPE 2500) FN(SR3010)	Hole in bypass tray, finisher front door broken
Ricoh AFICIO MP 25	183229	618	ST() RADF(DF3020) PC(TYPE 2500)	
Savin 7025	184865	287	ST() RADF(DF3020) PED(PB3030) PC(TYPE 2500) FAX(TYPE 2500) E(BN3020)	
Ricoh AFICIO MP 25	186253	179	ST() RADF(DF3020) PED(PB3030) PC(TYPE 2500) FN(SR3010) FAX(TYPE 2500) E(BN3020)	Dirty panels, finisher error - not tested, jamming in stapler,
Savin 7025	187549	77	ST() RADF(DF3020) PC(TYPE 2500) FN(SR3010) FAX(TYPE 2500) E(BN3020)	Off color panels
Ricoh AFICIO MP 25	188506	251	ST() RADF(DF3020) PC(TYPE 2500) FAX(TYPE 2500)	Black copies
Ricoh AFICIO MP 25	190767	304	ST() RADF(DF3020) PC(TYPE 2500)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8025E	179041	136	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Touch screen loses calibration when power off; yellowed RADF panels
Ricoh AFICIO MP 25	179752	151	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Yellow panels
Savin 8025E	180681	106	ST() RADF(DF83) FN(SR820) FAX(TYPE 3030)	
Ricoh AFICIO MP 25	181275	99	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	Touch screen not responding - not fully tested, off color and dirty, hard-drive removed, bypass tray broken
Savin 8025E	181303	525	ST() RADF(DF83)	Bypass tray broken
Lanier LD325	182826	123	ST() RADF(DF83)	Has PC and scanner buttons on control panel installed
Lanier LD325	182867	255	ST() RADF(DF83) PC(TYPE 3010)	RADF off color
Lanier LD325	182868	201	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	
Lanier LD325	182869	270	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	Bypass tray broken
Lanier LD325	182870	258	ST() RADF(DF83) PC(TYPE 3010)	Missing finisher - has bridge unit, not fusing to paper
Savin 8025E	182930	121	ST() RADF(DF83) PS(TYPE 3010) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	Bypass tray broken
Savin 8025E	183066	159	ST() RADF(DF83)	
Ricoh AFICIO MP 25	183154	244	ST() RADF(DF83) PC(TYPE 3010)	Missing finisher - has hardware and bridge installed
Ricoh AFICIO MP 25	183209	655	RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030)	
Ricoh AFICIO MP 25	183345	194	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790)	Off color panels
Ricoh AFICIO MP 25	184760	112	ST() RADF(DF83)	No power to machine - not tested
Ricoh AFICIO MP 25	184876	203	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030) E(PT280)	
Ricoh AFICIO MP 25	185138	214	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	
Ricoh AFICIO MP 25	185212	66	ST() RADF(DF83)	Has raised platen glass - RADF not tested
Ricoh AFICIO MP 25	185214	114	ST() RADF(DF83)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 25	185216	104	ST() RADF(DF83) FN(SR820)	RADF off color
Ricoh AFICIO MP 25	185223	209	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Lanier LD325	185608	100	ST() RADF(DF83) FN(SR820)	
Lanier LD325	185699	286	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	
Savin 8025E	186165	233	ST() RADF(DF83) PC(TYPE 3010) FN(SR790)	RADF off color, finisher bottom tray cracked, bypass tray broken, jamming in duplexer - not tested
Ricoh AFICIO MP 25	186301	184	ST() RADF(DF83) PC(TYPE 3010)	
Ricoh AFICIO MP 25	186959	477	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	
Ricoh AFICIO MP 25	187192	151	ST() RADF(DF83) PC(TYPE 3010)	
Ricoh AFICIO MP 25	187499	277	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	Yellow panels, dirty, off color
Lanier LD325	187738	1140	ST() RADF(DF83) PC(TYPE 3010)	Bypass hinge broken
Lanier LD325	187739	524	ST() RADF(DF83) PC(TYPE 3010)	Jamming out of cassette #1
Lanier LD325	187740	440	ST() RADF(DF83) PC(TYPE 3010)	
Lanier LD325	187741	364	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	RADF yellow
Lanier LD325	187744	145	ST() RADF(DF83) PC(TYPE 3010)	
Ricoh AFICIO MP 25	188206	202	ST() RADF(DF83)	Bypass brackets broken
Ricoh AFICIO MP 25	188207	373	ST() RADF(DF83)	
Ricoh AFICIO MP 25	188400	384	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Does not have scan option
Savin 8025E	189027	30	ST() RADF(DF83)	
Lanier LD325	189466	43	ST() RADF(DF83) FN(SR820)	Touch screen not responding - not fully tested
Ricoh AFICIO MP 25	190745	364	ST() SS(TYPE 1027) RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	
Ricoh AFICIO MP 25	190746	301	ST() RADF(DF83)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	
Ricoh AFICIO MP 25	190747	451	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	Byass tray broken
Ricoh AFICIO MP 25	190755	1131	RADF(DF83) PS(TYPE 3010) PED(PS500) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030) E(PT280)	Finisher yellow
Ricoh AFICIO MP 25	190895	113	SS(TYPE 1027) RADF(DF83) PED(PS490) PC(TYPE 3010) FAX(TYPE 3030)	No power to machine - not tested, toner spilled in/out of machine
Ricoh AFICIO MP 25	190954	201	PED(PS490)	Bypass tray broken
Lanier LD325	192041	61	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030) E(PT280)	Not feeding in bypass - not tested
Gestetner DSM725E	192466	316	ST() RADF(DF83) PC(TYPE 3010) FN(SR790)	
Ricoh AFICIO MP 25	174418	55	ST() RADF(DF3030)	
Ricoh AFICIO MP 25	175863	60	ST() RADF(DF3030)	
Ricoh AFICIO MP 25	179440	150	ST() RADF(DF3030)	Control panel cover off color
Savin 9025	179508	57	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350)	Finisher bracket bent - finisher not tested, off color panels, front door scratched, dirty
Ricoh AFICIO MP 25	180830	165	ST() RADF(DF3030)	Touch screen scratched
Ricoh AFICIO MP 25	180831	67	ST() RADF(DF3030)	Missing duplexer deflector
Ricoh AFICIO MP 25	180833	156	ST() RADF(DF3030)	
Ricoh AFICIO MP 25	180881	16	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	Error code SC798-8 upper limit sensor - finisher not tested
Ricoh AFICIO MP 25	181508	111	ST() RADF(DF3030)	
Lanier LD425	181831	148	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	
Ricoh AFICIO MP 25	181942	259	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	182212	179	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	182503	239	ST() RADF(DF3030)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(TYPE 3350 (S))	
Ricoh AFICIO MP 25	182800	115	ST() RADF(DF3030)	
Savin 9025	182950	30	RADF(DF3030) FN(SR790)	
Savin 9025	182951	315	ST() RADF(DF3030) PC(TYPE 3350 (S))	Bypass not recognized - not tested
Savin 9025	183073	230	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Lanier LD425	183100	31	ST() RADF(DF3030)	Dirty, yellow, jams in bypass - not tested
Ricoh AFICIO MP 25	184211	N/A	ST() RADF(DF3030) E(BN3030)	Machine will not power up
Ricoh AFICIO MP 25	184212	254	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	184216	275	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	184612	311	ST() RADF(DF3030) PC(TYPE 3350 (S))	Jamming out of cassette #1 and bypass
Lanier LD425	184613	267	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350)	
Lanier LD425	184614	487	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Duplexer deflector broken - not tested
Savin 9025	184862	251	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Error code SC671 - controller to operation panel communication error - not fully tested
Savin 9025	184895	323	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	184947	85	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 25	186259	148	ST() RADF(DF3030) E(BN3030)	Control panel cover yellow
Savin 9025	186271	332	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Savin 9025	186273	207	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 25	186274	82	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Outlet broken for shift sort tray
Ricoh AFICIO MP 25	186279	98	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	186754	111	RADF(DF3030) PS(TYPE 3350) PED(PB3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	RADF back panel gouged
Ricoh AFICIO MP 25	186755	321	SS(SH3010) RADF(DF3030) PS(TYPE 3350) PED(PB3030) PC(TYPE 3350 (S))	Came in with wrong LCT - not tested
Ricoh AFICIO MP 25	186756	200	SS(SH3010) RADF(DF3030) PS(TYPE 3350) PED(PB3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 25	186782	175	RADF(DF3030) PS(TYPE 3350) PED(PB3030) FN(SR790) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	186847	339	ST() RADF(DF3030) PS(TYPE 3350) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	186848	379	ST() RADF(DF3030) PS(TYPE 3350) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350) E(BN3030)	Finisher entrance guide spring missing - jamming in finisher entrance - finisher not tested
Lanier LD425	186897	104	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	
Lanier LD425	186899	352	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	187219	71	RADF(DF3030) PS(TYPE 3350) PED(PS500) PC(TYPE 3350 (S)) FN(SR790) E(BN3030)	Left side of control panel smashed, back panel dented
Ricoh AFICIO MP 25	187303	174	RADF(DF3030) PED(PB3030) FN(SR3050)	Right side panel cracked, duplexer latches broken, finisher tray bent upward- finisher not tested, finisher bracket bent

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 25	187304	121	RADF(DF3030) PED(PB3030) FN(SR3050)	Finisher bracket bent - finisher not tested
Savin 9025	187548	406	RADF(DF3030) PED(PS500) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Goes into error code 873 - email error or hard-drive; dirty panels
Ricoh AFICIO MP 25	187579	44	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S)) E(BN3030)	Yellow back panels
Ricoh AFICIO MP 25	188509	178	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	188836	90	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	189113	68	ST() SS(SH3010) RADF(DF3030) E(BN3030)	
Ricoh AFICIO MP 25	189141	83	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	Finisher tray mount out of alignment causing it to show jam 001 every try-inop
Lanier LD425	189976	32	ST() RADF(DF3030) FAX(TYPE 3350)	
Ricoh AFICIO MP 25	190700	166	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	Off color panels, dirty
Savin 9025	190818	109	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	Error code SC723 - feed out belt motor error - stapler tested, yellow panels, finisher top access door broken
Ricoh AFICIO MP 25	190952	38	ST() RADF(DF3030)	
Lanier LD425	191093	183	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	Control panel yellow
Lanier LD425	191104	118	ST() RADF(DF3030) FN(SR790)	Jamming in RADF - not tested, jamming in stapler unit - not tested
Ricoh AFICIO MP 25	191416	234	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	
Ricoh AFICIO MP 25	191617	42	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Savin 9025	191659	192	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 25	191890	52	RADF(DF3030) PED(PB3030) PC(TYPE	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			3350 (S)) FN(SR3050)	
Lanier LD425	191983	82	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	Finisher covers yellow, false jam in fuser - not tested
Ricoh AFICIO MP 25	192004	114	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	RADF feed rollers missing - RADF not tested
Lanier LD425	192102	85	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 25	192140	72	ST() RADF(DF3030)	
Savin 9025	192148	198	ST() RADF(DF3030)	
Lanier LD330	179386	105	ST() RADF(DF83) PC(TYPE 3010) FN(SR790)	Yellow panels
Lanier LD330	181536	351	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030) E(PT280)	Missing finisher exit tray
Savin 8030E	181771	532	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	Touch screen not responding - not fully tested, hard-drive removed
Savin 8030E	182934	435	ST() RADF(DF83) PS(TYPE 3010) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Ricoh AFICIO MP 30	184213	875	RADF(DF83) PED(PS490) FN(SR790)	Touch screen not responding - not fully tested, RADF and finisher yellow
Ricoh AFICIO MP 30	185215	639	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	Bypass tray broken
Lanier LD330	185786	324	ST() RADF(DF83) PS(TYPE 3010) PC(TYPE 3010) FAX(TYPE 3030)	Bypass tray broken, RADF yellow
Ricoh AFICIO MP 30	186303	450	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790)	
Ricoh AFICIO MP 30	186954	301	ST() SS(TYPE 1027) RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	Yellow panels
Ricoh AFICIO MP 30	188198	524	ST() RADF(DF83)	Bypass tray front hinge broken
Ricoh AFICIO MP 30	191022	376	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030) E(PT280)	Bypass tray broken
Ricoh AFICIO MP 30	191772	328	RADF(DF83) PS(TYPE 3010) PED(PS490) PC(TYPE 3010) FN(SR790)	
Lanier LD433	177258	226	RADF(DF3030) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD433	177259	88	ST() RADF(DF3030) FN(SR790)	
Ricoh AFICIO MP 33	178569	406	ST() RADF(DF3030) FN(SR790)	
Ricoh AFICIO MP 33	179032	86	SS(SH3010) RADF(DF3030)	Back panel yellow
Ricoh AFICIO MP 33	182776	180	ST() RADF(DF3030) FN(SR790)	
Savin 9033	182944	438	ST() RADF(DF3030) PC(TYPE 3350 (S))	Control panel yellow, stand front left door broken off
Ricoh AFICIO MP 33	182961	232	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350) E(BN3030)	Control panel cover yellow
Ricoh AFICIO MP 33	182963	145	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350) E(BN3030)	Finisher top access door broken, deflector not working - finisher not tested, frame bent inward
Ricoh AFICIO MP 33	182965	318	RADF(DF3030) PU(PU3000) PED(PB3030) PC(TYPE 3350 (S)) FN(SR3000) FAX(TYPE 3350) E(BN3030)	Error code SC764- paper position sensor slide motor - finisher not tested
Ricoh AFICIO MP 33	183234	438	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790)	
Lanier LD433	184615	262	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	#0748
Lanier LD433	184616	255	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	
Lanier LD433	184617	349	RADF(DF3030) PED(PS500) PC(TYPE 3350 (S)) FN(SR790)	Lower right side access door on PED broken
Savin 9033	186181	183	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 33	186260	145	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 33	186758	182	SS(SH3010) RADF(DF3030) PS(TYPE 3350) PED(PS500) PC(TYPE 3350 (S)) E(BN3030)	Cassette #1 always detects paper - even when empty

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 33	187076	459	RADF(DF3030) PS(TYPE 3350) PED(PB3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Duplexer interlock broken
Ricoh AFICIO MP 33	187214	304	RADF(DF3030) PS(TYPE 3350) PED(PB3030) PC(TYPE 3350 (S))	
Ricoh AFICIO MP 33	187215	388	RADF(DF3030) PS(TYPE 3350) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790) E(BN3030)	Finisher throat missing, jamming in bypass tray
Ricoh AFICIO MP 33	187216	265	RADF(DF3030) PS(TYPE 3350) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790) E(BN3030)	Finisher shift tray braocket bent - finisher not tested, right panel cracked
Ricoh AFICIO MP 33	189140	279	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	Missing toner cartridge- tested with another
Ricoh AFICIO MP 33	189142	313	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	Finisher tray mount badly bent & tray broken- inop
Lanier LD433	189342	163	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	Missing finisher control board- finisher inop
Savin 9033	189969	469	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Very dirty, ground in dirt, yellow
Ricoh AFICIO MP 33	192488	398	RADF(DF3030) PS(TYPE 3350) PED(PS500) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	
Ricoh AFICIO MP 33	192702	148	RADF(DF3030) PED(PB3030)	Toner spilled in machine, right side panel scuffed
Savin 8035E	181737	45	ST() PC(TYPE 4500)	Yellow panels
Lanier LD335	182884	646	ST() PC(TYPE 4500) FN(SR790)	Off color and dirty panels
Savin 8035E	182957	244	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	183212	752	PED(PS530) PC(TYPE 4500) FN(SR790)	Lower finisher tray missing, spring missing from finisher entrance guide plate
Ricoh AFICIO MP 35	183214	372	ST() FN(SR790) FAX(TYPE 3045)	Bypass off color

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 35	183218	691	PED(PS530) PC(TYPE 4500) FN(SR790)	Yellow panels
Lanier LD335	184670	594	PED(PS530) PC(TYPE 4500) FN(SR790)	
Ricoh AFICIO MP 35	184758	402	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Yellow panels
Ricoh AFICIO MP 35	185226	259	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Yellow panels
Ricoh AFICIO MP 35	185231	234	ST() PC(TYPE 4500) FN(SR880)	Bypass tray yellow, finisher off color
Ricoh AFICIO MP 35	186956	264	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	186957	918	ST() PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	Off color and dirty panels, finisher spring missing for paper deflector - stapler not tested
Ricoh AFICIO MP 35	187059	526	PS(TYPE 4500) PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Lower finisher exit tray cracked
Ricoh AFICIO MP 35	187188	179	ST() FAX(TYPE 3045)	Back panel very dirty
Savin 8035E	187835	308	PU(TYPE 1045) PED(PS530) FN(SR880)	Yellow panels, jams in stapler - not tested
Savin 8035E	188064	1094	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Jamming in bypass - not tested
Savin 8035E	188219	483	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880)	
Ricoh AFICIO MP 35	188505	489	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Savin 8035E	188965	723	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Jamming at finisher entranced - finisher not tested
Ricoh AFICIO MP 35	189060	384	ST() PS(TYPE 4500) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Off color, bypass tray yellow
Ricoh AFICIO MP 35	189061	397	ST() PS(TYPE 4500) PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM735E	190451	889	PED(PS530) FN(SR790)	Control panel very yellow
Gestetner DSM735E	190452	638	PED(PS530) FN(SR790)	
Ricoh AFICIO MP 35	190506	327	ST() PC(TYPE 4500)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8035E	190550	434	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Yellow panels
Ricoh AFICIO MP 35	190756	520	ST() PS(TYPE 4500) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	190757	611	ST() PS(TYPE 4500) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	190758	671	ST() PS(TYPE 4500) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	190759	523	ST() PS(TYPE 4500) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	190760	620	PS(TYPE 4500) PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Finisher tray cracked
Savin 8035E	190821	213	PS(TYPE 4500) PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Finisher entrance guide missing
Lanier LD335	191094	242	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Yellow panels
Savin 8035E	192099	566	ST() PS(TYPE 4500) PC(TYPE 4500) FAX(TYPE 3045)	Missing finisher - has bridge unit, off color panels
Ricoh AFICIO MP 35	192189	744	PS(TYPE 4500) PED(PS530) PC(TYPE 4500) FN(SR790)	Yellow panels, ground in dirt
Ricoh AFICIO MP 35	192363	524	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 40	175898	94	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Lower finisher tray mount out of alignment (finisher still works)
Ricoh AFICIO MP 40	176358	50	ST() FN(SR790)	
Ricoh AFICIO MP 40	176739	324	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Lanier LD040	178247	512	ST() FN(SR790)	
Lanier LD040	178542	240	PED(PB3040) PC(TYPE 5000 (S))	
Ricoh AFICIO MP 40	178785	267	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Has printer enhance option and scanner enhance option SD cards
Ricoh AFICIO MP 40	179432	358	ST() FAX(TYPE 5000)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			E(BN3040)	
Ricoh AFICIO MP 40	179646	480	PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	179647	159	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Missing LCT - has brackets, error - SD card authentication error - wrong SD card installed
Savin 9040	180196	450	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9040	180204	74	ST() PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 40	180874	207	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 40	181476	185	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	181510	179	ST() PC(TYPE 5000 (S))	
Savin 9040	182286	291	ST() FN(SR790)	Control panel panel cover yellow
Savin 9040	182287	373	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	Yellow panels, error code SC324 - LD drive current, yellow panels
Savin 9040	182288	447	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9040	182289	290	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9040	182290	220	ST() PC(TYPE 5000 (S))	
Savin 9040	182291	660	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Lanier LD040	182570	368	ST() PC(TYPE 5000 (S)) E(BN3040)	
Savin 9040	182586	94	ST() FN(SR790)	
Ricoh AFICIO MP 40	182590	1068	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	
Ricoh AFICIO MP 40	182591	597	PU(TYPE 3260) PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 40	182978	568	ST() PC(TYPE 5000 (S)) FN(SR790)	Finisher yellow
Ricoh AFICIO MP 40	183000	155	ST() PC(TYPE 5000 (S)) FN(SR790)	Error code SC870 - harddrive or software error, missing hard-drive
Ricoh AFICIO MP 40	183012	198	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000)	Very dirty

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			E(BN3040)	
Savin 9040	183236	22	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Removed hard drive after testing; Finisher top access door broken, RADF yellow, finisher top panel yellow
Ricoh AFICIO MP 40	183569	418	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Front door cracked
Lanier LD040	183667	86	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	Control panel cover yellow
Ricoh AFICIO MP 40	184039	301	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184040	669	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184041	213	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Control panel cover cracked
Ricoh AFICIO MP 40	184042	310	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Finisher door broken, not stapling paper
Ricoh AFICIO MP 40	184043	730	ST() PS(TYPE 5000) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184044	1140	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184045	370	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Finisher top access door broken
Lanier LD040	184143	525	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184222	204	ST() PC(TYPE 5000 (S)) FN(SR790)	Finisher tray mount bent - not tested, error code SC792 - finisher connection problem
Ricoh AFICIO MP 40	184223	574	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184224	349	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184225	327	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184234	219	ST() PC(TYPE 5000)	Missing scan enabler - has button,

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(SR790) FAX(TYPE 5000)	finisher exit tray cracked
Ricoh AFICIO MP 40	184235	345	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184241	122	ST() FN(SR790) FAX(TYPE 5000)	Staple jogger frame missing - jams in stapler
Ricoh AFICIO MP 40	184242	341	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184243	821	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184244	605	ST() PC(TYPE 5000 (S)) FN(SR790)	
Lanier LD040	184478	635	PS(TYPE 5000) PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184830	605	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Not stapling, toner spilled in cassette
Ricoh AFICIO MP 40	184831	221	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Hole in back panel
Ricoh AFICIO MP 40	184832	177	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184833	872	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 40	184834	442	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Broken back exhaust cover
Ricoh AFICIO MP 40	185145	232	ST() PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 40	185378	1211	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Cassette #1 oes not recognize paper - not tested
Savin 9040	185537	283	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Lanier LD040	185782	418	ST() PS(TYPE 5000) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Control panel cover yellow
Lanier LD040	185785	559	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 40	185957	130	PED(PB3040)	
Ricoh AFICIO MP 40	185958	424	PED(PB3040)	
Ricoh AFICIO MP 40	186465	313	PED(PB3040)	
Ricoh AFICIO MP 40	186759	784	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 40	186780	450	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030) FAX(TYPE 5000) E(BN3040)	Back panel broken
Ricoh AFICIO MP 40	186781	481	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 40	186849	243	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	
Ricoh AFICIO MP 40	186850	521	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	
Ricoh AFICIO MP 40	187131	110	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Left side panel cracked
Ricoh AFICIO MP 40	187132	126	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Slit glass cracked
Ricoh AFICIO MP 40	187302	571	PED(PB3040) FN(SR790)	Error code SC870 - hard-drive or software error, finisher exit area paper sensor out of position, duplexer gate spring mount broken
Ricoh AFICIO MP 40	187517	98	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	Jamming in RADF - not tested
Savin 9040	187546	503	PED(PB3040)	Control panel yellow
Savin 9040	187547	244	PED(PB3050)	
Ricoh AFICIO MP 40	188201	151	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Control panel cover yellow
Ricoh AFICIO MP 40	189112	743	ST() FN(SR790) FAX(TYPE 5000)	Cracked panel inside front door by actuator; missing back bypass paper guide
Ricoh AFICIO MP 40	189129	301	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD040	189341	333	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Yellowed control panel and finisher panels
Lanier LD040	189343	300	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Yellowed panel around touch screen; RADF will not feed- inop
Ricoh AFICIO MP 40	190035	354	ST() PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 40	190036	N/A	ST() PC(TYPE 5000) FN(SR790)	Touch screen not responding - not fully tested
Ricoh AFICIO MP 40	190484	388	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Lanier LD040	191100	1241	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	PED not recognizing paper - not tested
Lanier LD040	191101	789	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	Dirty panels
Lanier LD040	191102	483	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	Missing finisher - has bridge unit
Lanier LD040	191103	426	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	Finisher tray missing
Savin 9040	191681	323	ST() PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 40	192006	272	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Finisher top access door broken, finisher top tray broken and paper sensor broken - stapler not tested
Lanier LD040	192087	127	ST() FAX(TYPE 5000)	
Ricoh AFICIO MP 40	192701	156	ST() PC(TYPE 5000 (S))	
Ricoh AFICIO MP 40	185379	N/A	PED(PB3040) FN(SR3000) FAX(TYPE 5001)	Error code SC819 - software problem, hard-drive RADF shortage MBU, jumper wrong
Ricoh AFICIO MP 45	181330	1045	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	Yellow panels
Ricoh AFICIO MP 45	182246	315	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Control panel yellow
Ricoh AFICIO MP 45	183347	313	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) P(RT45) FN(SR880) FAX(TYPE 3045) E(PT330)	Machine will not detect paper deck- not tested; yellowed control panel, finisher & LCT panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM745E	184131	645	ST() PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	Finisher tray out of alignment - finisher not tested
Gestetner DSM745E	184132	828	ST() PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM745E	184133	671	ST() PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM745E	184135	707	ST() PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Lanier LD345	184761	374	ST() PS(TYPE 4500) PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO MP 45	185234	772	PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Toner spilled in top cassette, finisher front door will not latch
Ricoh AFICIO MP 45	185235	390	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880)	Jamming in finisher entrance - not tested
Ricoh AFICIO MP 45	185252	502	ST() PC(TYPE 4500) FN(SR790)	
Ricoh AFICIO MP 45	187180	264	ST() PS(TYPE 4500) PC(TYPE 4500) P(RT45) FN(SR790)	
Ricoh AFICIO MP 45	187383	255	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045)	Yellow panels
Ricoh AFICIO MP 45	188310	200	ST() PU(TYPE 1045) FN(SR880) FAX(TYPE 3045)	Finisher plug socket broken & missing - finisher not tested, finisher throat bent, top finisher tray out of alignment, finisher back panel cracked
Savin 8045E	188966	1366	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 45	189147	289	ST() PC(TYPE 4500) FN(SR790)	Missing front trim panel under door; yellowed panels
Ricoh AFICIO MP 45	190464	672	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045) E(PT330)	Very dirty
Savin 8045E	190531	332	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) P(RT45) FN(SR880) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO MP 45	191386	304	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 45	191832	700	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			E(PT330)	
Lanier LD345	192162	157	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Lanier LD345	192210	672	PED(PS530) PC(TYPE 4500) FN(SR790)	Off color panels, Missing fax - has control panel button
Lanier LD345	192364	583	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Off color panels, toner spilled in machine, jamming in bypass - not fully tested -shows false jam
Ricoh AFICIO MP 45	192699	413	PED(PS530) FN(SR790)	Error code SC726 - finisher shift tray lift motor - finisher tray frame bent, toner spilled in front door
Ricoh AFICIO MP 45	192847	235	ST() FAX(TYPE 3045) E(PT330)	Missing finisher - has brackets
Ricoh AFICIO MP 50	178592	259	PED(PB3040) PC(TYPE 5000 (S))	
Ricoh AFICIO MP 50	179648	302	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	179649	1511	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030) FAX(TYPE 5000)	Finisher exit tray yellow, right side paper guide broken only tested out of cassette #1, and bypass
Ricoh AFICIO MP 50	179650	1446	PU(TYPE 3260) PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030) FAX(TYPE 5000)	Finisher tray yellow
Ricoh AFICIO MP 50	179651	1479	PU(TYPE 3260) PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR3030) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	181539	472	PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030)	button #7 inop - could not get into sp mode, LCT front door broken, interchange cover broken
Ricoh AFICIO MP 50	181662	601	PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 50	182594	529	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Savin 9050	182749	254	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Removed hard drive after testing; Does not recognize toner bottle installed - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 9050	182949	404	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	
Ricoh AFICIO MP 50	182960	250	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	183193	245	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	Error code SC925 - netfile function error, error code SC870 - address book error, SC872 - Hard-drive mail receive error, error code SC860 - Hard-drive startup error - hard-drive missing - not fully tested
Ricoh AFICIO MP 50	183324	381	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	183325	535	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	183327	304	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Cracked front left side panel
Ricoh AFICIO MP 50	183328	305	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Control panel yellow
Ricoh AFICIO MP 50	183329	232	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	183502	519	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	183570	229	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	
Lanier LD050	184469	439	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Jamming out of cassette #1
Savin 9050	184595	144	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Removed hard drive after testing; Lower finisher tray missing, finisher entrance guide missing spring
Ricoh AFICIO MP 50	185400	190	ST() FN(SR790)	Top access door broken
Lanier LD050	185781	500	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Control panel yellow
Lanier LD050	185784	476	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Control panel yellow
Savin 9050	185939	190	PED(PB3050) FN(SR790)	
Ricoh AFICIO MP 50	186324	231	PED(PB3040) PC(TYPE	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			5000 (S)) FN(SR790) FAX(TYPE 5000)	
Ricoh AFICIO MP 50	186325	434	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	bypass tray broken, very dirty
Ricoh AFICIO MP 50	186326	384	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Finisher top access door broken, jalse jam in finisher - not tested, jamming in duplexer
Ricoh AFICIO MP 50	186765	203	PS(TYPE 5000) PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	Finisher top access door broken, Finisher yellow
Ricoh AFICIO MP 50	186801	636	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	RADF not recognizing paper - not tested, top access door will not open
Ricoh AFICIO MP 50	187077	380	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	Ground in dirt
Ricoh AFICIO MP 50	187373	343	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 50	188202	246	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Lanier LD050	188399	686	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	
Ricoh AFICIO MP 50	188497	100	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Has extended VM card Type F, missing finisher tray, gouge in front door
Ricoh AFICIO MP 50	189145	218	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	Broken top finisher door- door will not close properly (can't test finisher); yellowed control panel
Lanier LD050	189338	336	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Yellowed panel around touch screen
Lanier LD050	189340	427	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Yellowed panel around touch screen
Savin 9050	190140	399	ST() PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	190483	212	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	190737	567	ST()	
Ricoh AFICIO MP 50	190880	103	PED(PB3040) PC(TYPE	Off color and dirty

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			5000 (S)) FN(SR790)	
Ricoh AFICIO MP 50	190898	287	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	
Ricoh AFICIO MP 50	190899	194	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	Jamming at fuser - not fully tested
Savin 9050	191018	473	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Control panel yellow, finisher tray missing
Ricoh AFICIO MP 50	191026	586	PED(PB3040) PC(TYPE 5000 (S)) P(RT3000) FN(SR790) FAX(TYPE 5000)	RADF deflector gate broken - RADF not tested
Ricoh AFICIO MP 50	191643	195	PED(PB3040) FN(SR3030) FAX(TYPE 5001)	
Ricoh AFICIO MP 55	190188	2244	PU(TYPE 3260) FN(SR970)	Error code SC550 - fusing web end error, off color and dirty
Gestetner DSM755	190457	3958	PC(TYPE 7500) FN(SR4000)	Jamming in duplexer - not tested
Ricoh AFICIO MP 55	190949	1416	PU(TYPE 3260) PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	Machine will not come to ready - not tested, has VM security card type C
Ricoh AFICIO MP 55	191385	2662	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	
Savin 8055	192106	383	E()	
Lanier LD255	192467	2489	PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	
Lanier LD255	192468	2642	PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	
Ricoh AFICIO MP 55	192700	1108	PC(TYPE 7500)	Missing finisher (knockouts missing)
Savin 8060	178354	32	PU(TYPE 3260) FN(SR970) FAX(TYPE 7500)	Front door broken
Ricoh AFICIO MP 60	184817	284	PU(TYPE 3260) PC(TYPE 8000) FN(SR970)	Error code SC723 - finisher feed out belt error - stapler not tested
Ricoh AFICIO MP 60	185394	940	PC(TYPE 8000) FN(SR970)	Has CS391 mailbox, finisher catch tray bracket broken - will not move, jamming in finisher - not tested, finisher tray missing
Lanier LD260	189339	456	PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	
Ricoh AFICIO MP 60	190359	584	PU(TYPE 3260) FN(SR970)	Front door cracked
Ricoh AFICIO MP 60	190889	465	PU(TYPE 3260) PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 60	190890	613	PU(TYPE 3260) FN(SR970)	
Ricoh AFICIO MP 60	191027	457	PC(TYPE 8000) P(RT43) FN(SR970) FAX(TYPE 7500)	
Ricoh AFICIO MP 65	192705	2233	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Finisher entrance guide missing- tested with another, lower finisher tray yellow
Ricoh AFICIO MP 70	183265	599	PU(TYPE 3260) PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	
Ricoh AFICIO MP 70	185374	670	STK(CS391) PC(TYPE 8000) P(RT43) FN(SR970) FAX(TYPE 7500)	Error code SC502 - 2nd lift motor, motor sensor , blockage - cassette #2 not tested, squeeking noise in machine
Ricoh AFICIO MP 70	185375	603	STK(CS391) PC(TYPE 8000) P(RT43) FN(SR970) FAX(TYPE 7500)	Finisher exit tray missing, missing front finisher wheel, gouge in back panel, RADF feed tray scratched, Paperdeck front panel cracked, front door scraped
Ricoh AFICIO MP 70	185391	665	PS(TYPE 8000) PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	Has CS391 - mailbox, has CM card, not recognizing finisher - not tested
Lanier LD270	190043	874	PU(TYPE 3260) PC(TYPE 8000) FN(SR970)	
Ricoh AFICIO MP 70	191023	687	PC(TYPE 8000) P(RT43) FN(SR970) FAX(TYPE 7500)	Stapler jogging tray missing
Ricoh AFICIO MP 70	191025	1614	PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	Slit glass frame cracked
Ricoh AFICIO MP 70	191813	2709	PU(TYPE 3260) PC(TYPE 8000) P(RT43) FN(SR970) FAX(TYPE 7500)	Jamming in bypass - not tested
Ricoh AFICIO MP 70	192051	413	PU(TYPE 3260) PC(TYPE 8000) FN(SR970)	
Lanier LD275	192157	2131	PC(TYPE 7500) FN(SR970)	
Ricoh AFICIO MP 75	192696	1347	PU(TYPE 3260) PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	
Ricoh AFICIO MP 80	183813	498	STK(CS391) PC(TYPE 8000) FN(SR970)	front door bent, finisher door scraped
Ricoh AFICIO MP 80	183814	575	STK(CS391) PC(TYPE 8000) FN(SR970)	Front door scraped
Ricoh AFICIO MP 80	185368	381	STK(CS391) PC(TYPE 8000) FN(SR970)	Finisher entrance guide missing
Ricoh AFICIO MP 80	185369	488	STK(CS391) PC(TYPE 8000) FN(SR970)	Stacker brace broken, finisher exit tray missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 80	185370	571	STK(CS391) PC(TYPE 8000) FN(SR970)	Lower finisher tray missing, top stacker tray missing
Ricoh AFICIO MP 80	188402	1111	PS(TYPE 8000) PC(TYPE 8000) P(RT43) FN(SR970)	Finisher bracket bent, upper finisher trim plate missing
Ricoh AFICIO MP 80	189125	509	PU(TYPE 3260) PC(TYPE 8000) P(RT43) FN(SR970)	
Ricoh AFICIO MP 80	191024	2241	PC(TYPE 8000) P(RT43) FN(SR970) FAX(TYPE 7500)	
Ricoh AFICIO MP 80	192698	990	PU(TYPE 3260) PC(TYPE 8000) P(RT43) FN(SR970)	Finisher back panel crooked, finisher yellow, toner spilled in machine
Lanier LD280	192829	890	PU(TYPE 3260) FN(SR970)	
Savin 9080	192515	3680	PC(TYPE 9001) FN(SR4030)	Jamming out of cassettes 1,2 - not tested
Ricoh AFICIO MP 90	190948	2041	PU(PU5000) PS(TYPE 1350) PC(TYPE 1350) P(RT5010) FN(SR5000)	
Ricoh AFICIO MP 90	191412	4702	PU(PU5000) PS(TYPE 1350) PC(TYPE 1350) P(RT5000) FN(SR5000)	
Ricoh AFICIO MP 90	191417	1486	PU(PU5000) PC(TYPE 1350) P(RT5000) FN(SR5000) FN(BK5000)	Has stream punch unit III GBC, has cover interposer CI5000; Jamming in stream puncher - not tested, finisher punch unit not tested
Toshiba E-STUDIO901	191689	4123	PU(PU5000) PC(TYPE 1350) P(RT5000) FN(SR5000)	Has stream punch III GBC
Ricoh AFICIO MP 90	189494	960	PU(TYPE 3260) PC(TYPE 9001) FN(SR4030)	
Ricoh AFICIO MP C2	180190	24	ST()	Black meter = 14k, color meter = 10k
Lanier LD420C	181199	71	ST() PS(TYPE C3000)	Color = 20k; B/W = 52k
Ricoh AFICIO MP C2	184759	175	ST() FN(SR3010) FAX(TYPE MPC3000) E(BN3000)	Black meter = 155k, color meter = 20k
Savin C2020	185472	49	ST() FAX(TYPE MPC3000) E(BN3000)	Control panel broken on right side, control board broken - unable to fully test machine, left corner of PC dented, stand front doors missing, black meter = 48k, color meter = 16k
Ricoh AFICIO MP C2	186788	207	ST()	Black meter = 119k, color meter = 88k, power cord sheath torn
Lanier LD420C	188339	248	ST()	Black meter = 173k, color meter = 75k
Ricoh AFICIO MP C2	190885	219	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 192k, color meter = 27k
Ricoh AFICIO MP C2	191548	181	ST()	Color = 107k; B/W = 74k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD420C	192306	317 ST()	FAX(TYPE MPC3000)	Front door cracked, black meter = 225k, color meter = 93k
Ricoh AFICIO MP C2	180142	72 ST()		Black meter = 61k, color meter = 12k
Lanier LD520C	184666	54 ST()		Lower right side door broken, black meter = 32k, color meter = 22k
Lanier LD520C	184667	42 ST()		Yellow, ground in dirt, jamming in duplexer - deflector broken, error code SC536 - junction gate solenoid fan error - not fully tested, black meter = 37k, color meter = 6k
Ricoh AFICIO MP C2	185398	110 ST()		Black meter = 94k, color meter = 17k
Ricoh AFICIO MP C2	189118	146 ST()	FN(TYPE C2550)	Missing black, yellowed & magenta toner cartridges- tested with others; Color = 58k; B/W = 88k
Ricoh AFICIO MP C2	190891	63 ST()		Black meter = 50k, color meter = 13k
Lanier LD520C	192305	88 ST()	FAX(TYPE C2550)	Black meter = 62k, color meter = 27k
Ricoh AFICIO MP C2	181664	197 ST()	FN(SR790) FAX(TYPE MPC3000)	Error code SC553 - fuser heater roller temp too high - not tested, black meter = 160k, color meter = 38k
Lanier LD425C	183666	396 PED(PB3000)	FN(SR3000)	Black meter = 198k, color meter = 198k
Lanier LD425C	184141	334 PED(PB3000)	FN(SR790)	Black meter = 330k, color meter = 4k
Savin C2525	184359	313 ST()	FN(SR3010)	Black meter = 292k, color meter = 22k
Savin C2525	184370	259 PED(PB3000)	FAX(TYPE MPC3000) E(BN3000)	Black meter = 167k, color meter = 93k
Savin C2525	184569	195 ST()	SS(SH3000)	Black meter = 139k, color meter = 57k
Lanier LD425C	184662	267 ST()		Black meter = 199k, color meter = 68k
Lanier LD425C	184663	247 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000)	Black meter = 231k, color meter = 17k
Ricoh AFICIO MP C2	184945	202 PED(PB3000)	FAX(TYPE MPC3000)	Missing finisher - has brackets, black meter = 121k, color meter = 82k
Savin C2525	185110	393 PED(PB3000)		Black meter = 369k, color meter = 24k
Ricoh AFICIO MP C2	185140	293 PS(TYPE C3000)	PED(PB3000) FN(SR3010) FAX(TYPE MPC3000)	Yellow panels, black meter = 123k, color meter = 171k
Ricoh AFICIO MP C2	185241	263 ST()		Black meter = 226k, color meter = 38k
Gestetner DSC525	185242	659 ST()	FN(SR790)	Yellow panels, black meter = 484k, color meter = 175k
Ricoh AFICIO MP C2	185377	144 ST()	FN(SR3010) FAX(TYPE MPC3000)	Stapler not jogging - not stapling paper, black meter = 105k, color meter = 40k
Ricoh AFICIO MP C2	185396	N/A ST()	FN(SR3010) FAX(TYPE MPC3000)	Missing hard-drive - does not come to ready - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C2	185397	378	ST()	Black meter = 315k, color meter = 63k
Lanier LD425C	185777	646	PED(PB3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	has wireless PC card, control panel yellow, front door cracked, black meter = 152k, color meter = 495k
Gestetner DSC525	185789	258	ST()	Black meter = 221k, color meter = 37k
Lanier LD425C	186631	362	PED(PB3000) FN(SR3010) FAX(TYPE MPC3000)	Finisher exit tray missing - finisher not tested, black meter = 273k, color meter = 90k
Savin C2525	186685	333	ST() FAX(TYPE MPC3000) E(BN3000)	Control panels yellow, black meter = 290k, color meter = 44k
Gestetner DSC525	186722	724	ST() FN(SR790)	Black meter = 603k, color meter = 121k
Lanier LD425C	186729	141	PED(PB3000) FAX(TYPE MPC3000)	Jamming in bypass - not tested, yellow panels, black meter = 103k, color meter = 39k
Ricoh AFICIO MP C2	186750	323	PS(TYPE C3000) PED(PB3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Black meter = 288k, color meter = 35k
Ricoh AFICIO MP C2	186789	38	ST()	Black meter = 26k, color meter = 12k
Savin C2525	186873	384	ST() FN(SR3010)	Yellow panels
Lanier LD425C	186913	179	ST()	Black meter = 147k, color meter = 32k
Ricoh AFICIO MP C2	186944	376	PS(TYPE C3000) PED(PB3010)	Black meter = 254k, color meter = 123k
Ricoh AFICIO MP C2	187074	368	ST() PS(TYPE C3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Black meter = 357k, color meter = 11k, ground in dirt
Ricoh AFICIO MP C2	187218	218	PS(TYPE C3000) PED(PB3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Black meter = 156k, color meter = 62k
Savin C2525	187358	547	ST()	Black meter = 434k, color meter = 113k, off color and dirty
Lanier LD425C	187745	219	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 198k, color meter = 22k
Ricoh AFICIO MP C2	187815	220	ST() FAX(TYPE MPC3000)	Exit area cover missing, RADF actuator missing - RADF not tested, front door cracked at hinge, black meter = 206k, color meter = 14k
Ricoh AFICIO MP C2	188167	188	ST() FAX(TYPE MPC3000) E(BN3000)	Off color and dirty, half of image in black copies, black meter = 144k, color meter = 44k
Lanier LD425C	188338	393	ST() FN(SR790) FAX(TYPE MPC3000)	Finisher tray missing, black meter = 323k, color meter = 71k
Ricoh AFICIO MP C2	188695	165	ST() PS(TYPE C3000) FN(SR790) FAX(TYPE	Color = 27k; B/W = 138k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			MPC3000) E(BN3000)	
Lanier LD425C	188714	223 ST()	FAX(TYPE MPC3000)	Color = 17k; B/W = 207k
Ricoh AFICIO MP C2	188762	108 ST()	FN(SR3010) FAX(TYPE MPC3000)	Very dirty panels; color = 15k; B/W = 94k
Ricoh AFICIO MP C2	189123	244 ST()		Color = 59k; B/W = 185k
Ricoh AFICIO MP C2	190075	N/A	PED(PB3000) FN(SR3000)	Touch screen not responding - not fully tested
Lanier LD425C	190585	184 ST()		Black meter = 131k, color meter = 54k
Ricoh AFICIO MP C2	190768	315 PED(PB3000)	FAX(TYPE MPC3000) E(BN3000)	Black meter = 296k, color meter = 20k
Ricoh AFICIO MP C2	190951	129 PED(PB3000)		Black meter = 104k, color meter = 25k
Ricoh AFICIO MP C2	191020	425 SS(SH3000)	PED(PB3000) FAX(TYPE MPC3000)	Black meter = 155k, color meter = 270k
Ricoh AFICIO MP C2	191021	379 ST()	SS(SH3000) FAX(TYPE MPC3000)	Yellow panels, black meter = 205k, color meter = 174k
Gestetner DSC525	191390	459 ST()		Black meter = 341k, color meter = 119k
Ricoh AFICIO MP C2	191419	270 PED(PB3000)		Missing RADF - has book platen, Off color panels, black meter = 180k, color meter = 91k
Ricoh AFICIO MP C2	191420	73 PED(PB3000)		Black meter = 46k, color meter = 28k, has book platen- Missing RADF
Ricoh AFICIO MP C2	191421	157 PED(PB3000)		Has a book platen- missing RADF, control panel cover yellow, black meter = 120k, color meter = 37k, Missing RADF - has platten lid
Ricoh AFICIO MP C2	191422	104 PED(PB3000)		Missing RADF - has book platen, black meter = 69k, color meter = 35k
Ricoh AFICIO MP C2	191423	131 PED(PB3000)		Has a book platen- missing RADF, black meter = 98k, color meter = 33k
Ricoh AFICIO MP C2	191527	359 PED(PB3000)	FAX(TYPE MPC3000)	Black meter = 291k, color meter 69k, front door cracked
Ricoh AFICIO MP C2	191541	143 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000)	Missing finisher entrance guide, bottom finisher tray missing, error code SC792- finisher not recognized - not tested, finisher access door hinge broken, black meter = 99k, color meter = 45k
Ricoh AFICIO MP C2	191627	205 ST()	FN(SR3010) FAX(TYPE MPC3000) E(BN3000)	Finisher plug broken - finisher not tested, off color panels, black meter = 199k, color meter = 7k
Ricoh AFICIO MP C2	191634	232 ST()	FN(SR790) FAX(TYPE MPC3000)	Black meter = 136k, color meter = 95k, duplexer panel cracked
Ricoh AFICIO MP C2	191668	267 ST()	PU(PU3000) FN(SR3000) FAX(TYPE MPC3000)	Black meter = 223k, color meter = 44k, front door cracked

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C2	191814	58 ST()		Black meter = 56k, color meter = 2k
Lanier LD425C	191982	152 ST()	FAX(TYPE MPC3000)	Black meter = 90k, color meter = 63k
Lanier LD425C	192042	334 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000)	Black meter = 284k, color meter = 51k, Finisher panels yellow
Lanier LD425C	192044	452 ST()		Black meter = 230k, color meter = 223k
Savin C2525	192302	385 ST()	SS(SH3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 228k, color meter = 158k
Lanier LD425C	192304	190 ST()		Black meter = 160k, color meter = 30k
Savin C2525	192495	N/A ST()	PED(PB3010) FN(SR3010) FAX(TYPE MPC3000)	Touch screen not responding - not fully tested, off color panels, hard-drive removed
Ricoh AFICIO MP C2	192691	85 FN(SR3010)	FAX(TYPE MPC3000) E(BN3000)	RADF feed tray cracked, finisher yellow, black meter = 74k, color meter = 12k
Ricoh AFICIO MP C2	192706	N/A ST()	SS(SH3000) FAX(TYPE MPC3000) E(BN3000)	Touch screen not responding - not fully tested, back panels scratched
Ricoh AFICIO MP C2	182016	249 PED(PB3030)	FAX(TYPE C2550)	RADF socket bent, black meter = 229k, color meter = 20k
Ricoh AFICIO MP C2	182502	159 PED(PB3030)	FN(TYPE C2550) FAX(TYPE C2550)	Bypass jamming in fuser - not tested, black meter = 86k, color meter = 73k
Lanier LD525C	184157	166 ST()	FAX(TYPE C2550)	Fuser lock mechanism missing - jamming at fuser
Ricoh AFICIO MP C2	187190	125 ST()	FAX(TYPE C2550) E(TYPE C2550)	Black meter = 122k, color meter = 4k
Ricoh AFICIO MP C2	189119	361 PED(PB3030)	FN(TYPE C2550) FAX(TYPE C2550)	Broken RADF plug socket; color = 125k; B/W = 207k
Ricoh AFICIO MP C2	191642	62 ST()	FN(TYPE C2550) FAX(TYPE C2550)	Black meter = 55k, color meter = 8k
Lanier LD525C	192040	95 ST()	FAX(TYPE C2550)	Black meter = 73k, color meter = 23k
Ricoh AFICIO MP C2	192137	621 PU(PU3010NA)	PED(PB3030) FN(TYPE C2550) FAX(TYPE C2550)	Black meter = 350k, color meter = 272k
Ricoh AFICIO MP C2	192697	289 ST()	PS(TYPE C2550) FN(TYPE C2550) FAX(TYPE C2550)	Black meter = 159k, color meter = 131k
Savin C2828	180180	46 ST()	FN(SR790)	Jamming in stapler - not tested, black meter = 44k, color meter = 3k
Ricoh AFICIO MP C2	180836	207 ST()	FN(SR3050) FAX(TYPE C5000)	Error code SC798-1 finisher upper limit switch error - not tested, black meter = 165k, color meter = 42k
Lanier LD528C	190278	390 ST()	FN(SR3000) FAX(TYPE C5000)	Black meter = 230k, color meter = 161k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C2	191626	N/A	ST() FN(SR790) FAX(TYPE C5000)	Missing SD cards - machine will not come to ready - not tested, bottom finisher tray missing
Ricoh AFICIO MP C2	192053	116	ST()	Black meter = 84k, color meter = 33k
Ricoh AFICIO MP C3	178566	289	PED(PB3000) FAX(TYPE MPC3000)	Black meter = 135k, color meter = 154k
Ricoh AFICIO MP C3	179442	450	ST() FAX(TYPE MPC3000) E(BN3000)	Black meter = 446k, color meter = 5k, yellow panels
Ricoh AFICIO MP C3	180198	907	ST() FAX(TYPE MPC3000) E(BN3000)	Black meter = 848k, color meter - 60k
Ricoh AFICIO MP C3	180786	307	ST() FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Black meter = 67k, color meter = 240k
Lanier LD430C	181852	563	PED(PB3010) FAX(TYPE MPC3000) E(BN3000)	Missing finisher - has bridge unit, black meter = 325k, color meter = 239k
Ricoh AFICIO MP C3	184167	460	PED(PB3010) FN(SR790) FAX(TYPE MPC3000)	Color = 69k; B/W = 392k
Savin C3030	184866	265	ST() PED(PB3010) FAX(TYPE MPC3000)	Black meter = 191k. color meter = 75k
Lanier LD430C	185589	640	ST()	Black meter = 420k, color meter = 221
Savin C3030	186480	337	PED(PB3010) FN(SR3010)	Yellow finisher panels, black meter = 263k, color meter = 75k
Ricoh AFICIO MP C3	187213	438	ST() FN(SR3000)	Control panel off color, black meter = 330k, color meter = 108k
Ricoh AFICIO MP C3	187865	918	ST() FN(SR3010) FAX(TYPE MPC3000)	Finisher off color, black meter = 566k, color meter = 353k
Ricoh AFICIO MP C3	188499	234	ST() FAX(TYPE MPC3000)	Control panel offcolor, black meter = 219k, color meter = 15k
Ricoh AFICIO MP C3	189037	1249	ST() FN(SR790) FAX(TYPE MPC3000)	Finisher yellow, front panel cracked, black meter = 1217k, color meter = 32k, off color panels, front panel cracked
Ricoh AFICIO MP C3	189038	350	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 330k, color meter = 21k
Ricoh AFICIO MP C3	189039	255	ST() FN(SR790) FAX(TYPE MPC3000)	Error code SC742 - finisher stapler movement motor - stapler not tested, black meter = 238k, color meter = 16k
Ricoh AFICIO MP C3	189040	563	ST() FN(SR790) FAX(TYPE MPC3000)	Yellow panels, black meter = 520k, color meter = 43k
Ricoh AFICIO MP C3	189041	566	ST() FN(SR790) FAX(TYPE MPC3000)	Finisher yellow, black meter = 483k, color meter 84k
Ricoh AFICIO MP C3	189042	1602	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 1047k, color meter = 15k, front door cracked
Ricoh AFICIO MP C3	189043	878	ST() FN(SR790) FAX(TYPE MPC3000)	Finisher yellow, black meter = 860k, color meter = 19k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C3	189044	509	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 412k, color meter = 97k
Ricoh AFICIO MP C3	189045	478	PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Black meter = 418k, color meter = 60k
Ricoh AFICIO MP C3	189046	383	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 362k, color meter = 21k
Ricoh AFICIO MP C3	189047	437	ST() FN(SR790) FAX(TYPE MPC3000)	Finisher deflector spring missing from finisher, black meter = 422k, color meter = 15k
Ricoh AFICIO MP C3	189048	358	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 347k, color meter = 11k, missing staple cartridge
Ricoh AFICIO MP C3	189049	405	ST() FN(SR790) FAX(TYPE MPC3000)	Stand front door broken, black meter = 354k, color meter = 51k
Ricoh AFICIO MP C3	189050	419	ST() FN(SR790) FAX(TYPE MPC3000)	Yellow finisher panels and control panel cover yellow, lower finisher panel, door & front trim melted, Black meter = 392k, color meter = 27k
Ricoh AFICIO MP C3	189051	508	ST() FAX(TYPE MPC3000)	Missing finisher - has bridge and mounting hardware, error code SC792 due to missing finisher, black meter = 481k, color meter = 27k
Savin C3030	189365	880	PED(PB3000)	Missing black and yellow toner- will not cycle toner (can't test), black meter = 120k, color meter = 761k
Lanier LD430C	189600	564	PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 542k, color meter = 22k
Savin C3030	190216	555	SS(SH3000) PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	PED right side access door broken, back right panel broken, RADF connector bent, black meter = 437k, color meter = 118k
Lanier LD430C	190270	556	ST() FN(SR790) FAX(TYPE MPC3000)	Finisher yellow, black meter = 296k, color meter = 260k
Ricoh AFICIO MP C3	190561	N/A	ST() FN(SR3000) FAX(TYPE MPC3000)	Touch screen not responding - not fully tested, yellow panels
Ricoh AFICIO MP C3	190749	700	ST() PU(PU3000) FN(SR3000) FAX(TYPE MPC3000)	Black meter = 627k, color meter = 74k
Savin C3030	191552	305	PU(PU3000) PED(PB3000) FN(SR3000) FAX(TYPE MPC3000)	Error code SC760 - finisher punch motor error - not tested, front door cracked, black meter = 245k, color meter = 61k
Ricoh AFICIO MP C3	191966	374	PED(PB3010)	Off color and dirty panels, front door cracked by hinges, black meter = 266k, color meter = 108k
Gestetner DSC530	192790	989	PED(PB3010) FN(SR3000) FAX(TYPE MPC3000)	Finisher panel below entrance bent, black meter = 972k, color meter = 18k
Ricoh AFICIO MP C3	182972	303	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 268k, color meter = 36k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			C5000)	
Ricoh AFICIO MP C3	185395	355 ST()	FAX(TYPE C5000)	Error code SC792 - missing finisher, black meter = 222k, color meter = 133k
Ricoh AFICIO MP C3	192360	138 PED(PB3040)	FN(SR790)	Black meter = 64k, color meter = 74k
Ricoh AFICIO MP C3	178565	639 PED(PB3010)		Black meter = 568k, color meter = 72k
Lanier LD435C	179128	435 PED(PB3000)	FN(SR3030)	Has fax option but missing control panel button, black meter = 341k, color 95k
Ricoh AFICIO MP C3	179438	410 ST()		Black meter = 352k, color meter = 59k
Gestetner DSC535	179573	605 ST()	FAX(TYPE MPC4500)	Error code SC-792 - finisher communication error - missing finisher, black meter = 416k, color meter = 189k
Savin C3535	179666	376 PU(PU3000)	PED(PB3010) FN(SR3030)	Ground in dirt, paper guides in top cassette not aligning, black meter = 351k, color meter = 26k
Ricoh AFICIO MP C3	180133	901 PED(PB3000)	FN(SR3020) FAX(TYPE MPC4500) E(BN3010)	Saddlestitch tray missing, finisher tray yellow, color meter = 227k, black meter = 675k
Ricoh AFICIO MP C3	181641	226 PED(PB3000)	FN(SR790) E(BN3010)	Black meter = 129k, color meter = 97k
Ricoh AFICIO MP C3	182017	713 ST()	FN(SR790) FAX(TYPE MPC4500)	Black meter = 436k, color meter = 277k, yellow panels
Ricoh AFICIO MP C3	182244	385 PS(TYPE C4500)	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Black meter = 163k, color meter = 222k
Savin C3535	182285	316 ST()	FN(SR790) FAX(TYPE MPC4500)	Finisher top access door broken, black meter - 271k, color meter = 45k
Ricoh AFICIO MP C3	183346	618 PS(TYPE C4500)	PED(PB3000) FN(SR790)	Control panel off color, finisher panels yellow, black meter = 249k, color meter = 370k
Lanier LD435C	183542	483 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Black meter = 348k, color meter = 135k
Ricoh AFICIO MP C3	183566	665 PED(PB3000)		Black meter = 584k, color meter = 81k
Savin C3535	183653	497 ST()	PS(TYPE C4500)	Black meter = 241k, color meter = 257k
Gestetner DSC535	184477	576 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Black meter = 468k, color meter = 108k
Ricoh AFICIO MP C3	184527	504 PU(TYPE 3260)	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 411k, color meter = 93k
Ricoh AFICIO MP C3	185371	38 PED(PB3000)	PC(FIERY E-5000) FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Finisher top access door will not latch, stapler not attached - not tested, black meter = 32k, color meter = 7k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C3	185392	497	PU(TYPE 3260) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Yellow panels, black meter = 417k, color meter = 80k
Ricoh AFICIO MP C3	185864	500	ST() FAX(TYPE MPC4500)	Color = 169k; B/W = 332k
Ricoh AFICIO MP C3	186460	364	PED(PB3000) PC(FIERY E-5000) FN(SR790)	Black meter = 238k, color meter = 127k
Ricoh AFICIO MP C3	186786	123	PU(TYPE 3260) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Error code SC690 - BCU or laserboard - machine not tested, black meter = 44k, color meter = 79k
Ricoh AFICIO MP C3	187365	328	PS(TYPE C4500) PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 211k, color meter = 118k, cassette #1 handle broken
Ricoh AFICIO MP C3	187366	357	PS(TYPE C4500) PED(PB3000) FAX(TYPE MPC4500) E(BN3010)	Black meter = 265k, color meter = 93k
Lanier LD435C	187746	422	PS(TYPE C4500) PED(PB3000)	Black meter = 374k, color meter = 48k
Ricoh AFICIO MP C3	188200	277	ST() PS(TYPE C4500)	Black meter = 104k, color meter = 174k
Ricoh AFICIO MP C3	188498	348	PU(TYPE 3260) PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Black meter = 261k, color meter = 88k
Ricoh AFICIO MP C3	188502	213	PU(TYPE 3260) PED(PB3000) FN(SR3020)	Finisher exit tray missing, black meter = 93k, color meter = 121k
Ricoh AFICIO MP C3	188514	136	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Jamming in bypass, jamming out of cassette #2, jamming in duplexer, very dirty, Finisher top access door not latching, black meter = 94k, color meter = 43k
Lanier LD435C	188974	112	ST() PU(PU3000) FN(SR3020)	Missing external PC, has cable, black meter = 41k, color meter = 71k
Lanier LD435C	188976	N/A	PED(PB3000)	Error code SC689 - IH inverter error - not tested, touch screen frozen, missing fax board- has control panel button, hard-drive removed
Ricoh AFICIO MP C3	189110	335	ST() FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Color = 52k; B/W = 284k; missing front bypass paper guide
Ricoh AFICIO MP C3	189126	485	PED(PB3000) FN(SR3020)	Finisher frame bent, door broken & exit shift tray bracket bent- inop; finisher brackets bent; broken upper left side scanner trim panel; color = 31k; B/W = 454k
Ricoh AFICIO MP C3	189136	429	ST() FN(SR790) FAX(TYPE MPC4500)	Missing finisher tray; stapler jams- inop; color = 88k; B/W = 342k
Savin C3535	189967	379	ST() FAX(TYPE MPC4500) E(BN3010)	Control panel cover yellow, black meter = 365k, color meter = 14k
Ricoh AFICIO MP C3	190488	679	PED(PB3000) PC(FIERY	Color = 221k; B/W = 459k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			E-5000) FN(SR3020) FAX(TYPE MPC4500)	
Ricoh AFICIO MP C3	190507	953 PED(PB3000)	FN(SR790)	Black meter = 744k, color meter = 209k
Lanier LD435C	190586	380 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Black meter = 338k, color meter = 43k
Ricoh AFICIO MP C3	190736	425 PED(PB3000)	E(BN3010)	Black meter = 274k, color meter = 152k
Ricoh AFICIO MP C3	190883	443 PED(PB3000)	FN(SR790)	Black meter = 393k, color meter = 51k
Ricoh AFICIO MP C3	190896	694 PED(PB3010)	FN(SR3030) FAX(TYPE MPC4500)	Missing fiery PC - has control panel button and sticker, black meter = 550k, color meter = 145k
Ricoh AFICIO MP C3	190947	116 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Finisher top access door broken, finisher throat and entrance badly bent, - false jam in finisher - not tested, fax button missing on control panel, very dirty and off color, black meter = 80k, color meter = 36k
Ricoh AFICIO MP C3	190950	263 PED(PB3010)		Missing finisher- has brackets and bridge unit, black meter = 234k, color meter = 29k
Lanier LD435C	190953	448 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Has VM cardy type C, black meter = 119k, color meter = 329k
Gestetner DSC535	191111	519 ST()	FN(SR790)	Control panel yellow, RADF inverter broken gate - RADF not tested, right finisher hook missing, black meter = 407k, color meter = 112k
Ricoh AFICIO MP C3	191433	365 ST()	FAX(TYPE MPC4500) E(BN3010)	Black meter = 329k, color meter = 36k
Ricoh AFICIO MP C3	191625	221 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Dirty and off color panels, front door cracked & bent, black meter = 147k, color meter = 75k
Ricoh AFICIO MP C3	191953	422 PU(TYPE 3260)	PED(PB3000) FN(SR3030)	Jamming in punch unit - not tested, black meter = 254k, color meter = 168k
Lanier LD435C	191984	N/A PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Error code SC750 - Finisher eprom, error code SC792 - does not recognize finisher - machine not tested, touch screen inoperable, finisher very yellow
Ricoh AFICIO MP C3	192049	607 PED(PB3000)	FN(SR790)	Cassetet #4 not feeding - not tested, black meter = 508k, color meter = 100k
Ricoh AFICIO MP C3	192054	355 ST()	FN(SR790) FAX(TYPE MPC4500)	RADF plug socket broken, Finisher top access door broken - stapler not tested, black meter = 316k, color meter = 39k
Ricoh AFICIO MP C3	192101	638 PU(TYPE 3260)	PS(TYPE	Black meter = 605k, color meter = 34k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			C4500) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	
Ricoh AFICIO MP C3	192780	366	ST()	Missing all toner cartridges- tested with others; Black meter = 336k, color meter = 31k
Savin C3535	192793	223	ST() FN(SR3020) FAX(TYPE MPC4500)	Bottom finisher tray and bracket missing, black meter = 92k, color meter = 131k
Ricoh AFICIO MP C4	181521	202	PED(PB3050) FN(SR3020) FAX(TYPE C5000)	Black meter = 26k, color meter = 176
Ricoh AFICIO MP C4	186261	117	PED(PB3040) FAX(TYPE C5000) E(BN3070)	Error code SC872 - initialize or replace hard-drive, black meter = 91k, color meter = 27k
Ricoh AFICIO MP C4	187193	297	ST() FN(SR790) FAX(TYPE C5000)	Black meter = 264k, color meter = 33k
Ricoh AFICIO MP C4	190360	332	PED(PB3040) FAX(TYPE C5000) E(BN3070)	RADF socket bent, left side panel cracked, black meter = 299k, color meter = 34k
Ricoh AFICIO MP C4	190897	115	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Back panel cracked, front door cracked, black meter = 54k, color meter = 62k
Ricoh AFICIO MP C4	191646	708	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Finisher top access door broken, lower left side finisher panel broken, finisher metal bracket bent, jamming when duplexing - not tested, black meter = 708k, color meter = 1k
Lanier LD540C	192469	435	PED(PB3050) FN(SR790) FAX(TYPE C5000)	Black meter = 394k, color meter = 42k
Ricoh AFICIO MP C4	181636	967	PED(PB3000) FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Black meter = 810k, color meter = 158k
Lanier LD445C	182526	855	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500) E(BN3010)	yellow control panel cover, finisher tray yellow, black meter = 690k, color meter = 166k
Ricoh AFICIO MP C4	182560	260	PU(TYPE 3260) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Color = 121k; B/W = 140k
Ricoh AFICIO MP C4	182593	N/A	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Has wrong RADF attached to machine, touch screen not responding - not fully tested
Lanier LD445C	182877	530	PED(PB3010) FN(SR3020)	Black meter = 450k, color meter = 80k
Lanier LD445C	183098	428	PED(PB3000) FN(SR790)	Finisher top access door broken, black meter= 229k, color meter =
Lanier LD445C	183101	608	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	jamming at bridge unit - finisher not tested, jamming in RADF at slit glass - slit glass cracked, black meter = 598k, color meter = 11k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C4	183517	447	PED(PB3000) FN(SR790)	Black meter = 344k, color meter = 104k
Ricoh AFICIO MP C4	183974	483	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Missing toner cartridges- tested with others; color = 254k; B/W = 230k; missing serial tag on back panel
Gestetner DSC545	184138	515	ST() PU(TYPE 3260) FN(SR3020) FAX(TYPE MPC4500)	Error code sc819 -Kernel Mismatch, Download Firmware again, black meter = 333k, color meter = 183k
Ricoh AFICIO MP C4	184188	562	FN(SR3030) FAX(TYPE MPC4500)	Has wireless PC card, black meter = 546k, color meter = 16k
Lanier LD445C	184472	756	PS(TYPE C4500) PED(PB3010) FN(SR790) FAX(TYPE MPC4500)	Control panel yellow, black meter = 562k, color meter = 195k
Ricoh AFICIO MP C4	185139	427	ST() FN(SR790) FAX(TYPE MPC4500)	Black meter = 231k, color meter = 195k
Lanier LD445C	185744	N/A	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Finisher tray missing, finisher top access door broken, error code SC860 - hard-drive format error - not tesetd
Savin C4540	185940	295	PED(PB3010) FN(SR790)	Color = 77k; B/W = 219k
Ricoh AFICIO MP C4	186490	552	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Finisher paper deflector missing - finisher not tested, finisher exit tray cracked, black meter = 483k, color meter = 69k
Ricoh AFICIO MP C4	186958	1128	PU(TYPE 3260) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 815k, color meter = 313k
Ricoh AFICIO MP C4	187181	1880	PU(TYPE 3260) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Missing finisher throat, back panle broken, top finisher tray cover broken, paper sensor broken out of top finisher tray, black meter 449k, color meter = 1431k
Ricoh AFICIO MP C4	187191	325	ST() FN(SR790) FAX(TYPE MPC4500)	Black meter = 282k, color meter = 44k
Savin C4540	187550	763	ST() FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Rear bypass paper guide missing, RADF actuator broken, black meter = 762k, color meter = 2k
Lanier LD445C	187747	924	PED(PB3010) FN(SR790) FAX(TYPE MPC4500)	Black meter = 923k, color meter = 1k
Savin C4540	187752	855	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Control panel cover yellow, finisher yellow, black meter = 825k, color meter = 31k
Ricoh AFICIO MP C4	188503	325	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 240k, color meter = 85k
Ricoh AFICIO MP C4	188515	208	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Finisher tray yellow, control panel cover yellow, black meter = 160k, color meter = 48k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C4	188627	681	PED(PB3000) FAX(TYPE MPC4500) E(BN3010)	Color = 155k; B/W = 527k
Lanier LD445C	189117	785	PED(PB3010) FN(SR3020)	Color = 302k; B/W = 483k
Ricoh AFICIO MP C4	189623	748	PU(TYPE 3260) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Finisher exit tray yellow, black meter = 611k, color meter = 138k
Savin C4540	189965	586	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Control panel cover very yellow, black meter = 460k, color meter = 126k
Savin C4540	189966	497	ST() FAX(TYPE MPC4500) E(BN3010)	Black meter = 344k, color meter = 153k
Lanier LD445C	190190	456	PED(PB3000) FAX(TYPE MPC4500)	Missing finisher - has bridge unit, went into error code SC548 (fuser rotate error fuser belt sensor actuator sensor, IH inverter) during testing, black meter = 437k, color meter = 20k
Ricoh AFICIO MP C4	190463	684	PED(PB3000) FN(SR790)	Fax board removed - has button on control panel, black meter = 631k, color meter = 54k
Lanier LD445C	190591	596	PED(PB3000) FN(SR3020)	Black meter = 544k, color meter = 52k
Savin C4540	190817	717	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Finisher off color, Finisher not deflecting paper to lower finisher tray - not tested, right side vent cracked, black meter = 567k, color meter = 150k
Ricoh AFICIO MP C4	190823	648	PED(PB3000) FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Jamming in stapler - not tested, black meter = 587k, color meter = 61k
Ricoh AFICIO MP C4	190884	412	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Holes in right side access panels, bypass tray broken, black meter = 342k, color meter = 70k
Lanier LD445C	192475	916	PU(PU3000) PED(PB3000) FN(SR3020) FAX(TYPE MPC4500) E(BN3010)	Front door off color, black meter = 497k, color meter = 419k
Gestetner DSC545	192597	627	PED(PB3010) FAX(TYPE MPC4500)	Error code SC564- fuser pressure roller overheat - yellow control panel, black meter = 527k, color meter = 101k
Ricoh AFICIO MP C5	177843	347	PED(PB3050) FN(SR790)	Black meter = 338k; color meter = 9k
Savin C5050	181660	262	PS(TYPE C5000) PED(PB3040) FAX(TYPE C5000)	Hard drive removed after testing; Missing finisher causing error code SC792- communication problem with finisher; black meter = 213k, color meter = 50k
Ricoh AFICIO MP C5	182974	472	PED(PB3050) FN(SR790)	PED panels yellow, skewing paper in stapler conveyer tray - not tested, black meter = 314k, color meter = 158k
Ricoh AFICIO MP C5	184510	439	ST() FN(SR790) FAX(TYPE	Black meter = 380k, color meter = 59k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			C5000)	
Ricoh AFICIO MP C5	184511	685	ST() FN(SR790) FAX(TYPE C5000)	Jamming in stapler - not tested, black meter = 91k, color meter = 595k
Ricoh AFICIO MP C5	186257	135	PU(TYPE 3260) PED(PB3040) FN(SR3030) FAX(TYPE C5000) E(BN3070)	Lower finisher tray yellow, Control panel cover yellow, black meter = 127k, color meter = 9k
Ricoh AFICIO MP C5	188835	745	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Black meter = 503k, color meter = 243k
Savin C5050	189601	457	PED(PB3050)	Black meter = 407k, color meter = 51k
Ricoh AFICIO MP C5	190361	365	PED(PB3040) FAX(TYPE C5000) E(BN3070)	Black meter = 260k, color meter = 106k
Lanier LD550C	191384	794	PED(PB3050) FN(SR790) FAX(TYPE C5000)	Black meter = 114k, color meter = 681k
Ricoh AFICIO MP C5	191644	969	PED(PB3040) FN(SR3020) FAX(TYPE C5000) E(BN3070)	Black meter= 599k, color meter = 370k
Ricoh AFICIO MP C5	191645	586	PED(PB3040) P(RT3000) FN(SR3020)	Black meter = 322k, color meter = 265k
Ricoh AFICIO MP C5	192055	431	PS(TYPE C5000) PED(PB3040) FN(SR790) FAX(TYPE C5000)	Black meter = 136k, color meter = 295k
Ricoh AFICIO MP C5	192104	212	ST() PS(TYPE C5000) FN(SR790) FAX(TYPE C5000)	Finisher tray frame bent - finisher not tested, black meter = 207k, color meter = 6k
Ricoh AFICIO MP C5	192694	457	PU(TYPE 3260) PED(PB3050) FN(SR3030)	Black meter = 236k, color meter = 222k
Ricoh AFICIO MP C6	167181	741	FN(SR4010) FAX(TYPE C7500)	Color = 108k; B/W = 633k
Ricoh AFICIO MP C6	175037	518	PS(TYPE C7500) P(RT4000) FN(SR4010)	Black meter = 17k; color meter = 502k
Lanier LD260C	178541	1269	FN(SR4020)	Yellow panels, dirty, black meter = 1185k, color meter = 84k
Lanier LD260C	180678	916	PU(TYPE 3260) PS(TYPE C7500) P(RT43) FN(SR4010)	Black meter = 394k, color meter = 522k
Ricoh AFICIO MP C6	180849	794	P(RT4000) FN(SR4010)	bypass was removed to install paperdeck, black meter = 709k, color meter = 86k
Lanier LD260C	181273	319	PU(TYPE 3260) FN(SR5000)	RADF smashed - not tested, RADF top panel broken, RADF frame bent - not tested, black meter = 197k, color meter = 122k
Ricoh AFICIO MP C6	181523	557	PU(TYPE 3260) PS(TYPE C7500) FN(SR4020) FAX(TYPE C7500)	Right side panel cracked and dented, black meter = 223k, color meter = 334k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C6	183267	721	PU(TYPE 3260) PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Black meter = 513k, color meter = 208k
Ricoh AFICIO MP C6	183269	689	PU(TYPE 3260) PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Black meter = 411k, color meter = 279k
Ricoh AFICIO MP C6	183270	1418	PU(TYPE 3260) PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Black meter = 828k, color meter = 591k
Ricoh AFICIO MP C6	183271	880	PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Black meter = 563k, color meter = 318k
Ricoh AFICIO MP C6	186751	553	PU(TYPE 3260) PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Black meter = 496k, color meter = 57k
Ricoh AFICIO MP C6	186752	545	PU(TYPE 3260) PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Finisher access door interlock switch broken - finisher not tested, black meter = 439k, color meter = 106k
Ricoh AFICIO MP C6	186753	838	PU(TYPE 3260) PS(TYPE C7500) FN(SR4010) FAX(TYPE C7500)	Black meter = 469k, color meter = 370k
Ricoh AFICIO MP C6	186764	219	PS(TYPE C7500) P(RT4000)	Does not recognize paperdeck - not tested, black meter = 58k, color meter = 161k
Ricoh AFICIO MP C6	186784	1053	PS(TYPE C7500) FN(SR4020) FAX(TYPE C7500)	Left side cover missing, black meter = 660k, color meter = 394k
Ricoh AFICIO MP C6	186787	904	PU(TYPE 3260) FN(SR4020) FAX(TYPE C7500)	Has Z-fold unit, machine will not come to ready - not tested, black meter = 737k, color meter = 168k
Ricoh AFICIO MP C6	187182	857	PU(TYPE 3260) FN(SR4020)	Black meter = 565k, color meter = 292k
Ricoh AFICIO MP C6	188467	219	PC(FIERY E-7100) FN(SR4010)	Deep scratch in front door; color = 124k; B/W = 95k
Ricoh AFICIO MP C6	189135	676	STK(CS391) FN(SR4010)	Black meter = 511k, color meter = 165k
Ricoh AFICIO MP C6	189146	484	FN(SR4010) FAX(TYPE C7500)	Color copies and doc server are password protected - tested in SP mode, black meter = 459k, color meter = 26k
Lanier LD260C	189337	488	PU(TYPE 3260) FN(SR4010)	Color = 29k; B/W = 460k
Ricoh AFICIO MP C6	190888	381	FN(SR4010)	Black meter = 365k, color meter = 17k
Ricoh AFICIO MP C6	191351	414	PU(TYPE 3260) FN(SR4010)	Black meter = 371k, color meter = 44k
Ricoh AFICIO MP C6	191773	441	PU(TYPE 3260) FN(SR4010)	Lower finisher tray mount bent- trays clicking when cycling, black meter =

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				376k, color meter = 66k
Ricoh AFICIO MP C6	191877	423	PS(TYPE C7500) FN(SR4010)	Black meter = 367k, color meter = 56k
Ricoh AFICIO MP C6	192050	693	PU(TYPE 3260) FN(SR4010)	Missing finisher entrance guide, black meter = 433k, color meter = 261k
Ricoh AFICIO MP C6	192693	727	STK(CS391) PU(TYPE 3260) FN(SR4010)	Stacker disassembled - not tested, toner in machine, back panel crocked, black meter = 400k, color meter = 327k
Ricoh AFICIO MP C7	185147	1184	PU(TYPE 3260) P(RT43) FN(SR4010) FAX(TYPE C7500)	Paper deck paper sensor broken, black meter = 1023k, color meter = 162k
Ricoh AFICIO MP C7	185148	808	PU(TYPE 3260) P(RT43) FN(SR4010) FAX(TYPE C7500)	Jamming out of cassette #1 - not tested, black meter = 675k, color meter = 134k
Lanier LD275C	186749	936	PU(TYPE 3260) FN(SR4020) FAX(TYPE C7500)	Control panel cover yellow
Ricoh PRO 1106EX	189759	1313	PS(TYPE 1356) PC(TYPE 1356) P(RT5000) B(BY5000)	Missing finisher
Ricoh PRO 1106EX	189760	989	PS(TYPE 1356) PC(TYPE 1356) P(RT5010) B(BY5000)	Missing finisher - has brackets
Ricoh PRO 1357EX	191967	3252	PU(PU5000) P(RT5040) INSU(CI5010) FN(BK5010E) FN(SR5000)	Also has a TR5010e trimmer unit & BF5010e stacker; finisher in error code SC726 (stapler finisher shift roller error)- front finisher jogger broken off; missing Fiery print controller (has decal); BK5010e rail system is missing; booklet maker not recognized by machine but works independently

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.