

Wulff Enterprises

02/10/2012

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-163	185474	N/A	ST() ADF(AR-SP2)	Yellow panels
Sharp AR-163	185475	N/A	ST() ADF(AR-SP2)	Bypass tray broken, yellow panels, machine does not respond - not
Sharp AR-163	185478	N/A	ST() ADF(AR-SP2)	Does not respond - not tested
Sharp AR-163	185479	N/A	ST() ADF(AR-SP2)	yellow panels, not responding - not tested
Sharp AR-163	185480	156	ST() ADF(AR-SP2)	Yellow panels
Toshiba E-STUDIO162D	191206	N/A	RADF(MR-3017) FAX(GD-1190)	Will not come to ready - not tested
Toshiba E-STUDIO162D	191207	N/A	RADF(MR-3017) FAX(GD-1190)	Blank display - not tested
Sharp AR-168D	191665	152	FAX(AR-FX9)	Toner spilled in cassette
Sharp AR-407	185476	N/A	PED(AR-DE1N [A]) P(AR-LC1) FN(AR-FN1N)	Yellow panels. toner spilled thoughtout machine, does not respond - not tested
Sharp AR-407	185477	N/A	PED(AR-DE1N [A]) P(AR-LC1) FN(AR-FN1N)	Yellow panels, not respodning - not tested, back panel dented
Sharp AR-407	185481	1064	PED(AR-DE1N [A]) P(AR-LC1) FN(AR-FN1N)	Off color panels
Sharp AR-407	185482	100	PED(AR-DE1N [A]) P(AR-LC1) FN(AR-FN1N)	Yellow panels
Sharp AR-407	185483	717	PED(AR-DE1N [A]) P(AR-LC1) FN(AR-FN1N)	Yellow panels
Sharp AR-407	185484	N/A	PED(AR-DE1N [A]) P(AR-LC1) FN(AR-FN1N)	Error code L6-10 - polygon motor lock detection, yellow and dirty panels
Sharp AR-BC260	180106	221	PED(AR-D19N)	Black meter = 213k, color meter = 8k
Sharp AR-BC320	180522	623	PED(AR-D19N) FN(AR-F13)	Jamming in fuser = not tested, black meter = 488k, color meter = 136k, off color panels
Sharp AR-BC320	184559	275	PED(AR-D19N) FN(AR-F13)	Off color panels, Black meter = 134k, color meter = 142k
Sharp AR-BC320	187603	421	PED(AR-D19N) FN(AR-F13)	Black meter = 374k, color meter = 48k
Sharp AR-BC320	189989	334	PED(AR-D19N) P(AR-LC8) FN(AR-F13) FAX(AR-FX10)	Black meter = 307k, color meter = 28k
Sharp AR-BC320	190955	228	PS(AR-PK4) PED(AR-D19N) FAX(AR-FX10)	Off color panels, Inverter missing exit tray, black meter = 193k, color meter = 36k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-BC320	191301	289	PED(AR-D19N) P(AR-LC8) FN(AR-F13) FAX(AR-FX10)	Black meter = 119k, color meter = 171k
Sharp AR-M162	182380	59	FAX(AR-FX11) ADF(AR-SP6N)	Yellow panels
Sharp AR-M162	185485	158	ST() PFU(AR-D25) ADF(AR-SP6N)	
Sharp AR-M162	185486	144	ST() PFU(AR-D24) ADF(AR-SP6N)	
Sharp AR-M207	184070	149	ST() RADF(AR-RP6N) FAX(AR-FX11)	Off color panels
Sharp AR-M207E	184323	164	ST() RADF(AR-RP6N) NIC(AR-NB3) FAX(AR-FX11)	
Sharp AR-M207E	191311	158	ST() RADF(AR-RP6N) NIC(AR-NB3)	
Sharp AR-M237	187141	105	ST()	
Sharp AR-M237	189234	252	ST() FAX(AR-FX7) E(AR-TR3)	
Sharp AR-M237	189235	312	ST() FAX(AR-FX7)	
Sharp AR-M237	189236	192	ST() PS(AR-PK1N) FAX(AR-FX7) E(AR-TR3)	Missing PC upgrade with NIC - has PS
Sharp AR-M237	189237	367	ST() FAX(AR-FX7)	Right side access door will not latch, jamming in duplexer - not tested
Sharp AR-M237	190792	129	ST()	
Sharp AR-M237	190805	389	ST()	
Sharp AR-M237	191482	326	ST()	
Sharp AR-M237	191483	588	ST()	
Sharp AR-M237	191497	428	ST()	Start button inop - not tested, yellow panels
Sharp AR-M277	180153	497	ST() SCAN(AR-NS2) PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M277	182437	1	ST()	Missing exit tray, bypass tray broken
Sharp AR-M277	187243	140	ST() FN(AR-FN5N)	Jams in finisher - not tested, yellow panels
Sharp AR-M277	187255	51	ST() FN(AR-FN5N)	
Sharp AR-M277	191797	151	ST()	Bypass tray broken, Jamming in fuser when duplexing - not tested, off color
Sharp AR-M280	189636	91	RADF(AR-EF1) PC(AR-P14) FN(AR-FN6) DX(AR-DU4)	Missing toner - not tested, yellow panels
Sharp AR-M317	185910	152		Right side access door broken
Sharp AR-M317	186388	390	ST() FAX(AR-FX7)	Does not recognize printer installed - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M317	187165	186	ST() FN(AR-FN5A)	False door signal in finisher - not tested, needs toner - not tested
Sharp AR-M317	188602	221	ST() PC(AR-P27) FN(AR-FN5A) FAX(AR-FX7)	Missing finisher brackets- can't mount finisher to test
Sharp AR-M317	191477	327	ST() SCAN(MX-NSX1) PU(AR-PN1B) PC(AR-P27) FN(AR-F14N)	
Sharp AR-M317	191481	415	ST() SCAN(MX-NSX1) PU(AR-PN1B) PC(AR-P27) FN(AR-F14N)	
Sharp AR-M350	188369	276	RADF(AR-EF1) PED(AR-D15) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7)	Need toner, off color panels
Sharp AR-M350	189251	148	RADF(AR-EF1) PED(AR-D14) FN(AR-FN7) DX(AR-DU3)	
Sharp AR-M355	187109	448	PED(AR-D28) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	Error code F1-15 - finisher lift motor problem - finisher tray out of alignment - finisher not tested
Sharp AR-M355	188367	105	PED(AR-D27) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	Off color panels
Sharp AR-M355	189331	417	ST() PFU(AR-MU2) PC(AR-P20) DX(AR-DU4) DSPF(AR-EF3)	Off color and dirty
Sharp AR-M355	190380	104	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	
Sharp AR-M355	190381	16	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	
Sharp AR-M355	190382	196	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	
Sharp AR-M355	190384	78	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	Lower finisher tray mount missing
Sharp AR-M355	190385	28	ST() PFU(AR-MU2) DX(AR-DU3) DSPF(AR-EF3)	RADF exit tray missing
Sharp AR-M355	190386	485	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	Knocking in fuser
Sharp AR-M355	190389	83	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M355	190390	282	ST() PU(AR-PN1B) PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	Bypass not recognizing paper - not tested, RADF exit tray missing
Sharp AR-M355	190393	66	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	Error code F1-15 - finisher lift motor problem - finisher tray out of alignment - not tsted, scanner back panel scratched
Sharp AR-M355	190868	321	SCAN(AR-NS3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	
Sharp AR-M355	191007	175	SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Error code E2-03 - laser output error - not tested, off color panels
Sharp AR-M355	191307	422	STK(AR-MS1) SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN7) FAX(AR-FX12) DX(AR-DU3)	Stapler broken - no tested
Sharp AR-M355	191478	1098	PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4)	
Sharp AR-M355	191479	485	ST() PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4) DSPF(AR-EF3)	Missing fuser unit- tested with another, missing toner bottle, error code F1-15 (finisher lift motor error) caused by finisher tray mount bent - finisher not tested
Sharp AR-M355	191633	258	ST() PFU(AR-MU2) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	
Sharp AR-M355	192185	340	SCAN(AR-NS3) PED(AR-D28) PC(AR-P20) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	
Sharp AR-M355	192187	256	SCAN(AR-NS3) PED(AR-D28) PC(AR-P20) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	
Sharp AR-M455	183804	583	ST() PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Finisher panels yellow, cassette #2 will not lift paper - not tested
Sharp AR-M455	183805	463	ST() PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Finisher panels yellow, error code F1-15 - finisher or console finisher lift problem - not tested
Sharp AR-M455	186084	164	PED(AR-D27) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	RADF exit tray missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M455	187782	99	PED(AR-D27) DX(AR-DU4) DSPF(AR-EF3)	Jamming in bypass
Sharp AR-M455	187890	638	SCAN(AR-NS3) PS(AR-PK6) PED(AR-D27) PC(AR-P21) DX(AR-DU4) DSPF(AR-EF3)	
Imagistics IM4511	187919	359	SCAN(ZB3500610) PED(9292) PC(ZB3500620) FN(9244) FAX(ZB3500590) DX(9245)	
Sharp AR-M455	188133	529	SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) DX(AR-DU4) DSPF(AR-EF3)	
Sharp AR-M455	189985	314	STK(AR-MS1) SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN7) FAX(AR-FX12) DX(AR-DU3)	Finisher off color panels
Sharp AR-M455	189986	622	STK(AR-MS1) SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN7) FAX(AR-FX12) DX(AR-DU3)	Fax panel dented
Sharp AR-M455	189988	331	STK(AR-MS1) SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN7) FAX(AR-FX12) DX(AR-DU3)	Fax unit back panel dented
Sharp AR-M455	190383	250	ST() PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	
Sharp AR-M455	190387	228	ST() PU(AR-PN1B) PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Jamming in finisher during staple mode and punching mode - not tested
Sharp AR-M455	190391	176	ST() PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	RADF exit tray missing
Imagistics IM4511	190447	424	SCAN(ZB3500610) PED(9292) PC(ZB3500620) FN(9244) FAX(ZB3500590) DX(9245)	RADF exit tray missing, finisher panels yellow
Sharp AR-M455	191308	233	SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4)	Off color panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M455	191309	1019	SCAN(AR-NS3) PS(AR-PK6) PED(AR-D28) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4) DSPF(AR-EF3)	Error code F1-15 - finisher or console finisher lift motor problem - lower finisher tray bracket bent - finisher not tested
Sharp AR-M455	191314	1352	SCAN(AR-NS3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4)	
Sharp AR-M455	191631	350	ST() PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Finisher bracket latch broken, jamming at finisher exit area, finisher panels yellow, jamming during reversing
Sharp AR-M455	191632	N/A	ST() PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Control panel buttons not working - not tested
Sharp AR-M455	191636	669	ST() PFU(AR-MU2) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Finisher bracket lock broken, Finisher tray broken, finisher panels yellow
Sharp AR-M455	192186	304	SCAN(AR-NS3) PED(AR-D28) PC(AR-P20) FN(AR-FN7) DX(AR-DU3) DSPF(AR-EF3)	Error code F1-06 - finisher console slide motor
Sharp AR-M550	183807	394	PC(AR-P19) P(AR-LC6) FN(AR-F16)	Yellow finisher panels, right side panel cracked, left side panel cracked
Sharp AR-M550	191798	298	PU(AR-PN4B) FN(AR-F15)	
Sharp AR-M550	192673	672	PC(AR-P19) FN(AR-F15)	Missing toner bottle - not tested
Sharp AR-M620	190065	969	PU(AR-PN4B) PC(AR-P19) FN(AR-F15)	
Sharp MX-2300N	178801	309	ST() FAX(MX-FXX1)	Off color and yellow panels, black meter = 300k, color meter = 10k
Sharp MX-2300N	179142	678	PS(MX-PKX1) PED(MX-DEX2)	Yellowed panels; color = 298k; B/W = 381k
Sharp MX-2300N	180363	341	ST() FAX(MX-FXX1)	Black meter = 290k, color meter = 52k
Sharp MX-2300N	182373	460	PS(MX-PKX1) PED(MX-DEX2) FN(MX-FNX1) FAX(MX-FXX1)	Yellow panels, black meter = 347k, color meter = 114k
Sharp MX-2300N	182422	362	ST()	Black meter = 300k, color meter = 62k
Sharp MX-2300N	182985	114	ST() FAX(MX-FXX1)	Bypass tray broken, black meter = 99k, color meter = 16k
Sharp MX-2300N	184421	262	ST() PS(MX-PKX1) FN(MX-FNX1)	Black meter = 140k, color meter = 122k
Sharp MX-2300N	184717	93	ST() PS(MX-PKX1)	Black meter = 17k, color meter = 77k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp MX-2300N	184744	236	ST()	
Sharp MX-2300N	184809	150	ST()	Black meter = 147k, color meter = 3k
Sharp MX-2300N	185002	245	ST() FAX(MX-FXX1)	Fax cover bent, black meter = 224k, color meter = 21k
Sharp MX-2300N	185510	103	PED(MX-DEX2) FAX(MX-FXX1)	Back panel dented, control panel yellow, black meter = 94k, color meter = 9k
Sharp MX-2300N	185511	86	PED(MX-DEX2) FAX(MX-FXX1)	Control panel yellow, black meter = 81k, color meter = 5k
Sharp MX-2300N	187026	134	ST() PS(MX-PKX1) FAX(MX-FXX1)	Jamming at fuser - not tested, black meter = 116k, color meter = 18k
Sharp MX-2300N	187119	108	PED(MX-DEX1) FAX(MX-FXX1)	Black meter = 56k, color meter = 53k
Sharp MX-2300N	187474	338	PED(MX-DEX2)	Jamming in fuser - not tested, black meter = 217k, color meter = 121k
Sharp MX-2300N	187702	114	PS(MX-PKX1) PED(MX-DEX2) FAX(MX-FXX1)	Black meter = 91k, color meter = 24k, could not print reports
Sharp MX-2300N	188599	188	ST() PS(MX-PKX1) FAX(MX-FXX1)	Color = 159k; B/W = 30k
Sharp MX-2300N	189333	320	PED(MX-DEX1) FN(MX-FNX1) FAX(MX-FXX1)	Fax panel dented, back panel dented, jamming during color copying - color mode not fully tested, missing exit tray, black meter = 255k, color meter = 66k
Sharp MX-2300N	190243	403	ST() FAX(MX-FXX1)	Black meter = 235k, color meter = 169k
Sharp MX-2300N	192624	362	PS(MX-PKX1) PED(MX-DEX1)	Transfer belt torn - not tested, Black meter = 340k, color meter = 22k
Sharp MX-2300N	192664	250	PED(MX-DEX2) FAX(MX-FXX1)	Black meter = 239k, color meter = 12k, jamming in fuser - not tested - fuser rollers not turning
Sharp MX-2700N	183610	582	ST() PS(MX-PKX1) FN(MX-FNX1) FAX(MX-FXX1)	Fax panels dented, Yellow panels, right side frame bent, rear panel missing, left side frame bent, black meter = 381k, color meter = 201k
Sharp MX-2700N	184202	630	PED(MX-DEX1)	Yellow panels, black meter = 497k, color meter = 134k
Sharp MX-2700N	185330	653	PED(MX-DEX1) FAX(MX-FXX1)	Dirty, right side panels yellow, jamming in bypass, black meter = 377k, color meter = 277k
Sharp MX-2700N	185331	540	PED(MX-DEX1)	Control panel and RADF yellow, black meter = 419k, color meter = 122k
Sharp MX-2700N	185332	680	PED(MX-DEX1)	Control panel and RADF yellow, black meter = 408k, color meter = 272k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp MX-2700N	187915	1036	PED(MX-DEX1)	Jamming in fuser - not tested, back right side panel dented, back corner panel dented, off color, clicking noise in machine, black meter = 746k, color meter = 290k
Sharp MX-2700N	189077	576	PED(MX-DEX1) FAX(MX-FXX1)	Missing all toner cartridges & waste toner bottle- tested with others; dented fax board panel; color = 157k; B/W = 420k
Sharp MX-2700N	189089	850	PED(MX-DEX1) FAX(MX-FXX1)	Color = 306k; B/W = 545k
Sharp MX-2700N	189167	355	ST() FN(MX-FNX2)	Off color panels, jamming in bypass, black meter = 199k, color meter =
Sharp MX-2700N	190199	299	ST() PS(MX-PKX1) FAX(MX-FXX1)	Black meter = 285k, color meter = 14k
Sharp MX-2700N	190869	517	ST() P(MX-LCX1) FN(MX-FNX1) FAX(MX-FXX1)	Black copies are blurry, black meter = 251k, color meter = 266k
Sharp MX-2700N	190870	271	ST() PS(MX-PKX1) P(MX-LCX1) FN(MX-FNX1) FAX(MX-FXX1)	Jamming in fuser - not tested, yellow panels; color = 185k; B/W = 86k
Sharp MX-2700N	190906	694	ST() PS(MX-PKX1) FN(MX-FNX1) FAX(MX-FXX1)	Black meter = 652k, color meter = 42k
Sharp MX-2700N	190907	485	ST() PS(MX-PKX1) FN(MX-FNX1) FAX(MX-FXX1)	Jamming in bypass - not tested, black meter = 438k, color meter = 48k
Sharp MX-3500N	171962	462	PED(MX-DEX4)	Black meter - 419k; color meter = 44k
Sharp MX-3500N	187471	146	ST() FN(MX-FNX1)	Error code H4-30 - fuser thermistor temp error - not tested, black meter = 135k, color meter = 12k
Sharp MX-3501N	150864	676	PED(MX-DEX4)	Black meter = 203k; color meter = 473k
Sharp MX-3501N	162327	498	ST()	Dented & scratched back panel; Color = 156k; B/W = 342k
Sharp MX-3501N	168590	750	PU(AR-PN1B) PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX2)	Black meter = 701k; color meter = 50k
Sharp MX-3501N	173469	272	PED(MX-DEX3) FN(MX-FNX1) FAX(MX-FXX1)	Off color & dirty panels
Sharp MX-3501N	173664	417	PED(MX-DEX4) FAX(MX-FXX1) E(MX-TRX2)	Black meter = 378k; color meter = 39k
Sharp MX-3501N	174226	333	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1)	Has MX-AMX2; black meter = 285k; color meter = 49k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp MX-3501N	176993	458	PED(MX-DEX4)	Black meter = 375k; color meter = 83k
Sharp MX-3501N	177580	739	ST()	Black meter = 714k; color meter = 25k
Sharp MX-3501N	178044	407	PS(MX-PKX1) PED(MX-DEX4) FAX(MX-FXX1)	Bad fuser roller causing machine to jam every copy; dented & bent back panel; yellowed panels; color = 117k; B/W = 290k
Sharp MX-3501N	179143	353	PS(MX-PKX1) PED(MX-DEX4)	Yellowed panels; color = 268k; B/W = 85k
Sharp MX-3501N	179144	389	PS(MX-PKX1) PED(MX-DEX4)	Off color panels; color = 325k; B/W = 65k
Sharp MX-3501N	179415	351	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1)	Error code L4-31 - paper exit fan problem - not tested, black meter = 314k, color meter = 37k
Sharp MX-3501N	182171	369	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1)	Black meter = 308k, color meter = 61k
Sharp MX-3501N	183548	464	PED(MX-DEX4) FN(MX-FNX2) FAX(MX-FXX1)	Black meter = 401k, color meter = 63k
Sharp MX-3501N	183620	388	ST() PS(MX-PKX1) FN(MX-FNX1)	Black meter = 262k, color meter = 127k
Sharp MX-3501N	183823	588	ST() PU(MX-PNX1B) PS(MX-PKX1) FN(MX-FNX1) FAX(MX-FXX1)	Black meter = 541k, color meter = 48k
Sharp MX-3501N	183824	285	ST() PS(MX-PKX1) FN(MX-FNX1) FAX(MX-FXX1)	Black meter = 283k, color meter = 3k
Sharp MX-3501N	185197	530	PED(MX-DEX4) FN(MX-FNX1)	Jamming in bypass - not tested, off color, back panel dented, black meter = 496k, color meter = 34k
Sharp MX-3501N	185640	488	ST() FN(MX-FNX1)	Color = 84k; B/W = 404k
Sharp MX-3501N	188276	347	PED(MX-DEX4) FN(MX-FNX1) FAX(MX-FXX1)	Black meter = 337k, color meter = 11k
Sharp MX-3501N	188372	221	ST() PS(MX-PKX1) FN(MX-FNX1) FAX(MX-FXX1)	Jamming in bypass - not tested, jamming in duplexer deflector - duplexer not tested, black meter = 172k, color meter = 50k
Sharp MX-3501N	191664	567	ST() PS(MX-PKX1) FN(MX-FNX1) FAX(MX-FXX1)	Black meter = 406k, color meter = 162k
Sharp MX-3501N	192290	247	PU(MX-PNX1B) PS(MX-PKX1) PED(MX-DEX4) P(MX-LCX1) FN(MX-FNX1) FAX(MX-FXX1)	Error code E7-03 - laser output error - not tested, LCT Front cover broken, yellow panels, black meter = 213k, color meter = 34k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp MX-4501N	173254	678	ST() FN(MX-FNX2)	Off color & dirty panels; color = 32k; B/W = 646k
Sharp MX-4501N	176974	353	PS(MX-PKX1) PED(MX-DEX4) PC(MX-PEX2) FN(MX-FNX1) FAX(MX-FXX1)	Fax cover panels dented, yellow panels. black meter = 276k; color meter = 77k
Sharp MX-4501N	179148	1085	PU(MX-PNX1B) PS(MX-PKX1) PED(MX-DEX4) P(MX-LCX1) FN(MX-FNX1)	Off color panels, black meter = 950k, color meter = 136k
Sharp MX-4501N	180649	497	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1) FAX(MX-FXX1)	Black meter = 434k, color meter = 63k, off color panels, bypass not recognizing paper - no tested
Sharp MX-4501N	181530	267	ST() PU(AR-PN1B) FN(MX-FNX2) FAX(MX-FXX1)	Error code F1-02 - finisher transport motor or mailbin stacker drive problem - machine unable to be tested, yellow panels
Sharp MX-4501N	184019	364	PED(MX-DEX3) FN(MX-FNX1) FAX(MX-FXX1)	Does not recognize stapler - not tested, Control panel and RADF yellow, black meter = 275k, color meter = 89k
Sharp MX-4501N	184628	609	PU(AR-PN1B) PED(MX-DEX3) FN(MX-FNX2) FAX(MX-FXX1)	Black meter = 350k, color meter = 259k
Sharp MX-4501N	184795	535	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1)	Clicking noise in fuser, black meter = 364k, color meter = 172k
Sharp MX-4501N	185757	691	PED(MX-DEX4) PC(MX-PEX2) FN(MX-FNX2)	Yellow panels, Black meter = 246k, color meter = 446k
Sharp MX-4501N	186551	809	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1)	Off color panels; color = 683k; B/W = 127k
Sharp MX-4501N	187465	389	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1)	Black meter = 242k, color meter = 148k
Sharp MX-4501N	187704	1841	PU(AR-PN1B) PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX2)	Error code E7-03 - hard-drive error, back panel dented, black meter = 1255k, color meter = 586k
Sharp MX-4501N	188448	378	PED(MX-DEX4) FN(MX-FNX1)	Black meter = 322k, color meter = 57k, access panel missing on back
Sharp MX-4501N	188603	448	PS(MX-PKX1) PED(MX-DEX4) FN(MX-FNX1) FAX(MX-FXX1)	Error code E7-03 (hard drive error); off color panels; color = 97k; B/W = 352k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp MX-4501N	189090	395	PU(AR-PN1B) PS(MX-PKX1) PED(MX-DEX4) P(MX-LCX1) FN(MX-FNX2) FAX(MX-FXX1)	Black meter = 250k, color meter = 146k
Sharp MX-4501N	189638	467	PU(AR-PN1B) P(MX-LCX1) FN(MX-FNX2) FAX(MX-FXX1)	Off color panels, toner spilled in cassette #2, black meter = 391k, color meter = 77k
Sharp MX-4501N	192328	316	PED(MX-DEX3) FN(MX-FNX1) FAX(MX-FXX1)	Black meter = 224k, color meter = 93k
Sharp MX-5500N	176289	1967	PS(MX-PKX1) FN(MX-FNX3) FAX(MX-FXX1)	Paper tray #2 in error code F3-22 (paper tray desk trouble); yellowed panels; color = 243k; B/W = 1725k
Sharp MX-5500N	180245	761	PU(MX-PNX2B) P(MX-LCX2) FN(MX-FNX3)	Yellowed panels Color = 220k; B/W = 542k
Sharp MX-5500N	180518	1234	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX4)	Off color and yellow, black meter = 1118k, color meter = 116k
Sharp MX-5500N	180519	366	PS(MX-PKX1) FN(MX-FNX3) FAX(MX-FXX1)	Off color panels, black meter = 336k, color meter = 31k
Sharp MX-5500N	182369	584	FN(MX-FNX3)	Yellow panels, black meter = 578k, color meter = 7k
Sharp MX-5500N	182857	261	FN(MX-FNX4) FAX(MX-FXX1)	Error code F1-08 - finisher stapler shift motor trouble - nto tested, wheel on finisher broken, fax panel dented, black meter = 212k, color meter = 49k
Sharp MX-5500N	183779	284	FN(MX-FNX3) FAX(MX-FXX1)	Error code E7-03 - hard-drive trouble - removed hard-drive, black meter = 218k, color meter = 67k
Sharp MX-5500N	185747	1098	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX3) FAX(MX-FXX1)	Fax cover panel dented, black meter = 1008k, color meter = 91k
Sharp MX-5500N	185762	580	PS(MX-PKX1) P(MX-LCX2) FN(MX-FNX4)	Stapler not jogging paper - not tested, black meter = 548k, color meter = 33k
Sharp MX-5500N	187879	694	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX4)	Error code F1-33 - finisher punch shift motor trouble - finisher not tested, black meter 398k, color meter = 296k
Sharp MX-5500N	187880	704	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX4) FAX(MX-FXX1)	Error code F1-33 - finisher punch shift motor problem - finisher not tested, black meter = 372k, color meter = 333k
Sharp MX-5500N	187881	600	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX4)	Finisher jams in stapler or punch unit - both not tested, black meter = 214k, color meter = 386k
Sharp MX-5500N	188522	851	PU(MX-PNX2B) PS(MX-PKX1) P(MX-LCX3)	Color = 134k; B/W = 718k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MX-FNX4)	
Sharp MX-5500N	191009	1491	P(MX-LCX3) FAX(MX-FXX1)	Missing finisher - has hardware, yellow panels, jamming out of bypass - not tested, fax top panel dented, right side panel has hole, black meter = 342k, color meter = 1149k
Sharp MX-5500N	192647	510	PU(MX-PNX2B) P(MX-LCX2) FN(MX-FNX3) FAX(MX-FXX1)	Black meter = 422k, color meter = 88k
Sharp MX-6200N	176971	1074	PS(MX-PKX1) FN(MX-FNX3)	Black meter = 884k; color meter = 190k
Sharp MX-6200N	176972	823	PS(MX-PKX1) FN(MX-FNX3)	Error code L4-30 - motor lock signal detected during rotation - not tested, back panel dented. yellow panels. black meter - 730k; color meter = 93k
Sharp MX-6200N	181804	395	PU(MX-PNX2B) FN(MX-FNX4) FAX(MX-FXX1)	Stapler not stapling, black meter = 285k, color meter = 110k
Sharp MX-6200N	184230	1495	PS(MX-PKX1) FN(MX-FNX3)	Yellow panels, F3-12 - Paper tray desk trouble, black meter = 749k, Color meter = 147k
Sharp MX-6200N	186857	703	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX4) FAX(MX-FXX1) FAX(MX-FWX1)	Off color, jamming at fuser, black meter = 382k, color meter = 321k
Sharp MX-6200N	188036	596	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX3)	Black meter = 557k, color meter = 39k, Has ACM MX-AMX2
Sharp MX-6201N	180653	525	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX3)	Black meter = 455k, color meter = 70k
Sharp MX-6201N	185501	959	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX4) FAX(MX-FXX1)	Black meter = 590k, color meter = 369k
Sharp MX-6201N	192659	330	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX3) FAX(MX-FXX1)	Black meter = 167k, color meter = 163k
Sharp MX-M350	182423	524	ST() PFU(AR-MU2) PC(MX-NBX3) DSPF(MX-EFX1)	
Sharp MX-M350	182424	425	ST() PFU(AR-MU2) PC(MX-NBX3) DSPF(MX-EFX1)	
Sharp MX-M350	184231	508	PED(AR-D27) PC(MX-NBX3) DX(AR-DU4) DSPF(MX-EFX1)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp MX-M350	185435	367	ST() SCAN(MX-NSX1) PFU(AR-MU2) PC(MX-NBX3) FN(AR-FN6) FAX(AR-FX12) DSPF(MX-EFX1)	Finisher tray broken
Oce IM3512	185891	90	ST() PED(AR-D28) PC(MX-NBX3) DX(AR-DU4)	Void streaks in copies
Sharp MX-M350	186082	469	PED(AR-D28) PC(MX-NBX3) FAX(AR-FX12) DX(AR-DU4) DSPF(MX-EFX1)	
Oce IM3512	187325	91	PS(AR-PK6) PED(AR-D27) PC(MX-NBX3) FN(AR-FN6) DX(AR-DU4)	
Oce IM3512	187698	177	PU(AR-PN1B) PED(AR-D28) PC(MX-NBX3) FN(AR-FN7) DX(AR-DU4)	
Sharp MX-M350	188356	135	PED(AR-D28) FN(AR-FN6) DX(AR-DU4) DSPF(MX-EFX1)	
Oce IM3512	189776	116	SCAN(MX-NSX1) PS(AR-PK6) PED(AR-D27) PC(MX-NBX3) FAX(AR-FX12) DX(AR-DU4)	Dirty panels
Oce IM3512	190441	N/A	PED(AR-D27) PC(MX-NBX3) FN(AR-FN6) FAX(AR-FX12)	No power to machine - not tested
Oce IM3512	191116	275	SCAN(MX-NSX1) PS(AR-PK6) PC(MX-NBX3) FAX(AR-FX12) DX(AR-DU4)	Squeaking noise in machine
Sharp MX-M350	192275	553	SCAN(MX-NSX1) PED(AR-D27) PC(MX-NBX3) FAX(AR-FX12) DX(AR-DU4) DSPF(MX-EFX1)	RADF exit tray missing
Oce IM3512	192552	236	SCAN(MX-NSX1) PU(AR-PN1B) PED(AR-D27) FN(AR-FN7) DX(AR-DU4)	Error code L4-02 - drum drive motor error - not tested
Sharp MX-M350	192641	339	SCAN(MX-NSX1) PED(AR-D27) FAX(AR-FX12) DX(AR-DU4) DSPF(MX-EFX1)	Jamming in DSPF - not tested
Sharp MX-M450	182860	368	PED(AR-D28) PC(MX-NBX3) FN(AR-FN6)	Very dirty, Deep scratches on RADF

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(AR-FX12) DX(AR-DU4) DSPF(MX-EFX1)	
Sharp MX-M450	186841	615	SCAN(MX-NSX1) PED(AR-D28) PC(MX-NBX3) FN(AR-FN6) DX(AR-DU4) DSPF(MX-EFX1)	
Sharp MX-M450	186845	384	SCAN(MX-NSX1) PED(AR-D27) PC(MX-NBX3) FN(AR-FN6) DX(AR-DU4) DSPF(MX-EFX1)	Finisher tray out of alignment - causing error code F1-15 - finisher lift motor problem - finisher not tested
Oce IM4512	187699	161	PU(AR-PN1B) PED(AR-D28) FN(AR-FN7) DX(AR-DU4)	
Sharp MX-M450	190197	930	SCAN(MX-NSX1) PS(AR-PK6) PED(AR-D27) PC(MX-NBX3) FN(AR-FN7) DX(AR-DU3) DSPF(MX-EFX1)	
Sharp MX-M450	190658	559	SCAN(MX-NSX1) PS(AR-PK6) PED(AR-D28) PC(MX-NBX3) FN(AR-FN6) FAX(MX-FWX1) DX(AR-DU4) DSPF(MX-EFX1)	
Sharp MX-M550	185437	753	SCAN(MX-NSX1) PC(MX-NBX1) FN(AR-F15) FAX(AR-FX8)	Finisher front door broken, top fax panel dented, RADF exit tray missing, Finisher entrance guide broken out of top access door - finisher not tested
Sharp MX-M550	185753	927	SCAN(MX-NSX1) PU(AR-PN4B) PS(MX-PKX1) PC(MX-NBX1) FN(AR-F15) FAX(AR-FX8)	Fax cover panel dented
Sharp MX-M550	190203	707	SCAN(MX-NSX1) PC(MX-NBX1) FN(AR-F15)	
Sharp MX-M550	190204	946	SCAN(MX-NSX1) PC(MX-NBX1) FN(AR-F15)	
Sharp MX-M550	190206	698	SCAN(MX-NSX1) PC(MX-NBX1) FN(AR-F15)	Yellow finisher panels
Sharp MX-M550	190227	1284	SCAN(MX-NSX1) PU(AR-PN4B) PS(MX-PKX1) PC(MX-NBX1) FN(AR-F15)	

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.