

Wulff Enterprises

02/10/2012

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO900	183110	862	FN(MJ-1026)	Jamming in duplexer
Toshiba E-STUDIO900	184999	712	PC(TYPE 2105)	Has SR880 finisher with interposer MJ-7002, finisher throat frame bent - finisher not tested, finisher trays missing, monitor mounting arm broken
Toshiba E-STUDIO900	192609	1353	PC(TYPE 2105) P(MP-4501L) FN(MJ-1026)	Lower finisher tray broken, finisher expansion cover missing, RADF exit tray broken, missing ecopy tower - has monitor and keyboard
Toshiba E-STUDIO4500	178841	436	PC(TYPE 3260)	Came in with wrong finisher, black meter = 277k, color meter = 160k
Toshiba E-STUDIO4500	180054	662	FN(SR970)	Has external HP PC with windows XP pro, black meter = 569k, color meter = 93k
Toshiba E-STUDIO4500	185025	305	PC(FIERY E-7000) FN(SR4000)	Front door broken, right side access door bent - does not latch, lower finisher tray support bent - not tested, black meter = 197k, color meter = 108k
Toshiba E-STUDIO4500	189561	222	PC(TYPE 3260) E()	Black meter = 64k, color meter = 158k
Toshiba E-STUDIO5500	180055	331		Has external HP PC with windows XP pro. occasional jamming at fuser, black meter = 265k, color meter = 66k
Toshiba E-STUDIO5500	190230	179	PC(FIERY E-7000)	Has SR 4010 finisher, toner spilled throughout machine, Missing PC crossover cable - PC not tested, Jamming in finisher throat - finisher not tested, black meter = 32k, color meter = 147k
Toshiba E-STUDIO162D	191206	N/A	RADF(MR-3017) FAX(GD-1190)	Will not come to ready - not tested
Toshiba E-STUDIO162D	191207	N/A	RADF(MR-3017) FAX(GD-1190)	Blank display - not tested
Xerox 416	191654	179	RADF(MR-3011) PFU(MY-1015) E(MJ-5001) DX(MD-0101)	Dirty and off color panels
Toshiba E-STUDIO167	185082	98	ST() ADF(MR-2017)	
Toshiba E-STUDIO202L	180934	206	ST() RADF(MR-3020) FAX(GD-1150) E(MJ-5004) DX(MD-0102)	Will not come to ready - not tested
Toshiba E-STUDIO202L	181024	208	ST()	Right side access door broken - not tested, front corner panel broken, very dirty

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO202L	181033	N/A	ST()	Control panel not powering up - not tested, very dirty panels, Hard-drive removed
Toshiba E-STUDIO202L	181814	240	ST()	Off color and dirty panels
Toshiba E-STUDIO202L	183338	78	ST() RADF(MR-3020) PC(GM-2080)	
Toshiba E-STUDIO202L	183661	N/A	RADF(MR-3020) PFU(MY-1021) PED(KD-1011 [A]) FN(MJ-1022) DX(MD-0102)	Control panel buttons not working - not tested, hard-drive removed, control panel cracked
Toshiba E-STUDIO202L	184052	138	ST() RADF(MR-3020) PFU(MY-1021) PC(GM-2080) FAX(GD-1150)	
Toshiba E-STUDIO202L	184056	120	RADF(MR-3020) PED(KD-1011 [A]) PC(GM-2080) FN(MJ-1022) FAX(GD-1150) DX(MD-0102)	Very dirty
Toshiba E-STUDIO202L	184500	84	ST() RADF(MR-3020) PC(GM-2080) FAX(GD-1150) E(MJ-5004)	
Toshiba E-STUDIO202L	186558	158	ST() RADF(MR-3020) FN(MJ-1022) DX(MD-0102)	Finisher jams frequently
Toshiba E-STUDIO202L	187328	146	ST() RADF(MR-3020) PFU(MY-1021) PC(GM-2080) FAX(GD-1150) E(MJ-5004)	
Toshiba E-STUDIO202L	187678	244	ST() RADF(MR-3020) FAX(GD-1150) E(MJ-5004) DX(MD-0102)	
Toshiba E-STUDIO202L	187896	218	ST() RADF(MR-3020) PC(GM-2080) FAX(GD-1150) E(MJ-5004)	Toner all over copies - not fused
Toshiba E-STUDIO202L	188521	N/A	ST() RADF(MR-3020) PC(GM-2080) FAX(GD-1150)	Hard drive mount failed- can't test; removed hard drive
Toshiba E-STUDIO202L	188871	100	ST() RADF(MR-3020) FAX(GD-1150)	Broken panels all over
Toshiba E-STUDIO202L	188872	281	ST() RADF(MR-3020) PC(GM-1080) DX(MD-0102)	Broken bypass table
Toshiba E-STUDIO202L	188873	257	ST() RADF(MR-3020) FAX(GD-1150)	
Toshiba E-STUDIO202L	188874	N/A	ST() RADF(MR-3020) PC(GM-1080) FAX(GD-1150) DX(MD-0102)	Hard drive was scrubbed- cannot test machine (machine will not come to ready)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO202L	188875	210	ST() RADF(MR-3020) PC(GM-1080) FAX(GD-1150) DX(MD-0102)	
Toshiba E-STUDIO202L	188877	N/A	ST() RADF(MR-3020) FAX(GD-1150) DX(MD-0102)	Hard drive was scrubbed- cannot test machine (machine will not come to ready); scratched LCD
Toshiba E-STUDIO202L	190725	149	ST() RADF(MR-3020) DX(MD-0102)	Void lines on copies
Toshiba E-STUDIO202L	192282	263	ST() RADF(MR-3020) DX(MD-0102)	
Toshiba E-STUDIO202L	192284	54	ST() RADF(MR-3020) DX(MD-0102)	
Toshiba E-STUDIO202L	192640	180	ST() RADF(MR-3020) FAX(GD-1150) DX(MD-0102)	
Toshiba E-STUDIO203L	176770	N/A	ST()	Touch screen shattered - not tested, hard-drive removed, transfer door bent, fuser frame assembly bent
Toshiba E-STUDIO203L	178750	126	ST()	Back panel cracked, side panel bent
Toshiba E-STUDIO203L	179295	94	ST()	Off color panels
Toshiba E-STUDIO203L	181022	161	ST()	Front door interlock switch missing - not tested, very dirty panels
Toshiba E-STUDIO203L	181023	217	ST()	Front door interlock switch missing - not tested
Toshiba E-STUDIO203L	181025	N/A	ST()	Control panel smashed - not tested, back panel broken, very dirty, panel below bypass tray broken, Hard-drive removed
Toshiba E-STUDIO203L	181026	128	ST()	Right side access door broken - not tested, very dirty panels
Toshiba E-STUDIO203L	181027	128	ST()	Jamming at fuser - not tested, bypass tray paper guide broken, very dirty panels
Toshiba E-STUDIO203L	181028	103	ST()	Smashed LCD- can't test; removed hard drive; hole in back panel; broken right side panel; broken panel under paper tray' permanent marker on platen top
Toshiba E-STUDIO203L	181029	179	ST()	Broken back panel; permanent marker on platen top
Toshiba E-STUDIO203L	181030	260	ST()	Jams and goes into error code C430 (fuser temp) dented upper back screwholes broken; left rear panel crushed, right side knockout bent in
Toshiba E-STUDIO203L	181031	93	ST()	Very dirty, jamming in fuser, pre-lamp charge broken

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO203L	181032	198	ST()	Right side paper access door broken - not tested, right side panel below bypass broken, very dirty panels
Toshiba E-STUDIO203L	192682	54	ST() RADF(MR-3020) FAX(GD-1150) DX(MD-0102)	
Toshiba E-STUDIO207	176914	8	ST() RADF(MR-3019)	
Toshiba E-STUDIO207	190434	21	PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO2100	192612	145	RADF(MR-3006A) PC(GA-1121) DX(MD-5007)	Missing finisher - has hardware, jamming in RADF - not tested, black meter = 69k, color meter = 77k
Toshiba E-STUDIO230	187893	422	ST() SCAN(GM-3020) RADF(MR-3016) PC(GM-1020) FN(MJ-1022) FAX(GD-1150)	Jamming in the duplexer, off color panels
Oce IM2330	181596	17	ST() RADF(9255)	
Toshiba E-STUDIO232	181714	N/A	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	Will not come to ready - not tested, hard-drive removed
Toshiba E-STUDIO232	183178	145	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022)	Missing enabler cover
Oce IM2330	184991	169	RADF(9255)	Right side panel broken
Toshiba E-STUDIO232	185070	310	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022)	Missing fax board - has installation sticker
Toshiba E-STUDIO232	185076	217	RADF(MR-3020) PED(KD-1011 [A]) PC(GM-2070) FAX(GD-1150)	Right side corner broken
Toshiba E-STUDIO232	185077	167	RADF(MR-3020) PED(KD-1011 [A]) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	185078	130	RADF(MR-3020) PED(KD-1011 [A]) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	186415	149	ST() RADF(MR-3020)	Back panel broken
Toshiba E-STUDIO232	186595	29	ST() RADF(MR-3020)	Touch screen not responding -not tested, hard-drive removed
Toshiba E-STUDIO232	186711	514	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	187674	173	RADF(MR-3020) PED(KD-1012) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	Error code CC90 - top tray lift motor - finisher not tested, lower finisher tray cover panel missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Oce IM2330	188790	209	ST() RADF(9255)	
Toshiba E-STUDIO232	189091	110	ST() RADF(MR-3020)	
Toshiba E-STUDIO232	189557	163	RADF(MR-3020) PED(KD-1011 [B]) PC(GM-2070) FN(MJ-1022)	RADF jams when duplexing
Toshiba E-STUDIO232	190726	393	RADF(MR-3020) PED(KD-1012) PC(GM-2070) FAX(GD-1150)	Jamming at fuser, jamming out of LCT, void lines through copies
Oce IM2330	192554	212	ST() RADF(9255)	Wrong finisher with machine, cassette #2 not lifting - not tested, back panel cracked
Toshiba E-STUDIO232	192618	181	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022)	
Toshiba E-STUDIO232	192648	67	ST() RADF(MR-3020)	RADF jams- inop
Toshiba E-STUDIO233	176916	47	ST() RADF(MR-3020) FN(MJ-1022)	
Toshiba E-STUDIO233	177066	75	ST() RADF(MR-3020) E(MJ-5004)	
Toshiba E-STUDIO233	182845	40	ST() RADF(MR-3020)	
Toshiba E-STUDIO233	184063	89	ST() RADF(MR-3020)	
Toshiba E-STUDIO233	186603	190	RADF(MR-3020) PED(KD-1011 [A])	
Toshiba E-STUDIO233	187329	163	ST() RADF(MR-3020) FN(MJ-1022) FAX(GD-1150)	Front door scratched
Toshiba E-STUDIO233	189088	279	ST() RADF(MR-3020) PC(GM-2071)	
Toshiba E-STUDIO233	190727	42	ST() RADF(MR-3020) FN(MJ-1022)	Front door interlock switch broken - not tested
Toshiba E-STUDIO233	190801	514	ST() RADF(MR-3020) FAX(GD-1150)	
Toshiba E-STUDIO2330	190797	33	ST() RADF(MR-3018) FN(MJ-1031)	Black meter= 26k, color meter = 8k
Toshiba E-STUDIO2330	190798	N/A	ST() RADF(MR-3018) FN(MJ-1031) FAX(GD-1250)	Hard-drive mount fail - not tested
Toshiba E-STUDIO2500	181816	269	RADF(MR-3018) PED(KD-1018 [A]) FN(MJ-1030) FAX(GD-1210)	Black meter = 276k, color meter = 44k
Toshiba E-STUDIO2500	187587	292	RADF(MR-3018) PED(KD-1018 [B])	Front door interlock broken, black meter = 270k, color meter = 22k
Toshiba E-STUDIO2500	191848	400	RADF(MR-3018) PED(KD-1018 [A])	Jamming in cassette #3 - not tested, void lines on copies, black meter =

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1101)	210k, color meter = 191k
Toshiba E-STUDIO2500	191985	625 ST()	RADF(MR-3018)	Void streaks on color copies, shading on black copies, black meter = 538k, color meter = 87k
Toshiba E-STUDIO2500	191998	341	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Error code CE40 - test pattern problem - not tested, front door interlock broken, finisher front door interlock broken, black meter = 183k, colorm etr = 159k
Toshiba E-STUDIO2500	192655	465	RADF(MR-3018) PU(MJ-6101) FN(MJ-1101) FAX(GD-1210)	Jamming in finisher - not tested, black meter = 194k, color meter = 211k
Toshiba E-STUDIO280	185524	242 ST()	RADF(MR-3016) FN(MJ-1022)	Error code CC90 - finisher upper stack tray lift motor - finisher not tested, finisher latch broken
Toshiba E-STUDIO280	191649	578	RADF(MR-3016) PED(KD-1012) FAX(GD-1150)	Missing enabler -has cover, jamming in RADF - not tested, error code c440 - fuser problem after warmup - not fully tested
Toshiba E-STUDIO281C	186574	343	RADF(MR-3018) PED(KD-1011 [B]) FN(MJ-1022) FAX(GD-1200)	Black meter = 237k, color meter = 106k, finisher top tray out of alignment, error code CC90 - finisher upper lift tray motor - finisher not tested
Toshiba E-STUDIO281C	186588	324 ST()	RADF(MR-3018)	Black meter = 322k, color meter = 2k
Toshiba E-STUDIO281C	186589	247 ST()	RADF(MR-3018)	Black meter = 249k, color meter = 9k, front door scratched, left side of display is bad blurred together
Toshiba E-STUDIO281C	186591	68 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Black meter = 39k, color meter = 29k, void lines through copies
Toshiba E-STUDIO281C	186592	397 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Black meter = 288k, color meter = 110k, Finisher top panel scratched, void lines in copies
Toshiba E-STUDIO281C	187172	133 ST()	RADF(MR-3018) FN(MJ-1022)	Error code CC80 - front aligning plate motor abnormality - finisher not tested, off color, black meter - 132k, color meter - 2k
Toshiba E-STUDIO281C	188524	368 ST()	RADF(MR-3018)	Color = 121k; B/W = 247k
Toshiba E-STUDIO281C	189149	377	RADF(MR-3018) PED(KD-1011 [A]) FAX(GD-1200)	Black meter = 282k, color meter = 95k
Toshiba E-STUDIO281C	189555	287	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Off color panels, black meter = 370k, color meter = 17k
Toshiba E-STUDIO281C	190724	193	RADF(MR-3018) PED(KD-1011 [B]) FAX(GD-1200)	Black meter = 183k, color meter = 11k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO281C	190731	479 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Black meter = 465k, color meter = 14k
Toshiba E-STUDIO281C	191232	342 RADF(MR-3018)	PED(KD-1012) FN(MJ-1022)	Black meter = 328k, color meter = 15k
Toshiba E-STUDIO281C	191657	195 ST()	RADF(MR-3018) FN(MJ-1022)	Black meter = 181k, color meter = 14k
Toshiba E-STUDIO281C	191987	84 ST()	RADF(MR-3018)	Black meter = 74k, color meter = 10k
Toshiba E-STUDIO282	181829	277 RADF(MR-3020)	PED(KD-1011 [A]) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO282	186604	269 ST()	RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Oce IM2830	186833	71 RADF(9255)	PED(9283) PC(IM2300060) FN(9284) FAX(CM4530110)	Hard drive removed after testing
Oce IM2830	187115	83 ST()	RADF(9255) PC(IM2300060) FAX(CM4530110)	
Toshiba E-STUDIO282	187691	240 ST()	RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Oce IM2830	187700	249 RADF(9255)	PU(IM2300020) PED(9283) PC(IM2300060) FN(9256) FAX(CM4530110)	Error code CC50 - finisher horizontal registration motor - finisher not tested
Toshiba E-STUDIO282	187716	246 ST()	RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Oce IM2830	187718	154 ST()	RADF(9255) PU(IM2300020) PC(IM2300060) FN(9256) FAX(CM4530110)	
Oce IM2830	188532	948 ST()	RADF(9255) PC(IM2300060) FN(9284) FAX(CM4530110)	
Toshiba E-STUDIO282	189157	293 ST()	RADF(MR-3020)	
Toshiba E-STUDIO282	190354	780 ST()	RADF(MR-3020) PC(GM-2070) FN(MJ-1022)	
Oce IM2830	190633	158 ST()	PC(IM2300050) FAX(CM4530110)	
Oce IM2830	191055	106 ST()	RADF(9255) FAX(CM4530110)	
Toshiba E-STUDIO283	178168	201 ST()	RADF(MR-3020)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(GD-1150) E(MJ-5004)	
Toshiba E-STUDIO283	182844	163	ST() RADF(MR-3020) PC(GM-2071) FN(MJ-1022) FAX(GD-1160)	
Toshiba E-STUDIO283	182847	183	ST() PC(GM-2071) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO283	184057	127	ST() RADF(MR-3020) FAX(GD-1150)	Cassette #2 front panel cracked
Toshiba E-STUDIO283	191228	47	ST() RADF(MR-3020) FAX(GD-1150)	
Toshiba E-STUDIO2830	180623	615	RADF(MR-3018) PU(MJ-6101) PED(KD-1024) FN(MJ-1101)	Jamming in stapler - stapler not tested, black meter = 582k, color meter = 33k
Toshiba E-STUDIO2830	188119	188	ST() RADF(MR-3018)	Black meter = 114k, color meter = 74k
Toshiba E-STUDIO2830	190802	262	RADF(MR-3018) PU(MJ-6004) PED(KD-1024) FN(MJ-1030)	Black meter = 199k, color meter = 63k
Toshiba E-STUDIO2830	191942	111	ST() RADF(MR-3018)	Black meter = 90k, color meter = 21k
Toshiba E-STUDIO2830	191943	332	ST() RADF(MR-3018)	Black meter = 180k, color meter = 153k
Toshiba E-STUDIO2830	191945	167	ST() RADF(MR-3018)	Black meter = 141k, color meter = 27k
Toshiba E-STUDIO305	189001	422	RADF(MR-3021) PED(KD-1026) FN(MJ-1031) FAX(GD-1250)	RADF latch broken
Toshiba E-STUDIO3500	188346	232	ST() RADF(MR-3018) FN(MJ-1030)	Stapler jogger not jogging paper correctly, off color panels, Color meter 41k, Blk meter 192K
Toshiba E-STUDIO3500	189584	401	RADF(MR-3018) PED(KD-1019) FN(MJ-1030)	Color = 175k; B/W = 226k
Toshiba E-STUDIO3500	190675	360	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Dark streak on color copies. black meter = 298k, color meter = 63k
Toshiba E-STUDIO3500	191732	822	RADF(MR-3018) PU(MJ-6004) PED(KD-1019) FN(MJ-1030)	Finisher wires broken - finisher not tested, black meter = 696k, color meter = 127k
Toshiba E-STUDIO3510	189558	244	RADF(MR-3018) PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	Black meter = 202k, color meter = 42k
Toshiba E-STUDIO3510	190733	498	RADF(MR-3018) PED(KD-1019)	Cassettes 1,2 not lifting paper - not tested, jamming in RADF, jamming in

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1030) FAX(GD-1210)	stapler - not tested, black meter = 433k, color meter = 65k
Toshiba E-STUDIO3511	185934	218	RADF(MR-3015) PED(KD-1011 [B]) FAX(GD-1150)	Black meter = 188k, color meter = 30k, off color panels, fan vent cover bent
Toshiba E-STUDIO3511	188409	906	RADF(MR-3015) PED(KD-1012) FN(MJ-1024)	Black meter = 739k, color meter = 168k, RADF feed tray broken
Toshiba E-STUDIO351C	178633	N/A	RADF(MR-3018) PED(KD-1012) FAX(GD-1200)	Hard-drive missing - unable to test
Toshiba E-STUDIO351C	184779	840	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Black meter = 809k, color meter = 32k
Toshiba E-STUDIO351C	186601	192	RADF(MR-3018) PU(MJ-6101) PED(KD-1011 [B]) FN(MJ-1101)	Error code CEB0 (black developer lift problem)
Toshiba E-STUDIO351C	186713	N/A	ST() RADF(MR-3018) FN(MJ-1022)	Error code CEAO- revolver home problme - not tested, power switch cover broken, control panel housing broken, right side panel broken. back panle broken, left side panel broken
Toshiba E-STUDIO351C	189099	292	RADF(MR-3018) PED(KD-1012) FN(MJ-1024)	Back panel cracked, black meter = 383k, color meter = 9k
Toshiba E-STUDIO351C	190728	337	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101)	Finisher frame bent below finisher entrance guide, black meter = 325k, color meter = 13k
Toshiba E-STUDIO351C	191748	174	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101)	Ped not recognizing paper - not tested, black meter = 161k, color meter = 14k
Toshiba E-STUDIO352	185001	169	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022)	
Toshiba E-STUDIO352	186596	152	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1022)	
Toshiba E-STUDIO352	187035	841	ST() RADF(MR-3018) PC(GM-1060)	Fuser cover broken, developer spilled in cassettes, off color
Toshiba E-STUDIO352	192280	304	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FAX(GD-1200)	
Toshiba E-STUDIO352	192610	442	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1101) FAX(GD-1200)	Jamming in duplexer - not tested, jamming out of LCT - not tested, left side panel broken

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO352	192611	527	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1101) FAX(GD-1200)	Not stapling
Toshiba E-STUDIO352	192644	499	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101)	Deep scratch on touch screen
Toshiba E-STUDIO352	192653	926	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	
Toshiba E-STUDIO353	171728	668	ST() RADF(MR-3018) FN(MJ-1022)	Missing enabler - has cover
Toshiba E-STUDIO353	171729	485	ST() RADF(MR-3018) FN(MJ-1022)	Missing enabler - has cover
Toshiba E-STUDIO353	171924	287	ST() RADF(MR-3018) FN(MJ-1022)	
Toshiba E-STUDIO353	174149	136	RADF(MR-3018) PED(KD-1011 [A])	
Toshiba E-STUDIO353	182848	329	ST() RADF(MR-3018) PU(MJ-6101) PC(GM-2061) FN(MJ-1101)	Error code CB31 - finisher lift motor - finisher not tested
Toshiba E-STUDIO353	183626	42	ST() RADF(MR-3018)	
Toshiba E-STUDIO353	183644	54	ST() RADF(MR-3018) FN(MJ-1022)	
Toshiba E-STUDIO353	185019	26	ST() RADF(MR-3018) FAX(GD-1200)	
Toshiba E-STUDIO353	186834	84	RADF(MR-3018) PED(KD-1012)	Came in with wrong finisher
Toshiba E-STUDIO353	187330	N/A	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Missing hard-drive - not tested
Toshiba E-STUDIO353	187331	225	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Jamming at finisher entrance - finisher not tested
Toshiba E-STUDIO353	187477	181	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	
Toshiba E-STUDIO353	187899	141	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	
Toshiba E-STUDIO353	189554	237	RADF(MR-3018) PED(KD-1011 [A]) PC(GM-2061) FN(MJ-1022)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(GD-1200)	
Toshiba E-STUDIO3530	187912	397 ST()	RADF(MR-3018) FN(MJ-1101)	Front door yellow, Off color panels black meter = 243k, color meter = 155k
Toshiba E-STUDIO3530	191915	521	RADF(MR-3018) PED(KD-1024)	Missing finisher - has hardware, black meter = 209k, color meter = 312k, right back panel scratched
Toshiba E-STUDIO4511	184499	772 ST()	RADF(MR-3015) PU(MJ-6004) FN(MJ-1023) FAX(GD-1150)	Error code F105 (hard drive error); color = 114k; B/W = 659k
Toshiba E-STUDIO451C	187897	329	RADF(MR-3018) PED(KD-1012) FN(MJ-1023) FAX(GD-1200)	Error code C360 - corona wire cleaner motor - not tested, fuser is disconnected, needs waste toner bottle, left side panel cracked
Toshiba E-STUDIO451C	192183	138	RADF(MR-3018) PU(MJ-6004) PED(KD-1012) FN(MJ-1023)	Black meter = 108k, color meter = 29k
Toshiba E-STUDIO452	184062	173 ST()	RADF(MR-3018) FN(MJ-1024)	
Toshiba E-STUDIO452	187307	450	RADF(MR-3018) PED(KD-1011 [A]) FN(MJ-1024) FAX(GD-1200)	
Toshiba E-STUDIO452	187656	287	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO452	187876	576	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	
Oce IM4530	191117	1022	RADF(MR-3018) PED(KD-1012) PC(GM-1060) FN(MJ-1024) FAX(GD-1200)	
Toshiba E-STUDIO452	191230	272	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101)	
Oce IM4530	192555	364 ST()	SCAN(GM-4060) RADF(MR-3018) PU(MJ-6004) FN(MJ-1024)	
Oce IM4530	192556	155	RADF(MR-3018) PU(MJ-6004) FN(MJ-1024)	Waste toner interlock broken
Oce IM4530	192557	253 ST()	RADF(MR-3018) PU(MJ-6004) FN(MJ-1024)	Missing bridge unit - finisher not tested
Toshiba E-STUDIO452	192645	683	RADF(MR-3018) PU(MJ-6101) PED(KD-1012)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1101)	
Toshiba E-STUDIO452	192646	946	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101)	
Toshiba E-STUDIO4520	189092	494	RADF(MR-3018) PU(MJ-6004) PED(KD-1024) FN(MJ-1030)	Broken bridge unit latch; off color panels; color = 244k; B/W = 250k
Toshiba E-STUDIO453	172096	666	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	
Toshiba E-STUDIO453	172499	585	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	
Toshiba E-STUDIO453	177386	812	RADF(MR-3018) PED(KD-1012) PC(GM-1061)	Error code C580- communication problem between IPC and finisher , came in with wrong finisher
Toshiba E-STUDIO453	179260	609	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	Error code F103 - hard-drive time out - not fully tested
Toshiba E-STUDIO453	181357	693	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO453	182409	171	ST() RADF(MR-3018)	Stand front panel dented
Toshiba E-STUDIO453	183786	604	ST() RADF(MR-3018) FN(MJ-1101)	Could not print NIC page
Toshiba E-STUDIO453	183787	902	ST() RADF(MR-3018) FN(MJ-1101)	Error code C580 - communication problem between IPC and finisher - finisher not tested
Toshiba E-STUDIO453	184768	914	SCAN(GM-4060) RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	
Toshiba E-STUDIO453	185929	708	ST() RADF(MR-3018) PC(GM-2061)	
Toshiba E-STUDIO453	186443	455	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1024)	
Toshiba E-STUDIO453	188135	44	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO453	188377	408	ST() RADF(MR-3018) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Enabler cover broken
Toshiba E-STUDIO455	183781	193	RADF(MR-3022) PED(KD-1026)	Back panel dented; passes blanks

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1031)	
Toshiba E-STUDIO520	185072	750	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO520	185074	996	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	Jamming in finisher - not tested
Oce IM5530	185763	532	FN(MJ-1027) FAX(GD-1170)	Blurry copies
Toshiba E-STUDIO520	187884	837	PC(GM-2040) FN(MJ-1027)	Cassette #4 will not lift paper- inop
Toshiba E-STUDIO520	188347	208	FN(MJ-1027)	Error code CB30 - finisher tray lift motor - finisher not tested, blurry and dark copies
Toshiba E-STUDIO520	188995	187	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	
Oce IM5530	188999	584	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	Jams every copy
Toshiba E-STUDIO520	192570	1163	FN(MJ-1027)	
Toshiba E-STUDIO520	192571	1099	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO523	183294	106	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Glass broken
Toshiba E-STUDIO523	183300	232	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	RADF yellow, finisher yellow
Toshiba E-STUDIO523	183312	422	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Finisher panels yellow
Toshiba E-STUDIO523	183316	281	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Error code CA10 - laser motor polygon motor - not tested
Toshiba E-STUDIO523	183318	387	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Error code CB10 - finisher feed motor - not tested
Toshiba E-STUDIO523	183319	824	PU(MJ-6003) FN(MJ-1027)	Finisher top access door broken, back panel dented, Missing LCT has brackets installed
Toshiba E-STUDIO523	183354	401	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	LCT cables broken - not tested
Toshiba E-STUDIO523	183356	884	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO523	183357	1106	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO523	183358	481	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO523	183361	499	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO523	183364	517	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO523T	181349	1176	PU(MJ-6003) PC(GM-2041) FN(MJ-1027)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Oce IM6030	186317	518	PU(MJ-6003N) PC(GM-1050) FN(MJ-1027)	touch screen not responding - not fully tested, crack through touch screen
Oce IM6030	186339	147	PU(MJ-6003N) FN(MJ-1027) FAX(GD-1170)	Missing enabler - has cover, void lines in copies
Toshiba E-STUDIO600	186556	508	PU(MJ-6003N) PC(GM-1050) P(MP-4004) INSU(MJ-7001) FN(MJ-1027)	Finisher shows "close inserter cover" & will not clear- inop; bent finisher actuator plate; broken inserter top & lower right covers; broken left side corner panel
Toshiba E-STUDIO600	186557	518	PU(MJ-6003N) PC(GM-1050) P(MP-4004) INSU(MJ-7001) FN(MJ-1028)	LCT will not lift- inop; broken rear inserter tray hinge
Toshiba E-STUDIO600	187898	549	FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO600	188166	97	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO600	188413	451	PC(GM-2040) P(MP-4004) FN(MJ-1027)	Error code F100 - hard-drive failure, removed hard-drive, back panel dented
Toshiba E-STUDIO600	188894	484	PU(MJ-6003N) FN(MJ-1027)	Finisher frame bent causing it to jam every try- inop; unable to generate a NIC report
Toshiba E-STUDIO600	189093	460	FN(MJ-1027)	
Toshiba E-STUDIO600	189150	1031	PC(GM-2040) FN(MJ-1027)	Error code C-260 - exposure lamp not detected - not tested, off color panels
Toshiba E-STUDIO600	190057	843	PC(GM-2040) FN(MJ-1027)	
Oce IM6030	192569	428	PU(MJ-6003N) PC(GM-2040) P(MP-4004) INSU(MJ-7001) FN(MJ-1027)	Black lines on LCD screen, jamming in finisher - not tested
Toshiba E-STUDIO600T	186598	517	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO603	180965	569		Missing finisher
Toshiba E-STUDIO603	182383	678	FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO603	185081	823	FN(MJ-1028) FAX(GD-1170)	
Toshiba E-STUDIO603	187332	359	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603	187677	110	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Paper deck door badly scratched
Toshiba E-STUDIO603	189411	648	FN(MJ-1027)	
Toshiba E-STUDIO603	191916	778	PU(MJ-6003) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO603T	183298	228	PU(MJ-6003) FN(MJ-1027)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO723	180952	1572	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027)	Needs new web unit - not tested
Toshiba E-STUDIO723T	183293	446	PU(MJ-6003) FN(MJ-1027)	
Toshiba E-STUDIO723T	183306	1409	FN(MJ-1027)	Does not recognize proper LCT installed
Toshiba E-STUDIO723T	183308	1775	PU(MJ-6003) FN(MJ-1027)	Punch unit front panel missing
Toshiba E-STUDIO723T	183310	1263	PU(MJ-6003) FN(MJ-1027)	Not recognizing toner, finisher top access panel broken, jamming at finisher - not tested
Toshiba E-STUDIO723T	183317	316	PU(MJ-6003) FN(MJ-1027)	Would not staple - not tested
Toshiba E-STUDIO723T	183351	186	PU(MJ-6003) FN(MJ-1027)	
Toshiba E-STUDIO723T	183355	295	PU(MJ-6003) FN(MJ-1027)	LCT not lifting paper - not tested, back panel dented
Toshiba E-STUDIO850	182281	170	PU(MJ-6003N) PC(GM-2040) P(MP-4004) FN(MJ-1027)	Touch screen not responding - not tested, error code CD10 - cleaning brush problem, has mouse droppings all throughout machine and urine, very poor condition
Toshiba E-STUDIO850	188275	723	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	Does not recognize toner - says toner low, blank copies
Toshiba E-STUDIO853	183296	1794	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Front door interlock switch broken, Jamming out of LCT - nto tested, jamming in duplexer
Toshiba E-STUDIO853	183299	2126	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Finisher panels yellow
Toshiba E-STUDIO853	183301	2138	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Error code C-471 - IH power voltage (power supply) - not fully tested, finisher top access door broken
Toshiba E-STUDIO853	183303	2684	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Error code C471 - IH power voltage (power supply) - not fully tested
Toshiba E-STUDIO853	183304	1508	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.