

Wulff Enterprises

02/10/2012

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO4500	181675	244	PC(FIERY E-7000) FN(SR841)	Error code SC723 - finisher feed out error -stapler not tested, stacker feed out belt broken, has GBS stream punch III, has punch assembly, black meter = 52k, color meter = 193k
Toshiba E-STUDIO4500	181676	805	PC(FIERY E-7000) P(RT43) FN(SR4000)	Bottom finisher tray yellow. black meter = 587k, color meter = 218l
Toshiba E-STUDIO4500	182495	508	PC(FIERY E-7000) P(RT43) FN(SR4000)	Color = 473k; B/W = 36k
Toshiba E-STUDIO4500	188272	1114	PU(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	Jamming at finisher exit rollers - finisher not tested, knockout missing at right side access door interlock switch, black meter = 973k, color meter = 142k
Toshiba E-STUDIO4500	191235	448	PC(TYPE 3260) FN(SR970)	Black meter = 330k, color meter = 119k
Toshiba E-STUDIO4500	191690	1425	PC(TYPE 3260) FN(SR4000)	Finisher exit tray yellow, black meter = 790k, color meter = 636k
Toshiba E-STUDIO5500	178317	963	PS(TYPE 3260) PC(TYPE 3260) P(RT43)	Has SR842 finisher, black meter = 770k, color meter = 194k
Toshiba E-STUDIO5500	191820	423	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Toner spilled inside machine, black meter = 157k, color meter = 267k
Toshiba E-STUDIO901	191689	4123	PU(PU5000) PC(TYPE 1350) P(RT5000) FN(SR5000)	Has stream punch III GBC
Toshiba E-STUDIO150	180651	73		Very yellow, dirty
Xerox 416	170816	61	RADF(MR-3011) PED(KD-1009 [A]) PC(GA-1031) NIC(GF-1110) E(MJ-5001) DX(MD-0101) B(MY-1016)	Platen glass & slit glass smashed; line in copies due to no glass
Toshiba E-STUDIO165	183044	259	ST() RADF(MR-3019) PFU(MY-1027) PC(GA-1190) FAX(GD-1220) DX(MD-0103)	
Toshiba E-STUDIO165	186087	115	ST() SCAN(GA-1200) PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	Broken right guide rail in paper tray
Toshiba E-STUDIO165	186089	54	ST() SCAN(GA-1200) PC(GA-1190) FAX(GD-1220)	Chipped ADF slit glass; unable to access print or scan modes

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			ADF(MR-2017)	
Toshiba E-STUDIO165	186091	99 ST()	SCAN(GA-1200) PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	Shows initializing network when trying to print reports
Toshiba E-STUDIO165	189026	172 ST()	SCAN(GA-1200) RADF(MR-3019) PFU(MY-1027) PC(GA-1190) FAX(GD-1220) DX(MD-0103)	
Toshiba E-STUDIO165	190008	37	PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO165	190009	N/A	PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	Does not come to ready - not tested
Toshiba E-STUDIO165	190029	40	PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO165	190030	39	PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO167	185826	14 ST()	FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO167	186092	32 ST()	SCAN(GA-1200) PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO167	186214	17	SCAN(GA-1200) PC(GA-1190) ADF(MR-2017)	Dirty inside and out
Toshiba E-STUDIO167	186469	87 ST()	RADF(MR-3019) PFU(MY-1027) PC(GA-1190) FAX(GD-1220) DX(MD-0103)	
Toshiba E-STUDIO167	191908	46 ST()	PFU(MY-1027) ADF(MR-2017)	
Toshiba E-STUDIO167	192480	120	SCAN(GA-1200) RADF(MR-3019) PC(GA-1190) DX(MD-0103)	
Toshiba E-STUDIO203L	168815	148 ST()		Top inside panel smashed; right side panel cracked; error code C260 - peak detection error; scan bulb not turning on
Toshiba E-STUDIO203L	172617	300 ST()		Front cover broken; duplexer frame bent; right side cover won't latch - not tested; back corner panel cracked; yellow

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO203L	191168	747	RADF(MR-3020) PU(MJ-6005) PFU(MY-1021) PED(KD-1011 [B]) PC(GM-2081) FN(MJ-1025) FAX(GD-1150) DX(MD-0102)	Jamming in machine & RADF occasionally
Toshiba E-STUDIO205	179380	162	RADF(MR-3019) PFU(MY-1027) FAX(GD-1220) DX(MD-0103)	Fax button pushed down in machine, slit glass chipped, False jam in RADF - not tested
Toshiba E-STUDIO205	187297	80	ST() RADF(MR-3019) PFU(MY-1027) DX(MD-0103)	
Toshiba E-STUDIO205	187298	157	ST() RADF(MR-3019) PFU(MY-1027) DX(MD-0103)	Right corner chipped
Toshiba E-STUDIO205	187299	196	ST() RADF(MR-3019) PFU(MY-1027) DX(MD-0103)	Slit glass chipped
Toshiba E-STUDIO205	187300	124	ST() RADF(MR-3019) PFU(MY-1027) DX(MD-0103)	
Toshiba E-STUDIO205	187301	97	ST() RADF(MR-3019) PFU(MY-1027) DX(MD-0103)	Front door cracked
Toshiba E-STUDIO211C	191911	182	RADF(MR-3006A) E() DX(MD-5007)	Black meter = 152k, color meter = 30k
Toshiba E-STUDIO230	192272	170	RADF(MR-3016) PED(KD-1011 [A]) PC(GM-2020) FAX(GD-1150) E(MJ-5004)	
Oce IM2330	183716	19	RADF(9255) PED(9283) FN(9284) FAX(CM4530110)	Finisher top access door broken, lines through touch screen, Scuff marks on RADF and finisher top panel, not recognizing PED not tested
Oce IM2330	183717	490	RADF(9255) PED(9283) FN(9284) FAX(CM4530110)	Jamming in RADF when reversing
Oce IM2330	185049	190	ST() RADF(9255) FN(9284)	
Toshiba E-STUDIO232	187294	N/A	ST() RADF(MR-3020) PC(GM-1070) FN(MJ-1022)	Top finisher tray broken and out of alignment, right side control panel smashed, stand front door will not latch, bypass feed tires broken, back panel has hole, right side knockout missing, does not recognize right side access door closed
Oce IM2330	187931	44	ST() RADF(9255) PC(IM2300060) FN(9284)	
Oce IM2330	192126	182	ST() RADF(9255) FN(9284)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Oce IM2330	192143	27	ST() RADF(9255) PC(IM2300060)	
Toshiba E-STUDIO233	187093	37	ST() RADF(MR-3020) FAX(GD-1150)	
Toshiba E-STUDIO233	189400	135	ST() RADF(MR-3020) PC(GM-1071) FN(MJ-1022)	Finisher in error code CC90 (upper tray lift motor)
Toshiba E-STUDIO233	189464	397	RADF(MR-3020) PED(KD-1011 [B]) PC(GM-2071) FN(MJ-1022)	
Toshiba E-STUDIO2330	189596	162	RADF(MR-3018) PED(KD-1024) FN(MJ-1030)	Not jogging paper correctly in stapler - not stapling correctly, charge cleaner handle broken on cyan drum, black meter = 73k, color meter = 89k
Toshiba E-STUDIO2330	191031	237	ST() RADF(MR-3018)	Waste toner door missing, black meter= 183k, color meter = 54k
Toshiba E-STUDIO2330	191831	142	ST() RADF(MR-3018) FN(MJ-1031)	Error code CCF1 - unknown - disconnected finisher to test, black meter = 79k, color meter = 63k
Toshiba E-STUDIO2330	191898	301	RADF(MR-3018) PED(KD-1023 [B])	Black meter = 76k, color meter = 225k
Toshiba E-STUDIO2330	191899	256	ST() RADF(MR-3018)	Waste toner bottle door missing, black meter = 182k, color meter = 75k
Toshiba E-STUDIO237	169852	128	ST()	
Toshiba E-STUDIO237	174197	N/A	ST() RADF(MR-3019) PFU(MY-1027) PC(GA-1190) DX(MD-0103)	Does not come to ready - not tested
Toshiba E-STUDIO237	181577	70	SCAN(GA-1200) RADF(MR-3019) PFU(MY-1027) PED(KD-1022 [B]) PC(GA-1190) DX(MD-0103)	
Toshiba E-STUDIO2500	188211	78	ST() RADF(MR-3018) PU(MJ-6004) FN(MJ-1030)	Black meter = 28k, color meter = 51k
Toshiba E-STUDIO2500	188255	128	ST() RADF(MR-3018) FAX(GD-1210)	Black meter = 39k, color meter = 89k
Toshiba E-STUDIO2500	189004	145	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 121k, color meter = 24k
Toshiba E-STUDIO2500	189401	211	ST() RADF(MR-3018) FN(MJ-1101)	Finisher in error code C570 (communication problem between CPU & IPC); color = 91k; B/W = 121k
Toshiba E-STUDIO2500	189540	194	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 70k, color meter = 125k
Toshiba E-STUDIO2500	189602	309	RADF(MR-3018) PED(KD-1019) FAX(GD-1210)	Black meter = 293k, color meter = 16k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO2500	191161	242	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 198k, color meter = 44k
Toshiba E-STUDIO2500	192155	56	ST() RADF(MR-3018)	Black meter = 45k, color meter = 11k
Toshiba E-STUDIO2500	192500	227	RADF(MR-3018) PED(KD-1018 [B]) FAX(GD-1210)	Black meter = 174k, color meter = 53k
Toshiba E-STUDIO2500	192501	531	ST() RADF(MR-3018) FAX(GD-1210)	Front door off color, RADF platen matt torn
Toshiba E-STUDIO2500	192509	492	RADF(MR-3018) PED(KD-1018 [B]) FAX(GD-1210)	Front door off color, black meter = 489k, color meter = 3k
Toshiba E-STUDIO28	191693	241	ST() RADF(MR-3012) PC(GA-1040) FAX(GD-1080)	Yellow and dirty
Toshiba E-STUDIO281C	172891	340	ST() RADF(MR-3018) FAX(GD-1200)	Cassettes 1 #2 will not lift; back panel cracked; looks like it had a finisher; error code CEE1 - transfer belt position not detected - not tested; black meter = 307k; color meter = 34k
Toshiba E-STUDIO282	191905	304	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO283	179937	251	ST() RADF(MR-3020) FAX(GD-1150)	
Toshiba E-STUDIO283	183630	258	ST() RADF(MR-3020)	
Toshiba E-STUDIO283	185099	273	FN(MJ-1022) FAX(GD-1150)	Right side access door broken
Toshiba E-STUDIO283	186464	117	RADF(MR-3020) PED(KD-1011 [A]) FN(MJ-1022)	Missing enabler - has count
Toshiba E-STUDIO3500	186219	268	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Black meter = 79k, color meter = 190k
Toshiba E-STUDIO3500	190422	339	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Left corner cover missing, Black meter = 52k, color meter = 287k
Toshiba E-STUDIO3500	191697	116	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Black meter = 52k, color meter = 65k
Toshiba E-STUDIO3500	191841	70	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1210)	Yellow panels, magic marker on bypass tray, black meter = 25k, color meter = 46k
Toshiba E-STUDIO3510	192482	334	PU(MJ-6004)	Has wireless card and bluetooth, has

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	second fax line, black meter = 43k, color meter = 291k, paper not jogging correctly when exiting finisher
Toshiba E-STUDIO3511	191852	231 ST()	RADF(MR-3015)	Black meter = 229k, color meter = 3k, slit glass broken
Toshiba E-STUDIO351C	178666	274	RADF(MR-3018) PU(MJ-6004) PED(KD-1011 [A])	Yellow apnels, false jam in finisher - not tested, black meter - 196k, color meter = 79k
Toshiba E-STUDIO351C	178806	296	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Jamming in RADF, finsher latch broken, black meter = 238k, color meter = 59k
Toshiba E-STUDIO351C	188970	812	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Black meter = 810k, color meter = 3k
Toshiba E-STUDIO351C	189016	607 ST()	RADF(MR-3018)	Black meter = 577k, color meter = 31k
Toshiba E-STUDIO351C	190535	291 ST()	RADF(MR-3018) FAX(GD-1200)	Black meter = 242k, color meter = 49k
Toshiba E-STUDIO351C	190536	144 ST()	RADF(MR-3018) FAX(GD-1200)	Black meter = 96k, color meter = 49k
Toshiba E-STUDIO351C	190538	102 ST()	RADF(MR-3018) FAX(GD-1200)	Jamming in RADF - not tested, black meter = 66k, color meter = 36k
Toshiba E-STUDIO351C	191912	393	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Black meter = 349k, color meter = 44k
Toshiba E-STUDIO352	183039	304	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1101)	Duplex jams at finisher when stapling
Toshiba E-STUDIO352	185825	240	RADF(MR-3018) PED(KD-1011 [B]) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	
Toshiba E-STUDIO352	186051	161	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	Lower finisher tray motor cover broken
Toshiba E-STUDIO352	186777	50 ST()	RADF(MR-3018) PC(GM-1060)	
Toshiba E-STUDIO352	187081	314	RADF(MR-3018) PED(KD-1011 [B]) PC(GM-2060) FN(MJ-1023) FAX(GD-1200)	
Toshiba E-STUDIO352	188456	262	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO352	190010	166	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	
Toshiba E-STUDIO352	190011	277	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	
Toshiba E-STUDIO352	190012	219	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	
Toshiba E-STUDIO352	190028	138	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	Finisher rear jogger arm bent, control panel has deep scratch
Toshiba E-STUDIO352	190425	97	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	Finisher latch handle broken
Toshiba E-STUDIO352	190788	116	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	Finisher trays and motor covers broken, bottom finisher tray motor cover missing
Toshiba E-STUDIO352	191338	482	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1101)	
Toshiba E-STUDIO352	191894	193	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022)	Right side access door missing, fuser panel broken
Toshiba E-STUDIO352	192271	131	ST() RADF(MR-3018) PC(GM-2060) FAX(GD-1200)	
Toshiba E-STUDIO353	179026	1025	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	Back panel scratched
Toshiba E-STUDIO353	183512	371	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Finisher making squealing noises
Toshiba E-STUDIO353	183631	157	ST() RADF(MR-3018) PC(GM-2061) FN(MJ-1022)	Fax panel gouged, finisher trim flap broken
Toshiba E-STUDIO353	183632	336	ST() RADF(MR-3018) PC(GM-2061) FN(MJ-1022)	
Toshiba E-STUDIO353	183657	237	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022)	Machine squeaking
Toshiba E-STUDIO353	184348	172	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101) FAX(GD-1200)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO353	184349	288	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO353	184351	67	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Error code C580 - communication error between IPC board and finisher - not tested
Toshiba E-STUDIO353	185278	88	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Error code C570 - communication problem between Engine CPU and IPC board - finisher not tested
Toshiba E-STUDIO353	185281	294	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FAX(GD-1200)	
Toshiba E-STUDIO353	185282	92	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022) FAX(GD-1200)	Cassette #2 jams, LCT not lifting paper - not tested
Toshiba E-STUDIO353	185290	76	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022) FAX(GD-1200)	Very dirty
Toshiba E-STUDIO353	185293	N/A	RADF(MR-3018) PC(GM-2061) FAX(GD-1200)	No power to machine - not tested
Toshiba E-STUDIO353	185296	142	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022) FAX(GD-1200)	
Toshiba E-STUDIO353	185316	175	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO353	185324	227	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022) FAX(GD-1200)	Very dirty
Toshiba E-STUDIO353	185796	135	RADF(MR-3018) PED(KD-1011 [B]) PC(GM-1061)	
Toshiba E-STUDIO353	186222	274	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Missing enabler - has count
Toshiba E-STUDIO353	186228	N/A	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	Cannot find hard drive data - not tested
Toshiba E-STUDIO353	186241	262	RADF(MR-3018)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO353	186414	284	PED(KD-1011 [B]) FN(MJ-1022) RADF(MR-3018) PU(MJ-6101) PED(KD-1011 [A]) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO353	186453	265	ST() RADF(MR-3018) PC(GM-2061)	
Toshiba E-STUDIO353	187580	610	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	Error code CC30 - finisher stack motor abnormality - finisher not tested, finisher latch handle broken
Toshiba E-STUDIO353	187581	498	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	Lower finisher tray and tray mount missing, top finisher tray motor cover missing
Toshiba E-STUDIO353	187647	110	RADF(MR-3018) PED(KD-1011 [A])	
Toshiba E-STUDIO353	187651	667	ST() RADF(MR-3018)	Has PC count - missing enabler, grinding noise in machine
Toshiba E-STUDIO353	188273	176	ST() RADF(MR-3018) FN(MJ-1022)	Has PC count - missing enabler
Toshiba E-STUDIO353	188274	194	ST() RADF(MR-3018) FN(MJ-1022)	
Toshiba E-STUDIO353	188606	216	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO353	188958	247	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Very dirty, skewing paper in RADF
Toshiba E-STUDIO353	189458	502	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022) FAX(GD-1200)	
Toshiba E-STUDIO353	189542	220	ST() RADF(MR-3018) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO353	189590	396	ST() RADF(MR-3018) PC(GM-2061) FAX(GD-1200)	Cracked panel around controller area
Toshiba E-STUDIO353	189603	236	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1024)	
Toshiba E-STUDIO353	189773	80	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022)	Error code CC90 - finisher upper tray motor - finisher not tested, machine left wheel broken off
Toshiba E-STUDIO353	190431	323	ST() RADF(MR-3018) PC(GM-2061)	Off color panels, ground in dirt, missing fax board- has count

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO353	191033	245	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO353	192081	434	RADF(MR-3018) PED(KD-1011 [A]) PC(GM-2061) FN(MJ-1022) FAX(GD-1200)	
Toshiba E-STUDIO353	192090	104	ST() RADF(MR-3018) FN(MJ-1022)	Jamming in RADF - not tested, stand front door dented
Toshiba E-STUDIO353	192128	358	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FAX(GD-1200)	
Toshiba E-STUDIO353	192303	270	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022)	
Toshiba E-STUDIO3530	188260	521	RADF(MR-3018) PED(KD-1024) FN(MJ-1101) FAX(GD-1250)	Error code CE20 - image quality sensor - not tested, deep scratch on touch screen, front door cracked, left corner trim panel broke, off color panels, black meter = 226k, color meter = 296k
Toshiba E-STUDIO3530	188337	336	RADF(MR-3018) PED(KD-1023 [B]) FN(MJ-1101) FAX(GD-1250)	Black meter = 274k, color meter = 63k
Toshiba E-STUDIO3530	188954	255	RADF(MR-3018) PED(KD-1024) FN(MJ-1031) FAX(GD-1250)	Ground in dirty, very dirty, finisher interlock switch broken - finisher not tested, black meter = 239k, color meter = 16k
Toshiba E-STUDIO3530	189465	374	RADF(MR-3018) PU(MJ-6101) PED(KD-1024) FN(MJ-1101) FAX(GD-1250)	Black meter = 326k, color meter = 48k
Toshiba E-STUDIO3530	191828	435	RADF(MR-3018) PED(KD-1024) FN(MJ-1101) FAX(GD-1250)	Black meter = 392k, color meter = 43k
Imagistics CM4530	189853	47	PED(9283) FN(9285) FAX(CM4530110)	Slit glass broken, black meter = 40k, color meter = 8k
Toshiba E-STUDIO451C	188972	620	PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Black meter = 593k, color meter = 27k
Toshiba E-STUDIO452	192455	265	ST() RADF(MR-3018)	Jamming in RADF - not tested, wrinkling duplexed copies
Toshiba E-STUDIO4520	191029	988	RADF(MR-3018) PU(MJ-6004) PED(KD-1024) FN(MJ-1030)	Black meter = 496k, color meter = 492k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO4520	191030	732	RADF(MR-3018) PED(KD-1024) FN(MJ-1030)	Bridge unit latch broken, black meter = 509k, color meter = 223k
Toshiba E-STUDIO453	168226	257	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	Missing finisher upper back panel; finisher board & wires are damaged causing a false open door- can't test
Toshiba E-STUDIO453	178916	214	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Missing enabler - has count
Toshiba E-STUDIO453	180436	277	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO453	183008	940	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	Rigth access door broken
Toshiba E-STUDIO453	183032	308	RADF(MR-3018) PED(KD-1011 [B])	
Toshiba E-STUDIO453	183539	498	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	
Toshiba E-STUDIO453	184113	246	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	
Toshiba E-STUDIO453	184347	381	RADF(MR-3018) PED(KD-1012)	Error code CC51 - sideways adjustment motor M2 abnormality sideways adjust motor- finisher not tested
Toshiba E-STUDIO453	184352	297	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Ground in dirt, Jamming in RADF - not tested
Toshiba E-STUDIO453	184353	227	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Scratches on RADF
Toshiba E-STUDIO453	184451	533	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO453	184452	499	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101)	
Toshiba E-STUDIO453	184453	603	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	
Toshiba E-STUDIO453	185094	133	RADF(MR-3018) PU(MJ-6101)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO453	185285	241	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Jamming out of cassette #2 - not tested
Toshiba E-STUDIO453	185300	113	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Finisher front door broken
Toshiba E-STUDIO453	185831	205	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO453	185832	383	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Hole punch skews when duplexing
Toshiba E-STUDIO453	186215	490	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	False jam in finisher - not tested
Toshiba E-STUDIO453	186221	411	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	Fax board missing - has count
Toshiba E-STUDIO453	186520	274	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Front door of punch unit broken
Toshiba E-STUDIO453	187342	212	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO453	188293	422	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO453	189030	354	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO453	189447	512	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	Jamming at RADF exit area
Toshiba E-STUDIO453	189467	298	RADF(MR-3018) PED(KD-1011 [A]) FN(MJ-1101) FAX(GD-1200)	Missing enabler - has count
Toshiba E-STUDIO453	189468	122	RADF(MR-3018) PED(KD-1011 [A])	Jamming in stapler - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO453	190143	1335	ST() RADF(MR-3018) FN(MJ-1101)	
Toshiba E-STUDIO453	190145	1027	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	
Toshiba E-STUDIO453	190146	1146	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	Error code C970 - high voltage leak from main charge detected - not fully tested
Toshiba E-STUDIO453	190147	894	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	
Toshiba E-STUDIO453	190426	440	RADF(MR-3018) PED(KD-1012) PC(GM-2061) E(MJ-5004)	Deep scratch on touch screen
Toshiba E-STUDIO453	191468	529	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	Punch unit trim panel missing
Toshiba E-STUDIO453	191692	265	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	Jamming in RADF - skewing paper
Toshiba E-STUDIO453	191909	367	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO453	191910	329	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO455	186877	631	RADF(MR-3022) PU(MJ-6101) PED(KD-1026) FN(MJ-1101) FAX(GD-1250)	
Toshiba E-STUDIO455	189598	107	RADF(MR-3022) PED(KD-1026) FN(MJ-1101)	Error code C440 - fuser error - not tested
Toshiba E-STUDIO455	190961	435	ST() RADF(MR-3022) FAX(GD-1250)	Cassette #1 lift motor grinding - not tested
Toshiba E-STUDIO455	191698	169	RADF(MR-3022) PED(KD-1026) FN(MJ-1101) FAX(GD-1250)	
Toshiba E-STUDIO455	191699	213	RADF(MR-3022) PED(KD-1026) FN(MJ-1101)	False paper sensor in exit tray - tested through finisher
Toshiba E-STUDIO455	191700	145	RADF(MR-3022) PED(KD-1026)	Bottom cassette not tested - does not recognize paper

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1101) FAX(GD-1250)	
Toshiba E-STUDIO520	181412	405	PU(MJ-6003N) FN(MJ-1027) FAX(GD-1170)	Missing finisher actuator - not tested, missing enabler - has count, bottom cassette sticking
Toshiba E-STUDIO520	181563	329	PC(GM-2040) FN(MJ-1027)	Finisher rails yellow, front toner door will not latch, machine making whining noise
Toshiba E-STUDIO520	187573	413	FN(MJ-1027)	Right side panel cracked
Toshiba E-STUDIO520	189017	412	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO520	189029	572	PC(GM-2040) FN(MJ-1027)	Does not recognize toner installed
Toshiba E-STUDIO520	189364	120	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO520	190160	N/A	PC(GM-2040) P(MP-4004) FN(MJ-1027)	Missing hard-drive - not tested
Toshiba E-STUDIO520	190775	456	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	Does recognize toner, missing paperdeck - has brackets
Toshiba E-STUDIO520	190777	223	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO520	192456	436	PC(GM-2040) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO520T	188757	185	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO520T	189484	223	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO520T	190027	551	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	RADF feed tray broken
Toshiba E-STUDIO523	178937	198	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Cassette #2 frame bent
Toshiba E-STUDIO523	180787	1504	PC(GM-2041) P(MP-4004) FN(MJ-1027)	Finisher wiring harness broken - finisher not tested, cassette #3 feed tires off - not tested,
Toshiba E-STUDIO523	183034	407	PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Left side panel broken
Toshiba E-STUDIO523	183436	982	FN(MJ-1027)	
Toshiba E-STUDIO523	183643	731	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	LCT not tested - cables not raising paper evenly, grinding noise at drum, jamming at drum unit - not fully tested
Toshiba E-STUDIO523	184119	558	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO523	186515	163	PC(GM-2041) FN(MJ-1027)	Chattering noise in finisher, does not staple
Toshiba E-STUDIO523	187344	384	PC(GM-2041) FN(MJ-1027)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(GD-1170)	
Toshiba E-STUDIO523	188252	930 FN(MJ-1027)		
Toshiba E-STUDIO523	188264	483 PC(GM-2041) FN(MJ-1027)	FAX(GD-1170)	
Toshiba E-STUDIO523	188265	980 PC(GM-2041) FN(MJ-1027)	FAX(GD-1170)	
Toshiba E-STUDIO523	188283	605 PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523	188284	694 PC(GM-2041) FN(MJ-1027)		Bypass not recognizing paper - not tested
Toshiba E-STUDIO523	188285	809 PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523	188286	646 PC(GM-2041) FN(MJ-1027)		Front door handle broken
Toshiba E-STUDIO523	188287	1115 PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523	188288	445 PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523	188289	418 PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523	188290	1549 PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523	191842	503 PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027)		Error code F103 - hard-drive transfer timeout reading/writing - not tested
Toshiba E-STUDIO523	192359	619 P(MP-4004) FN(MJ-1027) FAX(GD-1170)		Paper deck interlock actuator out of alignment
Toshiba E-STUDIO523T	179170	N/A PU(MJ-6003) PC(GM-2041) FN(MJ-1027)		Missing hard drive- cannot test or get meter counts
Toshiba E-STUDIO523T	179172	N/A PU(MJ-6003) PC(GM-2041) FN(MJ-1027)		Missing hard-drive - not tested, RADF connector cable cut
Toshiba E-STUDIO523T	183635	655 PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027)		
Toshiba E-STUDIO523T	184117	1007 PU(MJ-6003) PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523T	184118	641 FN(MJ-1027)		Finisher tray scraped
Toshiba E-STUDIO523T	185821	448 FN(MJ-1027)		
Toshiba E-STUDIO523T	185822	834 FN(MJ-1027)		Jamming in duplexer
Toshiba E-STUDIO523T	185823	524 PC(GM-2041) FN(MJ-1027) FAX(GD-1170)		Finisher rails off color
Toshiba E-STUDIO523T	186231	412 PC(GM-2041) FN(MJ-1027)		Right panel smashed
Toshiba E-STUDIO523T	186530	594 FN(MJ-1027)		
Toshiba E-STUDIO523T	188453	387 PC(GM-2041) FN(MJ-1027)		
Toshiba E-STUDIO523T	189595	277 PU(MJ-6003) FN(MJ-1027)		
Toshiba E-STUDIO523T	191034	1357 PC(GM-2041) P(MP-4004) FN(MJ-1027)		Right side trim plate missing
Toshiba E-STUDIO523T	192088	739 FN(MJ-1027)		
Toshiba E-STUDIO523T	192089	985 PC(GM-2041) FN(MJ-1027)		

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO523T	192368	168	PU(MJ-6003) PC(GM-2041) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO550	191853	815	FN(MJ-1018)	Cassette #1 not lifting - not tested, yellow panels
Toshiba E-STUDIO600	188760	578	PU(MJ-6003N) PC(GM-2040) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO600	189005	627	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO600T	191857	636	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	Cassette #2 not feeding - not tested
Toshiba E-STUDIO603	178303	1798	PU(MJ-6003) FN(MJ-1027)	Has enabler GM-1051, upper finisher tray yellow
Toshiba E-STUDIO603	178422	394	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Error code CC50 - finisher horizontal registration motor - finisher not tested, jamming in paper deck - not tested
Toshiba E-STUDIO603	186523	924	FN(MJ-1027) FAX(GD-1170)	Broken paper tray #3 panel; missing print enabler (has count = 591k)
Toshiba E-STUDIO603	186533	N/A	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Machine shows "cannot start application"- unable to clear or test
Toshiba E-STUDIO603	188828	203	PC(GM-2041) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO603	188830	383	PC(GM-2041) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO603	190421	1120	PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Error code CF70 - toner transport motor problem - not tested, enabler broken, blank copies
Toshiba E-STUDIO603	191903	1232	PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO603	191904	464	PC(GM-2041) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO603	192173	1134	PU(MJ-6003) PC(GM-2041) FN(MJ-1027) FAX(GD-1170)	Toner door interlock broken
Toshiba E-STUDIO603T	179114	3658	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603T	179115	2823	PC(GM-2041) FN(MJ-1027)	Error code CB60 - staple shift motor problem - finisher not tested, could not print NIC page
Toshiba E-STUDIO603T	179116	3449	PC(GM-2041) P(MP-4004) FN(MJ-1027)	skewing paper in exit tray - stapler not tested
Toshiba E-STUDIO603T	179117	3021	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603T	179118	4682	FN(MJ-1027)	Front door interlock switch broken - unable to test

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO603T	179121	3063	PC(GM-2041) FN(MJ-1027)	Could not print NIC page
Toshiba E-STUDIO603T	179122	2738	PC(GM-2041) FN(MJ-1027)	Could not print NIC page
Toshiba E-STUDIO603T	179238	2647	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603T	179239	3169	PC(GM-2041) FN(MJ-1027)	Could not print NIC page
Toshiba E-STUDIO603T	179669	388	PU(MJ-6003) PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603T	180773	2020	PU(MJ-6003) PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603T	180774	2383	PU(MJ-6003) PC(GM-2041) FN(MJ-1027)	Not recognizing toner
Toshiba E-STUDIO603T	185319	1395	PC(GM-2041) FN(MJ-1027) FAX(GD-1170)	Very dirty
Toshiba E-STUDIO603T	186277	663	PU(MJ-6003) PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603T	187379	263	FN(MJ-1027)	
Toshiba E-STUDIO603T	188295	891	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO603T	190148	1132	PC(GM-2041) FN(MJ-1027)	Back panel scraped
Toshiba E-STUDIO720	189547	454	PU(MJ-6003N) PC(GM-2040) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Error code C570 - communication error between engine CPU and IPC board- finisher not tested, finisher bracket bent, finisher rail yellow
Oce IM7230	191878	2148	SCAN(GM-4010) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Paperdeck wiring broken - paperdeck not tested, toner spilled throughout machine, very dirty, front door handle missing, cassette #1,2 not recognizing paper - not tested
Oce IM7230	191879	2042	P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Finisher connector housing broken, paperdeck handle broken
Oce IM7230	191880	2131	SCAN(GM-4010) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Missing PC enabler, jamming in finisher - not tested
Oce IM7230	191881	1722	P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Cassette #1 not recognizing paper - not tested
Oce IM7230	191882	2697	SCAN(GM-4010) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	
Oce IM7230	191883	1882	SCAN(GM-4010) P(MP-4004) FN(MJ-1027)	Cassettes 3, 4 not recognizing paper - not tested, frton door handle missing, missing PC enabler
Oce IM7230	191884	2295	PC(GM-2040) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Back panel cracked
Oce IM7230	191885	2277	SCAN(GM-4010) PC(GM-1050) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	LCT right side panel missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Oce IM7230	191886	1547	SCAN(GM-4010) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	
Oce IM7230	191887	2240	SCAN(GM-4010) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Error code CF-70 - toner transport motor abnormality
Oce IM7230	191888	1998	P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Missing enabler - has count, stapler not stapling
Oce IM7230	191889	2286	SCAN(GM-4010) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Front door release handle missing, control panel broken at print data LED
Toshiba E-STUDIO723	178245	2167	PU(MJ-6003) PC(GM-2041) FN(MJ-1029)	Error code F110 - communication error between scan CPU and system CPU - not tested, front door interlock switch broken, right back panel
Toshiba E-STUDIO723	181582	446	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Jamming at punch unit - not tested, right side corner by pc cracked
Toshiba E-STUDIO723	184454	1508	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO723	184455	2057	PU(MJ-6003) P(MP-4004) FN(MJ-1027)	Error code CF70 - communication problem between system CPU and engine CPU - not tested
Toshiba E-STUDIO723	190420	1008	PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Exit door interlock switch broken - not tested
Toshiba E-STUDIO723T	180422	2590	FN(MJ-1027)	Error code CF70 - toner transport motor problem - not tested
Toshiba E-STUDIO723T	180423	2694	FN(MJ-1027)	
Toshiba E-STUDIO723T	183640	408	FN(MJ-1027) FAX(GD-1170)	Finisher front door broken
Toshiba E-STUDIO723T	188263	1884	PC(GM-1051) P(MP-4004) FN(MJ-1027)	Control panel cracked, jamming in LCT - not tested
Toshiba E-STUDIO723T	189391	708	PU(MJ-6003) PC(GM-2041) FN(MJ-1027)	Right side panel dented at screw hole, back panel dented
Toshiba E-STUDIO723T	189960	653	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Paper deck actuator & rail missing - LCT not tested
Toshiba E-STUDIO850	191688	3469	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO853	179106	4444	P(MP-4004) FN(MJ-1027)	Error code C570 - communication problem between engine CPU and IPC - finisher not tested, could not print NIC page, LCT rail missing
Toshiba E-STUDIO853	179107	N/A	PC(GM-2041) FN(MJ-1027)	Firmware update failure - not tested, hard-drive removed, looks like it had LCT - knockouts missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO853	179597	4306	PU(MJ-6003) PC(GM-1051) P(MP-4004) FN(MJ-1028)	
Toshiba E-STUDIO853	186230	990	PC(GM-2041) P(MP-4004) FN(MJ-1027)	Error code CD30 - recycle toner transport problem - not able to test, finisher rails off color
Toshiba E-STUDIO853	186472	563	PU(MJ-6003) PC(GM-2041) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Paperdeck platform wiring not set evenly - paper deck - not tested, finisher rails off color
Toshiba E-STUDIO853	188261	1630	PC(GM-1051) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO853	188262	2690	PC(GM-1051) P(MP-4004) FN(MJ-1027)	Jamming at drum - not fully tested

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.