

Wulff Enterprises

01/07/2009

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica COLORPRINTER	112079	212		7830DXN w/ pedestal; yellowed panels; shows yellow toner sensor error; tray #4 access door will not stay closed
Konica COLORPRINTER	120771	N/A		7820dxn; error code 140; cracked top front panels
Kyocera COLORPRINTER	120696	N/A		FS-8000C w/ pedestal; smashed corona wire housing & wires broken & bent; toner spilled throughout machine; smashed back panel
Kyocera COLORPRINTER	122656	126		FS-C5030N
Kyocera COLORPRINTER	123307	107		FS-C5020DN w/ duplex & PFU
Kyocera LASERPRINTER	122100	N/A		FS-3830N; Error code 7410 - not tested
Kyocera LASERPRINTER	122105	N/A		FS-3830N; Error code SC7410 - not tested
Kyocera LASERPRINTER	122108	N/A		FS-3830N; Error code 7410 - not tested
Kyocera LASERPRINTER	124730	109		FS-3830N w/ pedestal & stacker
Kyocera LASERPRINTER	124731	130		FS-3830N w/ pedestal & stacker
Lexmark COLORPRINTER	123049	122		X945E copier/printer w/ RADF, fax board, LCT pedestal & finisher; cracked right side panel; missing bridge unit- unable to test finisher
Lexmark COLORPRINTER	123050	79		X945E copier/printer w/ RADF, fax board, LCT pedestal & finisher; left side access door has bad interlock & shows open; color = 72k; B/W = 8k
Minolta CF2001P	124607	132	PED(PF-117) FN(FN-108) DX(AD-14)	LCT pickup rollers stuck in down position- inop; broken bridge unit- can't test finisher; color = 120k; B/W = 13k
Minolta COLORPRINTER	125014	43		QMS MagicColor 7300
Mita COLORPRINTER	121090	N/A		FS-C5016N; calling for waste toner box to be emptied and unable to clear; very dirty inside
Mita COLORPRINTER	124096	73		FS-C5016N
Mita LASERPRINTER	119395	162		FS-3900DN w/ PFU
Mita LASERPRINTER	120325	1225		FS-9500DN w/ finisher & pedestal
Mita LASERPRINTER	123302	510		FS-3800

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita LASERPRINTER	123617	70		FS-9100DN w/ finisher & pedestal; dirty & offcolored panels
Mita LASERPRINTER	124482	264		FS-1900
Mita LASERPRINTER	124483	317		FS-1900
Mita LASERPRINTER	124488	241		FS-1900
Okidata COLORPRINTER	118877	101		2426n; yellowed panels
Okidata COLORPRINTER	120894	39		3037 w/ image scanner; error code 400 (paper size error) but still able to test; scanner not communicating with printer; yellowed panels; scanner feed tray will not stay up
Okidata COLORPRINTER	122967	79		C9300; yellowed panels
Okidata COLORPRINTER	124815	13		2024n; yellowed & dirty panels
Lanier 2138	111526	63	ST() E() DX(TYPE 3800C)	
Lanier 2138	117130	168	PED(3800C [A]) E() DX(TYPE 3800C)	Missing cyan & magenta toner cartridges- tested with others; color = 141k; B/W = 28k
Lanier 2138	117131	143	ST() E()	Missing duplex unit (has mounting brackets); Color = 125k; B/W = 19k
Ricoh AP3800C	119565	131	PED(3800C [A]) FN(SR770) DX(TYPE 3800C)	Yellowed panels; color = 96k; B/W = 36k
Ricoh AP3800C	120718	259	PU(TYPE 1045) PED(3800C [A]) FN(SR770) = 53k	Dented back panel; color = 207k; B/W
Lanier 2138	123327	16	PED(PS470) E() DX(TYPE 3800C)	Color = 2k; B/W = 16k
Savin SLP38C	124931	134	PED(PS470) DX(TYPE 3800C)	Color = 13k; B/W = 121k; missing exit tray
Lanier 2138E	111527	157	PED(3800C [B]) E() DX(TYPE 3800C)	
Gestetner DSC38F	122954	509	PED(3800C [B]) E() DX(TYPE 3800C)	Error code SC260 (laser position home sensor); yellowed panels
Ricoh CL7000	111331	N/A	PED(3800C [A]) E() DX(TYPE 7000)	Machine is calling for fuser oil unit to be installed but it is installed correctly (bad sensor?); dented left side back panel
Ricoh CL7000	114710	286	ST() E() DX(TYPE 7000)	
Ricoh CL7000	118628	N/A	ST() E() DX(TYPE 7000)	Error code 440-1 Transfer belt problem
Savin CLP28	123576	243	PED(3800C [A]) FN(SR770) DX(TYPE 7000)	Smashed front top left corner of machine; hole in front door; color = 225k; B/W = 19k
Ricoh CL7000	123653	732	PED(3800C [A]) FN(SR770) DX(TYPE 7000)	Missing door below bypass; color = 217k; B/W = 515k
Ricoh COLORPRINTER	110540	146		CL7100 w/ duplex & pedestal

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier COLORPRINTER	119340	39		LP235C w/ duplex unit & PFU; duplex unit will not function- machine is calling for it to be reset and will not clear; missing exit tray
Ricoh COLORPRINTER	119427	305		CL7100 w/ pedestal
Ricoh COLORPRINTER	121065	66		CL7100 w/ finisher & pedestal; dented back of scanner stand; offcolored panels; color = 8k; B/W = 58k
Ricoh COLORPRINTER	121194	222		CL7100 w/ pedestal & SR910 finisher
Ricoh COLORPRINTER	121308	66		CL2000N w/ IS100E image scanner; cracked left back panels; broken original tray on scanner; missing two keypad buttons; broken toner access doot interlock pin; very dirty panels
Ricoh COLORPRINTER	121726	371		Aficio CL7100 w/ SR910 finisher & pedestal
Ricoh COLORPRINTER	122176	79		SP C410DN
Ricoh COLORPRINTER	122323	120		CL7100
Gestetner COLORPRINTER	122614	47		CL5000 w/ pedestal
Ricoh COLORPRINTER	123735	151		CL7100 w/ pedestal
Lanier COLORPRINTER	124066	16		LP122C w/ PFU
Ricoh COLORPRINTER	124104	17		Aficio CL3500N
Ricoh COLORPRINTER	124660	75		AFICIO CL7300 w/ PFU & SR950 finisher; color = 54k; B/W = 22k
Ricoh COLORPRINTER	124672	445		AFICIO CL7100 w/ stand; dented left side back panel
Ricoh COLORPRINTER	124920	17		CL2000N; jams every print
Ricoh COLORPRINTER	124921	29		CL2000N
Ricoh COLORPRINTER	124922	32		CL2000N
Ricoh COLORPRINTER	124923	4		CL2000N
Ricoh COLORPRINTER	124935	217		CL7100 w/ SR910 finisher & pedestal
Savin LASERPRINTER	119406	1240		MLP45; yellowed panels; bypass tray broken off
Ricoh LASERPRINTER	122633	N/A		AC204; missing developer unit- can't test; dirty & offcolored panels
Savin LASERPRINTER	124700	16		AC205; works, but goes into LSU error at times
Savin LASERPRINTER	124701	19		AC205
Samsung LASERPRINTER	121568	N/A		SCX-4720F
Sharp AR-P350	124503	291	NIC(AR-NC5J) DX(AR-DU4)	Yellowed & dirty panels; broken exit traY & mounts
Sharp COLORPRINTER	123810	1		AR-C200P; Open port on controller panel- appears NIC was removed;

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				showing a yellow toner sensor error
Sharp COLORPRINTER	124584	205		AR-C200P w/ PFU; yellowed panels
Toshiba COLORPRINTER	117249	4		E-STUDIO20cp
Toshiba COLORPRINTER	124212	49		E-STUDIO20cp
Xerox COLORPRINTER	116546	219		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116547	259		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116548	242		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116549	419		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116550	334		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116551	288		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116552	72		Phaser 8200 w/ PFU; needs a new maintenance kit
Xerox COLORPRINTER	116554	343		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116555	290		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116556	688		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116557	372		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116559	253		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116560	378		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116561	204		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116562	200		Phaser 8200 w/ PFU; PFU in false jam code- tested without
Xerox COLORPRINTER	116563	455		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116564	234		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116565	315		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116568	137		Phaser 8200 w/ PFU; jams frequently at exit area
Xerox COLORPRINTER	116569	227		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116570	395		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116572	300		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116573	234		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116574	341		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116575	228		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116577	142		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116578	446		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116579	222		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116583	162		Phaser 8200 w/ PFU
Xerox COLORPRINTER	116584	249		Phaser 8200 w/ PFU; broken top access panel at left hinge

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox COLORPRINTER	116585	161		Phaser 8200 w/ PFU
Xerox LASERPRINTER	122513	164		Phaser 5400

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.