

# Wulff Enterprises

07/29/2010

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Copystar KM-C2230	156171	442	ST() RADF(DP-621) FN(DF-626) DX(DU-621)	Color = 181k; B/W = 261k
Copystar CS-1820	155043	64	FAX(K) ADF(DP-100)	
Copystar CS-1820	155044	117	FAX(K) ADF(DP-100)	
Copystar CS-2550	152991	67	ST() RADF(DP-410) DX(DU-410)	RADF has a bad hinge & will not stay open
Copystar CS-2550	156015	155	ST() SCAN(F) RADF(DP-410) DX(DU-410)	Yellowed panels
Copystar CS-3050	152992	290	ST() RADF(DP-700) FN(DF-710)	
Copystar CS-C2520	149432	289	ST() RADF(DP-710)	Ran fine, now touch screen is locked up; Black meter = 227k; color meter = 63k
Copystar CS-C3225	157073	300		Back left corner panel out of alignment; color = 162k; B/W = 139k
Copystar CS-3035	152129	136	ST() RADF(SRDF-2) FN(DF-73)	
Copystar CS-3035	152134	143	RADF(SRDF-2) PED(PF-75) FN(DF-73)	
Copystar CS-3035	156341	222	ST() RADF(SRDF-2) FN(DF-71U)	Stapler inop- shows functions cannot be combined; broken finisher interlock switch cover
Royal RI-4030	143946	437	ST() RADF(SRDF-2) FN(DF-78) DX(AD-63)	Cracked RADF panel; broken RADF plug socket; dented & bent lower back panle; unable to test stapler (functions cannot be combined); missing fax board (Has fax count of 63,344); broken end cap on finisher tray
Copystar CS-4530	147316	2543	FN(DF-600)	Finisher socket broken; yellow panels; cassette #1 inop - not tested; does not staple
Copystar CS-4530	156467	237	PC(Q)	Front door actuator broken; has finisher brackets - missing finisher; Error code C5110 - transfer separator corona; back panel dented

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.