

# Wulff Enterprises

02/10/2012

## GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM415	176986	46		Off color panels
Gestetner DSM415PF	189422	192		
Gestetner DSM415PF	189423	103		Off color panels
Gestetner DSM415PF	189424	117		Off color panels
Gestetner DSM415PF	189425	158		ADF not turning on - not tested, off color panels
Gestetner DSM415PF	189426	135		Off color panels
Gestetner DSM415PF	189427	220		Error code SC670 - engine startup error, off color panels
Gestetner DSM415PF	189428	244		
Gestetner DSM415PF	189429	72		Off color panels
Gestetner DSM620	189158	49	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340) ADF(DF78)	Cassette #2 front panel broken
Gestetner DSM620	189159	28	ST() FAX(TYPE 2018) E(PT340) ADF(DF78)	Wireless PC card
Gestetner DSM620	189166	60	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340) ADF(DF78)	
Gestetner DSC332	187715	659	PED(PS540) FN(SR920) FAX(TYPE 2238) E(PT460)	Off color panels, black meter = 571k, color meter = 88k
Gestetner DSC332	192622	53	ST() E(PT460)	Not feeding paper - not tested, off color panels, black meter = 36k, color meter = 17k
Gestetner DSM725	179671	76	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030)	Yellow, jamming at fuser - not tested
Gestetner DSM725	183149	313	ST() RADF(DF83) PC(TYPE 3030 (S))	Bypass tray broken - not tested
Gestetner DSM725	184813	232	ST() RADF(DF83)	
Gestetner DSM725	185339	372	ST() RADF(DF83) PC(TYPE 3030 (S))	
Gestetner DSM725	188375	97	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	
Gestetner DSM725	188376	168	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	Yellowed RADF panels
Gestetner DSM725	192339	361	ST() RADF(DF83) PC(TYPE 3030) FAX(TYPE 3030) E(PT280)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM725	192674	83	ST() RADF(DF83) PC(TYPE 3030 (S))	
Gestetner DSM730	179259	251	ST() RADF(DF83) PC(TYPE 3030 (S))	Error code SC501 - cassette #1 out of order - not tested, yellow
Gestetner DSM730	190195	248	RADF(DF83) PED(PS490) PC(TYPE 3030)	
Gestetner DSM735	179714	268	PED(PS530) FN(SR790)	Yellow panels
Gestetner DSM735	185646	593	ST() PC(TYPE 3045) FAX(TYPE 3045) E(PT330)	Stand off color
Gestetner DSM735	188530	194	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Broken bypass tray; yellowed panels
Gestetner DSM735	189161	219	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM735	190196	816	PED(PS530) FAX(TYPE 3045) E(PT330)	
Gestetner DSM735	192690	312	ST()	
Gestetner DSC424	126842	190	ST()	
Gestetner DSC428	182232	636	PU(TYPE 2238) PED(PS580) FN(SR950) FAX(TYPE 3245) E(PT460)	Error code SC542- fuser heat roller temp too low - not tested, off color panels, black meter = 321k, color meter = 315k
Gestetner DSC435	181464	254	ST() FAX(TYPE 3245) E(PT460)	Error code 440-02 - color drum motor error - not tested, off color, black meter - 219k, color meter = 35k
Gestetner DSC435	187460	553	PED(PS580) FAX(TYPE 3245)	Machine would not copy - not fully tested (does not show an error code), black meter = 227k, color meter = 327k
Gestetner DSC435	191743	665	PED(PS590) FAX(TYPE 3245) E(PT460)	Black meter = 373k, color meter = 293k
Gestetner DSC445	187461	562	PED(PS590) FN(SR950)	False door indicator in finisher - not tested, error code SC391 - black charge AC output error - not tested, off color panels, black meter = 131k, color meter = 431k
Gestetner DSC460	180964	1465	PU(TYPE 3260) PC(TYPE 3260) FN(SR980)	Color = 23k; B/W = 1442k
Gestetner DSC460	180967	2080	PU(TYPE 1075) PC(TYPE 3260) FN(SR841)	Color = 244k; B/W = 1837k
Gestetner DSC460	181165	1577	PU(TYPE 3260) PC(TYPE 3260) FN(SR4000)	Jamming in finisher - not tested, error code SC760 - finisher punch motor, sensor, motor drive or main board, black meter = 1010k, color meter = 567k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSC460	183167	1067	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Finisher off color. black meter = 975k, color meter = 92k
Gestetner DSC460	185872	224	PC(FIERY E-7000) E()	Black meter = 27k, color meter = 197k
Gestetner DSC460	185873	329	PC(FIERY E-7000) E()	Black meter = 41k, color meter = 289k
Gestetner DSC460	187894	906	PU(TYPE 3260) FN(SR980)	Black meter = 276k, color meter = 631k
Gestetner CS555	180068	724	PU(TYPE 3260) PC(FIERY E-7000) FN(SR4000)	Black meter = 597k, color meter = 127k
Gestetner CS555	183323	978	PU(TYPE 3260) PC(FIERY E-7000) FN(SR4000)	Black meter = 635k, color meter = 343k
Gestetner CS555	189421	563	PU(TYPE 3260) PC(FIERY E-7000) FN(SR970)	Black meter = 414k, color meter = 150k
Gestetner DSM721D	181730	55	ST() RADF(DF2010) FAX(TYPE 2000)	
Gestetner DSM725E	180932	142	ST() RADF(DF83)	
Gestetner DSM725E	187878	161	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Toner spilled in top cassette
Gestetner DSM735E	184408	279	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	Off color panels
Gestetner DSM735E	187467	292	ST() PC(TYPE 4500) FAX(TYPE 3045)	
Gestetner DSM735E	187468	377	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM735E	190192	278	PED(PS530) PC(TYPE 4500) E(PT330)	
Gestetner DSM745E	190241	154	ST() PC(TYPE 4500) P(RT45) FN(SR880) FAX(TYPE 3045)	
Gestetner DSC525	183900	157	ST() FN(SR790)	Error code SC750 - tray lift motor error - finisher not tested, black meter = 68k, color meter = 90k
Gestetner DSC525	184814	290	PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 214k, color meter = 77k
Gestetner DSC525	185880	170	ST() FN(SR3010)	Finisher top panel yellow, black meter = 132k, color meter = 39k
Gestetner DSC525	192681	N/A	ST() FAX(TYPE MPC3000)	Touch screen not responding - not fully tested; hard drive removed
Gestetner DSC530	181493	264	ST() PS(TYPE C3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Black meter = 207k, color meter = 58k
Gestetner DSC530	184915	244	ST() FN(SR3010) FAX(TYPE MPC3000)	Control panel yellow, black meter = 191k, color meter = 53k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSC530	184916	295 ST()	FN(SR3010) FAX(TYPE MPC3000)	Black meter = 154k, color meter = 141k
Gestetner DSC530	184917	265 ST()	FN(SR3010) FAX(TYPE MPC3000)	Black meter = 123k, color meter = 142k
Gestetner DSC530	192336	667 ST()		Missing toner bottles- tested with others, Black meter = 616k, color meter = 52k
Gestetner DSC535	185617	816 PS(TYPE C4500)	PED(PB3000) FN(SR3030)	Bypass tray broken, black meter= 515k, color meter = 301k
Gestetner DSC545	185442	323 PED(PB3000)	FN(SR3020) FAX(TYPE MPC4500)	RADF jamming when reversing, jamming in punch unit, black meter = 258k, color meter = 65k
Gestetner DSC545	186580	330 PU(TYPE 3260)	PS(TYPE C4500) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 159k, color meter = 171k
Gestetner DSC545	186658	566 PU(TYPE 3260)	PED(PB3000) FN(SR3030)	Black meter = 482k, color meter = 85k
Gestetner DSC545	187775	1090 PU(TYPE 3260)	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Jamming in bypass, jamming in duplexer, jamming in stapler, black meter = 631k, color meter = 460k
Gestetner DSC545	191921	697 PU(TYPE 3260)	PED(PB3000) FN(SR3020)	Error code SC547 - zero cross error, fuser relay, 24 volt fuse on PSU, , cassette #3 will not close, black meter = 536k, color meter = 162k
Gestetner DSC545	192208	601 PED(PB3010)	FN(SR3020)	Jamming in finisher - not tested, black meter = 530k, color meter = 72k
Gestetner DSC545	192585	377 ST()	PU(TYPE 3260) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 317k, color meter = 60k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.