

Wulff Enterprises

07/29/2010

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner 10502	156814	6057	PU(TYPE 850) P(RT42) FN(SR810)	Missing finisher entrance guide; offcolor & very dirty panels; lower paper deck panel scratched
Gestetner DSM415PF	157333	47		Yellowed panels
Gestetner DSM615	157121	115	ADF(DF78)	Jamming in bypass; off color and dirty; jamming in machine
Gestetner DSM635	153432	88	ST() PU(TYPE 1045) PC(TYPE 2045E) FN(SR880)	Off color panels; RADF tray cracked
Gestetner DSM635	153558	74	ST() FN(SR880) FAX(TYPE 2045E)	
Gestetner DSM725	157331	175	ST() RADF(DF83) PC(TYPE 3030 (S))	Bypass tray broken off machine; yellowed RADF panels
Gestetner DSM735	156842	434	ST()	Serial number has been removed (electronic s/n matches)
Gestetner DSC424	126842	190	ST()	
Gestetner 3235E	155928	497	ST() RADF(DF67) FN(SR720) FAX(TYPE 450E)	Error code SC322 (laser synch 1 problem); cracked RADF tray; offcolor panels
Gestetner CS555	152241	2058	FN(SR970)	Error code SC-520 - fuser motor; black meter = 1784k; color meter = 274k
Gestetner DSM416	157276	9		
Gestetner DSM416PF	157100	12	ST()	Print & fax do not show up under user tools (no config page or jurnal printed)- both show up when you press print & fax buttons
Gestetner DSM721D	157273	93	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Gestetner DSM721D	157274	115	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Goes into error code SC591 (toner supply motor) after every copy; broken cooling fan vent in back panel; offcolor panels
Gestetner DSM721D	157275	158	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Offcolor panels
Gestetner DSM725E	155413	120	ST() RADF(DF83) PC(TYPE 3010)	
Gestetner DSM725E	157336	37	ST() RADF(DF83) FN(SR820)	Missing hard drive; error code SC541 (fuser thermistor or low line voltage)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM730E	157334	112 ST()	RADF(DF83) FN(SR820)	Missing hard drive; fuser roller is broken loose & fuser unit will not set
Gestetner DSM735E	157335	319 FN(SR790)		Offcolor panels
Gestetner DSC545	145164	710 PED(PB3010)	FAX(TYPE MPC4500)	Finisher jamming during finisher functions
Gestetner DSC545	149618	622 PS(TYPE C4500)	PED(PB3010) FN(SR3030)	Ran fine, now touch screen is locked up; Black meter = 499k; color meter = 124k
Gestetner DSC545	152717	N/A ST()	FN(SR790) FAX(TYPE MPC4500)	Touch screen stopped working; Jamming in duplexer
Gestetner DSC545	152719	243 ST()	FAX(TYPE MPC4500)	False jam in fuser - not tested; black meter = 142k; color meter = 102k
Gestetner DSC545	152721	791 ST()	FAX(TYPE MPC4500)	Black meter = 504k; color meter = 288k
Gestetner DSC545	152722	279 ST()	FAX(TYPE MPC4500)	Black meter = 181k; color meter = 98k
Gestetner DSC545	153425	N/A ST()	FN(SR3020)	Touch screen inop - not tested; Has fiery E-5000 controller
Gestetner DSC545	154043	221 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	False jam in stapler - stapler not tested; black meter = 108k; color meter = 114k
Gestetner DSC545	154809	265 PS(TYPE C4500)	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Jams when combining duplex & stapling; color = 152k; B/W = 114k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.