

Wulff Enterprises

02/10/2012

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner 3502	191355	1613	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) P(RT36) panels NIC(TYPE 1045) FN(SR720) FAX(TYPE 1045)	Jammin in stapler - not tested, yellow
Gestetner 4502	191360	973	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR760) FAX(TYPE 1045)	Bypass tray broken, yellow panels
Gestetner 6002	191363	1102	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Error code SC542 - fuser temp to olow - not tested, Cassette #3 - not tested - partition missing
Gestetner 7502	191367	1419	PU(TYPE 1075) PC(TYPE 1075[S])	Has SR861 finisher (works OK)
Gestetner 7502	191403	1614	PC(TYPE 1075[S]) FN(SR850)	
Gestetner DSM415	190454	98		ADF tray broken, ADF yellow
Gestetner DSM618D	191381	173	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE	Jamming in duplexer
Gestetner DSM618D	191408	135	ST() RADF(DF79)	RADF yellow
Gestetner DSM620D	191105	469	ST() RADF(DF79) PFU(PS460) PC(TYPE 2018)	Yellow panels, PFU connector cover missing
Gestetner DSM620D	191106	291	ST() RADF(DF79) PC(TYPE 2018)	RADF off color
Gestetner DSM620D	191394	317	ST() RADF(DF79) PC(TYPE 2018)	
Gestetner DSM627	191401	538	ST() RADF(DF75) PC(TYPE 2027) FN(SR790) FAX(TYPE 2027)	Off color panels
Gestetner DSM635	192476	236	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	Yellow panels
Gestetner DSM651	190485	3916	PC(TYPE 2075) E()	Missing tandem tray left side paper fence; broken fuser unit release handle; missing serial tag; exit overflow actuator displaced
Gestetner DSC338	189975	384	PED(PS550) FN(SR920) FAX(TYPE 2238)	Yellow panels, black meter = 365k, color meter = 19k
Gestetner DSM725	182569	209	ST() RADF(DF83)	RADF yellow

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(TYPE 3030)	
Gestetner DSM725	183195	248 ST()	RADF(DF83) PC(TYPE 3030 (S))	RADF and control panel yellow
Gestetner DSM725	186900	157 ST()	RADF(DF83) FN(SR820)	Does not recognize staples in stapler - not tested, RADF yellow
Gestetner DSM725	189054	292 ST()	RADF(DF83)	Yellow control panel, RADF yellow
Gestetner DSM725	190214	928 ST()	RADF(DF83) PC(TYPE 3030 (S))	Toner spilled in cassettes, bypass tray broken, RADF off color
Gestetner DSM725	191391	82 ST()	RADF(DF83) FAX(TYPE 3030)	
Gestetner DSM735	186874	59 ST()		
Gestetner DSM735	190833	259 ST()	PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Error code SC819 - control board, system program or optional board - appeared after testing
Gestetner DSM735	191108	154 ST()	PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM735	191532	361 PU(TYPE 1045)	PED(PS530) FN(SR880)	Finisher tray cracked, very dirty and off color
Gestetner DSM735	191533	293 PU(TYPE 1045)	PED(PS530) FN(SR880)	Off color and dirty
Gestetner DSM735	191963	488 ST()		Yellow and dirty panels
Gestetner DSM745	190784	299 PED(PS530)	PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Gestetner DSM745	190785	233 PED(PS530)	PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Gestetner DSM745	190786	304 PED(PS530)	PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Gestetner DSC428	186875	90 PED(PS590)	FAX(TYPE 3245) E(PT460)	Needs black toner - not tested, black meter = 67k, color meter = 24k
Gestetner DSC428	191110	521 PS(TYPE 3245)	PED(PS580) FN(SR960) FAX(TYPE 3245) E(PT460)	Off color panels, black meter = 313k, color meter = 208k
Gestetner DSC445	181253	1117 PED(PS580)	E(PT460)	Yellowed panels; color = 541k; B/W = 577k
Gestetner DSC445	188706	240 ST()	PU(TYPE 2238) FN(SR960) FAX(TYPE 3245) E(PT460)	Jams in area Z1 every try- can't test; off color & dirty panels
Gestetner DSC460	179904	510 PU(TYPE 3260)	FN(SR4000)	Black meter = 291k, color meter = 220k
Gestetner DSC460	191393	1163 PU(TYPE 3260)	PC(FIERY E-7000) FN(SR4000)	No magenta or yellow on color copies, black meter = 135k, color meter = 1029k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM725E	192466	316 ST()	RADF(DF83) PC(TYPE 3010) FN(SR790)	
Gestetner DSM735E	190451	889 PED(PS530)	FN(SR790)	Control panel very yellow
Gestetner DSM735E	190452	638 PED(PS530)	FN(SR790)	
Gestetner DSM745E	184131	645 ST()	PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	Finisher tray out of alignment - finisher not tested
Gestetner DSM745E	184132	828 ST()	PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM745E	184133	671 ST()	PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM745E	184135	707 ST()	PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Gestetner DSM755	190457	3958 PC(TYPE 7500)	FN(SR4000)	Jamming in duplexer - not tested
Gestetner DSC525	185242	659 ST()	FN(SR790)	Yellow panels, black meter = 484k, color meter = 175k
Gestetner DSC525	185789	258 ST()		Black meter = 221k, color meter = 37k
Gestetner DSC525	186722	724 ST()	FN(SR790)	Black meter = 603k, color meter = 121k
Gestetner DSC525	191390	459 ST()		Black meter = 341k, color meter = 119k
Gestetner DSC530	192790	989 PED(PB3010)	FN(SR3000) FAX(TYPE MPC3000)	Finisher panel below entrance bent, black meter = 972k, color meter = 18k
Gestetner DSC535	179573	605 ST()	FAX(TYPE MPC4500)	Error code SC-792 - finisher communication error - missing finisher, black meter = 416k, color meter = 189k
Gestetner DSC535	184477	576 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Black meter = 468k, color meter = 108k
Gestetner DSC535	191111	519 ST()	FN(SR790)	Control panel yellow, RADF inverter broken gate - RADF not tested, right finisher hook missing, black meter = 407k, color meter = 112k
Gestetner DSC545	184138	515 ST()	PU(TYPE 3260) FN(SR3020) FAX(TYPE MPC4500)	Error code sc819 -Kernel Mismatch, Download Firmware again, black meter = 333k, color meter = 183k
Gestetner DSC545	192597	627 PED(PB3010)	FAX(TYPE MPC4500)	Error code SC564- fuser pressure roller overheat - yellow control panel, black meter = 527k, color meter = 101k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.