

# Wulff Enterprises

07/29/2010

## GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C2230	153273	241	RADF(DP-621) PED(PF-621) FN(DF-626) DX(DU-621)	Black meter = 152k; color meter = 90k
Kyocera KM-C2230	155089	189	RADF(DP-621) PED(PF-621) DX(DU-621)	Black meter = 95k; color meter = 95k
Kyocera KM-C2230	155090	67	ST() RADF(DP-621) DX(DU-621)	Black meter = 21k; color meter = 46k
Kyocera KM-C2230	155094	111	RADF(DP-621) PED(PF-621) DX(DU-621)	Black meter = 27k; color meter = 84k
Kyocera KM-C2230	157110	309	ST() RADF(DP-621) DX(DU-621)	Black meter = 238k; color meter = 71k
Kyocera KM-1650	155099	77	ST() RADF(DP-410)	Off color and dirty panels
Kyocera KM-1815	154806	49	ADF(DP-100)	
Kyocera KM-1820	151002	65	ADF(DP-100)	Broken ADF access door- ADF jams every try
Kyocera KM-1820	151596	39	ADF(DP-100)	Jams ever ycopy- can't test; offcolor & dirty panels
Kyocera KM-1820	155447	96	FAX(K) ADF(DP-100)	Off color and dirty panels
Copystar CS-1820	156028	45	FAX(K) ADF(DP-100)	Offcolor & dirty panels
Copystar CS-1820	156029	28	FAX(K) ADF(DP-100)	Offcolor & dirty panels
Copystar CS-1820	156030	81	FAX(K) ADF(DP-100)	
Kyocera KM-1820	156706	27	ADF(DP-100)	Off color panels
Kyocera KM-1820	156707	12	ADF(DP-100)	Error code C3200 - exposure lamp, scan board, inverter board, shading plate position, connections; off color panels
Kyocera KM-2050	148182	95	ST() SCAN(F) RADF(DP-410) FAX(L) E(JS-410) DX(DU-410)	Off color panels; errors out when trying to print config page
Kyocera KM-2050	151292	16	RADF(DP-410) DX(DU-410)	Offcolor & dirty panels
Kyocera KM-2050	152464	74	ST() RADF(DP-410) DX(DU-410)	Offcolor & dirty panels; paint spray all over panels
Kyocera KM-2050	153417	171	ST() RADF(DP-410) DX(DU-410)	Off color panels
Kyocera KM-2050	153448	214		
Kyocera KM-2050	154479	113	RADF(DP-410) DX(DU-410)	Off color panels
Kyocera KM-2050	154599	33	ST() RADF(DP-410) FAX(L)	Offcolor & dirty panels
Kyocera KM-2050	154810	133	ST() RADF(DP-410)	Offcolor panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			DX(DU-410)	
Kyocera KM-2050	155749	N/A	ST() RADF(DP-410) FAX(L)	
Kyocera KM-2050	156433	165	ST() SCAN(F) RADF(DP-410) DX(DU-410)	
Kyocera KM-2050	156434	167	ST() RADF(DP-410) FAX(L) DX(DU-410)	
Kyocera KM-2050	156710	86	ST() SCAN(F) RADF(DP-410) PFU(PF-410 [A]) FAX(L) DX(DU-410)	Off color panels
Kyocera KM-2050	157114	119	ST() RADF(DP-410) FAX(L) DX(DU-410)	Off color and dirty panels
Kyocera KM-2550	151304	279	ST() SCAN(F) RADF(DP-410) FAX(L) E(JS-410) DX(DU-410)	Offcolor panels
Copystar CS-2550	153571	288	ST() SCAN(F) RADF(DP-410) FAX(L) DX(DU-410)	Off color panels
Kyocera KM-2550	153991	274	ST() RADF(DP-410) DX(DU-410)	Yellow panels
Kyocera KM-2550	153992	282	ST() RADF(DP-410) DX(DU-410)	Yellow panels
Kyocera KM-2550	154067	149	ST() RADF(DP-410) FAX(L) DX(DU-410)	Paper guide broken off & missing in top paper tray- inop
Kyocera KM-2550	154468	123	ST() SCAN(F) RADF(DP-410) FAX(L) DX(DU-410)	Off color panels; RADF not feeding - not tested
Kyocera KM-2550	155051	31	ST() RADF(DP-410)	Almost no image on copies
Kyocera KM-2550	155105	89	ST() RADF(DP-410) DX(DU-410)	
Copystar CS-2550	156325	211	ST() RADF(DP-410) FN(DF-410) FAX(L) E(JS-410) DX(DU-410)	Off color panels
Copystar CS-2550	156925	257	ST() RADF(DP-410) FN(DF-410) DX(DU-410)	Front door latch broken; off color panels
Kyocera KM-3050	156708	216	RADF(DP-700) PED(PF-750) FN(DF-730)	Off color panels; fax cover panel missing
Kyocera KM-3050	156709	280	ST() RADF(DP-700) FAX(M)	Off color panels
Kyocera KM-4050	154070	564	ST() RADF(DP-700) FN(DF-730)	
Kyocera KM-5050	154068	951	RADF(DP-700) PU(PH-5A) PED(PF-700) FN(DF-710)	Unable to clear admin login to fully test
Copystar CS-8030	156780	1077	SCAN(G) PC(V) P(PF-650) FN(DF-650)	Touch screen inoperable- cannot test machine

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Copystar CS-8030	156783	2701	SCAN(G) PC(V) P(PF-650) FN(DF-650)	Broken paper deck locking hooks
Kyocera KM-C2520	157079	201	ST() RADF(DP-710)	Touch screen is out of adjustment; offcolor & dirty panels; dented back panel; Color = 20k; B/W = 181k
Kyocera KM-C3225	150437	358	ST() RADF(DP-710)	Black meter = 315k; color meter = 43k
Kyocera KM-C3225	151952	122	ST() RADF(DP-710)	Color = 22k; B/W = 101k
Kyocera KM-C3225	153476	333	ST() RADF(DP-710) PU(PH-5A) FN(DF-710) FAX(N) E(JS-710)	Touch screen inop = not tested
Kyocera KM-C3225	156137	550	RADF(DP-710) FN(DF-730) FAX(N) E(JS-710)	Color = 111k; B/W = 108k; has a PF-710 pedestal (works OK)
Kyocera KM-C3225	156991	144	RADF(DP-710) PED(PF-750)	Color = 48k; B/W = 97k
Mita KM-C2030	148233	334	RADF(DP-620) PU(DF-620) PED(PF-620) PC(FIERY X3E 31) FN(DF-625) DX(DU-620)	Black meter = 21k; color meter = 313k; will not come to ready - not tested
Mita KM-C2030	148374	110	ST() RADF(DP-620)	Looks like duplexer was removed; black metre = 76k; color meter = 34k
Mita KM-C3130	154804	176	RADF(DP-620) PU(DF-620) PFU(ST-530 [B]) PC(FIERY X3E 31) FN(DF-625) DX(DU-620)	Bridge unit is smashed- can't test finisher; offcolor panels; color = 30k; B/W = 147k
Mita KM-C3130	155679	281	ST() RADF(DP-620) PC(FIERY X3E 31) DX(DU-620)	Duplex back lock is broken- will not stay closed; error code C-0045 (colling fan error); offcolor panels
Mita KM-C3130	155729	158	RADF(DP-620) PED(PF-620) PC(FIERY X3E 31) FN(DF-620) DX(DU-620)	Bridge unit is smashed- can't test finisher; offcolor panels; color = 139k; B/W = 19k
Mita KM-C3130	156432	120	RADF(DP-620) PFU(ST-530 [B]) PC(FIERY X3E 31) FN(DF-620) DX(DU-620)	Bridge unit broken - finisher not tested; black meter = 55k; color meter = 65k
Mita KM-1500	153817	16	ADF(DP-100)	Offcolor panels
Mita KM-1810	148989	90		ADF feed tray cracked
Mita KM-1810	148990	886	ST()	ADF paper tray cracked
Mita KM-1810	148993	150	ST()	Off color panels; ADF feed tray cracked
Royal RI-3530	152430	292	ST() RADF(SRDF-2) PC(N)	Back panel dented
Mita KM-4030	146972	401	ST() RADF(SRDF-2) PC(N) FN(DF-71U) DX(AD-63)	
Mita KM-4030	149007	1296	ST() RADF(SRDF-2) FN(DF-71U)	Finisher not recognized - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita KM-4030	149008	1504	ST() RADF(SRDF-2) FN(DF-71U) DX(AD-63)	bypass tray shredding paper - not tested
Copystar CS-4035	156479	221	RADF(SRDF-2) PU(PH-2A) PED(PF-75) FN(DF-73)	
Mita KM-4530	149010	1720	PU(PH-3) FN(DF-610)	Rear panel dented
Mita KM-4530	149011	2021	FN(DF-610)	Error code - C3300 - Exposure lamp, CCD, shading plate position engine board or inverter board - not tested
Mita KM-5530	155572	1509	PC(Q) FN(DF-610)	Shows a false open front door- can't test machine; offcolor panels
Mita KM-5530	155574	1779	PC(Q) FN(DF-610)	Machine shows a false open front door- door is cracked & bent (can't test machine); offcolor panels

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.