

# Wulff Enterprises

02/10/2012

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C2230	189647	62	RADF(DP-621) PED(PF-621) PC(FIERY X3E22C) FN(DF-621) DX(DU-621)	Bridge unit brackets bent - bridge unit and finisher not tested due to bridge unit out of alignment, duplexer bottom cover broken, jamming in duplexer - not tested; color = 31k; B/W = 32k
Copystar CS-1650	188744	200	ST() RADF(DP-410) PFU(PF-410 [A]) DX(DU-410)	
Copystar CS-1650	188745	43	ST() RADF(DP-410) PFU(PF-410 [A]) DX(DU-410)	
Kyocera KM-1650	188746	75	RADF(DP-410) FAX(L)	Yellowed panels
Kyocera KM-1650	192832	265	ST() RADF(DP-410) DX(DU-410)	Missing control panel flipgate for fax options
Kyocera KM-1820	190598	21	ADF(DP-100)	
Copystar CS-1820	191777	17	PFU(PF-17) FAX(K) ADF(DP-100)	Very dirty, broken ADF hinge, Registration off on copies
Kyocera KM-1820	192831	54	FAX(K) ADF(DP-100)	
Kyocera KM-2550	187818	197	ST() SCAN(F) RADF(DP-410) FAX(L) E(JS-410) DX(DU-410)	
Copystar CS-2560	179024	283	ST() RADF(DP-670)	
Kyocera KM-2560	186925	440	ST() RADF(DP-670) FN(DF-730)	
Kyocera KM-2560	186927	374	ST() RADF(DP-670) FN(DF-730)	
Kyocera KM-3040	182824	222	ST() RADF(DP-670) FAX(P) E(JS-670)	
Kyocera KM-3060	182333	250	ST() RADF(DP-670)	Touch screen not responding - not fully tested
Kyocera KM-3060	182349	464	ST() RADF(DP-670)	Touch screen not responding - not fully tested
Kyocera KM-3060	182351	336	ST() RADF(DP-670)	Touch screen not responding - not fully tested
Kyocera KM-3060	183905	634	ST() RADF(DP-670) FAX(M)	Right side panel broken, back panel dented
Kyocera KM-3060	186929	417	ST() RADF(DP-670) FN(DF-730) FAX(M)	
Kyocera KM-3060	188754	308	RADF(DP-670) PED(PF-670) FN(DF-730)	Loose platen mat

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(M)	
Copystar CS-5050	192483	262	PU(PH-5A) PED(PF-750) FN(DF-710) DSPF(DP-700)	
Kyocera KM-6030	176468	479	SCAN(G) PC(V) FN(DF-650)	
Kyocera KM-6030	180467	785	PU(PH-4) PC(V) FN(DF-650)	Finisher in error code C8020 (punch motor or finisher board); also shows a false jam in finisher; dented & bent back panel
Kyocera KM-6030	182733	1260	FN(DF-650)	Jamming in stapler - not tested, jamming out of cassette #4
Kyocera KM-6030	183784	1072	PU(PH-4) FN(DF-650)	
Kyocera KM-6030	185451	399	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	
Copystar CS-6030	186948	1847	SCAN(G) PC(V) FN(DF-650)	
Kyocera KM-6030	188734	2061	PU(PH-4) FN(DF-650)	Finisher in error code C8140 (elevator motor problem); touch screen inoperable- unable to fully test; control panel will not lock in place
Kyocera KM-6030	188735	N/A	PU(PH-4) FN(DF-650)	Touch screen inoperable- unable to clear account code to test
Kyocera KM-6030	188736	1216	PU(PH-4) FN(DF-650)	Tray #2 will not feed; dented & holes in right side panel
Kyocera KM-6030	188737	671	PU(PH-4) FN(DF-650)	
Kyocera KM-6030	188738	982	PU(PH-4) FN(DF-650)	
Copystar CS-6030	190017	393	SCAN(G) PC(V) FN(DF-650)	Lower right side panel broken, Yellow panels
Kyocera KM-6030	190410	2570	SCAN(G) PC(V) FN(DF-650)	
Kyocera KM-6030	191487	628	SCAN(G) PC(V) FN(DF-650)	Error code C0640 - hard-drive problem - not fully tested
Copystar CS-6030	192351	244	SCAN(G) PC(V) FN(DF-650)	Grinding noise in fuser - not turning - not tested, cassette #2 not recognizing paper
Kyocera KM-6030	192824	345	PU(PH-4) FN(DF-650)	
Kyocera KM-6030	192827	695		Missing finisher - has brackets, jamming in duplexer - not tested
Kyocera KM-8030	187534	441	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	Missing paperdeck - has brackets, right side access panel broken & will not latch- unable to fully test machine, saddlestitch tray broken - not fully tested
Kyocera KM-8030	187803	4439	P(PF-650) FN(DF-650)	
Kyocera KM-8030	187804	4801	P(PF-650) FN(DF-650)	Paper deck not feeding paper - not

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				tested, stapler inop (not detecting cartridge)
Kyocera KM-8030	187805	1998	PU(PH-4) P(PF-650) FN(DF-650)	
Kyocera KM-8030	192795	361	SCAN(G) PC(V)	Jamming out of cassette #2 - not tested, missing finisher - has brackets
Kyocera KM-C2520	187545	113	ST() RADF(DP-710)	Cassette #2 not feeding -not tested, duplexer makes noise, black meter = 87k, color meter = 26k
Kyocera KM-C2520	189388	405	ST() RADF(DP-710)	Black meter = 226k, color meter = 180k
Kyocera KM-C2525E	174799	300	ST() RADF(DP-710)	Black meter = 242k; color meter = 59k
Kyocera KM-C2525E	180131	468	ST() RADF(DP-710) FN(DF-710)	Black meter = 320k, color meter = 149k
Kyocera KM-C2525E	180199	124	ST() RADF(DP-710)	Control panel cover broken, touch screen out of alignment, black meter - 110k, color meter = 15k
Kyocera KM-C2525E	182199	238	ST() RADF(DP-710) FAX(N) E(JS-710)	Black meter = 184k, color meter = 55k
Kyocera KM-C2525E	183909	361	ST() RADF(DP-710)	Black meter = 269k, color meter = 92k
Kyocera KM-C2525E	184100	270	ST() RADF(DP-710)	Jamming in fuser - not tested, black meter = 157k, color meter = 114k
Copystar CS-C2525E	187084	149	ST() RADF(DP-710)	Black meter = 61k, color meter = 89k
Kyocera KM-C2525E	187535	169	ST() RADF(DP-710)	Black meter = 102k, color meter = 68k
Kyocera KM-C2525E	189031	142	ST() RADF(DP-710)	Needs magenta toner - goes in to cycle toner mode and does not allow printing, black meter = 132k, color meter = 10k
Kyocera KM-C2525E	192093	267	ST() RADF(DP-710)	Jamming in cassette #2 - not tested, black meter - 131k, color meter =
Copystar CS-C3225	173686	271	RADF(DP-710) PED(PF-710)	Black meter = 161k; color meter = 110k; looks like it had a finisher; back panel scraped
Kyocera KM-C3225	177651	1039	ST() RADF(DP-710)	Fax report printing solid black - no image, black meter = 1020k; color meter = 19k
Copystar CS-C3225	178047	368	ST() RADF(DP-710) FAX(N) E(JS-710)	Black meter = 204k; color meter = 164k
Kyocera KM-C3225	182566	118	RADF(DP-710) PED(PF-750) FN(DF-710) FAX(N)	Black meter = 67k, color meter = 51k
Copystar CS-C3225	182829	223	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710) E(JS-710)	Jamming at paper deflector - finisher nor duplexer tested, jamming out of cassettes #2
Kyocera KM-C3225	183083	395	ST() RADF(DP-710)	Black meter = 207k, color meter = 178k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C3225	184127	1513	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710)	Cassette #2 will not feed, cassette #1 handle broken
Copystar CS-C3225	184656	1154	ST() RADF(DP-710)	Jamming in RADF - not tested, black meter = 233k, color meter = 922k
Kyocera KM-C3225	185142	555	ST() RADF(DP-710) FN(DF-730)	Black meter = 502k, color meter = 54k
Kyocera KM-C3225	186452	51	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710)	Cassette #2 jamming, black meter = 42k, color meter = 10k
Kyocera KM-C3225	187795	310	RADF(DP-710) PED(PF-750)	Cassette #2 will not feed paper, black meter = 88k, color meter = 223k
Kyocera KM-C3225	187826	319	ST() RADF(DP-710) PU(PH-5A) FN(DF-710) FAX(N)	RADF does not recognize paper - not tested, does not allow duplexing, stapler and punch unit - not tested, black meter = 249k, color meter = 71k
Kyocera KM-C3225	190228	341	ST() RADF(DP-710) PU(PH-5A) FN(DF-710) E(JS-710)	Right panel cracked, finisher door scraped, left side access door broken - jamming out of cassette #2, jamming in finisher - not tested, black meter = 206k, color meter = 135k
Kyocera KM-C3225	192352	352	RADF(DP-710) PED(PF-750) FN(DF-710) FAX(N) E(JS-710)	Black meter = 313k, color meter = 39k
Kyocera KM-C3225E	184095	339	ST() RADF(DP-710) FN(DF-730) FAX(N) E(JS-710)	Black meter = 283k, color meter = 56k
Kyocera KM-C3225E	186932	245	ST() RADF(DP-710)	Black meter = 219k, color meter = 27k
Kyocera KM-C3225E	187356	192	ST() RADF(DP-710)	Black meter = 65k, color meter = 127k
Kyocera KM-C3225E	188639	547	RADF(DP-710) PED(PF-710) FN(DF-730) FAX(N) E(JS-710)	Left door on finisher not hitting interlock switch, stapler inop, RADF pins broken, black meter = 545k, color meter - 2k
Kyocera KM-C3225E	188640	220	RADF(DP-710) PED(PF-710) FN(DF-730) FAX(N) E(JS-710)	Black meter = 216k, color meter = 4k fax journal prints out completely black
Kyocera KM-C3225E	191399	180	ST() RADF(DP-710) FN(DF-730) FAX(N) E(JS-710)	Black meter = 32k, color meter = 149k, stand frame bent
Kyocera KM-C3225E	192194	633	RADF(DP-710) PED(PF-750) FN(DF-730) FAX(N) E(JS-710)	Black meter = 553k, color meter = 81k
Copystar CS-C3232	177976	584	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710) FAX(N)	RADF brackets bent- not tested, jamming in bypass, very dirty, black meter = 543k; color meter = 42k
Kyocera KM-C3232	183555	133	RADF(DP-710) PED(PF-750) FN(DF-710)	Exit paper sensor sticking, black meter = 41k, color meter = 92k
Copystar CS-C3232	189474	492	RADF(DP-710) PED(PF-710) FN(DF-710)	Blank copies, jamming in duplexer and stapler, black meter = 67k, color

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			E(JS-710)	meter = 425k
Kyocera KM-C3232	189613	267 ST()	RADF(DP-710) FN(DF-710) E(JS-710)	Error code C6030 - fuser thermistor error
Copystar CS-C3232	191011	358 ST()	RADF(DP-710) FAX(N) E(JS-710)	Missing finisher - has brackets, black meter = 130k, color meter = 229k
Copystar CS-C3232E	174797	179	RADF(DP-710) PED(PF-710)	Color = 88k; B/W = 91k
Copystar CS-C3232E	176323	140 ST()	RADF(DP-710)	Color = 9k; B/W = 132k
Copystar CS-C3232E	176846	92 ST()	RADF(DP-710)	Black meter = 48k; color meter = 45k
Copystar CS-C3232E	181670	238 ST()	RADF(DP-710)	Black meter - 91k, color meter = 147k
Copystar CS-C3232E	189473	307	RADF(DP-710) PED(PF-750) FN(DF-730) E(JS-710)	False jam in finisher - not teste, finisher top access door bent - will not latch, black meter 141k, color meter = 166k
Kyocera KM-C3232E	190373	161	RADF(DP-710) PED(PF-710) FN(DF-710) FAX(N) E(JS-710)	Jamming out of cassette #2 - not tested, bypass jamming, bottom trim panel broken, black meter= 111k, color meter = 50k
Kyocera KM-C4008	183037	153 ST()	RADF(SRDF-2) FAX(G)	Black meter = 134k, color meter = 19k, Dirty and off color panel
Kyocera KM-C4035E	176340	162	RADF(DP-710) PU(PH-5A) FOLD(BF-710) FN(DF-710)	Has a PF710 pedestal (works OK); color = 61k; B/W = 101k
Kyocera KM-C4035E	178182	242	RADF(DP-710) PED(PF-750) FN(DF-710) FAX(N)	Fax board not activating; color = 21k; B/W = 218k
Kyocera KM-C4035E	181217	219	RADF(DP-710) FN(DF-730) E(JS-710)	Has PF-710 PED, black meter = 16k, color meter = 204k
Kyocera KM-C4035E	181218	194	RADF(DP-710) FN(DF-730)	Has PF-710 PED, black meter = 10k, color meter = 185k
Copystar CS-C4035E	183868	269	RADF(DP-710) PED(PF-750) FN(DF-710)	Cassette #2 will not feed - not tested, control panel loose, deep scratches on RADF, black meter = 166k, color meter = 104k
Kyocera KM-C4035E	183911	N/A		Black meter = 274k, color meter = 279k, paint on Finisher top panel
Copystar CS-C4035E	185131	276	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710)	Black meter = 165k, color meter = 111k
Kyocera KM-C4035E	185464	323	RADF(DP-710) PED(PF-700) FN(DF-730)	Back panel scratched, black meter = 270k, color meter = 54k
Kyocera KM-C4035E	188473	548	RADF(DP-710) PED(PF-750) FN(DF-710)	Black meter = 434k, color meter = 115k, front door of finisher gouged
Kyocera KM-C4035E	189008	340	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710) E(JS-710)	Black meter = 299k, color meter = 42k
Mita KM-3035	187376	1080	RADF(SRDF-2) PED(PF-75) PC(U)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(DF-73)	
Mita KM-3035	188978	403	ST() RADF(SRDF-2) PC(U) FAX(J) E(J-1402)	Jamming out of cassette #2 - not tested
Mita KM-3035	190815	912	ST() RADF(SRDF-2) PC(U) FN(DF-73) FAX(J)	Off color and dirty
Mita KM-3035	190867	535	RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-73)	Cassette #3 not lifting - not tested, bypass tray broken
Mita KM-3035	191486	192	ST() RADF(SRDF-2)	Slit glass broken at top, platen glass chipped on right side
Mita KM-3035	192825	136	ST() RADF(SRDF-2)	
Mita KM-3035	192826	378	ST() RADF(SRDF-2) FAX(J) E(J-1402)	
Mita KM-3035	192828	140	ST() RADF(SRDF-2)	
Mita KM-4035	188634	N/A	ST() RADF(SRDF-2) PC(U)	Will not power up -not tested; dented back panel
Mita KM-4035	188981	170	RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-71U) FAX(J) E(J-1402)	Error code C0640 - hard-drive error - hard-drive missing, fan cover missing
Mita KM-4035	188984	124	ST() RADF(SRDF-2) PC(U) FN(DF-71U) FAX(J) E(J-1402)	Error code C2500 - paper feed motor error, hard-drive removed
Mita KM-4035	188986	192	RADF(SRDF-2) PED(PF-75) PC(U) FAX(J) E(J-1402)	Error code C0640 - hard-drive - hard-drive removed
Mita KM-4035	189615	1191	RADF(SRDF-2) PED(PF-75) PC(U) FAX(J)	
Copystar CS-4035	192788	N/A	RADF(SRDF-2) PED(PF-70) PC(U)	Very dirty inside machine, will not power up - not tested
Mita KM-4035	192823	186	RADF(SRDF-2) PED(PF-75) PC(U)	
Mita KM-5035	184554	1383	ST() PC(U) FN(DF-71U) FAX(J)	
Mita KM-5035	185364	1152	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Yellow finisher panels
Mita KM-5035	187292	1617	ST() RADF(SRDF-2) PC(U) FN(DF-73)	Jamming in bypass, finisher top access door broken, yellow
Mita KM-5035	187807	2592	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Jamming at verticle transport - not tested, finisher has only one stapler unit
Mita KM-5035	187808	1851	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Front door interlock out of alignment, touch screen pushed in
Mita KM-5035	187809	2677	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Jamming in bypass tray, left side access door broken

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita KM-5035	187810	3058	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	
Mita KM-5035	187811	2426	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Very light copies (almost no image)
Mita KM-5035	187812	1494	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Jamming in duplexer
Mita KM-5035	187813	2605	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Error code C8010 - finisher paper conveying motor - stapler & punch not tested
Mita KM-5035	187814	1789	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Finisher front door interlock bent & out of alignment
Copystar CS-5035	191775	254	STK(M-2107) RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-71U) FAX(J)	Jamming in finisher entrance - not tested, yellow finisher panels
Mita KM-5035	192353	550	ST() RADF(SRDF-2) PC(U) FN(DF-71U)	Finisher yellow
Copystar CS-5530	185143	1458	SCAN(D) PC(Q) FN(DF-610)	Finisher plug insulation pulled away from socket - finisher not tested, cassette #4 not recognizing paper, yellow panels, error code C0240 - PC not tested
Copystar CS-5530	188732	759	PU(PH-3) FN(DF-610)	Showing a false open cover- can't test; yellowed panels; finisher plug wires pulled away from plug
Copystar CS-5530	188733	123	SCAN(D) PC(Q) E()	Dented lower back panel and frame may be slightly bent
Mita KM-5530	190810	1401	PC(Q) FN(DF-610)	False door indicator in finisher - not tested, yellow panels
Mita KM-6330	190620	800	SCAN(D) PU(PH-3) PC(R) FN(DF-610)	Finisher yellow

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.