

# Wulff Enterprises

01/07/2009

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C2230	122566	50	ST() RADF(DP-621) PC(FIERY X3E22C) DX(DU-621)	Color = 41k; B/W = 10k
Mita KM-8530	122971	629	P(LT-402) FN(DF-635)	Paper deck in false jam code- inop; has inserter unit
Kyocera KM-1820	124954	57		
Kyocera KM-C2630D-B	117615	537	RADF(SRDF-2)	Missing fuser rails causing machine to jam every copy; color = 92k; B/W = 445k
Kyocera KM-C850D	123289	125	RADF(SRDF-2) PED(PF-35) PC(S) FN(DF-35) FAX(G)	Missing attachment kit for finisher (not tested); color = 6k; B/W = 119k
Mita KM-C2030	116475	167	ST() PC(FIERY X3E 31) DX(DU-620)	Crushed power cable between scanner & main unit- spliced together to test; color = 155k; B/W = 13k
Mita KM-C2030	122979	344	RADF(DP-620) PED(PF-620) PC(FIERY X3E 31) FN(DF-620) DX(DU-620)	Color = 132k; B/W = 213k
Mita KM-C2030	124706	84	RADF(DP-620) PFU(ST-530 [B]) FN(DF-620) DX(DU-620)	Missing bridge unit- can't test finisher; broken RADF plug socket; duplex unit will not latch- held shut for testing; trays #2 & #3 will not feed- rollers seized up; tray #4 will not detect paper- inop
Mita KM-C3130	118267	582	RADF(DP-620) PU(DF-620) PFU(ST-530 [B]) PC(FIERY X3E 31) FN(DF-625) DX(DU-620)	Bridge unit gears broken off- can't test finisher; bypass tray broken off; color = 135k; B/W = 447k
Mita KM-C3130	120048	565	RADF(DP-620) PU(DF-620) PED(PF-620) PC(FIERY X3E 31) FN(DF-625) DX(DU-620)	Color = 174k; B/W = 392k
Mita KM-C3130	123588	1351	RADF(DP-620) PFU(ST-530 [B]) PC(FIERY X3E 31) FN(DF-625) DX(DU-620)	Finisher damaged- broken paper guide, broken top access panel, front panel broken off, wiring damaged at plug; cracked control panel on right side; bridge unit plug socket pushed into machine; broken RADF, finisher & pedestal plug sockets; cracked back panel; broken fuser cover; blurred copies; offcolored panels; color = 638k; B/W = 713k
Mita CI 7500	118685	52		Cannot get passed access code -not tested; sc c0920- upper drawer lift

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				problem; rear panel dented; missing top drawer front cover; dent on right side panel; missing exit tray; Black meter =5k; colored meter =48k
Mita AI 2310	119522	225	RADF(SRDF-1) PED(ST-10) FN(F-3130) DX(AD-60)	Finisher tray mount stuck in lower position & will not raise; missing finisher tray; yellowed panels
Mita AI 2310	120575	234	ST() RADF(SRDF-1) FN(F-3130) DX(AD-60) B()	Offcolored & dirty panels
Royal 2310	121745	299	ST() RADF(SRDF-1) FAX(A) E(J-1202) DX(AD-60) B()	Broken RADF plug socket
Mita AI 3010	119523	331	ST() RADF(SRDF-1) DX(AD-60) B()	Missing finisher; broken RADF plug socket
Royal 3010	121181	401	ST() RADF(SRDF-1) DX(AD-60) B()	Missing developer unit- can't test; offcolored panels
Mita AI 3010	121921	223	RADF(SRDF-1) PED(ST-10) B()	Machine in false jam code due to left side access door not staying shut; yellowed panels
Royal 3010L	118684	70	ST() RADF(SRDF-1) FN(F-3130) DX(AD-60)	RADF socket broken
Mita AI 3010L	119005	455	ST() RADF(SRDF-1) FAX(A) DX(AD-60) B()	Yellowed panels
Mita AI 3010L	119006	451	ST() RADF(SRDF-1) FAX(A) DX(AD-60) B()	Missing finisher (has brackets); yellowed panels
Royal 3010L	120744	139	ST() RADF(SRDF-1) FN(F-3130) FAX(A) E(J-1202) DX(AD-60) B()	Error code C710 (toner sensor); broken RADF plug socket; broken finisher panel; yellowed panels
Copystar CS-1500	119411	57		
Mita KM-1510	123364	N/A	PC(M) NIC(IB-20)	Error code E-70 (SDF error); cracked & broken SDF hinges
Mita KM-1510	123365	33		
Mita KM-1510	123366	209		Yellowed panels
Mita KM-1510	123367	26		Yellowed panels
Mita KM-1510	123504	10		Goes into error code C710 (toner sensor) when copying; broken SDF hinge
Mita KM-1510	123505	59		Goes into error code C710 (toner sensor) when copying
Mita KM-1510	123507	47		SDF will not detect paper- inop
Mita KM-1510	123508	27		
Mita KM-1510	123509	31		Goes into error code C710 (toner sensor) when copying; broken SDF hinges
Mita KM-1510	123864	27		SDF not functioning properly;

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				yellowed panels
Copystar CS-1530	119415	95 ST()	PFU(ST-12 [B]) ADF(STDF-3)	
Copystar CS-1530	119959	52 ST()	PFU(ST-12 [A]) ADF(STDF-3)	Yellowed ADF panels
Copystar CS-1530	119960	91 ST()	PFU(ST-12 [A]) ADF(STDF-3)	
Copystar CS-1530	119961	48 ST()	PFU(ST-12 [A]) ADF(STDF-3)	
Copystar CS-1530	119962	46 ST()	PFU(ST-12 [A]) ADF(STDF-3)	
Copystar CS-1530	119963	73 ST()	PFU(ST-12 [A]) ADF(STDF-3)	
Copystar CS-1530	119964	83 ST()	PFU(ST-12 [A]) ADF(STDF-3)	
Copystar CS-1530	119965	49 PFU(ST-12 [A])	ADF(STDF-3)	
Mita KM-1530	124493	274		
Copystar CS-2030	111327	235 ST()	RADF(SRDF-1) E(J-1302) DX(AD-61)	Yellowed panels
Copystar CS-2030	111328	178 ST()	RADF(SRDF-1) E(J-1302) DX(AD-61)	Yellowed panels
Mita KM-2030	112508	200 RADF(SRDF-1)	PFU(ST-12 [A]) E(J-1302) DX(AD-61)	Missing back duplex bracket
Copystar CS-2030	113404	156 RADF(SRDF-1)	E(J-1302) DX(AD-61)	
Mita KM-2030	114406	88 ST()	ADF(STDF-3)	
Mita KM-2030	114415	403 ADF(STDF-3)		Broken ADF access door
Mita KM-2030	115394	101 ST()	FAX(B) E(J-1302) ADF(STDF-3)	
Mita KM-2030	115667	122 ST()	RADF(SRDF-1) E(J-1302) DX(AD-61)	
Mita KM-2030	116630	85 ST()	RADF(SRDF-1) E(J-1302) DX(AD-61)	Duplex inop
Mita KM-2030	117027	333 ST()	RADF(SRDF-1) E(J-1302) DX(AD-61)	Yellowed panels
Mita KM-2030	119414	153 ST()	RADF(SRDF-1) E(J-1302) DX(AD-61)	Offcolored panels
Mita KM-2030	119657	92 ST()	RADF(SRDF-1) E(J-1302) DX(AD-61)	
Mita KM-2030	120360	69 ST()		Bent bypass frame- will not detect paper
Mita KM-2030	120461	134 ST()	RADF(SRDF-1) PC(K)	Missing duplex unit; bypass tray

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				broken; stand door broken off hinge; broken left side access door actuator; scratched RADF panels; yellowed & dirty panels
Mita KM-2030	121172	116	ST() RADF(SRDF-1) DX(AD-61)	Jams in fuser; yellowed panels
Mita KM-2530	119082	434	RADF(SRDF-2) PED(PF-70) FN(DF-71U) DX(AD-63)	
Mita KM-2530	119890	118	ST() RADF(SRDF-2) DX(AD-63)	
Mita KM-2530	120079	124	ST() RADF(SRDF-2)	
Royal RI-2530	120243	202	ST() RADF(SRDF-2) FN(DF-75) DX(AD-63)	Missing finisher release handle
Royal RI-2530	121032	146	ST() RADF(SRDF-2)	
Mita KM-2530	121047	814	ST() RADF(SRDF-2) FN(DF-71U) DX(AD-63)	Missing toner cartridge (tested with another)
Mita KM-2530	121701	163	ST() RADF(SRDF-2) PC(N) FN(DF-71U) FAX(C) DX(AD-63)	Stapler inop- cartridge is jammed
Royal RI-2530	122552	732	ST() RADF(SRDF-2) DX(AD-63)	Missing print controller (cover missing); broken RADF access door; broken RADF plug socket; left side access door will not open all the way
Royal RI-2530	122553	62	ST() FN(DF-78) DX(AD-63) ADF(STDF-3)	Missing lift motor in top paper tray causing error code C1010; missing print controller & fax board (covers missing)
Mita KM-2530	123449	246	ST() RADF(SRDF-2) DX(AD-63)	Control panel buttons not functioning- can't test
Mita KM-2530	124487	471	ST() RADF(SRDF-2) FN(DF-78) DX(AD-63)	
Mita KM-3035	119656	206	ST() RADF(SRDF-2)	
Mita KM-3035	119999	160	ST() RADF(SRDF-2)	
Mita KM-3035	120008	328	ST() RADF(SRDF-2)	
Mita KM-3035	120072	659	ST() RADF(SRDF-2)	
Mita KM-3035	120073	293	ST() RADF(SRDF-2)	
Mita KM-3035	120565	111	ST() RADF(SRDF-2)	Broken RADF plug socket
Mita KM-3035	121170	1346	ST() RADF(SRDF-2)	Missing size detection sensor in tray #2 causing it to jam; fax board inop; machine will not power down properly
Mita KM-3035	121216	240	ST() RADF(SRDF-2)	
Copystar CS-3035	121955	526	ST() RADF(SRDF-2)	Broken RADF plug socket
Copystar CS-3035	122099	135	ST() RADF(SRDF-2)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita KM-3035	122275	239	RADF(SRDF-2)	
Mita KM-3035	122492	292	ST() RADF(SRDF-2)	Error code C6000 (low fuser temp)
Mita KM-3035	122608	304	ST() RADF(SRDF-2) FN(DF-73)	Finisher jams; broken finisher panel
Mita KM-3035	123297	365	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Duplex jams; finisher jams (unable to test stapler & punch); broken bypass tray; dirty & offcolored panels; broken right plate glass frame
Copystar CS-3035	123362	386	ST() RADF(SRDF-2)	
Mita KM-3035	124486	255	ST() RADF(SRDF-2)	
Mita KM-3035	124637	308	ST() RADF(SRDF-2) PC(U)	
Mita KM-3530	119419	115	ST() RADF(SRDF-2) FN(DF-71U) DX(AD-63)	
Mita KM-3530	121571	464	ST() RADF(SRDF-2) FAX(C) DX(AD-63)	
Mita KM-3530	123890	1182	RADF(SRDF-2) PED(PF-75) PC(N) DX(AD-63)	
Mita KM-3530	124312	59	ST() RADF(SRDF-2) PC(N) FAX(C) E(J-1402) DX(AD-63)	
Mita KM-3530	124953	64	ST() RADF(SRDF-2) PC(N) FAX(C) E(J-1402) DX(AD-63)	Hard drive shows a format error & will not clear; dirty panels
Mita KM-4030	116932	297	ST() RADF(SRDF-2) FN(DF-71U) DX(AD-63)	Bent plate in punch unit by waste box-inop
Mita KM-4030	119953	460	RADF(SRDF-2) PED(PF-75) FN(DF-71U) DX(AD-63)	
Mita KM-4030	119954	354	RADF(SRDF-2) PED(PF-75) FN(DF-71U) DX(AD-63)	
Mita KM-4030	119955	777	RADF(SRDF-2) PED(PF-75) FN(DF-71U) DX(AD-63)	
Mita KM-4030	119956	595	RADF(SRDF-2) PED(PF-75) FN(DF-71U) DX(AD-63)	Yellowed finisher panels
Mita KM-4030	119957	221	RADF(SRDF-2) PED(PF-75) FN(DF-71U) DX(AD-63)	Yellowed finisher panels
Mita KM-4030	120070	1164	RADF(SRDF-2) PED(PF-70) FN(DF-71U) DX(AD-63)	Yellowed finisher panels
Mita KM-4030	120071	773	RADF(SRDF-2) PED(PF-70) FN(DF-71U)	Broken bypass tray

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			DX(AD-63)	
Royal RI-4030	122186	485	RADF(SRDF-2) PED(PF-75) E(J-1402) DX(AD-63)	Missing print controller (has print meter count of 94,908)
Royal RI-4030	122189	851	RADF(SRDF-2) PED(PF-75) E(J-1402) DX(AD-63)	Missing fax board (port covers missing)
Mita KM-4030	122657	432	RADF(SRDF-2) PED(PF-75) DX(AD-63)	
Mita KM-4035	118377	962	ST() RADF(SRDF-2) FN(DF-71U)	
Mita KM-4035	119352	248	RADF(SRDF-2) PED(PF-75) FN(DF-73)	Broken RADF plug socket; dented & bent back panel
Mita KM-4035	119353	372	RADF(SRDF-2) PED(PF-75) FN(DF-73)	
Mita KM-4035	119995	211	ST() RADF(SRDF-2) FN(DF-71U)	Broken RADF plug socket
Mita KM-4035	120577	506	ST() RADF(SRDF-2) FN(DF-73)	Broken RADF plug socket
Mita KM-4035	120877	427	ST() RADF(SRDF-2) FN(DF-71U)	
Mita KM-4035	120882	306	ST() RADF(SRDF-2) PC(U) FAX(J)	
Mita KM-4035	121217	310	RADF(SRDF-2) PED(PF-75)	
Mita KM-4035	121519	1096	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Cracked lower finisher tray; punch unit inop- will not detect punch unit waste box
Mita KM-4035	122019	528	ST() RADF(SRDF-2) FN(DF-73)	
Mita KM-4035	122020	224	RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-73)	
Mita KM-4035	122022	231	ST() RADF(SRDF-2) FN(DF-73)	rear panel dented
Mita KM-4035	122023	241	ST() RADF(SRDF-2) FN(DF-73)	
Copystar CS-4035	122098	499	RADF(SRDF-2) PED(PF-75)	
Mita KM-4035	122300	1847	RADF(SRDF-2) PED(PF-70) PC(U)	
Mita KM-4035	123952	312	RADF(SRDF-2) PED(PF-70) PC(U) FN(DF-73) FAX(J) E(J-1402)	Missing toner cartridge- tested with another

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita KM-4035	124481	294	RADF(SRDF-2) PED(PF-70)	Broken paper feed motor gears in both paper trays- inop
Mita KM-4035	124485	255	RADF(SRDF-2) PED(PF-70) FAX(J)	
Mita KM-4035	124505	408	RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-71U) FAX(J)	
Copystar CS-4035	124663	463	ST() RADF(SRDF-2) FN(DF-78)	
Mita KM-4530	116186	1064	FN(DF-610)	Missing both finisher trays; broken front door interlock actuator
Mita KM-4530	120129	1106	PU(PH-3) FN(DF-610)	Broken right side door handle
Mita KM-4530	120807	304	STK(MT-1) SCAN(D) PU(PH-3) FN(DF-610)	Tray #3 will not detect paper- inop; missing a pulley in tray #1; stapler inop
Mita KM-4530	120808	893	STK(MT-1) SCAN(D) PU(PH-3) PC(Q) FN(DF-610)	
Mita KM-4530	120866	855	SCAN(D) PC(Q) FN(DF-600)	Yellowed finisher panels; broken finisher plug socket
Mita KM-4530	120984	752	STK(MT-1) PU(PH-3) PC(Q) FN(DF-610)	Bent finisher brackets
Mita KM-4530	120985	948	STK(MT-1) PU(PH-3) PC(Q) FN(DF-610)	
Mita KM-4530	121878	909	PU(PH-3) PC(Q) FN(DF-610)	
Mita KM-4530	122301	1882	SCAN(D) PC(Q) FN(DF-600)	Broken finisher plug socket
Mita KM-5035	117207	614	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	
Mita KM-5035	119416	512	RADF(SRDF-2) PED(PF-75)	
Copystar CS-5035	121468	1002	ST() RADF(SRDF-2)	Missing a plate cover on left side above copies button; RADF skews copies
Mita KM-5035	121540	457	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	Broken RADF plug socket
Mita KM-5035	121850	571	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	
Mita KM-5035	121851	583	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	
Mita KM-5035	121852	629	RADF(SRDF-2) PED(PF-75) FN(DF-71U)	
Copystar CS-5035	122012	645	RADF(SRDF-2) PU(PH-2A) PC(U) FN(DF-71U)	RADF plug socket broken

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(DF-75) FAX(J)	
Mita KM-5035	122584	95	RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-71U) FAX(J)	Lower finisher tray mount bent (still works)
Mita KM-5035	124303	135	RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-71U) FAX(J)	
Mita KM-5230	116331	1050	FN(F-4130)	Broken top finisher panel; bent front door hinge (will not close); yellowed panels
Royal RI-5230	120390	1058	E()	Yellowed & dirty panels
Mita KM-5530	116055	1853	PU(PH-3) P(ST-11) FN(DF-610)	Broken handle on right side access door; paper deck jams; duplex jams; copies skew through feed unit; paper tray #3 inop- not detected
Copystar CS-5530	118374	713		Broken tray #4 paper roller
Copystar CS-5530	120391	189	FN(DF-610)	Broken RADF plug socket; yellowed panels
Mita KM-5530	120400	507	SCAN(D) FN(DF-610)	
Mita KM-5530	120805	599	STK(MT-1) SCAN(D) PU(PH-3) PC(Q) FN(DF-610)	Smashed lower back panel; bypass feed clutch not working
Mita KM-5530	120806	746	STK(MT-1) SCAN(D) PU(PH-3) PC(Q) FN(DF-610)	
Mita KM-5530	121535	813	PU(PH-3) PC(Q) FN(DF-610)	RADF cable insulation is cut; missing finisher bracket
Mita KM-5530	121718	842	SCAN(D) PU(PH-3) PC(Q) FN(DF-610)	Needs toner to test (error code C7100); paper tray #3 will not stay closed
Mita KM-5530	122018	1001	PU(PH-3) P(ST-11) FN(DF-610)	Exit tray broken
Mita KM-5530	122244	862	SCAN(D) PU(PH-3) PC(Q) FN(DF-610)	Finisher plug wiring damaged- inop; broken paper tray #4 left side latch rail
Mita KM-5530	122567	484	FN(DF-610)	
Mita KM-5530	122995	251	FN(DF-610)	
Mita KM-6230	119089	921	FN(F-4330)	Yellowed panels; LCD not fully lit
Royal RI-6230	120915	913	FN(F-4330)	Yellowed panels
Mita KM-6330	116823	282	FN(DF-610)	Missing finisher brackets (not tested); tray #1 inop; LCTwill not set in machine- inop
Mita KM-6330	118971	383	PU(PH-3) PC(R) FN(DF-610)	RADF wiring damaged- inop (shows false jam code); yellowed finisher panels; scratched finisher front door
Mita KM-6330	119086	980	PU(PH-3) PC(R) P(ST-11)	Unable to generate a config page

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(DF-610)	
Royal RI-6330	119766	487		Error code C0240 (communication between printer board & main board)-inop; yellowed top finisher panel
Mita KM-6330	120324	2615	STK(MT-1) SCAN(D) PU(PH-3) PC(R) P(ST-11) FN(DF-610)	
Mita KM-6330	120804	1154	STK(MT-1) SCAN(D) PU(PH-3) PC(R) P(ST-11) FN(DF-610)	Paper deck in error codes C2550 & C2500 (feed motor)
Mita KM-6330	120809	746	STK(MT-1) SCAN(D) PU(PH-3) PC(R) P(ST-11) FN(DF-610)	Dented & bent back panel; 0 button inop
Mita KM-6330	121538	333	PC(R) FN(DF-610)	Finisher plug wiring pulled loose; missing finisher bracket; yellowed panels
Mita KM-6330	122302	4809	SCAN(D) PC(R) FN(DF-610)	Error code C-2550 (drive motor)
Mita KM-6330	122303	5613	FN(DF-610)	Error code C-2550 (drive motor)
Mita KM-6330	122305	4104	SCAN(D) PC(R) FN(DF-610)	Jams every copy- unable to test; scratched front door
Mita KM-6330	122306	4685	SCAN(D) PC(R)	Has wrong finisher (DF-600); tray #1 inop
Mita KM-6330	123298	1837	PC(R) P(ST-11) FN(DF-610)	Finisher tray out of alignment causing error code SC4180; LCT in false jam code- inop
Mita KM-6330	123299	1583	SCAN(D) PC(R) FN(DF-610)	Jams every copy- can't test; cracked & scratched front door
Mita KM-6330	123363	1288	PU(PH-3) PC(R) FN(DF-610)	
Mita KM-6330	123644	1099	SCAN(D) PC(R) FN(DF-610)	Error code C-2550 (drive motor)
Mita KM-6330	123648	1493	PU(PH-3) PC(R) FN(DF-610)	
Mita KM-6330	124357	501	PU(PH-3) FN(DF-610)	Error code C-2550 (drive motor); dented front door
Mita KM-7530	118973	641	SCAN(D) PU(PH-3) PC(R) FN(DF-610)	Badlky scratched back panel; scratched front door; yellowed finisher panels
Mita KM-7530	120326	2006	SCAN(D) PU(PH-3) P(ST-11) FN(DF-610)	
Mita KM-7530	122545	748	SCAN(D) PC(R) FN(DF-610)	
Mita KM-7530	123296	1340	SCAN(D) PU(PH-3) PC(R) P(ST-11) FN(DF-610)	Dented & bent back panels; dented controller panel; finisher will not function; yellowed finisher panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita KM-7530	123645	1130	SCAN(D) FN(DF-610)	Dented & scratched back panel
Mita KM-C830D	121606	12	RADF(SRDF-2) PED(PF-35) PC(P) FN(DF-35) FAX(E)	Needs cyan toner to test; offcolored panels

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.  
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.  
Please call our sales team for current availability.