

Wulff Enterprises

02/10/2012

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier 5515	181724	349	ST() RADF(DF72) FAX(TYPE 1018)	Yellow and dirty panels
Lanier LD015SPF	174547	278		
Lanier LD015SPF	174548	149		Off color; Jamming in RADF
Lanier LD015SPF	189727	43		Cassette paper sensor broken - not tested (ran through bypass only)
Lanier LD122	190653	288	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	
Lanier LD238C	181455	967	PED(PS550) E(PT460)	Exit tray broken, off color, yellow, black meter = 782k, color meter = 186k
Lanier LD238C	186400	348	PED(PS550) FN(SR920) FAX(TYPE 2238) E(PT460)	Off color panels, right side corner cover panel broken, cover below bypass tray missing, black meter - 278k, color meter = 71k
Lanier LD160C	179207	1503	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Color = 367k; B/W = 1136k
Lanier LD160C	179731	1377	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	Has inverter type 3260, black meter - 112k, color meter = 1265k
Lanier LD160C	185630	821	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR4000)	
Lanier LD1135	188380	2560	P(RT5000) FN(SR5000)	Machine will not come to ready- shows "please wait" and will not go beyond; broken lower right access door; off color panels
Lanier LD316	189958	11	ADF(DF2000)	ADF yellow
Lanier LD016	192675	15		
Lanier LD016SPF	192683	274		Jamming in fuser when duplexing, front door broken at left hinge
Lanier LD016SPF	192684	229		
Lanier LD320D	183113	37	RADF(DF2010)	
Lanier LD320D	183671	28	ST() RADF(DF2010)	Cassette #1, bypass not feeding - not tested, RADF yellow, ground in dirt
Lanier LD320D	185438	487	RADF(DF2010) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	Right side access door broken, off color
Lanier LD320D	186582	55	ST() ADF(DF2000)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD320D	187944	27	ST() RADF(DF2010) FAX(TYPE 2000)	
Lanier LD320D	191498	116	ST() RADF(DF2010)	
Lanier LD320D	191499	163	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Lanier LD320D	192672	46	ST() RADF(DF2010)	
Lanier LD325	183899	428	ST() RADF(DF83)	Jamming out of bypass tray - not tested, RADF panels yellow, Has PC and NIC
Lanier LD325	189329	56	ST() RADF(DF83) FAX(TYPE 3030)	
Lanier LD325	189865	91	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	
Lanier LD325	190239	259	ST() RADF(DF83)	Bypass not feeding - not tested
Lanier LD425	180954	186	ST() RADF(DF3030)	
Lanier LD425	182104	205	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	187771	12	ST() RADF(DF3030)	
Lanier LD425	190395	211	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Lanier LD425	192332	191	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	192333	151	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	192334	311	ST() RADF(DF3030) FAX(TYPE 3350)	
Lanier LD425	192335	112	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	192677	239	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Lanier LD433	180326	690	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	Top finisher guide broken. lower finisher tray broken, jamming in stapler
Lanier LD433	180931	434	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD433	192678	143	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050)	
Lanier LD433	192679	57	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Lanier LD433	192680	231	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S)) FN(SR790)	
Lanier LD335	181781	526	ST()	
Lanier LD335	183592	530	ST() PC(TYPE 4500) FAX(TYPE 3045)	Jamming in RADF
Lanier LD335	183597	696	ST() PC(TYPE 4500) FAX(TYPE 3045)	
Lanier LD040	179261	475	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3020) FAX(TYPE 5000)	
Lanier LD040	180930	95	PED(PB3040) PC(TYPE 5000 (S))	
Lanier LD040	181456	184	ST() PC(TYPE 5000 (S)) FN(SR790)	Jamming in stapler - not tested, left side panel cracked
Lanier LD040	182427	517	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	
Lanier LD040	184556	642	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Finisher tray bent - not tested, jamming in bypass tray
Lanier LD040	188551	341	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	RADF jams when duplexing
Lanier LD040	192671	650	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Lanier LD345	183614	815	ST() PC(TYPE 4500) FAX(TYPE 3045)	Toner spilled in back of machine
Lanier LD345	187138	688	ST() PC(TYPE 4500) FAX(TYPE 3045)	Fuser knob broken, toner spilled in machine, off color
Lanier LD345	191999	729	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	
Lanier LD345	192331	298	PED(PS530) FAX(TYPE 3045)	
Lanier LD050	180344	301	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	
Lanier LD050	180345	309	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD260	187868	547	PU(TYPE 3260) P(RT43) FN(SR970)	
Lanier LD260	192330	239	FN(SR970)	
Lanier LD265	189170	628	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Jamming in finisher when punching and stapling
Lanier LD265	191997	997	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Stapler not recognizing staples - not tested
Lanier LD420C	186074	117	ST() FAX(TYPE MPC3000)	Black meter = 80k, color meter = 38k
Lanier LD425C	189078	145	PED(PB3000)	Has external fiery - missing cables - not tested, black meter = 83k, color meter = 63k
Lanier LD435C	188039	551	PED(PB3000) FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Black meter = 432k, color meter = 119k
Lanier LD435C	191844	581	PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Jamming in punch unit - not tested, black meter = 378k, color meter = 204k
Lanier LD435C	191845	305	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 263k, color meter = 43k
Lanier LD435C	191936	23	ST()	RADF plug socket broken, black meter = 12k, color meter = 12k
Lanier LD445C	189163	293	ST() FN(SR790) FAX(TYPE MPC4500)	Black meter = 265k, color meter = 29k
Lanier LD260C	192670	487	PU(TYPE 3260) FN(SR4020)	Missing finisher entrance guide - tested with another; Black meter = 298k, color meter = 190k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.