

Wulff Enterprises

01/07/2009

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Minolta DI 850	121777	1389	PC(PI8500) P(C-403) FN(FN-115)	Error code E90-01 (duplex drive board problem); james every copy at registration rollers; paper deck not detected by machine
Minolta DI 551	122989	489	FN(FN-6)	
Minolta DI 650	123477	493	FN(FN-113)	
Minolta DI 5510	117522	286	FN(FN-121)	Missing RADF drive assembly parts-inop (unable to test finisher)
Minolta DI 5510	122920	787	PC(PI7200E) E()	
Konica 8020	113503	134	RADF(DF-332) PFU(PF-232 [B]) PC(FIERY 15k X3E+) FN(FS-135)	Black meter = 120K; colored meter =
Minolta CF2002	119255	577	RADF(AFR-18) PED(PF-121) PC(CN3102E) FN(FN-8) DX(AD-14)	Duplex unit smashed & lower paper feed section damaged- unable to test; front door out of alignment; blue toner spilled through machine; color = 335k; B/W = 243k
Mita KM-C2030	119511	29	ST() PC(FIERY X3E 31)	Color = 26k; B/W = 4k
Minolta CF2002	119662	268	RADF(AFR-18) PU(PK-4) PED(PF-121) PC(CN3102E) FN(FN-8) DX(AD-14)	Broken RADF access door; broken duplex access door; color = 83k; B/W = 156k
Minolta CF2002	120773	N/A	RADF(AFR-18) FN(FN-8) DX(AD-14)	Machine will not come to ready (continuous warmup)- unable to test
Mita KM-C2030	122479	297	ST() RADF(DP-620) FN(DF-620) DX(DU-620)	Color = 90k; B/W = 207k
Minolta CF2002	122988	35	ST() RADF(AFR-18) FN(FN-116) DX(AD-14)	Color = 31k; B/W = 4k
Mita KM-C3130	123867	16	ST() PC(FIERY X3E 31)	Machine will not boot- can't test
Konica 8050	112881	146	RADF(DF-319) PC(IP-921) FN(FS-115)	Dented & bent left side panel; broken waste toner door; color = 95k; B/W = 51k
Konica 8050	113458	667	RADF(DF-319) PC(IP-901) P(LT-211) FN(FS-215)	Paper deck will not feed- inop; Color = 245k; B/W = 643k
Konica 8050	121800	913	RADF(DF-319) PC(IP-901) FN(FS-115)	Color = 852k; B/W = 62k
NEC 805	116351	119	ST()	
NEC 805	121760	68		
Konica 7115	122757	20		
Minolta DI 2010	122480	86	ST() DX(AD-16)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Minolta DI 2010	122481	77 ST()	DX(AD-16)	Broken platen top at hinge
Minolta DI 2010	123457	49 ST()	RADF(AFR-19) DX(AD-16)	Cracked right side panel; back panel bent in on right side; bent RADF plug socket
Minolta DI 2010	123876	132 ST()	RADF(AFR-19) DX(AD-16)	Broken RADF interlock actuator- inop
Pitney Bowes DL260	118498	73 ST()	RADF(AFR-14) DX(AD-10)	Has FN-100 finisher; has pc embedded; Error code C0070 - toner motor; Error code COBOF makes loud noise; On off switch bent; Side latch broken; Imagistics front door; Missing finisher base covers
Minolta DI 251	122801	263 ST()	RADF(AFR-17) PC(PI3502)	
Minolta DI 2510	119919	75 RADF(AFR-19)	PED(PF-124)	Tray #2 inop- will not lift
Minolta DI 2510	121792	33 ST()	RADF(AFR-19)	Machine will not boot up- unable to test
Imagistics IM2520	122886	76 ST()		
Muratec MFX-2530	122919	216 ST()	DX(AD-15)	RADF jams when duplexing
Minolta DI 3010	122459	294 ST()	RADF(AFR-19)	
Minolta DI 350	115727	200 RADF(AFR-14)	PFU(PF-110) PED(PF-106) FN(FN-100)	Broken RADF tray; broken paper tray #2 at lift hinge
Minolta DI 350	118499	287 ST()	RADF(AFR-14) PFU(PF-108 [A]) PC(PI3500) FN(FN-100)	Error code COBOF0- Horz trans route switch finisher not tested; on/ off switch bent; yellowed panels; finisher base cover missing
Imagistics IM3520	119282	397 ST()	FN(FN-117)	Finisher in error code C0BA0 (lift motor); denetd & bent back panel
Minolta DI 3510	121197	420 ST()	RADF(AFR-19) FN(FN-117)	
Minolta DI 3510	121774	336 ST()	RADF(AFR-19) FN(FN-117)	
Minolta DI 3510	121775	84 ST()	RADF(AFR-19)	
Minolta DI 3510	121776	447		
Minolta DI 3510	121778	111 ST()	RADF(AFR-19)	
Minolta DI 3510	121779	242 ST()	RADF(AFR-19) FN(FN-117)	
Minolta DI 3510	121780	181 ST()	RADF(AFR-19) PC(PI3505E [PS]) NIC(NC-4) FN(FN-117)	
Minolta DI 3510	121781	174 ST()	RADF(AFR-19)	
Minolta DI 3510	121782	372 ST()	RADF(AFR-19) FN(FN-117)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Minolta DI 3510	121783	102 ST()	RADF(AFR-19)	
Minolta DI 3510	121784	320 ST()	RADF(AFR-19)	
Minolta DI 3510	121786	183 ST()	RADF(AFR-19) PC(PI3505E) NIC(NC-4) FN(FN-117)	
Minolta DI 3510	121787	152 ST()	RADF(AFR-19)	
Minolta DI 3510	121788	61 ST()	RADF(AFR-19)	
Minolta DI 3510	121789	159 ST()	RADF(AFR-19)	
Minolta DI 3510	121790	461 ST()	RADF(AFR-19) FN(FN-117)	Finisher missing top shelf brackets- not tested
Minolta DI 3510	121794	604 ST()	RADF(AFR-19)	
Minolta DI 3510	122525	81		
Imagistics IM3520	124382	155 ST()		
Minolta DI 450	122802	341 PED(PF-7D)	NIC(NC-2) FN(FN-105)	
Imagistics IM4720	124384	657 PED(PF-115)	NIC(NC-2) FN(FN-105)	Jams every copy- will not pass paper; back panel bent; missing waste toner door; lower finisher tray mount bent & out of alignment
Imagistics IM5520	123546	64 PED(PF-115)	FN(FN-105)	Missing entire fuser unit causing error code C500
Minolta DI 620	122790	1575 PC(PI6200)	FN(FN-102)	

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.