

Wulff Enterprises

07/29/2010

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Minolta DI 850	157255	1321	PU(PK-7) PC(PI8500) P(C-403) FN(FN-7)	No power (power supply appears to be faulty); dented & bent paper deck
Minolta DI 551	153121	197	PU(PK-5) FN(FN-113)	Jamming in fuser; off color panels
Mita KM-C2030	148233	334	RADF(DP-620) PU(DF-620) PED(PF-620) PC(FIERY X3E 31) FN(DF-625) DX(DU-620)	Black meter = 21k; color meter = 313k; will not come to ready - not tested
Mita KM-C2030	148374	110	ST() RADF(DP-620)	Looks like duplexer was removed; black metre = 76k; color meter = 34k
Minolta CF3102	149263	726	ST() RADF(AFR-18) PC(CN3102E)	Duplexer missing - knockouts removed; jamming in fuser - not tested; lower cassette cover broken; off color and dirty panels; black meter = 589k; color meter = 137k
Minolta CF3102	150286	596	ST() RADF(AFR-18) PC(CN3102E) DX(AD-14)	Offcolor panels; Color = 255k; B/W = 341k
Minolta CF3102	151779	283	RADF(AFR-18) PU(PK-4) PED(PF-121) PC(CN3102E) FN(FN-8) DX(AD-14)	Error code C12C0 (hard disk error); duplex unit will not latch- broken right side access door latch hooks; yellowed panels; color = 146k; B/W = 138k
Mita KM-C3130	154804	176	RADF(DP-620) PU(DF-620) PFU(ST-530 [B]) PC(FIERY X3E 31) FN(DF-625) DX(DU-620)	Bridge unit is smashed- can't test finisher; offcolor panels; color = 30k; B/W = 147k
Minolta CF3102	154957	632	RADF(AFR-18) PU(PK-4) PFU(PF-118 [B]) PC(CN3102E) FN(FN-8) DX(AD-14)	Tray #1 will not detect paper- inop; offcolor panels; color = 80k; B/W = 553k
Mita KM-C3130	155679	281	ST() RADF(DP-620) PC(FIERY X3E 31) DX(DU-620)	Duplex back lock is broken- will not stay closed; error code C-0045 (colling fan error); offcolor panels
Mita KM-C3130	155729	158	RADF(DP-620) PED(PF-620) PC(FIERY X3E 31) FN(DF-620) DX(DU-620)	Bridge unit is smashed- can't test finisher; offcolor panels; color = 139k; B/W = 19k
Minolta CF3102	156237	113	RADF(AFR-18) PED(PF-121) PC(CN3102E) DX(AD-14)	Jamming in machine - not tested; duplexer latch broken; fuser top panels yellowing; black meter = 32k; color meter = 81k
Mita KM-C3130	156432	120	RADF(DP-620) PFU(ST-530 [B]) PC(FIERY X3E 31) FN(DF-620) DX(DU-620)	Bridge unit broken - finisher not tested; black meter = 55k; color meter = 65k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 8031	157391	158	RADF(DF-332) PFU(PF-232 [B])	Error code C0010 (cyan PC motor); offcolor panels; color = 66k; B/W = 93k
Hewlett Packard 9850MFP	153647	369		RADF Q3228A; FN Q5687A w/ punch unit; no toner - not tested; black meter = 45k; color meter = 324k
Hewlett Packard 9850MFP	157035	1812	RADF(AFR-20) PC(FIERY X3E) FN(FN-9)	Color = 237k; B/W = 1576k
Konica 8050	157256	382	RADF(DF-319) PC(IP-921) P(LT-211) FN(FS-215)	Color = 270k; B/W = 113k
Minolta DI 1610	146658	59	NIC(NC-5) ADF(AF-11)	Missing toner - not tested; cassette broken; left side panel broken
Minolta DI 1610	146659	27	NIC(NC-5) ADF(AF-11)	Missing toner - not tested; cassette broken
Minolta DI 1610	153842	30	PFU(PF-125) ADF(AF-11)	Missing toner cartridge- can't test; broken paper tray at hinges; offcolor & dirty panels
Minolta DI 1610	156226	570	ADF(AF-11)	Broken paper tray at miunts & tray door is broken
Minolta DI 2010	154600	96	ST() RADF(AFR-19)	
Minolta DI 2010F	153120	72	ST() RADF(AFR-19) PC(PI3505E) NIC(NC-4) DX(AD-16)	
Minolta DI 2010F	153123	41	ST() RADF(AFR-19) PC(PI3505E) NIC(NC-4)	
Minolta DI 2010F	154846	185	ST() RADF(AFR-19) DX(AD-16)	
Minolta DI 2010F	154847	116	ST() RADF(AFR-19) DX(AD-16)	
Minolta DI 2010F	154848	113	ST() RADF(AFR-19) DX(AD-16)	Bypass jams
Minolta DI 2010F	154851	64	ST() RADF(AFR-19) DX(AD-16)	Front door & left side panel cracked & broken
Minolta DI 2510	153822	194	ST() RADF(AFR-19) PU(PK-6) PC(PI3505E) NIC(NC-4) FN(FN-117)	
Minolta DI 2510	154469	140	ST() RADF(AFR-19) PC(PI3505E) NIC(NC-4) FN(FN-117)	
Minolta DI 2510	154619	44	ST() RADF(AFR-19) FN(FN-117)	
Minolta DI 2510	155901	169	ST() RADF(AFR-19) PU(PK-6) PC(PI3505E) NIC(NC-4) FN(FN-117)	
Minolta DI 2510F	153535	183	ST() RADF(AFR-19) PC(PI3505E) NIC(NC-4)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Minolta DI 2510F	154664	95	RADF(AFR-19) PED(PF-122) PC(PI3505E) NIC(NC-4) FN(FN-117)	Missing LCT panel
Minolta DI 2510F	154861	119	ST() RADF(AFR-19)	
Minolta DI 3010F	150313	132	RADF(AFR-19) PED(PF-210) PC(PI3505E) NIC(NC-4) FN(FN-117)	
Minolta DI 3510	156843	442	RADF(AFR-19) PED(PF-210) FN(FN-117)	No power; broken front door; finisher tray mounts are missing- not tested; broken RADF access door; offcolor & dirty panels
Minolta DI 3510	157612	601	ST() RADF(AFR-19) PU(PK-6) PC(PI3505E) NIC(NC-4) FN(FN-117)	Broken bottom finisher tray; has SK-1 folder
Minolta DI 3510F	153062	324	RADF(AFR-19) PU(PK-6) PED(PF-124) PC(PI3505E) NIC(NC-4) FN(FN-117)	
Minolta DI 3510F	154611	250	RADF(AFR-19) PU(PK-6) PED(PF-122) PC(PI3505E) NIC(NC-4) FN(FN-117)	
Minolta DI 3510F	154856	244	RADF(AFR-19) PED(PF-122) FN(FN-117)	

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.