

Wulff Enterprises

01/07/2009

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-2010E	107542	58 ST()	RADF(DA-AR201)	Missing toner cartridge & waste bottle-tested with another
Panasonic DP-2010E	107543	123 ST()	RADF(DA-AR201)	Missing toner cartridge & waste bottle-tested with another
Panasonic DP-2010E	107544	20 ST()	RADF(DA-AR201)	Missing toner cartridge & waste bottle-tested with another
Panasonic DP-2010E	107546	43 ST()	RADF(DA-AR201)	Missing toner cartridge & waste bottle-tested with another
Panasonic DP-2010E	107548	156 ST()	RADF(DA-AR201)	
Panasonic DP-2010E	107549	106 ST()	RADF(DA-AR201)	Missing toner cartridge & waste bottle-tested with another
Panasonic DP-2010E	107550	65 ST()	RADF(DA-AR201)	Missing toner cartridge & waste bottle-tested with another
Panasonic DP-2010E	109059	98 ST()	RADF(DA-AR201)	Missing toner cartridge & waste toner bottle
Panasonic DP-2330	115738	120 ST()		Cassette #1 inop causing error code E02-01; Missing finisher (has brackets)
Panasonic DP-2330	120210	N/A ST()		Will not power up- can't test; missing finisher & fax board (knockouts missing); cracked bypass tray
Panasonic DP-2330	121749	154 ST()	SCAN(DA-NS600)	
Panasonic DP-3010	123458	132 ST()	PFU(DA-DS303) FN(DA-FS300)	Finisher detecting paper but none is in finisher (bad sensor); missing fax board (port covers missing)
Panasonic DP-3010	123459	217 ST()	PFU(DA-DS303) FN(DA-FS300)	Finisher in error code E07-59; missing fax board (port covers missing)
Panasonic DP-3010	123460	147 ST()	PFU(DA-DS303) FN(DA-FS300)	Finisher in error code E07-59
Panasonic DP-3030	112839	137 ST()	FN(DA-FS300)	
Panasonic DP-3510	122891	851	SCAN(DA-NS600) PED(DA-DS601) PC(DA-PC600) FAX(DA-FG600)	
Panasonic DP-3530	115732	122 ST()	FN(DA-FS330)	
Panasonic DP-3530	115741	249	PED(DA-DS604)	No power to machine; Missing exit tray
Panasonic DP-3530	115887	498	PED(DA-DS604)	tray 3 inop - does not recognize paper
Panasonic DP-3530	117111	195 ST()	FN(DA-FS330)	Broken finisher latches- unable to test

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-4510	122239	213 ST()	PC(DA-PC600)	Control panel is smashed- unable to test all functions; missing finisher (has brackets)
Panasonic DP-4510	122493	134 ST()	SCAN(DA-NS600) PC(DA-PC600) FN(DA-FS600) FAX(DA-NF600)	
Panasonic DP-4520	113625	420 ST()	PU(DA-XT600) FN(DA-FS600)	
Panasonic DP-4530	120213	203 PED(DA-DS603) FN(DA-FS600)		Missing finisher (has brackets); cracked front door; machine will not detect finisher- can't test; broken finisher trays; cracked back wheel mount on finisher
Panasonic DP-4530	124246	154 ST()	PU(DA-XT600) FN(DA-FS600)	
Panasonic DP-4530	124249	68 ST()	FN(DA-FS600)	
Panasonic DP-4530	124250	162 ST()	FN(DA-FS600)	
Panasonic DP-4530	124292	139 ST()	PU(DA-XT600) FN(DA-FS600)	
Panasonic DP-4530	124330	140 ST()	PU(DA-XT600) FN(DA-FS600)	Broken bottom finisher tray
Panasonic DP-6010	115743	224 PED(DA-DS602) FN(DA-FS600)		Finisher bracket bent broken- unable to latch finisher (not tested); duplex jams; RADF misfeeds
Panasonic DP-6010	119584	453 ST()	SCAN(DA-NS600) PC(DA-PC600) FN(DA-FS600)	Dented & bent back panel; cut RADF interface cable- inop; broken lower finisher tray; missing finisher latch spring
Panasonic DP-6010	123461	464 PED(DA-DS601) PC(DA-PC600) FN(DA-FS600)		Missing fax board (port covers missing)
Panasonic DP-6030	117110	747 PED(DA-DS604) FAX(DA-FG600)		Missing exit tray
Panasonic DP-6030	120214	493 PED(DA-DS603)		Duplex jams; front door will not stay closed (bad interlock)

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.