

# Wulff Enterprises

01/07/2009

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic D620	116195	1046	P(FA-L3010) FN(F640)	Missing external print controller; broken RADF plug socket; missing paper deck interlock
Panasonic DP-150FX	119879	117		Yellowed panels
Panasonic DP-150FX	119881	151		Yellowed panels
Panasonic DP-150FX	124253	148		Yellowed panels
Panasonic DP-150FX	124255	167		Missing front right cover on ADF; yellowed panels
Panasonic DP-1810	116034	90	ST() ADF(DA-AS180)	Dirty panels
Panasonic DP-1810	120652	116	ST() NIC(DA-NE200) FAX(DA-NE200) ADF(DA-AS180)	Cracked start button
Panasonic DP-1810	124251	170	FAX(DA-NE200) ADF(DA-AS180)	Broken back & left side lower panels
Panasonic DP-1810	124252	253	FAX(DA-NE200) ADF(DA-AS180)	
Panasonic DP-1810	124256	167	ST() PFU(DA-DS182) ADF(DA-AS180)	
Panasonic DP-1810	124796	52		
Panasonic DP-1810	124839	83	ADF(DA-AS180)	Error code U90 (change battery); loud noise when warming up
Panasonic DP-1820E	124111	99	ST() RADF(DA-AR202) PFU(DA-DS184 [A]) FAX(DA-FG180)	Duplex jams
Panasonic DP-2310	117501	142	ST()	Broken plate above fuser unit & paper sensor actuator causing machine to jam every copy
Panasonic DP-2310	124829	163	ST() FN(DA-FS300) FAX(DA-FG300)	RADF jams when duplexing; registration off on copies
Panasonic DP-2330	124403	192	PFU(DA-DS306) PFU(DA-DS305) FN(DA-FS300) FAX(DA-FG300) E(DA-XN201)	
Panasonic DP-2500	116671	36	ST() ADF(DA-AS200)	
Panasonic DP-3000	123041	406	ST() RADF(DA-AR250) FN(DA-FS200)	
Panasonic DP-3010	119744	290	ST()	RADF jams every copy; dirty & offcolored panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-3010	122943	125	ST()	
Panasonic DP-3010	124398	94	ST()	
Panasonic DP-3030	120045	195	ST()	
Panasonic DP-3030	123549	308	ST()	
Panasonic DP-3510	115536	911	PED(DA-DS602) PC(DA-PC600) FN(DA-FS330)	
Panasonic DP-3510	119333	597	ST() PC(DA-PC600) FN(DA-FS330)	Scanner out of alignment- can't test; broken platen glass; broken finisher entrance guide; toner spilled throughout machine; broken finisher plug socket
Panasonic DP-3510	123278	436	PED(DA-DS601) PC(DA-PC600)	Jams every copy at exit rollers (not able to fully test); missing exit tray
Panasonic DP-3510	124254	1301	PED(DA-DS601) PC(DA-PC600) FN(DA-FS330) FAX(DA-FG600)	Went into a false jam code when testing duplex- won't clear; dirty & offcolored panels; dented & bent back panel; broken RADF & finisher plug sockets
Panasonic DP-3510	124804	385	PED(DA-DS602) PC(DA-PC600)	Scanner broken loose in machine- can't test; lower front frame of pedestal bent; RADF bent & broken- inop; lower pedestal tray broken & bent; missing finisher (knockouts missing); dented & bent back panel; dirty panels
Panasonic DP-3520	124831	350	ST() SCAN(DA-NS601) FAX(DA-FG600) E(DA-XT600)	Paper tray #2 will not lift- inop
Panasonic DP-3520	124833	222	ST() E(DA-XT600)	Broken RADF front paper guide
Panasonic DP-3520	124834	368	ST() SCAN(DA-NS601) FAX(DA-FG600) E(DA-XT600)	
Panasonic DP-3520	124835	677	ST() SCAN(DA-NS601) FN(DA-FS330) FAX(DA-FG600)	Finisher paper entrance guide broken off- inop
Panasonic DP-3520	124836	285	ST() SCAN(DA-NS601) FN(DA-FS330) FAX(DA-FG600)	Broken finisher paper entrance guide- finisher inop
Panasonic DP-3520	124840	226	ST() SCAN(DA-NS601) FAX(DA-FG600) E(DA-XT600)	
Panasonic DP-3520	124841	145	ST() SCAN(DA-NS601) FAX(DA-FG600) E(DA-XT600)	Jams every copy- unable to fully test
Panasonic DP-3520	124842	360	ST() FAX(DA-FG600)	Missing an exit tray
Panasonic DP-3520	124843	281	ST() SCAN(DA-NS601) FAX(DA-FG600)	Yellowed panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			E(DA-XT600)	
Panasonic DP-3520	124844	335	ST() SCAN(DA-NS601) FAX(DA-FG600) E(DA-XT600)	
Panasonic DP-3520	124973	329	ST() E(DA-XT600)	
Panasonic DP-3520	124975	84	ST() E(DA-XT600)	
Panasonic DP-3530	122925	264	PED(DA-DS603) FN(DA-FS330) FAX(DA-FG600)	Finisher entranc eguide all bent up & back panel dented- can't test
Panasonic DP-4510	115634	241	PED(DA-DS602) PC(DA-PC600) FN(DA-FS600)	
Panasonic DP-4510	119334	622	ST() PU(DA-XT600) PC(DA-PC600) FN(DA-FS600)	Jams every copy- can't test; hole in front door; bent left side stand panel; finisher smashed- inop; toner spilled throughout machine
Panasonic DP-4510	123483	552	SCAN(DA-NS600) PED(DA-DS601) PC(DA-PC600) FN(DA-FS600)	
Panasonic DP-4510	123924	343	PED(DA-DS601) PC(DA-PC600) FN(DA-FS600)	Missing a finisher tray; broken hinge pin on top finisher access door
Panasonic DP-4510	124442	325	ST() PU(DA-XT600) PC(DA-PC600) FN(DA-FS600)	Broken finisher trays; yellowed panels
Panasonic DP-4520	120224	438	ST() PU(DA-SP41) FN(DA-FS355)	Broken top finisher door; finisher in error code F7-51 (delivery motor); gouged front door; dirty & yellowed panels
Panasonic DP-4520	122965	605	ST() PU(DA-XT600) FN(DA-FS600) FAX(DA-FG600)	
Panasonic DP-4520	124974	500	ST() FN(DA-FS600)	Broken finisher tray
Panasonic DP-4530	116108	684	PU(DA-XT600) PED(DA-DS603) FN(DA-FS600)	Broken lower finisher tray; dirty panels
Panasonic DP-6010	115059	1227	SCAN(DA-NS600) PED(DA-DS601) PC(DA-PC600) P(DA-MA301) FN(DA-FS600)	Broken wires in tray #1- will not detect paper; dented back panel; broken paper deck plug socket
Panasonic DP-6010	118160	576	PED(DA-DS601) PC(DA-PC600) FN(DA-FS600)	Finisher tray broken; Ped plug socket frame broken
Panasonic DP-6020	121014	543	ST() SCAN(DA-NS600) E(DA-XT600)	Broken panel on underside of RADF; unable to clear user ID

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-6020	122411	435 ST()	FN(DA-FS600)	
Panasonic DP-6020	124408	745 PED(DA-DS601)	FN(DA-FS600)	Broken pedestal plug socket
Panasonic DP-6020	124838	647 ST()	SCAN(DA-NS600) FN(DA-FS600) FAX(DA-FG600)	

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.  
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.  
Please call our sales team for current availability.