

Wulff Enterprises

07/29/2010

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier 5518	157492	158 ST()	RADF(DF72)	Yellow panels; missing bypass tray - broken off
Savin 2518D	153732	124 ST()	RADF(DF71)	Offcolor panels
Gestetner 10502	156814	6057 PU(TYPE 850) P(RT42) FN(SR810)		Missing finisher entrance guide; offcolor & very dirty panels; lower paper deck panel scratched
Savin C2408	150952	116 ST()	RADF(DF75) PC(TYPE 1232) FN(SR830)	Front door broken at hinges; off color panels
Lanier LD024C	151390	252 ST()	RADF(DF75) FN(SR830) FAX(TYPE 1232)	Off color panels; black meter = 238k; color meter = 15k
Ricoh AFICIO 1224C	154313	208 ST()	RADF(DF75) FN(SR790)	Off color panels; black meter = 192k; color meter = 17k
Savin C2408	154651	175 ST()	RADF(DF75) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Error code SC826 (RTD or NVRAM); yellowed panels; color =14k; B/W = 161k
Ricoh AFICIO 1232C	148521	283 RADF(DF75) PED(PS520) PC(TYPE 1232) FAX(TYPE 1232)		Front door broken; bypass tray broken; rear fan motor cover broken; yellow panels; black meter = 269k; color meter = 15k
Ricoh AFICIO 1232C	154630	136 RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)		Big hole in lower paper tray panel; ooffcolor panels
Savin C3210	154880	268 ST()	RADF(DF75) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Offcolor panels; color = 8k; B/W = 260k
Savin 3515	153772	79		Off color panels
Ricoh AFICIO 1515	154159	18		
Ricoh AFICIO 1515	154160	47		Jamming in machine
Ricoh AFICIO 1515	155603	15 ST()		Offcolor & dirty panels
Ricoh AFICIO 1515M	157177	36		Offcolor & dirty panels
Gestetner DSM415PF	157333	47		Yellowed panels
Ricoh AFICIO 1515M	157445	70		
Ricoh AFICIO 1515M	157446	149		Off color panels
Ricoh AFICIO 1515M	157448	34		Off color panels
Ricoh AFICIO 1515M	157449	52 PFU(PS480)		
Ricoh AFICIO 1515M	157450	49 PFU(PS480)		
Gestetner DSM615	157121	115 ADF(DF78)		Jamming in bypass; off color and dirty; jamming in machine

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2020D	157452	79	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Off color panels
Ricoh AFICIO 2020D	157456	96	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Off color panels
Ricoh AFICIO 2020D	157457	88	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Off color panels
Ricoh AFICIO 2022	157116	71	ST() RADF(DF75) FN(SR820)	Error code SC120 - scan home problem, motor, drive board; off color panels; finisher exit tray missing
Ricoh AFICIO 2022	157422	158	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR820) FAX(TYPE 2027)	Yellowed panels
Ricoh AFICIO 2035	157473	414	ST() PC(TYPE 2045) FAX(TYPE 2045)	Off color panels
Ricoh AFICIO 2035E	149223	126	ST() PC(TYPE 2045E)	
Savin 4035E	151080	141	ST() PC(TYPE 2045E) FN(SR790)	Off color panels
Savin 4035E	151338	354	ST() FN(SR790)	Off color panels
Ricoh AFICIO 2035E	152338	107	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	
Gestetner DSM635	153432	88	ST() PU(TYPE 1045) PC(TYPE 2045E) FN(SR880)	Off color panels; RADF tray cracked
Gestetner DSM635	153558	74	ST() FN(SR880) FAX(TYPE 2045E)	
Ricoh AFICIO 2035E	156278	144	ST() PC(TYPE 2045E) FAX(TYPE 2045E)	Off color panels
Ricoh AFICIO 2035E	156290	175	ST() PS(TYPE 2045) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Off color panels; bypass tray broken
Savin 4035E	157052	227	ST() FN(SR790)	Off color panels
Savin 4035E	157475	527	ST() PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2045E	157423	613	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	Missing the bypass feed roller; offcolor panels
Ricoh AFICIO 2051	155842	263	FN(SR850)	Half of touch screen is blank- cannot fully test machine; offcolor panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4051	157403	483	PC(TYPE 2075) FN(SR850)	Control panel is pushed up at power switch & switch cover broken
Ricoh AFICIO 2075	157250	299	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	
Ricoh AFICIO 2090	156037	997	P(RT46)	Misisng finisher (received a Canon K2N finisher wiht this machine); missing print controller- can't test; print controller mount is bent; RADF plug socket is bent & cracked
Ricoh AFICIO 270	147708	368	ST() SS(TYPE 270) RADF(DF69)	Error code SC320- laser motor problem; Shift sort socket broken; RADF socket bent; dirty and off color panels
Ricoh AFICIO 270	155281	136	SS(TYPE 270) RADF(DF69) PED(PS440) PC(TYPE 270) NIC(TYPE 185-E) FAX(TYPE 270) DX(AD360) B(TYPE 270)	Broken power button on control panel; broken lower lefts side panel; offcolor & dirty panels
Ricoh AFICIO 3025	156405	472	ST() RADF(DF83) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE	Control panel inop; bypass tray
Ricoh AFICIO 3025	156406	191	ST() RADF(DF83) PC(TYPE 3030 (S))	Off color and yellow panels; left side panel dented; back panel dented; front door label missing
Ricoh AFICIO 3025	156407	73	ST() RADF(DF83) FN(SR790)	Off color panels; jamming in finisher - not tested
Ricoh AFICIO 3025	156408	99	ST() RADF(DF83) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE	Back panel dented in; lower finisher tray broken; yellow panels
Ricoh AFICIO 3025	156409	126	ST() RADF(DF83)	Off color and dirty panels; has finisher brackets but missing finisher
Gestetner DSM725	157331	175	ST() RADF(DF83) PC(TYPE 3030 (S))	Bypass tray broken off machine; yellowed RADF panels
Ricoh AFICIO 3025	157413	339	ST() RADF(DF83) PC(TYPE 3030 (S))	Toner spilled throughout machine; machine jams very try in fuser; back panel is cracked & badly scratched up; bypass tray broken off
Ricoh AFICIO 3030	157036	116	ST() RADF(DF83) FN(SR790)	Cassette #1 inop - not tested; Off color panels
Savin 8030	157416	195	ST() RADF(DF83) PC(TYPE 3030 (S))	Bypass tray broken; offcolor panels
Ricoh AFICIO 3035	155663	151	PED(PS530) FN(SR790) FAX(TYPE 3045)	Jams every copy; lower finisher tray mount is bent (still works); missing lower finisher tray; broken top finisher access door; lower paper tray panel cracked; yellowed & dirty panels
Ricoh AFICIO 3035	156235	316	PED(PS530) FN(SR790) FAX(TYPE 3045)	Yellow panels; lower finisher bracket bent - not tested; bypass tray broken; front panel cracked

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3035	156413	175 ST()		Error code SC329 - Laser beam pitch error; touch screen inop; hard-drive removed; yellow panels
Gestetner DSM735	156842	434 ST()		Serial number has been removed (electronic s/n matches)
Savin 8035	157048	109 PED(PS530) FN(SR790)		Finisher panels off color
Savin 8035	157143	255 PED(PS530) PC(TYPE 3045) FAX(TYPE 3045)		Off color panels; Missing finisher - has brackets
Lanier LD235	157474	200 PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)		Off color panels
Ricoh AFICIO 3045	157415	680 ST() PC(TYPE 3045) FAX(TYPE 3045)		Offcolor panels
Ricoh AFICIO 3045	157466	1612 PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)		Goes into error code SC329 (laser beam pitch error) after every copy; offcolor panels
Gestetner DSC424	126842	190 ST()		
Lanier LD124C	140049	142 PED(PS510) FN(SR790) FAX(TYPE 3232)		Touch screen inop - not tested; fuser oil panel missing; black meter = 115k; color meter = 28k
Savin C2410	150852	88 ST() FAX(TYPE 3232)		Error code SC-520 - fuser motor; off color and dirty panels
Ricoh AFICIO 3260C	153392	184 PC(TYPE 3260) E()		Black meter = 117k; color meter = 67k
Toshiba E-STUDIO4500	157173	289 PC(FIERY E-7000) FN(SR4000)		Cracked front door in lower left corner; broken bottom left side panel; broken finisher tray; color = 383k; B/W = 7k
Ricoh AFICIO 350E	154690	416 RADF(DF67) PED(PS360) FN(SR720) FAX(TYPE 450E)		Missing print controller/NIC; jams every copy- can't test; finisher in error code SC726-00 (shift/lift motor); broken bypass tray; rear finisher panel broken
Gestetner 3235E	155928	497 ST() RADF(DF67) FN(SR720) FAX(TYPE 450E)		Error code SC322 (laser synch 1 problem); cracked RADF tray; offcolor panels
Savin 9945 DPE	139315	381 RADF(DF67) PED(PS360) PC(TYPE 450E) FN(SR730) FAX(TYPE 450E)		Yellow panels; says "close cover but does not specify which one; RADF tray broken; NIC was removed
Savin 9945 DPE	151813	804 RADF(DF67) PU(TYPE 450) PED(PS360) FN(SR730) FAX(TYPE 450E) E(PT300)		Missing finishere tray
Savin 2045 DPE	153232	1013 RADF(DF67) PED(PS360) PC(TYPE 450E) NIC(TYPE 450-E) FAX(TYPE 450E)		Off color panels; RADF panels broken; Bypass tray boken; Back panel broken; says "to close doors" - not tested
Ricoh AFICIO 5560	125954	510 FN(SR980)		Black meter -149k; colored meter -361k; error code sc534 finisher error

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				-not tested
Savin SDC555	135835	464	PC(TYPE 3260) FN(SR970)	Missing all toner cartridges- can't test; color = 436k; B/W = 29k
Ricoh AFICIO 5560	146334	555	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Power cord plug is broken (still works); color = 235k; B/W = 321k
Savin SDC555	149217	615	PS(TYPE 3260) PC(TYPE 3260)	Came in with wrong finisher (SR960); missing fuser section - not tested; black meter = 197k; color meter = 419k
Ricoh AFICIO 5560	149620	171	E()	Missing print controller (has print meter count); color = 166k; B/W = 5k
Toshiba E-STUDIO5500	151753	219	PU(TYPE 3260) FN(SR4000)	Missing print controller (cover missing & print count = 18,341); missing magenta toner- can't test color copies; color = 196k; B/W = 23k
Gestetner CS555	152241	2058	FN(SR970)	Error code SC-520 - fuser motor; black meter = 1784k; color meter = 274k
Toshiba E-STUDIO5500	152741	1222		Black meter = 265k; color meter = 957k
Lanier LD215CG	153391	118	ST() RADF(DF2010) FAX(TYPE C1500) DX(AD2000)	Front door label missing; black meter = 70k; color meter = 49k
Savin SDC413	151785	216	PC(E-710) E()	Offcolor & dirty panels; print controller will not boot- inop; broken paper tray #2 panel; broken exit tray; color = 159k; B/W = 57k
Ricoh AFICIO MP 16	157037	5	ST() PC(TYPE 2000) FAX(TYPE 2000)	Has ADF DF2010; off color panels; Has PC and fax hardware but was not responding
Gestetner DSM416	157276	9		
Ricoh AFICIO MP 16	155660	346		Error code SC824-L401 (NVRAM or battery bad) offcolor & dirty panels
Gestetner DSM416PF	157100	12	ST()	Print & fax do not show up under user tools (no config page or jurnal printed)- both show up when you press print & fax buttons
Ricoh AFICIO MP 20	152923	64	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Off color and dirty panels
Ricoh AFICIO MP 20	154206	93	ST() RADF(DF2010) PC(TYPE 2000)	
Ricoh AFICIO MP 20	156230	210	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Front door label missing; off color panels; jamming in fuser
Gestetner DSM721D	157273	93	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM721D	157274	115	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Goes into error code SC591 (toner supply motor) after every copy; broken cooling fan vent in back panel; offcolor panels
Gestetner DSM721D	157275	158	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Offcolor panels
Ricoh AFICIO MP 25	154162	138	ST() FN(SR790)	
Savin 8025E	155194	77	RADF(DF83) PED(PS490) PC(TYPE 3010) FAX(TYPE 3030)	
Savin 8025E	155408	69	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR820)	Rear panel cracked
Savin 8025E	155410	318	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR820)	Back panel cracked
Gestetner DSM725E	155413	120	ST() RADF(DF83) PC(TYPE 3010)	
Savin 8025E	157054	350	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	
Gestetner DSM725E	157336	37	ST() RADF(DF83) FN(SR820)	Missing hard drive; error code SC541 (fuser thermistor or low line voltage)
Ricoh AFICIO MP 25	157504	87	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030)	Off color panels and dirty
Ricoh AFICIO MP 25	155969	77	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Gestetner DSM730E	157334	112	ST() RADF(DF83) FN(SR820)	Missing hard drive; fuser roller is broken loose & fuser unit will not set
Savin 9033	156287	114	ST() RADF(DF3030) E(BN3030)	
Savin 8035E	155837	151	PS(TYPE 4500) PED(PS530) PC(TYPE 4500) FN(SR790)	
Savin 8035E	155926	537	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Gestetner DSM735E	157335	319	FN(SR790)	Offcolor panels
Ricoh AFICIO MP 35	157484	368	ST() PC(TYPE 4500)	
Ricoh AFICIO MP 40	154014	616	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Jams when trying to duplex & staple at the same time
Ricoh AFICIO MP 45	150762	201	ST() PC(TYPE 4500) FN(SR790)	
Savin 8045E	155406	111	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8045E	155407	96	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880)	
Ricoh AFICIO MP 45	156119	125	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880)	Offcolor panels
Ricoh AFICIO MP 45	156149	259	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880)	Offcolor panels
Ricoh AFICIO MP 45	157064	664	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 45	157066	404	PED(PS530) PC(TYPE 4500) FN(SR790)	Off color panels
Savin 8045E	157503	234	PED(PS530) FN(SR790)	Touch screen not responding - not tested; off color panels
Ricoh AFICIO MP 55	155681	454	PU(TYPE 3260) PC(TYPE 7500) P(RT43) FN(SR970)	Cracked & pushed in front paper deck panel
Savin 8065	157402	783	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	
Savin 8075	155140	133	FN(SR970)	Missing lower finisher tray
Ricoh AFICIO MP 75	156948	455	PC(TYPE 7500) FN(SR970)	
Ricoh AFICIO MP 75	156950	216	PC(TYPE 7500) FN(SR970)	
Savin 8075	157476	1774	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Off color panels; RADF jamming - not tested
Savin 8090	149222	2100	PU(PU5000) FN(SR5000)	Power button on control panel broken
Savin 8090	151814	3140	PU(PU5000) PC(TYPE 1350) FN(SR5000)	No power
Savin 8090	151815	6526	PU(PU5000) P(RT5000) FN(SR5000)	
Ricoh AFICIO MP C2	152248	124	ST() FN(SR790) E(BN3000)	Black meter = 89k; color meter = 35k
Ricoh AFICIO MP C2	152256	85	ST() E(BN3000)	Black meter = 76k; color meter = 10k
Ricoh AFICIO MP C2	152805	159	PED(PB3000) FN(SR3010) FAX(TYPE MPC3000) E(BN3000)	Finisher tray is broken off- unable to test finisher; color = 79k; B/W = 81k
Ricoh AFICIO MP C2	153517	237	PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 199k; color meter = 38k
Lanier LD425C	153559	91	PED(PB3000) E(BN3000)	Needs yellow toner to test color copies; color = 76k; B/W = 16k
Ricoh AFICIO MP C2	154007	101	ST() FAX(TYPE MPC3000) E(BN3000)	Color = 1k; B/W = 100k
Ricoh AFICIO MP C2	155071	N/A	PED(PB3000) FN(SR3000) FAX(TYPE MPC3000)	touch sreen inop - not tested; slightly off color panels
Ricoh AFICIO MP C2	155435	231	PED(PB3000) E(BN3000)	Off color and dirty panels; black meter = 110k; color meter = 122k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C2525	155544	97 ST()	FN(SR3010) FAX(TYPE MPC3000) E(BN3000)	Color = 21k; B/W = 76k
Savin C2525	155748	70 ST()	SS(SH3000) PS(TYPE C3000) FAX(TYPE MPC3000)	Color = 52k; B/W = 19k
Ricoh AFICIO MP C2	156483	62 PED(PB3000)	FAX(TYPE MPC3000) E(BN3000)	Black meter = 44k; color meter = 18k
Ricoh AFICIO MP C2	156560	507 ST()	PED(PB3010) FAX(TYPE MPC3000) E(BN3000)	Black meter = 332k; color meter = 175k
Ricoh AFICIO MP C2	156778	N/A PED(PB3000)	E(BN3000)	Touch screen inoperable- cannot fully test machine
Ricoh AFICIO MP C2	157102	291 ST()	FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Color = 78k; B/W = 213k
Savin C3030	151816	338 PU(PU3000)	PED(PB3000) FN(SR3000) FAX(TYPE MPC3000) E(BN3000)	Color = 126k; B/W = 212k
Ricoh AFICIO MP C3	152053	413 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Color = 189k; B/W = 224k
Ricoh AFICIO MP C3	154229	181 ST()	PED(PB3010) FAX(TYPE MPC3000) E(BN3000)	Black meter = 119k; color meter = 63k
Savin C3030	155196	N/A PED(PB3000)	FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Touch screen inoperable - cannot test machine
Ricoh AFICIO MP C3	156279	208 ST()	FN(SR790) FAX(TYPE MPC3000)	Black meter = 165k; color meter = 44k
Ricoh AFICIO MP C3	156478	107 PS(TYPE C3000)	PED(PB3010) FN(SR3010) E(BN3000)	Finisher tray gears broken - finisher not tested; Off color panels on finisher; black meter - 61k; color meter
Lanier LD430C	156836	212 PED(PB3000)	E(BN3000)	Color = 120k; B/W = 93k
Ricoh AFICIO MP C3	144653	168 ST()	FN(SR790) FAX(TYPE MPC4500)	Black meter = 156k; color meter = 12k; touch screen inop
Savin C3535	145757	431 ST()	PS(TYPE C4500)	Black meter = 86k; color meter = 345k
Ricoh AFICIO MP C3	148364	227 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Ran fine, now touch screen is locked up; Lower finisher tray bent; black meter = 115k; color meter = 112k
Ricoh AFICIO MP C3	149242	232 PED(PB3000)	FN(SR3030) FAX(TYPE MPC4500) E(BN3010)	Control panel inop
Ricoh AFICIO MP C3	149353	137 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Offcolor panels; Color = 2k; B/W = 135k
Ricoh AFICIO MP C3	151323	236 PED(PB3000)		Missing finisher (has bridge unit & brackets); color = 84k; B/W = 153k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C3	151352	267	ST() FN(SR790) FAX(TYPE MPC4500)	Black meter = 207k; color meter = 60k
Savin C3535	152459	N/A	PED(PB3010) FN(SR790)	Touch screen inop - not tested
Ricoh AFICIO MP C3	153554	246	PED(PB3000) FAX(TYPE MPC4500) E(BN3010)	Color = 4k; B/W = 242k
Ricoh AFICIO MP C3	154357	522	ST() FN(SR790) FAX(TYPE MPC4500)	Unable to turn off color control- tested in SP mode; paper tray #2 will not closed; offcolor & dirty panels; color = 98k; B/W = 424k
Ricoh AFICIO MP C3	154772	349	PS(TYPE C4500) PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 272k; color meter = 77k
Ricoh AFICIO MP C3	155964	N/A	PED(PB3000) FN(SR790)	Error code SC860 (hard drive)- hard drive appears to have been replaced; touch screen inoperable
Ricoh AFICIO MP C3	155965	139	PED(PB3000) FN(SR790)	Error codes SC860 & SC925 (hard drive)- hard drive appears to have been replaced
Lanier LD435C	156388	N/A	PED(PB3000) FN(SR790)	Touch screen inop - not tested; missing front door label
Lanier LD435C	156389	411	PED(PB3000) FN(SR790)	Black meter = 251k; color meter = 161k; front door label missing; jamming in machine; error code SC549 - ferrite core rotate error; heat roller, ferrite roller sensor, ferrite roller motor, 24 V fuse on PSU, IOB - not tested
Lanier LD435C	157065	184	ST() FAX(TYPE MPC4500)	Black meter = 75k; color meter = 112k
Ricoh AFICIO MP C3	157472	N/A	ST() FN(SR790) FAX(TYPE MPC4500)	Error code SC860 - connection or controller; error code SC925 - initialize hard-drive
Ricoh AFICIO MP C4	143113	499	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 459k; color meter = 40k; touch screen inop
Ricoh AFICIO MP C4	143577	425	PS(TYPE C4500) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 354k; color meter = 72k; touch screen inop
Lanier LD445C	143869	N/A	PED(PB3000) FAX(TYPE MPC4500) E(BN3010)	Touch panel inop - not tested
Ricoh AFICIO MP C4	144293	376	PS(TYPE C4500) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Ran fine, now touch screen is locked up; Black meter = 280k; color meter = 96k
Gestetner DSC545	145164	710	PED(PB3010) FAX(TYPE MPC4500)	Finisher jamming during finisher functions
Ricoh AFICIO MP C4	145290	496	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	has copy audit keypad; black meter = 212k; color meter = 284k
Ricoh AFICIO MP C4	145964	628	PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 622k; color meter = 6k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C4	146024	311	PED(PB3010) FN(SR790) FAX(TYPE MPC4500)	Ecopy system -missing cables; black meter = 256k; color meter = 56k; constant jamming in machine
Savin C4540	146815	338	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Fuser pressure roller has cuts causing jamming in fuser; black meter = 196k; color meter = 142k
Ricoh AFICIO MP C4	147542	387	PS(TYPE C4500) PED(PB3010) FN(SR3030)	Deep scratches on top finisher panels; black meter = 189k; color meter = 199k
Ricoh AFICIO MP C4	148438	255	PS(TYPE C4500) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Ran fine, now touch screen is locked up; Black meter = 185k; color meter = 71k
Ricoh AFICIO MP C4	148449	369	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Black meter = 259k; color meter = 110k
Ricoh AFICIO MP C4	148661	358	PED(PB3000) FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Black meter = 282k; color meter = 77k
Gestetner DSC545	149618	622	PS(TYPE C4500) PED(PB3010) FN(SR3030)	Ran fine, now touch screen is locked up; Black meter = 499k; color meter = 124k
Savin C4540	149630	236	ST() FN(SR790)	Finisher jams every try; broken top finisher access door; color = 81k; B/W = 155k
Ricoh AFICIO MP C4	151531	N/A	ST() FAX(TYPE MPC4500)	Touch screen not working - not tested
Gestetner DSC545	152717	N/A	ST() FN(SR790) FAX(TYPE MPC4500)	Touch screen stopped working; Jamming in duplexer
Gestetner DSC545	152719	243	ST() FAX(TYPE MPC4500)	False jam in fuser - not tested; black meter = 142k; color meter = 102k
Gestetner DSC545	152721	791	ST() FAX(TYPE MPC4500)	Black meter = 504k; color meter = 288k
Gestetner DSC545	152722	279	ST() FAX(TYPE MPC4500)	Black meter = 181k; color meter = 98k
Ricoh AFICIO MP C4	152797	204	PED(PB3010) FN(SR790) FAX(TYPE MPC4500)	Front door label says MP 4500; lines through touch screen; Black meter = 177k; color meter = 27k
Ricoh AFICIO MP C4	153094	682	PED(PB3010) FN(SR3030)	Missing finisher throat - finisher not tested; finisher trays yellow; black meter - 395k; color meter = 287k
Ricoh AFICIO MP C4	153150	449	PED(PB3000) E(BN3010)	Black meter = 98k; color meter = 352k; front door label missing
Gestetner DSC545	153425	N/A	ST() FN(SR3020)	Touch screen inop - not tested; Has fiery E-5000 controller
Ricoh AFICIO MP C4	153910	N/A	PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Touch screen inoperable- can't test machine
Gestetner DSC545	154043	221	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	False jam in stapler - stapler not tested; black meter = 108k; color meter = 114k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C4	154336	229	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 150k; color meter = 80k
Gestetner DSC545	154809	265	PS(TYPE C4500) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Jams when combining duplex & stapling; color = 152k; B/W = 114k
Lanier LD445C	154894	381	ST()	Offcolor panels; color = 57k; B/W = 325k
Ricoh AFICIO MP C4	155545	379	PED(PB3010) FN(SR3020) FAX(TYPE MPC4500)	Offcolor panels; B/W = 154k; B/W = 226k
Ricoh AFICIO MP C4	156142	413	PED(PB3010) FN(SR790) FAX(TYPE MPC4500)	Color = 289k; B/W = 124k
Ricoh AFICIO MP C4	156903	N/A	PED(PB3000) FAX(TYPE MPC4500)	Wrong finisher came with machine - came in with SR3000 finisher; front label missing from front panel; touch screen inop
Ricoh AFICIO MP C4	157471	257	ST() FN(SR3030)	Error code SC565 - TD sensor or PCU - k,m,c,y; off color panels; black meter = 520k; color meter = 197k
Ricoh AFICIO MP C4	157477	N/A	FN(SR3030) FAX(TYPE MPC4500)	Touch screen not responding
Savin SLP38CS	148189	2125	RADF(DF73) PU(TYPE 1045) FN(SR770)	Off color panels; black meter = 698k; color meter = 1428k
Ricoh CL7000CMF	142027	391	E()	Black meter = 333k; color meter = 58k; glass is cracked; RADF cover panel broken; yellow panels
Ricoh CL7000CMF	147715	370	FN(SR770) FAX(TYPE 3800C)	Black meter = 281k; color meter = 89k; Finisher entrance guide bent
Savin CLP28S	153774	539	PU(TYPE 1045) FN(SR770) E()	False indicator - output tray full - not tested; Black meter = 285k; color meter = 254k; off color panels
Ricoh AFICIO 3131	145299	94	RADF(DF81) PC(E-750) DX(AD470)	Error code CE4 - test pattern problem; has finisher brackets - missing finisher; rear panel bent; front lable missing

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.