

# Wulff Enterprises

07/29/2010

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 1013F	152572	283		Broken ADF tray
Savin 2515	157198	19	ST() RADF(DF72)	
Lanier 5515	157379	51	ST() RADF(DF72) FAX(TYPE 1018)	Yellowed panels
Ricoh AFICIO 1018	155205	305	ST() RADF(DF71)	Error code SC302 (charge roller, drum unit or HVT)
Savin 2518	156314	116	ST() RADF(DF72)	Error code SC320 (laser polygon motor)
Savin 2518D	157039	52	ST() RADF(DF71) PC(TYPE 1018) NIC(TYPE 1018) FAX(TYPE 1018)	Yellowed panels
Ricoh AFICIO 1018D	157314	184	ST() RADF(DF71) PC(TYPE 1018)	Jams in fuser every copy- can't test
Gestetner 2212	157324	262	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	
Lanier 5622	157380	370	ST() RADF(DF75) FAX(TYPE 1027) DX(AD420) B(TYPE 1027)	Yellowed & dirty panels
Lanier 5622	157381	269	ST() RADF(DF75) FN(SR820) FAX(TYPE 1027) DX(AD420) B(TYPE 1027)	Yellowed panels
Ricoh AFICIO 1027	157373	94	RADF(DF75) PED(PS490) FAX(TYPE 1027) DX(AD420)	Broken guide under primary feed tires in RADF- inop; yellowed & dirty panels
Savin 2545	157258	541	ST() RADF(DF70) PU(TYPE 1045) PC(TYPE 1045) NIC(TYPE 1045) FN(SR760) E(PT1045)	Error code SC863 (hard drive)- unable to test all functions; hard drive removed from machine; broken back finisher panel; yellowed panels; LCD glows red; broken bypass handle; missing print button on control panel
Ricoh AFICIO 1224C	148149	441	RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Color = 13k; B/W = 428k
Ricoh AFICIO 1224C	148847	37	ST() RADF(DF75) PC(TYPE 1232)	Deep gouge & scratch in front door; color = 3k; B/W = 35k
Savin C2408	148868	326	ST() SS(TYPE 1232) RADF(DF75) FAX(TYPE 1232)	Broken RADF plug socket
Gestetner DSC224	150895	120	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830) 114k FAX(TYPE 1232) E(PT290)	Offcolor panels; color = 7k; B/W =

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD024C	151711	118	RADF(DF75) PED(PS510) PC(TYPE 1232)	Void area in top of B/W copies; Color = 86k; B/W = 32k
Ricoh AFICIO 1224C	153543	129	ST() RADF(DF75) PC(TYPE 1232) FAX(TYPE	DirtY & yellowed panels; Color = 2k; B/W = 128k
Savin C2408	153654	64	RADF(DF75) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232)	Cracked finisher tray; void edge on copies; color = 11k; b/w = 53k
Savin C2408	155854	211	ST() RADF(DF75) PC(TYPE 1232) FAX(TYPE	Bypass tray broken off; color = 49k; B/W = 163k
Ricoh AFICIO 1224C	156523	129	ST() RADF(DF75) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232) E(PT290)	Yellow panels; black meter = 107k; color meter = 22k
Ricoh AFICIO 1232C	128855	203	ST() RADF(DF75) PC(TYPE 1232)	Color = 18k; B/W = 186k; cracked paper tray #2 handle
Ricoh AFICIO 1232C	143312	148	ST() RADF(DF75) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Color = 3k; B/W = 145k
Gestetner DSC232	147966	281	ST() RADF(DF75) PC(TYPE 1232)	Registration off on copies; color = 10k; B/W = 272k
Lanier LD032C	149770	502	ST() RADF(DF75) PC(TYPE 1232) FN(SR830)	Yellowed panels; color = 17k; B/W = 486k
Lanier LD032C	150116	576	RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Error code SC421 (discharge plate short, HVT or harness); missing bypass tray; color = 192k; B/W = 385k
Ricoh AFICIO 1515	155207	106	ST()	Broken ADF tray; yellowed panels
Ricoh AFICIO 1515	155208	102	ST()	Broken ADF tray; offcolor panels
Ricoh AFICIO 1515	155611	67		Broken ADF tray
Ricoh AFICIO 1515	156501	44		Yellow and dirty panels; Feed tray broken
Gestetner DSM415	156631	19		Error code SC547 (zero cross problem); broken feed tray
Gestetner DSM415	156632	56		Error code SC541 (fuser lamp); broken feed tray
Savin 3515MF	156581	294	ST() PFU(PS480)	
Ricoh AFICIO 1515M	156986	201		
Savin 3515MF	157040	88	ST()	Broken ADF tray
Savin 4018	157341	101	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018) E(PT340) ADF(DF78)	Yellowed RADF panels
Savin 4018D	154316	169	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE	Loose scanner
Gestetner DSM618D	157317	94	ST() RADF(DF79)	Yellowed RADF panels
Gestetner DSM620D	155493	87	ST() RADF(DF79) FAX(TYPE 2018)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2020D	156316	28	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Tray #1 will not initialize- inop
Ricoh AFICIO 2022	155029	116	ST() RADF(DF75)	
Gestetner DSM622	156634	205	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	
Gestetner DSM622	156635	103	ST() RADF(DF75)	Bypass will not feed; yellowed RADF panels
Lanier LD122	156636	100	ST() RADF(DF75) FN(SR820)	Scratched front door
Gestetner DSM627	152919	171	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR790) FAX(TYPE 2027)	
Savin 4027	154314	168	ST() RADF(DF75) PC(TYPE 2027) FN(SR820) FAX(TYPE 2027)	
Gestetner DSM627	156670	299	ST() RADF(DF75) PC(TYPE 2027) FN(SR790)	
Savin 4027	156964	131	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR790)	Stapler jams
Savin 4027	157338	270	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR820) FAX(TYPE 2027)	Finisher jams- inop; offcolor panels
Savin 4035E	151195	172	ST() PS(TYPE 2045) PC(TYPE 2045E)	
Ricoh AFICIO 2035E	155203	134	ST()	
Ricoh AFICIO 2035E	156070	202	ST() PC(TYPE 2045E) FN(SR790)	Yellowed panels
Ricoh AFICIO 2035E	156071	144	ST() PC(TYPE 2045E) FN(SR790)	Offcolo & dirty panels
Ricoh AFICIO 2035E	156075	227	PED(PS530) PC(TYPE 2045E) FN(SR790)	Yellowed panels; missing finisher tray
Ricoh AFICIO 2035E	156356	281	ST() PC(TYPE 2045E) FN(SR790)	
Ricoh AFICIO 2035E	157032	326	PED(PS530) PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	Offcolor & dirty panels; broken panel around controller
Gestetner DSM635	157300	573	ST() PU(TYPE 1045) PC(TYPE 2045E) P(RT45) FN(SR880)	Duplex jams; offcolor panels
Savin 4045E	155652	339	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	Offcolor panels
Savin 4045E	155863	602	PU(TYPE 1045) PED(PS530) PC(TYPE	Went into error code SC863 (bad hard drive sector) during testing; offcolor

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			2045E) FN(SR880)	panels
Ricoh AFICIO 2045E	156073	138 ST()	PC(TYPE 2045E) P(RT45) FN(SR790)	Yellowed & dirty panels
Ricoh AFICIO 2045E	156586	556 PED(PS530)	PC(TYPE 2045E) FAX(TYPE 2045E)	Offcolor panels
Gestetner DSM645	156608	458 PU(TYPE 1045)	PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E) E(PT330)	
Lanier 5222	149762	72 RADF(RADF-527)	PED(PS440) DX(ADM-527) B(TYPE 270)	Offcolor panels
Lanier 5222	154422	268 ST()	SS(TYPE 270) RADF(RADF-527) FAX(TYPE 270) E(TYPE 270) DX(ADM-527) B(TYPE 270)	Yellowed panels
Gestetner 3227	157075	96 ST()	RADF(DF69) FAX(TYPE 270) B(TYPE 270)	Yellowed panels
Ricoh AFICIO 3025	155231	147 RADF(DF83)	PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030) E(PT280)	Offcolor RADF panels
Ricoh AFICIO 3224C	130359	62 SS(TYPE 3232)	PED(PS510) FAX(TYPE 3232) E(PT350)	Broken front door trim panel; loose interlock switch; color = 16k; B/W = 47k
Gestetner DSC424	132333	81 ST()	FAX(TYPE 3232)	Side-side registration is off on copies; color = 19k; B/W = 63k
Savin C2410	135398	86 ST()	FAX(TYPE 3232)	Color = 36k; B/W = 50k
Ricoh AFICIO 3224C	135636	66 ST()	FN(SR790)	Touch screen is inoperable- can't fully test machine; no magenta in color copies; color = 25k; B/W = 41k
Gestetner DSC424	140347	104 ST()		Cracked front door; broken access door C at pivot pin; color = 22k; B/W = 83k
Savin C2410	141202	35 ST()		Color = 27k; B/W = 9k
Ricoh AFICIO 3224C	144349	225 ST()	FN(SR830) FAX(TYPE 3232) E(PT350)	Top finisher access panel broken & leveler plates broken; - can't test; black meter = 217k; color meter = 8k
Savin C2410	146687	253 ST()	FAX(TYPE 3232) E(PT350)	Cracked back panel; color = 124k; B/W = 130k
Lanier LD124C	149986	268 PED(PS510)	FN(SR790) FAX(TYPE 3232)	Ran in SP mode- unable to clear user login; broken paper tray handle; broken pedestal bottom trim panel; finisher height needs adjusted- not tested; duplex jams; color = 227k; B/W = 41k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3224C	152996	90	ST()	Color = 5k; B/W = 86k
Savin C2410	154317	117	ST() FAX(TYPE 3232) E(PT350)	Color = 9k; B/W = 109k
Savin C2410	154318	98	ST() FAX(TYPE 3232) E(PT350)	Color = 10k; B/W = 89k
Savin C2410	154319	108	ST() FAX(TYPE 3232) E(PT350)	Color = 93k; B/W = 15k
Savin C2410	154320	76	ST() FAX(TYPE 3232) E(PT350)	Touch screen will not respond- cannot fully test machine; color = 7k; B/W = 70k
Savin C2410	154526	149	ST() FN(SR830)	Cracked front door; color = 27k; B/W = 122k
Savin C2410	155940	54	ST()	Front door interlock actuator is out of alignment; color = 14k; B/W = 41k
Gestetner DSC428	154415	426	ST() PU(TYPE 2238) FN(SR950) FAX(TYPE 3245) E(PT460)	Color = 100k; B/W = 326k
Ricoh AFICIO 3228C	155022	299	PED(PS590) FAX(TYPE 3245) E(PT460)	Offcolor panels; color = 73k; B/W = 226k
Savin C2824	155653	140	PU(TYPE 1045) PED(PS580) FN(SR960) FAX(TYPE 3245)	Offcolor panels; color = 17k; B/W = 123k
Ricoh AFICIO 3228C	157131	472	PED(PS580) FN(SR960) E(PT460)	Color = 43k; B/W = 429k
Gestetner DSC428	157144	263	ST() FN(SR950) FAX(TYPE 3245)	Missing hard drive- unable to fully test machine; shows error code SC819; missing finisher interlock actuator on door R3 (unable to test finisher); color = 11k; B/W = 252k
Ricoh AFICIO 3260C	140350	179	PC(TYPE 3260) E()	Jams frequently at A1/B1 (flat spots in registration roller); unable to print a config page due to jamming; color = 148k; B/W = 32k
Savin C6045	142179	549	PC(TYPE 3260) E()	Needs yellow toner to test color copies and print config pages; paper tray #2 inop- shows reset tray; not detecting tray #3- inop; color = 306k; B/W = 243k
Ricoh AFICIO 3260C	143535	623	PC(TYPE 3260)	Missing finisher (has brackets); color = 290k; B/W = 334k
Ricoh AFICIO 3260C	151496	375		Color = 334k; B/W = 42k
Gestetner DSC460	153657	N/A	PS(TYPE 3260) PC(TYPE 3260)	Machine will not come to ready- can't test
Lanier LD160C	156068	344	PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Finisher jams at entrance every try- inop; color = 26k; B/W = 319k
Toshiba E-STUDIO4500	156672	670	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260)	Jams every copy at transfer belt- can't test; color = 128k; B/W = 542k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(SR4000)	
Ricoh AFICIO 3260C	157214	1092	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Yellowed lower finisher tray; color = 244k; B/W = 848k
Ricoh AFICIO 3260C	157220	982	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Color = 324k; B/W = 658k
Ricoh AFICIO 3260C	157221	899	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Color = 314k; B/W = 586k
Ricoh AFICIO 3260C	157311	451	PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Color = 404k; B/W = 47k
Gestetner 3235E	157325	573	ST() RADF(DF67) PC(TYPE 450E) NIC(TYPE	Error code SC329-00 (laser beam pitch error); offcolor panels
Toshiba E-STUDIO5500	126366	639	PU(TYPE 3260) PC(FIERY E-7000) P(RT43) FN(SR4000)	Finisher in false jam code at R8 & R12- will not clear; print controller will not come to ready- inop; color = 481k; B/W = 158k
Ricoh AFICIO 5560	137714	608	P(RT43) FN(SR980)	Color = 563k; B/W = 46k
Savin SDC555	138066	274	E()	Color = 130k; B/W = 144k
Ricoh AFICIO 5560	148908	687	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	100% copies appear to be slightly reduces and there are some blurred areas in reports; color = 321k; B/W = 367k
Ricoh AFICIO 5560	148909	619	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Finisher entrance guide all bent up- tested with another; color = 214k; B/W = 406k
Savin SDC555	149793	1352	PC(TYPE 3260) FN(SR970)	Cracked lower finisher tray; color = 423k; B/W = 930k
Ricoh AFICIO 5560	151844	461	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Stpler & punch jam; color = 17k; B/W = 445k
Ricoh AFICIO 5560	152023	872	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Color = 215k; B/W = 658k
Ricoh AFICIO 5560	152024	580	PU(TYPE 3260) PC(TYPE 3260) FN(SR970)	Color = 25k; B/W = 556k
Toshiba E-STUDIO5500	153945	1501	PC(FIERY E-7000) P(RT43) FN(SR4000)	toner spilled throughout machine; black meter = 230k; color meter = 1272k
Toshiba E-STUDIO5500	154418	644	PU(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR970)	Color = 296k; B/W = 349k
Ricoh AFICIO 615C	155503	21	ST() RADF(DF2010) PFU(PS460) DX(AD2000)	Color = 1k; B/W = 22k
Lanier LD215CG	157213	165	ST() RADF(DF2010) FAX(TYPE C1500) DX(AD2000)	Full waste toner tank- unable to test; dent & crack in front door; color = 36k; B/W = 130k
Ricoh AFICIO MP 11	157235	3440	PU(PU5000) PC(TYPE 1350) P(RT5000) FN(SR5000)	Goes into error code SC440 (drum motor locked)- was able to reset and test; has CI5000 interposer unit

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM716	150827	134	FAX(TYPE 2000) ADF(DF2000)	
Ricoh AFICIO MP 16	152809	29	ADF(DF2000)	
Ricoh AFICIO MP 16	154549	92	PS(TYPE 2000) PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	
Lanier LD316	157191	73		
Gestetner DSM416	156618	30		
Lanier LD016F	156262	35	ST()	
Gestetner DSM721D	149073	70	ST() RADF(DF2010)	
Lanier LD320D	150812	66	ST() RADF(DF2010) PFU(PS460)	
Ricoh AFICIO MP 20	153950	82	ST() RADF(DF2010)	
Gestetner DSM721D	156063	103	ST() RADF(DF2010)	
Ricoh AFICIO MP 20	156980	111	ST() RADF(DF2010)	Paper tray #1 broken at right back side acuating it to jam every try
Ricoh AFICIO MP 20	157132	27	ST() ADF(DF2000)	
Ricoh AFICIO MP 20	157236	126	ST() RADF(DF2010) PFU(PS450) PC(TYPE 2000) FAX(TYPE 2000)	Broken paper tray by back paper guide
Ricoh AFICIO MP 25	153582	22	ST() RADF(DF3020) PC(TYPE 2500)	
Ricoh AFICIO MP 25	150796	172	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	
Ricoh AFICIO MP 25	151571	35	ST() RADF(DF83) FAX(TYPE 3030)	
Savin 8025E	151656	156	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	Paper tray #1 in false jam code
Ricoh AFICIO MP 25	152643	3	ST() RADF(DF83) FN(SR790)	
Ricoh AFICIO MP 25	152944	56	ST() RADF(DF83)	
Gestetner DSM725E	153353	162	RADF(DF83) PED(PS490) PC(TYPE 3010) FAX(TYPE 3030)	Broken bypass tray
Savin 8025E	153865	43	RADF(DF83) PED(PS490) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	Broken bypass tray; RADF jams every try- inop; broken top left side panel
Lanier LD325	156066	42	ST() RADF(DF83)	
Savin 8025E	156313	59	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	
Lanier LD325	156621	78	ST() RADF(DF83)	Touch screen inoperable- cannot fully test machine

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8025E	156875	169	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Touch screen inoperable- cannot fully test machine
Ricoh AFICIO MP 25	156900	167	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	Bypass tray broken off; cracked upper back panel; very dirty panels
Lanier LD325	156960	75	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Broken RADF plug socket & machine frame bent by socket; back right corner panel bent out
Ricoh AFICIO MP 25	156983	240	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	
Ricoh AFICIO MP 25	157189	83	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE	Touch screen inoperable- cannot fully test machine; hard drive removed; missing toner cartridge; several loose buttons on control panel
Ricoh AFICIO MP 30	151497	75	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790)	Broken bridge unit plug socket
Ricoh AFICIO MP 30	152027	158	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790)	
Ricoh AFICIO MP 30	154550	71	ST() RADF(DF83) FN(SR820)	Broken bypass tray
Savin 8030E	154674	256	RADF(DF83) PED(PS500) PC(TYPE 3010) FN(SR790)	Duplex jams; finisher turnaround gate missing spring- unable to test stapler
Ricoh AFICIO MP 33	155972	54	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 33	156885	147	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Ricoh AFICIO MP 33	156886	120	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	
Savin 8035E	151657	161	ST() PC(TYPE 4500) FN(SR790)	Missing spring on finisher flip gate causing it to jam every try- inop
Ricoh AFICIO MP 35	153813	195	PED(PS530) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	153888	197	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO MP 35	155521	199	ST()	
Ricoh AFICIO MP 35	155882	143	PED(PS530) FN(SR790) FAX(TYPE 3045)	Bent bottom finisher panel; offcolor panels
Ricoh AFICIO MP 35	156260	161	PED(PS530) FN(SR790) FAX(TYPE 3045)	Cracked finisher tray; finisher jams frequently- unable to test stapler; dirty & offcolor panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 35	156261	166	PED(PS530) FN(SR790) FAX(TYPE 3045)	Missing finisher top gate spring- can't test; offcolor & dirty panels
Gestetner DSM735E	156264	156	ST() FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO MP 35	156265	178	PED(PS530) FN(SR790) FAX(TYPE 3045)	Missing finisher top gate spring- can't test
Lanier LD335	156318	149	PU(TYPE 1045) PED(PS530) FN(SR880)	
Ricoh AFICIO MP 35	157210	580	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO MP 40	148882	79	PED(PB3040)	
Lanier LD040	152437	480	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Lanier LD040	152438	464	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	
Lanier LD040	152439	430	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 40	153809	432	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Gestetner DSM745E	154948	199	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	Fax board inoperable- machine will not allow access (shows no privileges)
Ricoh AFICIO MP 45	155524	384	PS(TYPE 4500) PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO MP 45	156504	380	ST() PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	
Ricoh AFICIO MP 45	156890	477	PED(PS530) PC(TYPE 4500) FN(SR790)	
Lanier LD050	152440	652	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Has Copy Data Security unit
Lanier LD050	156637	440	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	
Lanier LD050	156639	614	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	
Ricoh AFICIO MP 65	152407	653	PU(TYPE 3260) PS(TYPE 7500) PC(TYPE 7500) P(RT43) FN(SR970)	Broken finisher tray
Ricoh AFICIO MP 65	154867	667	PC(TYPE 7500) FN(SR970)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP 65	156891	891	PU(TYPE 3260) PC(TYPE 7500) P(RT43) FN(SR970)	
Savin 8075	154670	548	PC(TYPE 7500) P(RT43) FN(SR970)	
Ricoh AFICIO MP 75	155522	885	PS(TYPE 7500) PC(TYPE 7500) P(RT43) FN(SR970) FAX(TYPE 7500)	
Savin 8075	156584	750	PC(TYPE 7500) P(RT43) FN(SR970)	
Ricoh AFICIO MP 75	156898	483	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Cracked finisher tray
Ricoh AFICIO MP 75	157211	543	PC(TYPE 7500)	Missing finisher & paper deck (has brackets & mounting studs)
Ricoh AFICIO MP 75	157216	766	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	
Lanier LD425C	141463	176	ST() FN(SR790) E(BN3000)	Machine ran fine and completed all tests, now touch screen is frozen; Color = 34k; B/W = 142k
Ricoh AFICIO MP C2	144361	277	PED(PB3000)	Gouge in back panel; black meter = 209k; color meter = 68k
Lanier LD425C	144926	193	PED(PB3000) FN(SR790) E(BN3000)	Broken plastic anti-tip foot broken on front of machine; Color = 50k; B/W = 143k
Ricoh AFICIO MP C2	145005	236	ST()	Color = 11k; B/W = 226k
Ricoh AFICIO MP C2	145006	232	ST() E(BN3000)	Color = 7k; B/W = 226k
Lanier LD425C	146030	319	ST() FN(SR790) FAX(TYPE MPC3000)	Machine ran fine and completed all tests, now touch screen is frozen; Color = 222k; B/W = 97k
Ricoh AFICIO MP C2	146138	136	ST() FN(SR3010) FAX(TYPE MPC3000)	No fax button on control panel (has ports and shows up in user tools and prints a journal); color = 3k; B/W = 134k
Savin C2525	147047	204	ST()	Color = 119k; B/W = 86k
Lanier LD425C	147946	182	ST() FAX(TYPE MPC3000) E(BN3000)	Color = 8k; B/W = 175k
Ricoh AFICIO MP C2	147993	467	PED(PB3000) FN(SR790)	Missing all toner cartridges- tested with others; Color = 314k; B/W = 153k
Ricoh AFICIO MP C2	148846	163	ST() E(BN3000)	Error code SC491 (high voltage problem); cracked front door; cracked back left panel; color = 65k; B/W =
Ricoh AFICIO MP C2	148891	376	PED(PB3010) FAX(TYPE MPC3000) E(BN3000)	Cracked & scratched lower back panel; missing all toner cartridges- tested with others; color = 21k; B/W= 355k
Ricoh AFICIO MP C2	148957	241	ST() FAX(TYPE MPC3000) E(BN3000)	Machine ran fine and completed all tests, now touch screen is frozen;

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				Color = 28k; B/W = 213k
Ricoh AFICIO MP C2	148977	200 ST()	FAX(TYPE MPC3000) E(BN3000)	Color = 39k; B/W = 161k
Ricoh AFICIO MP C2	149690	295 ST()	FN(SR790) FAX(TYPE MPC3000)	Color = 66k; B/W = 230k
Savin C2525	149790	524 ST()		Ran in SP mode- unable to clear user login & password (unable to run reports); color registration is way off; color = 236k; B/W = 288k
Savin C2525	149795	390 PED(PB3000)		Ran in SP mode- unable to bypass user login (unable to clear doc server or run reports); registration off on copies; machine will not detect bypass- inop
Savin C2525	149801	250 PED(PB3000) FN(SR790)	FAX(TYPE MPC3000)	Color = 50k; B/W = 200k
Savin C2525	150651	171 ST()	FN(SR3010)	Finisher missing exit section & tray causing a false jam code J168; color = 29k; B/W = 143k; Machine ran fine, now touch screen will not respond
Ricoh AFICIO MP C2	150908	187 PED(PB3000) FN(SR3010)		Color = 41k; B/W = 146k
Ricoh AFICIO MP C2	151420	239 PED(PB3000) FN(SR790)	FAX(TYPE MPC3000)	Scratched back inside finisher panel; color = 34k; B/W = 206k
Lanier LD425C	151454	213 ST()	FN(SR790)	Color = 14k; B/W = 200k
Ricoh AFICIO MP C2	151586	271 PED(PB3000) FN(SR790)	FAX(TYPE MPC3000)	Color = 10k; B/W = 261k
Ricoh AFICIO MP C2	151607	151 ST()		Color = 47k; B/W = 105k
Ricoh AFICIO MP C2	151608	168 ST()	PED(PB3010)	Broken & cracked inner duplex reversing tray; color = 19k; B/W = 150k
Ricoh AFICIO MP C2	151609	97 ST()	FN(SR3010)	
Savin C2525	151662	295 ST()	FAX(TYPE MPC3000) E(BN3000)	Color = 144k; B/W = 151k
Ricoh AFICIO MP C2	152490	471 ST()	FAX(TYPE MPC3000)	Color = 59k; B/W = 413k
Ricoh AFICIO MP C2	152580	428 ST()		Color = 363k; B/W = 66k
Ricoh AFICIO MP C2	152589	300 ST()	FAX(TYPE MPC3000)	Color = 107k; B/W = 194k
Ricoh AFICIO MP C2	152831	139 PED(PB3000) FAX(TYPE MPC3000)	E(BN3000)	Color = 48k; B/W = 91k
Ricoh AFICIO MP C2	152937	157 ST()	PS(TYPE C3000) FN(SR790) FAX(TYPE MPC3000)	Color = 70k; B/W = 87k
Ricoh AFICIO MP C2	153901	85 ST()		Color = 23k; B/W = 62k
Ricoh AFICIO MP C2	153902	162 ST()		Touch screen is frozen- cannot fully test machine; color = 41k; B/W = 122k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C2525	154322	N/A	SS(SH3000) PED(PB3000)	Color = 54k; B/W = 164k
Lanier LD425C	154683	N/A	ST() FN(SR3010) FAX(TYPE MPC3000) E(BN3000)	Touch screen inoperable- cannot fully test machine
Ricoh AFICIO MP C2	154901	267	ST() SS(SH3000) FAX(TYPE MPC3000) E(BN3000)	Dirty panels inside & out; color = 114k; B/W = 153k
Ricoh AFICIO MP C2	156605	111	ST() FAX(TYPE MPC3000)	Color = 40k; B/W = 71k
Ricoh AFICIO MP C2	156606	465	ST() FAX(TYPE MPC3000)	Color = 187k; B/W = 279k
Lanier LD425C	156959	465	ST() PED(PB3010) FAX(TYPE MPC3000)	Color = 226k; B/W = 239k
Savin C2525	156968	N/A	ST() FN(SR3010) FAX(TYPE MPC3000)	Touch screen inoperable- cannot fully test machine; missing finisher tray
Ricoh AFICIO MP C2	157238	338	PED(PB3000) E(BN3000)	Deep scratch in back panel; color = 7k; B/W = 331k
Ricoh AFICIO MP C2	157259	195	ST() FAX(TYPE MPC3000) E(BN3000)	Missing black toner cartridge- tested with another; color = 35k; B/W = 161k
Ricoh AFICIO MP C3	146116	195	PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Machine ran fine and completed all tests, now touch screen is frozen; Color = 14k; B/W = 182k
Gestetner DSC530	148400	426	PED(PB3000) FN(SR790)	Color = 272k; B/W = 154k
Ricoh AFICIO MP C3	149340	188	PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Black meter = 42k; color meter = 146k
Ricoh AFICIO MP C3	149712	417	PED(PB3000) FN(SR3010)	Machine ran fine and completed all tests, now touch screen is frozen; Color = 137k; B/W = 280k
Savin C3030	149791	536	PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Machine ran fine and completed all tests, now touch screen is frozen; Color = 59k; B/W = 477k
Ricoh AFICIO MP C3	149819	214	ST() FN(SR790) FAX(TYPE MPC3000)	Broken bypass tray; color = 35k; B/W = 180k
Savin C3030	150538	222	PED(PB3000) FN(SR3000) FAX(TYPE MPC3000) E(BN3000)	Missing all toner cartridges- tested with others; color = 118k; B/W = 105k
Ricoh AFICIO MP C3	150755	139	SS(SH3000) PED(PB3000)	Has Fiery E-3000 external controller; ran in SP mode- unable to clear user password; registration off on color copies; color = 123k; B/W = 17k
Gestetner DSC530	150824	393	ST() FN(SR3000)	
Gestetner DSC530	151411	342	PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Finisher jamming at R5 when in staple mode; color = 55k; B/W = 288k
Ricoh AFICIO MP C3	151832	206	PED(PB3000) FN(SR790) E(BN3000)	Cracked back upper left side panel; color = 53k; B/W = 154k
Ricoh AFICIO MP C3	151850	665	ST()	Color = 248k; B/W = 417k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C3	152092	274	PED(PB3000) FN(SR790)	Color = 60k; B/W = 213k
Ricoh AFICIO MP C3	152997	385	PED(PB3010) FN(SR3010) FAX(TYPE MPC3000) E(BN3000)	Color = 113k; B/W = 273k
Ricoh AFICIO MP C3	153607	224	PED(PB3000)	Color = 66k; B/W = 158k
Ricoh AFICIO MP C3	153658	795	PED(PB3000) FN(SR790) E(BN3000)	Color = 234k; B/W = 561k
Ricoh AFICIO MP C3	154332	408	PED(PB3000) FN(SR790) E(BN3000)	Top finisher access door will not stay closed causing occasional jams; color =121k; B/W = 287k; cracked lower front right access door
Ricoh AFICIO MP C3	156078	217	PS(TYPE C3000) PED(PB3000) FAX(TYPE MPC3000)	Color = 115k; B/W = 102k
Lanier LD430C	156961	427	ST() FAX(TYPE MPC3000) E(BN3000)	Color = 79k; B/W = 349k
Ricoh AFICIO MP C3	157237	90	PED(PB3000) FN(SR790)	Touch screen not functioning properly- sluggish; cracked finisher tray; top finisher access door will not stay closed; paper jams from all paper sources when trying to staple; color = 15k; B/W = 76k
Ricoh AFICIO MP C3	147402	534	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Color = 137k; B/W = 398k
Ricoh AFICIO MP C3	147407	383	ST()	Machine ran fine, now touch screen will not respond; Color = 28k; B/W = 356k
Ricoh AFICIO MP C3	148845	313	PED(PB3000)	Machine will not come to ready (continuous warmup)- can't test; color = 300k; B/W = 13k
Savin C3535	148965	419	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Machine ran fine and completed all tests, now touch screen is frozen; Color = 27k; B/W = 393k
Ricoh AFICIO MP C3	149326	442	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Black meter = 377k; color meter = 65k
Lanier LD435C	150520	338	PED(PB3000) FN(SR790)	Color = 33k; B/W = 305k
Lanier LD435C	150686	222	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500) E(BN3010)	Color = 19k; B/W = 204k
Ricoh AFICIO MP C3	150906	186	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Color = 54k; B/W = 132k
Ricoh AFICIO MP C3	150907	308	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Missing rear side paper guide on bypass tray; Color = 119k; B/W =
Ricoh AFICIO MP C3	151104	156	ST()	Black meter = 231k; color meter = 132k
Ricoh AFICIO MP C3	151610	316	ST() FN(SR790)	Color = 59k; B/W = 257k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C3	152087	232	PS(TYPE C4500) PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Color = 137k; B/W = 95k
Ricoh AFICIO MP C3	152192	463	PS(TYPE C4500) PED(PB3000) FAX(TYPE MPC4500)	Missing finisher (has brackets); color = 168k; B/W = 296k
Ricoh AFICIO MP C3	152394	363	PED(PB3000) FN(SR790)	Error code SC-547 (zero cross error-fuser unit); color = 121k; B/W = 243k
Savin C3535	152681	472	PU(PU3000) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Color = 274k; B/W = 198k
Ricoh AFICIO MP C3	152833	172	PED(PB3010) FAX(TYPE MPC4500) E(BN3010)	Broken RADF plug socket; color = 8k; B/W = 165k
Savin C3535	153175	391	PU(PU3000) PS(TYPE C4500) PED(PB3000) FN(SR3030)	Color = 286k; B/W = 105k
Gestetner DSC535	153196	248	PED(PB3000) FN(SR790)	Color = 110k; B/W = 139k
Ricoh AFICIO MP C3	153313	615	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Color = 153k; B/W = 463k
Ricoh AFICIO MP C3	153546	98	ST() FAX(TYPE MPC4500)	Color = 35k; B/W = 63k
Ricoh AFICIO MP C3	153591	197	PED(PB3000) FN(SR790)	Has E-5000 external fiery controller; color = 142k; B/W = 56k
Lanier LD435C	153748	181	PED(PB3000) FN(SR790)	Broken P3 plate in RADF causing it to jam when duplexing; color = 102k; B/W = 80k
Ricoh AFICIO MP C3	153833	N/A	ST() FAX(TYPE MPC4500)	Touch screen inoperable- can't test
Ricoh AFICIO MP C3	153890	373	ST() FN(SR790)	Color = 41k; B/W = 332k
Ricoh AFICIO MP C3	154914	445	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500) E(BN3010)	Punch unit jams; big scratch on left side panel; color = 228k; B/W = 217k
Ricoh AFICIO MP C3	155490	447	PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Punch unit jams- inop; color = 163k; B/W = 284k
Ricoh AFICIO MP C3	155495	416	PS(TYPE C4500) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500) E(BN3010)	Punch unit jams- inop; color = 75k; B/W = 341k
Savin C3535	155684	209	PU(PU3000) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500) E(BN3010)	Punch & stapler jams at R2-R5; color = 148k; B/W = 62k
Ricoh AFICIO MP C3	155762	N/A	FAX(TYPE MPC4500)	Touch screen inoperable- cannot test machine
Ricoh AFICIO MP C3	156269	238	ST() FN(SR790)	Duplex jams; color = 35k; B/W = 203k
Savin C3535	156874	276	ST() FN(SR790)	Color = 2k; B/W = 275k
Ricoh AFICIO MP C3	157018	N/A	ST()	Touch screen inoperable- cannot fully test machine

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO MP C3	157312	162	PU(TYPE 3260) PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Color = 26k; B/W = 137k
Ricoh AFICIO MP C3	157326	259	ST()	Color = 21k; B/W = 239k
Lanier LD435C	157388	216	ST() PU(PU3000) FN(SR3030)	Punch & staple jam every try; color = 52k; B/W = 165k
Lanier LD435C	157389	142	ST() PU(PU3000) FN(SR3030)	Color = 69k; B/W = 74k
Savin C4540	145784	391	PU(PU3000) PED(PB3000) FN(SR3020)	Machine ran fine and completed all tests, now touch screen is frozen; Punch unit jams- inop; color = 104k; B/W = 288k
Ricoh AFICIO MP C4	150348	382	PS(TYPE C4500) PED(PB3010) FN(SR3030)	Machine ran fine and completed all tests, now touch screen is frozen; Color = 172k; B/W = 211k
Lanier LD445C	150506	177	PS(TYPE C4500) PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	
Gestetner DSC545	150524	395	PED(PB3000) FN(SR3020)	Has E-5000 external Fiery controller; color = 225k; B/W = 170k
Ricoh AFICIO MP C4	150718	255	PS(TYPE C4500) PED(PB3010) FN(SR3030)	Color = 117k; B/W = 138k
Ricoh AFICIO MP C4	151194	269	PS(TYPE C4500) PED(PB3010) FN(SR3020) FAX(TYPE MPC4500)	Ran OK, but throws error code SC533 (IJ inverter fan or toner supply tube fan) when turned on due to broken fan housing and broken wire inside back panel; cracked & broken right back corner panels under RADF; unable to test punch or print reports due to code; color = 181k; B/W = 89k
Ricoh AFICIO MP C4	151787	529	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Color = 80k; B/W = 450k
Ricoh AFICIO MP C4	151906	247	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500) E(BN3010)	Color = 76k; B/W = 172k
Lanier LD445C	151959	562	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Color = 94k; B/W = 468k
Ricoh AFICIO MP C4	152025	483	PED(PB3000) FN(SR3020)	Color = 215k; B/W = 269k
Lanier LD445C	152447	333	PU(PU3000) PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Has Copy Data Security unit; punch unit causes jams; color = 104k; B/W = 230k
Ricoh AFICIO MP C4	152603	1261	PED(PB3000) FN(SR3020) FAX(TYPE MPC4500)	Color = 380k; B/W = 881k
Ricoh AFICIO MP C4	152610	473	PED(PB3000) FN(SR3020)	Stapler jams; color = 445k; B/W = 28k
Ricoh AFICIO MP C4	152936	269	ST() FAX(TYPE MPC4500)	Color = 9k; B/W = 260k
Ricoh AFICIO MP C4	153236	272	PS(TYPE C4500) PED(PB3000)	Color = 240k; B/W = 33k; unable to clear user access code- ran in SP

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				mode only
Lanier LD445C	153717	357	PED(PB3000) FN(SR790)	Color = 112k; B/W = 245k
Ricoh AFICIO MP C4	153782	232	PED(PB3000) FN(SR790)	Finisher trays out of alignment causing error code SC750 (lift tray motor); missing right side upper panel; color = 24k; B/W = 208k
Ricoh AFICIO MP C4	154233	334	PED(PB3000)	Color = 39k; B/W = 295k
Savin C4540	154673	185	PS(TYPE C4500) PED(PB3000) FN(SR3020)	Color = 125k; B/W = 61k
Gestetner DSC545	156645	436	PED(PB3000) FN(SR790)	Color = 142k; B/W = 294k
Gestetner DSC545	157203	N/A	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500)	Touch screen inoperable- cannot test machine; finisher in error code SC529 (function gate #1 motor sensor) due to missing entrance guide
Ricoh AFICIO MP C4	157209	N/A	PED(PB3000) FAX(TYPE MPC4500) E(BN3010)	Touch screen not operating properly- cannot fully test machine
Ricoh AFICIO MP C4	157222	N/A	PU(TYPE 3260) PED(PB3010) FN(SR3020)	Touch screen inoperable- unable to fully test machine; missing lower finisher tray
Savin SLP38CS	109534	291	RADF(DF73) PU(TYPE 1045) FN(SR770) FAX(TYPE 3800C)	Color = 116k; B/W = 176k
Ricoh AP3800CMF	117212	567	RADF(DF73) FN(SR770)	Yellowed panels; color = 201k; B/W = 366k
Ricoh CL7000CMF	148341	672	PU(TYPE 1045) FN(SR770) E()	Cracked front door; broken front door interlock actuator; offcolor panels; color = 84k; B/W = 589k
Ricoh CL7000CMF	150798	1339	PU(TYPE 1045) FN(SR770) E()	Offcolor panels; color = 1031k; B/W = 308k
Savin CLP28S	156012	N/A	FAX(TYPE 3800C) E()	Machine powers up, but no response- can't test; offcolor panels
Ricoh AFICIO 3131	150502	212	RADF(DF81) PU(TYPE 3131) PC(E-750) FN(SR930) DX(AD470) C[1](PS570)	Color = 29k; B/W = 184k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.