

# Wulff Enterprises

01/07/2009

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 1013	104897	78		Left side of platen cover missing
Ricoh AFICIO 1013	104899	66		Yellow panels
Ricoh AFICIO 1013	104900	94		Platen cover broken
Savin 2513	113696	80	ADF(DF74)	Loud clicking noise when copying
Gestetner 1302	117312	95		Yellowed panels
Gestetner 1302	117313	154		Jams frame cassette- ran through bypass only
Gestetner 1302	117317	136		Missing pin & drive sprocket on cassette feed shaft- tested with another
Ricoh AFICIO 1013	119574	121	ADF(DF74)	
Savin 2513	120829	84	ADF(DF74)	Broken ADF hinges
Ricoh AFICIO 1013	122596	103	ADF(DF74)	Broken ADF tray; offcolored panels
Lanier 5613	123518	85		Broken latch on platen top front left
Lanier 5613	123528	58		Broken bypass tray
Lanier 5613F	116048	109	PS(TYPE 1018) PC(TYPE 1013) NIC(TYPE 1013)	
Ricoh AFICIO 1013F	117026	113		Toner spilled throughout machine
Ricoh AFICIO 1013F	118262	151	PC(TYPE 1013)	
Ricoh AFICIO 1013F	118263	146	PC(TYPE 1013) NIC(TYPE 1013)	
Gestetner 1302F	119168	187		
Ricoh AFICIO 1013F	119195	105		
Ricoh AFICIO 1013F	119196	190	ST() PC(TYPE 1013) NIC(TYPE 1013)	
Ricoh AFICIO 1013F	119198	41		Dirty & yellowed panels
Gestetner 1302F	121261	92		
Ricoh AFICIO 1013F	121690	177	ST() PFU(PS480)	
Ricoh AFICIO 1013F	122262	168	PC(TYPE 1013)	Dirty & offcolored panels
Lanier 5613F	123519	117		
Lanier 5613F	123520	136		Broken ADF tray hook
Lanier 5613F	123521	181	PC(TYPE 1013) NIC(TYPE 1013)	Broken ADF tray
Lanier 5613F	123522	170	PC(TYPE 1013) NIC(TYPE 1013)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier 5613F	123523	64	PC(TYPE 1013) NIC(TYPE 1013)	
Lanier 5613F	123524	101	PC(TYPE 1013) NIC(TYPE 1013)	Broken ADF tray
Lanier 5613F	123525	169	PC(TYPE 1013) NIC(TYPE 1013)	
Lanier 5613F	123526	130	PC(TYPE 1013) NIC(TYPE 1013)	
Lanier 5613F	123527	225	PC(TYPE 1013) NIC(TYPE 1013)	
Lanier 5613F	123529	411		
Lanier 5613F	123530	122	PC(TYPE 1013) NIC(TYPE 1013)	
Lanier 5613F	123594	279	PC(TYPE 1013) NIC(TYPE 1013)	Broken ADF tray hook
Lanier 5613F	123595	75	PFU(PS480) PC(TYPE 1013) NIC(TYPE 1013)	
Lanier 5613F	123596	88		Broken ADF tray hook
Lanier 5613F	123597	49	PC(TYPE 1013) NIC(TYPE 1013)	Broken ADF tray hook
Lanier 5613F	123598	35	PC(TYPE 1013) NIC(TYPE 1013)	
Lanier 5613F	123599	96	PC(TYPE 1013) NIC(TYPE 1013)	Broken ADF tray hook
Lanier 5613F	123603	27		
Lanier 5613F	123689	295	PC(TYPE 1013) NIC(TYPE 1013)	Broken ADF tray hook
Ricoh AFICIO 1015	117729	227		Dirty panels
Ricoh AFICIO 1015	119199	38	ST() RADF(DF72)	Dirty & offcolored panels
Ricoh AFICIO 1015	119200	126	ST() RADF(DF72)	Offcolored & dirty panels
Savin 2515	119277	97	RADF(DF72)	Has a DF78 RADF (works OK); yellowed RADF panels
Savin 2515	119992	215	ST() RADF(DF72) PFU(PS460) PC(TYPE 1018) NIC(TYPE 1018) FAX(TYPE 1018)	Dirty & yellowed panels; broken top paper tray handle
Savin 2515	120161	121	ST() RADF(DF72)	
Ricoh AFICIO 1015	120787	92	RADF(DF72)	
Ricoh AFICIO 1015	122313	100	ST()	Yellowed panels
Ricoh AFICIO 1015	122321	262	ST()	Serial number partly missing; original doc holder missing
Ricoh AFICIO 1015	123044	122	ST()	Broken bypass tray

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier 5515	123761	238	RADF(DF72) PC(TYPE 1018) NIC(TYPE 1018) FAX(TYPE 1018)	Broken paper tray handle
Ricoh AFICIO 1018	116859	69	ST() RADF(DF72)	
Ricoh AFICIO 1018	117655	253	ST() RADF(DF72)	
Ricoh AFICIO 1018	118358	56	ST() RADF(DF72)	
Savin 2518	118545	105	ST() RADF(DF72)	
Savin 2518	118557	52	ST() RADF(DF72)	
Savin 2518	118558	101	ST() RADF(DF72) PC(TYPE 1018) NIC(TYPE 1018)	
Ricoh AFICIO 1018	119575	157	ST() RADF(DF72)	Yellowed panels
Ricoh AFICIO 1018	121004	168	ST() RADF(DF72)	
Ricoh AFICIO 1018	121005	130	ST() RADF(DF72) FAX(TYPE 1018)	
Gestetner 1802	121258	391	RADF(DF72)	
Gestetner 1802	121259	198	ST() RADF(DF72)	Cassette handle cracked; fax knockout missing
Savin 2518	121746	217	ST() RADF(DF72)	Offcolored & dirty panels; broken paper guide in tray #1
Savin 2518	121747	339	ST() RADF(DF72)	Broken paper tray handles; yellowed & dirty panels
Savin 2518	122079	124	ST() RADF(DF72) PFU(PS460)	Yellowed panels; missing front name plate
Gestetner 1802	124629	93	ST() RADF(DF72)	
Savin 2518D	115367	137	ST() RADF(DF71) PFU(PS460) PC(TYPE 1018) NIC(TYPE 1018)	Yellowed panels
Ricoh AFICIO 1018D	116219	147	ST() RADF(DF71) FAX(TYPE 1018)	
Lanier 5618	117268	99	ST() RADF(DF71) PFU(PS460)	Yellowed panels
Gestetner 1802D	117314	44	ST() RADF(DF71) FAX(TYPE 1018)	Top tray paper sensor broken loose; needs toner (unable to test all functions)
Gestetner 1802D	117537	256	ST() RADF(DF71)	
Ricoh AFICIO 1018D	117643	129	ST() RADF(DF71)	
Ricoh AFICIO 1018D	119072	178	ST() RADF(DF71) PC(TYPE 1018) NIC(TYPE 1018) FAX(TYPE 1018)	
Ricoh AFICIO 1018D	119202	101	ST() RADF(DF71)	
Gestetner 1802D	119253	71	ST() RADF(DF71) PFU(PS450)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2518D	120162	226	ST() RADF(DF71)	
Savin 2518D	120199	282	ST() RADF(DF71)	Yellowed panels
Savin 2518D	120200	159	ST() RADF(DF71) PFU(PS460)	Duplex jams; yellowed panels
Savin 2518D	120201	239	ST() RADF(DF71)	Duplex unit & transfer section will not latch properly causing jams; yellowed panels
Savin 2518D	120340	173	ST() RADF(DF71)	
Savin 2518D	120682	134	ST() RADF(DF71) PC(TYPE 1018) FAX(TYPE	Needs toner- unable to finish testing
Ricoh AFICIO 1018D	121006	130	ST() RADF(DF71)	
Ricoh AFICIO 1018D	121007	435	ST() RADF(DF71) FAX(TYPE 1018)	Cracked paper tray #1 handle
Gestetner 1802D	121257	141	RADF(DF71) PC(TYPE 1018) NIC(TYPE 1018)	Right side panel broken
Ricoh AFICIO 1018D	121889	401	RADF(DF71)	Yellowed panels
Ricoh AFICIO 1018D	122621	149	ST() RADF(DF71)	Yellowed panels
Ricoh AFICIO 1018D	123096	116	ST() RADF(DF71)	
Ricoh AFICIO 1018D	123655	193	ST() RADF(DF71)	Yellowed panels
Ricoh AFICIO 1018D	123656	92	ST() RADF(DF71)	
Lanier 5618	123690	380	ST() RADF(DF71) PS(TYPE 1018) PC(TYPE 1018) NIC(TYPE 1018)	
Lanier 5618	123771	186	ST() RADF(DF71) FAX(TYPE 1018)	
Lanier 5618	123772	261	ST() RADF(DF71) PC(TYPE 1018) NIC(TYPE 1018) FAX(TYPE 1018)	
Ricoh AFICIO 1018D	123959	95	ST() RADF(DF71)	
Savin 2518D	124711	103	ST() RADF(DF71) FAX(TYPE 1018)	
Savin 2522	120189	141	ST() SS(TYPE 1027) RADF(DF75) DX(AD420) B(TYPE 1027)	Ripped platen mat
Savin 2522	120190	121	ST() SS(TYPE 1027) RADF(DF75) DX(AD420)	
Ricoh AFICIO 1022	120931	432	ST() SS(TYPE 1027) RADF(DF75) DX(AD420) B(TYPE 1027)	Missing front duplex cover panel; bypass tray broken off; duplex jams
Ricoh AFICIO 1022	120958	179	ST() RADF(DF75) DX(AD420)	
Ricoh AFICIO 1022	121008	493	ST() RADF(DF75) FN(SR790) FAX(TYPE 1027) DX(AD420) B(TYPE	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			1027)	
Ricoh AFICIO 1022	121035	68	ST() SS(TYPE 1027) RADF(DF75)	Offcolored panels
Savin 2522	121318	226	ST() RADF(DF75) FN(SR790) DX(AD420) B(TYPE 1027)	
Ricoh AFICIO 1022	121684	296	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	Broken bypass tray
Ricoh AFICIO 1022	122155	409	ST() RADF(DF75) B(TYPE 1027)	
Savin 2522	122417	502	ST() SS(TYPE 1027) RADF(DF75) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	Yellowed panels
Savin 2522	122418	385	ST() SS(TYPE 1027) RADF(DF75) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	Broken bypass tray
Savin 2522	122423	153	RADF(DF75) FN(SR820)	Missing stand
Ricoh AFICIO 1022	122622	176	ST() RADF(DF75) FN(SR820) DX(AD420)	Yellowed panels
Savin 2522	123004	144	ST() SS(TYPE 1027) RADF(DF75) DX(AD420) B(TYPE 1027)	Broken bypass tray
Ricoh AFICIO 1022	123098	178	ST() RADF(DF75) FN(SR820) DX(AD420)	Yellowed panels
Ricoh AFICIO 1022	123335	32	RADF(DF75) PED(PS490) PC(TYPE 1027[S]) NIC(TYPE 1027) DX(AD420) B(TYPE 1027)	
Ricoh AFICIO 1022	123336	227	RADF(DF75) PED(PS490) PC(TYPE 1027[S]) NIC(TYPE 1027) DX(AD420) B(TYPE 1027)	
Lanier 5622	123684	351	ST() RADF(DF75) FN(SR820) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	
Lanier 5622	123685	260	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	
Lanier 5622	123762	579	ST() RADF(DF75) PC(TYPE 1027[S]) FN(SR820) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	Broken bypass tray; broken finisher paper guides
Lanier 5622	123763	432	ST() RADF(DF75) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE	Broken bypass tray

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier 5622	123765	613	ST() RADF(DF75) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	Broken bypass tray
Lanier 5622	124084	212	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	Duplex jams
Lanier 5622	124355	136	ST() RADF(DF75) FAX(TYPE 1027) DX(AD420) B(TYPE 1027)	Bypass tray broken off & wiring damaged
Ricoh AFICIO 1027	121012	355	ST() RADF(DF75) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	
Ricoh AFICIO 1027	121549	290	ST() RADF(DF75) FN(SR790) DX(AD420) B(TYPE 1027)	Yellowed panels; broken bypass hinge
Gestetner 2712	122308	197	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	Tray #2 will not detect paper & tray #1 jams every copy (unable to test); has wrong finisher (SR830); broken RADF plug socket; broken bypass tray & panel; broken right side panel
Gestetner 2712	122617	501	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	
Ricoh AFICIO 1027	123371	203	RADF(DF75) PED(PS490) FN(SR790) DX(AD420) B(TYPE 1027)	Broken bypass tray
Lanier 5627	123582	698	ST() RADF(DF75) FN(SR820) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	Broken bypass tray
Savin 2527	124174	337	SS(TYPE 1027) RADF(DF75) PED(PS490) PC(TYPE 1027[S]) NIC(TYPE 1027) DX(AD420) B(TYPE 1027)	
Ricoh AFICIO 1027	124307	402	RADF(DF75) PED(PS490) PC(TYPE 1027[S]) NIC(TYPE 1027) FN(SR790) E(TYPE 1027) DX(AD420)	Broken top finisher access door; broken back paper guide in top paper tray
Lanier 5627	124955	586	ST() RADF(DF75) PC(TYPE 1027[S]) NIC(TYPE 1027) FN(SR820) FAX(TYPE 1027) E(TYPE 1027)	Broken bypass tray
Lanier 5627	124956	273	ST() RADF(DF75) PC(TYPE 1027[S]) NIC(TYPE 1027) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			1027)	
Lanier 5627	124959	830	ST() RADF(DF75) PC(TYPE 1027[S]) NIC(TYPE 1027) FN(SR820) FAX(TYPE 1027) E(TYPE 1027)	Broken bypass tray; blurred copies
Lanier 5627	124961	635	ST() RADF(DF75) PC(TYPE 1027[S]) NIC(TYPE 1027) FN(SR820) FAX(TYPE 1027) E(TYPE 1027)	
Lanier 5635	118779	808	RADF(DF70) PED(PS360) FN(SR720) FAX(TYPE 1045)	Broken lower finisher tray & broken bridge unit jam access door- unable to test finisher; yellowed & dirty panels
Ricoh AFICIO 1035	118928	513	ST() RADF(DF70) FN(SR720)	Finisher grinds & jams- inop
Ricoh AFICIO 1035	119559	973	ST() RADF(DF70) PU(TYPE 1045) FN(SR760)	
Ricoh AFICIO 1035	119970	647	RADF(DF70) PED(PS360) FN(SR720)	Offcolored panels
Savin 2535	120164	734	RADF(DF70) PED(PS360) FN(SR720)	Broken bypass tray
Savin 2535	120165	585	RADF(DF70) PED(PS360) FN(SR720)	Yellowed panels
Savin 2535	120166	859	RADF(DF70) PED(PS360) FN(SR720)	
Savin 2535	120167	545	RADF(DF70) PED(PS360) FN(SR720)	
Savin 2535	120168	1419	RADF(DF70) PED(PS360) FN(SR720)	Yellowed panels
Savin 2535	120169	1196	RADF(DF70) PED(PS360) FN(SR720)	Offcolored panels
Savin 2535	120170	755	RADF(DF70) PED(PS360) FN(SR720)	
Gestetner 3502	120814	710	ST() RADF(DF70) FAX(TYPE 1045) E(PT1045)	
Ricoh AFICIO 1035	120922	545	RADF(DF70) PU(TYPE 1045) PED(PS360) P(RT36) FN(SR760)	
Ricoh AFICIO 1035	121010	570	ST() RADF(DF70) FN(SR720)	
Ricoh AFICIO 1035	121074	223	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720) FAX(TYPE 1045)	Bypass tray broken off

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner 3502	121672	390	ST() RADF(DF70) FN(SR720)	
Ricoh AFICIO 1035	122623	406	ST() RADF(DF70) P(RT36) FN(SR720) FAX(TYPE 1045) E(PT1045)	Error code SC670 (BICU error); offcolored panels
Savin 2535	122852	256	RADF(DF70) PU(TYPE 1045) PED(PS360) PC(TYPE 1045) P(RT36) NIC(TYPE 1045) FN(SR760)	Noisy machine when copying
Ricoh AFICIO 1035	123913	222	ST() RADF(DF70) PC(TYPE 1045) P(RT36) NIC(TYPE 1045)	Offcolored panels
Savin 2535	124132	465	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FAX(TYPE 1045)	
Savin 2535	124136	467	ST() RADF(DF70) PC(TYPE 1045[S]) NIC(TYPE 1045)	
Lanier 5635	124515	348	RADF(DF70) PED(PS360) FN(SR720)	
Lanier 5635	124517	747	ST() RADF(DF70) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720) FAX(TYPE	
Ricoh AFICIO 1035	124674	579	RADF(DF70) PU(TYPE 1045) PED(PS360) FN(SR760)	Runs OK, but goes into error code SC350 (ID sensor) at times
Ricoh AFICIO 1035	124896	554	ST() RADF(DF70) PS(TYPE 1045) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720)	Yellowed & dirty panels
Lanier 5645	120364	516	ST() RADF(DF70) FN(SR720)	
Ricoh AFICIO 1045	121888	386	RADF(DF70) PED(PS360) PC(TYPE 1045) NIC(TYPE 1045) E(PT450)	Yellowed panels
Savin 2545	122939	966	RADF(DF70) PED(PS360) PC(TYPE 1045) P(RT36) NIC(TYPE 1045) FN(SR720)	Offcolored & dirty panels; cracked paper tray #4 panel & lower right side trim panel
Savin 2545	123131	833	RADF(DF70) PED(PS360) PC(TYPE 1045) P(RT36) NIC(TYPE 1045) FN(SR720)	
Ricoh AFICIO 1045	123660	852	STK(CS360) RADF(DF70) PU(TYPE 1045) PED(PS360) PC(TYPE	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			1045[S] P(RT36) NIC(TYPE 1045) FN(SR760)	
Ricoh AFICIO 1045	123740	770	RADF(DF70) PED(PS360) FAX(TYPE 1045) E(PT1045)	
Lanier 5645	124073	1036	ST() RADF(DF70) PC(TYPE 1045[S]) P(RT36) NIC(TYPE 1045)	Offcolored & dirty panels
Savin 2545	124134	712	ST() RADF(DF70) PC(TYPE 1045) NIC(TYPE 1045) FAX(TYPE 1045)	Missing transfer belt section causing error code SC402; also error code SC501 (tray #1 lift problem); yellowed panels
Ricoh AFICIO 1060	121984	315	PU(TYPE 1075) PC(TYPE 1075[S]) P(RT43) FN(SR850)	
Savin 2560	123304	824	PU(TYPE 1075) PC(TYPE 1075[S]) P(RT43) FN(SR850)	
Savin 2560	123305	942	PU(TYPE 1075) PC(TYPE 1075[S]) P(RT43) FN(SR850)	
Ricoh AFICIO 1060	123340	523	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	
Ricoh AFICIO 1060	124461	976	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Broken RADF plug socket
Ricoh AFICIO 1060	124576	830	PU(TYPE 1075) FN(SR850)	
Ricoh AFICIO 1060	124891	593	FN(SR850)	
Ricoh AFICIO 1075	122171	839	PU(TYPE 1075) PC(TYPE 1075[S]) P(RT43) FN(SR850)	
Savin 2575	123630	881	PU(TYPE 1075) FN(SR850)	
Ricoh AFICIO 1075	124918	1327	PU(TYPE 1075) PC(TYPE 1075[S]) P(RT43) FN(SR860)	Has type 1075 inserter unit
Savin 2585	122252	3991	PU(TYPE 850) PC(TYPE 850) NIC(TYPE 450-E) FN(SR810)	Jams alot in sections D & Z; yellowed panels
Lanier 5685	124886	2706	PU(TYPE 850) PC(TYPE 850) NIC(TYPE 450-E) FN(SR810)	
Ricoh AFICIO 1105	123651	9847	PU(TYPE 850) PC(EB-105E) P(RT42) FN(SR85) FN(SR810)	Has CD-RW Type 850 & trimmer unit; unable to fully test as needs toner; dirty & offcolored panels
Ricoh AFICIO 1105	123652	12157	PC(TYPE 850) P(RT42) NIC(TYPE 450-E) FN(SR810)	Has CD-RW type 850; finisher jams frequently

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 1224C	113465	114	ST() RADF(DF75)	Color = 13k; B/W = 101k
Ricoh AFICIO 1224C	115586	217	ST() RADF(DF75) PC(TYPE 1232)	Color = 34k; B/W = 184k
Ricoh AFICIO 1224C	117216	110	ST() RADF(DF75) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232)	Blank copies on upper half of B/W; color = 19k; B/W = 92k
Ricoh AFICIO 1224C	117532	75	ST() RADF(DF75) FAX(TYPE 1232)	Color = 32k; B/W = 43k
Ricoh AFICIO 1224C	117546	65	ST() RADF(DF75) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Broken top finisher access door; upper half of copies are blank; color = 20k; B/W = 45k
Ricoh AFICIO 1224C	117730	656	ST() RADF(DF75) PC(TYPE 1232)	Color = 393k; B/W = 264k
Lanier LD024C	117791	130	ST() SS(TYPE 1232) RADF(DF75) PC(TYPE 1232)	Color = 9k; B/W = 122k
Gestetner DSC224	118712	95	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Black meter =84k; colored meter =12k
Ricoh AFICIO 1224C	119129	156	ST() RADF(DF75) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Color = 18k; B/W = 139k
Ricoh AFICIO 1224C	119800	170	RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232)	Smashed back left corner panel; color = 121k; B/W = 49k
Ricoh AFICIO 1224C	119826	61	RADF(DF75) PED(PS510) PC(TYPE 1232)	Bypass tray broken off; RADF will not detect correct paper size- inop; color = 27k; B/W = 34k
Savin C2408	119872	336	ST() RADF(DF75) PC(TYPE 1232) FN(SR830)	Yellowed panels; color = 159k; B/W = 178k
Savin C2408	120060	253	RADF(DF75) PED(PS520) PC(TYPE 1232)	Color = 219k; B/W = 35k; bypass tray broken off
Savin C2408	120181	292	ST() SS(TYPE 1232) RADF(DF75)	Yellowed panels; broken top paper tray adjusting gear; color = 6k; B/W = 286k
Lanier LD024C	120393	209	ST() SS(TYPE 1232) RADF(DF75) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Yellowed & dirty panels; color = 20k; B/W = 190k; cracked paper tray #1 panel
Ricoh AFICIO 1224C	120484	128	RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Broken slit glass; yellowed panels; color = 29k; B/W = 100k
Savin C2408	120585	131	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Color = 20k; B/W = 112k
Savin C2408	120586	86	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830)	Finisher damaged- tray broken off & tray mount bent (inop); yellowed

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				panels; missing adjusting gear in tray #1; color = 12k; B/W = 74k
Ricoh AFICIO 1224C	120598	152	ST() SS(TYPE 1232) RADF(DF75) PC(TYPE 1232) FAX(TYPE 1232)	Yellowed panels; Color = 26k; B/W = 127k
Ricoh AFICIO 1224C	121312	33	PC(TYPE 1232)	Machine is smashed- total loss
Ricoh AFICIO 1224C	121947	164	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Lower finisher tray out of alignment- inop; yellowed & dirty panels; rear paper guide in tray #2 off track & missing center gear; color = 25k; B/W = 139k
Ricoh AFICIO 1224C	121969	154	ST() RADF(DF75) PC(TYPE 1232)	Black meter = 115; color meter = 40k
Gestetner DSC224	121991	577	RADF(DF75) PED(PS510)	Yellowed and dirty panels; Black meter = 458k; colored meter = 119k
Ricoh AFICIO 1224C	122194	173	ST() RADF(DF75) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232) E(PT290)	Color = 22k; B/W = 151k
Ricoh AFICIO 1224C	122529	49	ST() RADF(DF75)	Dirty & offcolored panels; color = 1k; B/W = 48k
Gestetner DSC224	123000	167	ST() RADF(DF75) PC(TYPE 1232)	Bypass tray broken off; color = 14k; B/W = 153k; blurred color copies; color = 14k; B/W = 153k
Ricoh AFICIO 1224C	123271	161	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790)	Color = 78k; B/W = 83k
Ricoh AFICIO 1224C	124091	167	RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Color = 17k; B/W = 151k
Savin C2408	124722	345	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790)	Color = 339k; B/W = 7k
Savin C2408	124856	197	SS(TYPE 1232) RADF(DF75) PED(PS520) PC(TYPE 1232)	Color = 24k; B/W = 174k
Ricoh AFICIO 1232C	111489	252	RADF(DF75) PED(PS520) PC(TYPE 1232)	1/3 of copies are blank; color = 47k; B/W = 206k
Gestetner DSC232	113493	829	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Yellowed panels
Lanier LD032C	115191	144	ST() RADF(DF75) PC(TYPE 1232)	Color = 20k; B/W = 124k
Gestetner DSC232	115679	280	RADF(DF75) PED(PS510) FN(SR830)	Color = 2k; B/W = 279k
Savin C3210	116802	429	RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232)	Color = 4k; B/W = 425k
Ricoh AFICIO 1232C	118341	79	ST() SS(TYPE 1232) RADF(DF75)	Color = 10k; B/W = 69k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSC232	119192	293	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR830)	Color = 18k; B/W = 275k
Ricoh AFICIO 1232C	119564	248	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR830)	Color = 16k; B/W = 233k
Ricoh AFICIO 1232C	120463	238	RADF(DF75) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232) E(PT290)	Broken paper tray #2 handle; missing fuser oil cover; color = 105k; B/W = 134k
Savin C3210	120561	335	RADF(DF75) PED(PS510)	Bypass tray assembly broken off & missing
Ricoh AFICIO 1232C	120761	232	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232) E(PT290)	Color = 100k; B/W = 133k
Ricoh AFICIO 1232C	120780	549	ST() RADF(DF75) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232)	Broken finisher tray; offcolored panels; void edge on black copies; color = 179k; B/W = 370k
Savin C3210	121277	502	SS(TYPE 1232) RADF(DF75) PED(PS510) PC(TYPE 1232)	Color = 27k; B/W = 476k
Ricoh AFICIO 1232C	121293	97	RADF(DF75) PED(PS510)	Bypass tray broken off; color = 31k; B/W = 66k
Ricoh AFICIO 1232C	121685	258	ST() RADF(DF75) PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	RADF will not duplex
Savin C3210	122547	542	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790)	Color = 127k; B/W = 416k; detached lower right side panel
Savin C3210	122822	398	RADF(DF75) PED(PS510) PC(TYPE 1232) E(PT290)	Yellowed panels; color = 61k; B/W = 338k
Savin C3210	122843	443	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790)	Color = 39k; B/W = 404k
Gestetner DSC232	122978	585	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Color = 69k; B/W = 516k
Gestetner DSC232	123895	420	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232)	Yellowed panels; blurred copies; color = 46k; B/W = 374k
Savin C3210	123967	505	ST() PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Color = 61k; B/W = 445k
Gestetner DSC232	124627	242	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232) E(PT290)	Color = 7k; B/W = 235k
Savin C3210	124855	677	SS(TYPE 1232) RADF(DF75) PED(PS520) PC(TYPE 1232)	Color = 23k; B/W = 654k
Ricoh AFICIO 1515	120986	88	PC(TYPE 1515)	
Savin 3515	121919	156		

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 3515	121920	30		
Ricoh AFICIO 1515	122535	83	PFU(PS480)	Offcolored & dirty panels; missing paper sensor & actuator in top paper tray- inop
Ricoh AFICIO 1515	122536	131	PFU(PS480)	Toner spilled throughout machine causing a false jam code; broken ADF tray; broken bypass tray
Ricoh AFICIO 1515	122625	33		Dirty & offcolored panels
Savin 3515	124820	61	ST()	
Ricoh AFICIO 1515F	118459	12		Right side panel cracked; ADF front clip broken
Savin 3515F	119397	197		
Ricoh AFICIO 1515F	121195	25	PC(TYPE 1515)	Error code SC-101 (exposure lamp)
Savin 3515F	122914	68		
Ricoh AFICIO 1515F	123641	10		
Ricoh AFICIO 1515F	123667	72	PFU(PS480)	Dirty panels
Ricoh AFICIO 1515M	122946	75		Broken ADF tray
Ricoh AFICIO 1515M	122949	66		
Ricoh AFICIO 1515M	122950	71		
Ricoh AFICIO 1515M	123018	62		Broken ADF tray
Ricoh AFICIO 1515M	123019	81		
Ricoh AFICIO 1515M	123021	30		
Ricoh AFICIO 1515M	123023	115		
Lanier LD015SPF	123514	164		
Lanier LD015SPF	123532	164		
Lanier LD015SPF	123533	198		
Lanier LD015SPF	123534	110		
Lanier LD015SPF	123539	91		
Lanier LD015SPF	123608	75		
Lanier LD015SPF	123612	100		
Ricoh AFICIO 1515M	123668	62		Dirty & yellowed panels
Ricoh AFICIO 1515M	123669	266		Dirty & yellowed panels
Lanier LD015SPF	123686	165		
Lanier LD015SPF	123687	147		
Ricoh AFICIO 1515M	123721	27		Broken ADF tray hook; broken lift tray at attaching point in cassette
Ricoh AFICIO 1515M	123722	24		Broken ADF tray hook
Ricoh AFICIO 1515M	124088	70	ST()	
Ricoh AFICIO 1515M	124221	75		Broken ADF tray

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 1515M	124244	65		Yellowed & dirty panels
Ricoh AFICIO 1515M	124847	75		
Gestetner 3218	120850	83	ST() PC(TYPE 185) NIC(TYPE 185) ADF(DF68)	
Savin 4015	120377	101	PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	
Savin 4015	120683	181	PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Error code SC302 (charge roller or HVT); dirty panels
Savin 4015	122915	78	ST() FAX(TYPE 2018) ADF(DF78)	
Savin 4015	123622	34	ADF(DF78)	
Savin 4015	123623	67	ADF(DF78)	
Savin 4015	123624	73	ADF(DF78)	
Savin 4015	123627	223	ADF(DF78)	Error code SC301 (broken paper tray motor); broken ADF plug socket; broken right side front door hinge
Ricoh AFICIO 2015	124563	100	PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	
Savin 8016	120687	32	ST() ADF(DF78)	
Savin 8016	120688	64	ST() ADF(DF78)	
Ricoh AFICIO 2016	121620	84	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	
Ricoh AFICIO 2016	124090	114	FAX(TYPE 2018) ADF(DF78)	
Savin 8016	124400	84	ST() ADF(DF78)	
Savin 8016	124949	26	ST() PFU(PS450) ADF(DF78)	
Savin 4018	120684	109	PFU(PS460)	Broken lower right side access door; dirty & offcolored panels
Gestetner DSM618	122196	88	ST() PFU(PS460) FAX(TYPE 2018) ADF(DF78)	
Ricoh AFICIO 2018	122349	62	ST() ADF(DF78)	
Savin 4018	122839	104	ST() PFU(PS460)	
Ricoh AFICIO 2018	123421	73	ST() PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	
Ricoh AFICIO 2018	123615	28	ST() FAX(TYPE 2018) ADF(DF78)	
Savin 4018	123621	163	ST() PFU(PS460) ADF(DF78)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2018	124574	10	ST() FAX(TYPE 2018) ADF(DF78)	
Ricoh AFICIO 2018D	119980	269	ST() RADF(DF79) PFU(PS460)	
Ricoh AFICIO 2018D	121683	167	ST() RADF(DF79)	
Savin 4018D	122831	258	RADF(DF79)	Bent lower right side access door
Savin 4018D	122952	291	RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018)	
Ricoh AFICIO 2018D	123420	44	ST() RADF(DF79)	
Ricoh AFICIO 2018D	123723	76	ST() RADF(DF79)	Passes blanks due to missing toner bottle
Ricoh AFICIO 2018D	123724	33	ST() RADF(DF79)	Passes blanks due to missing toner bottle; offcolored panels
Ricoh AFICIO 2018D	123725	35	ST() RADF(DF79)	Passes blanks due to missing toner bottle causing error code C330
Ricoh AFICIO 2018D	124069	117	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE	
Ricoh AFICIO 2018D	124071	119	ST() RADF(DF79) PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018)	
Ricoh AFICIO 2018D	124092	131	ST() RADF(DF79) PFU(PS460)	
Savin 4018D	124361	11	ST()	
Ricoh AFICIO 2018D	124929	16	ST() RADF(DF79)	Paper sensor in tray#2 inoperable
Ricoh AFICIO 2018D	124930	17	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE	
Ricoh AFICIO 2018D	125075	67	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE	Broken RADF plug socket
Ricoh AFICIO 2020	121168	57	RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Paper tray #2 inop- will not detect paper size
Ricoh AFICIO 2020	124634	5	ST()	
Ricoh AFICIO 2020D	121562	153	ST() RADF(DF79) PFU(PS460) PC(TYPE 2018)	
Lanier LD120D	124958	44	ST() RADF(DF79) PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018)	
Savin 4022	119394	116	ST() SS(TYPE 1027) RADF(DF75) FAX(TYPE 2027)	Broken shift sort plug socket
Savin 4022	120197	399	ST() SS(TYPE 1027) RADF(DF75)	Broken bypass mounting bracket

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2022	122329	42	ST() RADF(DF75) FN(SR820)	
Lanier LD122	122396	106	ST() RADF(DF75)	Gouged front door; missing exit tabel end cover
Gestetner DSM622	122449	108	ST()	Has a book platen
Gestetner DSM622	122450	119	ST()	Has a book platen
Ricoh AFICIO 2022	123220	112	ST() RADF(DF75) FAX(TYPE 2027) E(PT280)	Cracked panel below duplex unit
Savin 4022	123625	193	ST() RADF(DF75) FN(SR790)	
Lanier LD122	123760	244	ST() RADF(DF75) FN(SR820) FAX(TYPE 2027) E(PT280)	
Lanier LD122	124078	159	ST() SS(TYPE 1027) RADF(DF75)	Broken bypass tray
Ricoh AFICIO 2022	124086	478	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR820) E(PT280)	Broken bypass tray
Gestetner DSM622	124204	254	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR790)	Broken bypass tray
Ricoh AFICIO 2022	124317	61	ST() RADF(DF75) FN(SR790) FAX(TYPE 2027)	
Ricoh AFICIO 2022	124525	68	ST() RADF(DF75) FAX(TYPE 2027) E(PT280)	
Ricoh AFICIO 2022	124562	345	ST()	Bypass broken- inop
Ricoh AFICIO 2022	124575	283	ST()	Bypass tray broken off
Savin 4022	124704	95	ST() RADF(DF75) FAX(TYPE 2027)	
Ricoh AFICIO 2022	124898	39	ST() SS(TYPE 1027) RADF(DF75) FAX(TYPE 2027) E(PT280)	
Lanier LD122	124942	185	ST() RADF(DF75) PC(TYPE 2027)	
Lanier LD122	124960	239	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	
Ricoh AFICIO 2022	125089	50	SS(TYPE 1027) RADF(DF75) PED(PS490) PC(TYPE 2027) FAX(TYPE 2027)	
Savin 4027	121708	28	ST() RADF(DF75) FN(SR790)	Dirty panels; yellowed upper panels
Savin 4027	122853	162	ST() SS(TYPE 1027) RADF(DF75)	Offcolored RADF panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4027	123626	434	ST() RADF(DF75) FN(SR790)	Missing bypass tray; offcolored finisher panels
Savin 4027	123628	288	ST() RADF(DF75) FN(SR790)	
Lanier LD035	117877	445	ST() FN(SR790)	Missing finisher tray
Ricoh AFICIO 2035	119494	1133	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	
Savin 4035	120241	302	ST() PC(TYPE 2045) FN(SR790)	Yellowed panels
Gestetner 3532	120314	331	PS(TYPE 2045) PED(PS530) PC(TYPE 2045) FN(SR790)	
Ricoh AFICIO 2035	120336	156	ST()	Offcolored panels
Ricoh AFICIO 2035	120337	153	ST()	Offcolored panels
Savin 4035	120532	702	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	
Savin 4035	120691	481	PS(TYPE 2045) PED(PS530) PC(TYPE 2045) FAX(TYPE 2045)	
Gestetner 3532	120847	480	PED(PS360)	Broken inner exit panel
Gestetner 3532	120851	652	PED(PS530) PC(TYPE 2045) FAX(TYPE 2045) E(PT330)	
Savin 4035	121094	161	ST() PC(TYPE 2045) FAX(TYPE 2045)	Offcolored panels
Gestetner 3532	121263	201	PU(TYPE 1045) PED(PS530) PC(TYPE 2045) FN(SR880)	
Gestetner 3532	121265	309	PED(PS530) PC(TYPE 2045) FN(SR890) FAX(TYPE 2045)	
Gestetner 3532	121266	540	ST() PU(TYPE 1045) PC(TYPE 2045) FN(SR880) FAX(TYPE 2045)	RADF plug wires pulled loose- inop; missing paper deck (tested with another)
Savin 4035	121876	321	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	
Savin 4035	122080	271	PED(PS530) FAX(TYPE 2045)	Has finisher brackets but no finisher
Savin 4035	122081	542	PED(PS530)	Has finisher brackets but no finisher
Ricoh AFICIO 2035	122114	1075	ST() PC(TYPE 2045) P(RT45) FN(SR790) FAX(TYPE 2045)	Finisher in error code SC730 (stapler broken & detached)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2035	122172	178	ST() PC(TYPE 2045) FN(SR790)	Missing paper deck (missing access door); yellowed & dirty panels
Ricoh AFICIO 2035	122318	746	PED(PS530) FN(SR790)	Yellowed panels
Gestetner 3532	122769	173	ST()	
Lanier LD035	122863	723	PS(TYPE 2045) PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Bent finisher entrance guide
Savin 4035	122982	245	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Error codes SC322 & SC326 (laser) was able to clear & run copies, but copy quality is very poor; bent controller panel frame; cracked lower finisher tray; top paper tray will not detect paper size
Ricoh AFICIO 2035	123097	408	PED(PS530) PC(TYPE 2045) P(RT45) FN(SR790) FAX(TYPE 2045)	Offcolored & dirty panels
Ricoh AFICIO 2035	123334	460	PED(PS530) PC(TYPE 2045) FAX(TYPE 2045)	
Gestetner 3532	123369	427	ST() P(RT45) FN(SR790)	Broken turn around guide in tray #2-inop
Ricoh AFICIO 2035	123393	136	ST() P(RT45) FN(SR790)	Offcolored panels
Lanier LD035	123515	367	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	
Lanier LD035	123516	794	ST() PU(TYPE 1045) PC(TYPE 2045) FN(SR880) FAX(TYPE 2045) E(PT330)	
Lanier LD035	123581	566	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Missing finisher entrance guide (tested with another); missing top finisher deflector gate causing jams; cracked lower finisher tray
Lanier LD035	123583	231	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	
Ricoh AFICIO 2035	123654	611	ST() PC(TYPE 2045) P(RT45) FN(SR790)	Offcolored finisher panels
Lanier LD035	123693	287	ST() PC(TYPE 2045) FAX(TYPE 2045) E(PT330)	
Ricoh AFICIO 2035	123699	149	PED(PS530) FN(SR790)	
Lanier LD035	123767	793	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	
Lanier LD035	124082	240	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2035	124117	258	ST() FN(SR790)	
Savin 4035	124459	182	ST() FAX(TYPE 2045) E(PT330)	Yellowed panels
Ricoh AFICIO 2035	124669	832	ST() PC(TYPE 2045) FAX(TYPE 2045) E(PT330)	
Ricoh AFICIO 2035	124817	461	PU(TYPE 1045) PED(PS530) PC(TYPE 2045) P(RT45) FN(SR880)	
Ricoh AFICIO 2035	124899	95	ST() P(RT45)	Yellowed panels
Gestetner DSM635	116909	626	ST() PC(TYPE 2045E) P(RT45) FN(SR790)	
Ricoh AFICIO 2035E	117213	368	ST() PC(TYPE 2045E)	
Ricoh AFICIO 2035E	117632	514	PED(PS530) FN(SR790)	Broken finisher access door at hinge
Ricoh AFICIO 2035E	118167	314	PED(PS530) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	118337	258	ST() FN(SR790)	
Ricoh AFICIO 2035E	118349	300	ST() PC(TYPE 2045E) FN(SR790)	
Ricoh AFICIO 2035E	118354	367	ST() FN(SR790)	Offcolored top panels
Ricoh AFICIO 2035E	118362	230	PED(PS530) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	118364	579	PED(PS530) P(RT45) FN(SR790)	
Lanier LD135	118534	572	ST() PC(TYPE 2045E) P(RT45) FN(SR790)	
Ricoh AFICIO 2035E	118797	297	ST() FN(SR790)	
Ricoh AFICIO 2035E	118798	335	ST()	
Ricoh AFICIO 2035E	118916	324	PED(PS530) FN(SR790)	
Ricoh AFICIO 2035E	119435	138	PED(PS530) FN(SR790)	Yellowed upper panels
Ricoh AFICIO 2035E	119572	859	ST()	
Ricoh AFICIO 2035E	119577	741	PED(PS530) FN(SR790)	
Ricoh AFICIO 2035E	120478	232	ST() PC(TYPE 2045E)	
Ricoh AFICIO 2035E	120481	486	ST() PC(TYPE 2045E) FN(SR790)	
Ricoh AFICIO 2035E	120534	491	ST() PC(TYPE 2045E)	
Ricoh AFICIO 2035E	121013	498	PED(PS530) FAX(TYPE 2045E) E(PT330)	Error codes SC542 (low fuser temp) & SC402 (transfer belt open)
Savin 4035E	121099	574	PU(TYPE 1045) PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880)	Goes into error code SC863 (hard drive)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2035E	121187	205	ST() FAX(TYPE 2045E)	
Ricoh AFICIO 2035E	121625	205	ST() PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Gestetner DSM635	121678	578	PED(PS530) PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	121682	974	ST() PC(TYPE 2045E) P(RT45) FN(SR790)	Missing finisher paper entrance guide (tested with another); yellowed panels
Ricoh AFICIO 2035E	122044	90	ST() FN(SR790)	Broken finisher tray; offcolored & dirty panels
Ricoh AFICIO 2035E	122249	115	ST() FN(SR790) FAX(TYPE 2045E)	Error code SC863 (hard drive); yellowed & dirty panels
Savin 4035E	122258	336	ST() PU(TYPE 1045) PC(TYPE 2045E) FN(SR880)	
Ricoh AFICIO 2035E	122322	753	PED(PS530) PC(TYPE 2045E) P(RT45) FAX(TYPE 2045E) E(PT330)	
Lanier LD135	122374	269	ST() PC(TYPE 2045E) FN(SR790)	False jam in finisher - not tested
Savin 4035E	122823	134	PED(PS530) FN(SR790) FAX(TYPE 2045E)	
Savin 4035E	122844	315	ST() FN(SR790)	
Savin 4035E	122847	165	PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	
Savin 4035E	122850	271	PED(PS530) PC(TYPE 2045E) FN(SR880)	Finisher jams every copy- inop
Savin 4035E	122851	656	PED(PS530) PC(TYPE 2045E) FN(SR880)	
Savin 4035E	122854	279	PU(TYPE 1045) PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	
Ricoh AFICIO 2035E	122975	196	ST() PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Offcolored panels
Ricoh AFICIO 2035E	122981	127	ST() FN(SR790)	
Ricoh AFICIO 2035E	123030	429	ST() PC(TYPE 2045E) FN(SR790)	Offcolored & dirty panels; cracked finisher tray
Ricoh AFICIO 2035E	123039	767	ST() PU(TYPE 1045) PC(TYPE 2045E) P(RT45) FN(SR880) FAX(TYPE 2045E)	Duplex jams

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM635	123042	549	ST()	
Savin 4035E	123043	553	PC(TYPE 2045E) P(RT45) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	123142	242	PED(PS530) PC(TYPE 2045E) FN(SR790)	
Gestetner DSM635	123149	349	ST() PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	RADF dogears copies on exit
Ricoh AFICIO 2035E	123395	255	PED(PS530) PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	Error code SC819 (software performance error); dirty panels all over
Ricoh AFICIO 2035E	123432	168	PU(TYPE 1045) PS(TYPE 2045) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	Broken finisher tray
Savin 4035E	123560	548	ST() PC(TYPE 2045E) FN(SR790)	
Ricoh AFICIO 2035E	123677	261	PED(PS530) PC(TYPE 2045E) E(PT330)	Yellowed panels
Ricoh AFICIO 2035E	123726	449	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	RADF jams when duplexing; paper tray #3 handle broken off
Ricoh AFICIO 2035E	123730	223	PED(PS530) FN(SR790)	
Ricoh AFICIO 2035E	123731	181	PED(PS530) PC(TYPE 2045E) FN(SR790)	
Ricoh AFICIO 2035E	123738	906	ST() PC(TYPE 2045E)	
Ricoh AFICIO 2035E	123739	1273	ST() PC(TYPE 2045E)	
Ricoh AFICIO 2035E	123955	836	ST() FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	123956	580	ST() FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	123963	301	ST() PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	Cracked & broken controller panel frame
Ricoh AFICIO 2035E	123964	211	ST() PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	123965	728	PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	124087	197	ST() PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	124120	939	PED(PS530) PC(TYPE	Cracked & broken controller frame

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			2045E) P(RT45) FN(SR880)	
Savin 4035E	124133	654 ST()	PC(TYPE 2045E)	
Ricoh AFICIO 2035E	124152	708 PED(PS530)	PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Gestetner DSM635	124364	156 ST()		
Savin 4035E	124463	179 ST()	PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	124524	67 PED(PS530)	FN(SR790)	
Gestetner DSM635	124631	757 PED(PS530)	PC(TYPE 2045E) P(RT45) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2035E	124632	145 ST()	FAX(TYPE 2045E) E(PT330)	
Gestetner DSM635	124814	172 ST()	FAX(TYPE 2045E)	Missing paper deck & finisher (knockouts missing)
Ricoh AFICIO 2035E	124892	516 ST()	PC(TYPE 2045E)	
Ricoh AFICIO 2035E	124913	369 PED(PS530)	PC(TYPE 2045E) FAX(TYPE 2045E)	Print controller inop- missing NIC
Ricoh AFICIO 2035E	124925	61 PED(PS530)	PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	
Ricoh AFICIO 2035E	124926	58 PED(PS530)	PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Offcolored & dirty panels
Ricoh AFICIO 2035E	124927	341 PED(PS530)	PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Broken top pedestal paper guide causing it to jam every copy
Ricoh AFICIO 2035E	124928	307 PED(PS530)	PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	
Ricoh AFICIO 2035E	124932	198 ST()	FN(SR790)	
Lanier LD135	124957	288 PED(PS530)	PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2045	119578	265 PU(TYPE 1045)	PED(PS530) PC(TYPE 2045) FN(SR880)	
Ricoh AFICIO 2045	121031	338 PU(TYPE 1045)	PED(PS530) PC(TYPE 2045) P(RT45) FN(SR880) FAX(TYPE 2045)	Paper deck inop- insulation on cable damaged at plug

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4045	121634	168	PED(PS530) PC(TYPE 2045) FN(SR790)	
Ricoh AFICIO 2045	122115	1053	PU(TYPE 1045) PED(PS530) PC(TYPE 2045) P(RT45) FN(SR880) FAX(TYPE 2045)	
Ricoh AFICIO 2045	122319	1685	PED(PS530) FN(SR790)	
Ricoh AFICIO 2045	122320	1295	PED(PS530) FN(SR790)	
Gestetner 4532	122398	921	ST() PC(TYPE 2045)	
Savin 4045	122835	738	ST() P(RT45) FN(SR790) FAX(TYPE 2045)	
Ricoh AFICIO 2045	123093	584	PED(PS530) PC(TYPE 2045) FN(SR880) FAX(TYPE 2045)	Missing paper deck (access panel missing- tested with another); cracked finisher tray; offcolored & dirty panels
Savin 4045	123150	156	ST() P(RT45) FN(SR790)	Yellowed panels
Gestetner 4532	123154	1010	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	Goes into error code SC542 (low fuser temp) during copying- unable to fully test; offcolored & dirty panels; double image on copies; broken lower back panel
Ricoh AFICIO 2045	123332	476	PED(PS530) PC(TYPE 2045) FAX(TYPE 2045)	
Ricoh AFICIO 2045	123339	601	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Missing finisher diverter gate- finisher inop
Lanier LD045	123513	1100	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Missing front trim panel
Lanier LD045	123517	770	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	
Lanier LD045	123580	1371	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	
Lanier LD045	123584	564	ST() PC(TYPE 2045) FAX(TYPE 2045) E(PT330)	Registration is off on copies
Lanier LD045	123586	694	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	
Lanier LD045	123600	980	ST() PC(TYPE 2045) FAX(TYPE 2045) E(PT330)	
Lanier LD045	123688	1027	ST() PC(TYPE 2045) FAX(TYPE 2045) E(PT330)	Offcolored panels
Lanier LD045	123694	375	PED(PS530) P(RT45) FN(SR790) E(PT330)	Broken bottom finisher tray
Lanier LD045	123768	892	ST() PC(TYPE 2045)	Error code SC827 (memory problem)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD045	123769	920	FN(SR790) FAX(TYPE 2045) E(PT330) PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	
Savin 4045	124179	755	PED(PS530) PC(TYPE 2045) FN(SR890)	Yellowed panels
Savin 4045	124444	360	PS(TYPE 2045) PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	
Ricoh AFICIO 2045	124470	345	PED(PS530) PC(TYPE 2045) FAX(TYPE 2045)	
Savin 4045	124572	150	PED(PS530) PC(TYPE 2045)	Yellowed panels
Gestetner 4532	124630	1004	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	Broken R4 plate in finisher- stapler inop
Ricoh AFICIO 2045	125033	1178	PC(TYPE 2045) P(RT45) FN(SR880) FAX(TYPE 2045)	Missing finisher power control board- inop; yellowed panels
Ricoh AFICIO 2045	125034	718	ST() PC(TYPE 2045) P(RT45) FN(SR880) FAX(TYPE 2045)	Finisher paper entrance guide bent causing it to jam; yellowed & dirty panels
Ricoh AFICIO 2045E	120386	775	PED(PS530) FN(SR790)	Bent lower finisher tray mount- finisher inop
Savin 4045E	120501	237	ST() PC(TYPE 2045E) FAX(TYPE 2045E)	
Ricoh AFICIO 2045E	120801	344	PED(PS530) PC(TYPE 2045E) FN(SR880)	
Lanier LD145	120858	343	PED(PS530) PC(TYPE 2045E) P(RT45)	Broken top finisher tray; yellowed panels
Ricoh AFICIO 2045E	120923	1044	PED(PS530) FN(SR880) FAX(TYPE 2045E)	Offcolored panels
Gestetner DSM645	121680	1111	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880) FAX(TYPE 2045E) E(PT330)	
Gestetner DSM645	121681	1084	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880) FAX(TYPE 2045E) E(PT330)	Broken paper deck door actuator
Ricoh AFICIO 2045E	121912	422	ST() PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Cracked lower right side panel; dirty panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2045E	122404	428	PU(TYPE 1045) PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	Missing paper deck- unable to test pedestal due to missing panel
Ricoh AFICIO 2045E	122534	1013	ST() PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Finisher tray out of alignment (still works); offcolored & dirty panels
Ricoh AFICIO 2045E	122557	596	PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR790) FAX(TYPE 2045E)	
Savin 4045E	122836	347	PED(PS530) PC(TYPE 2045E) FN(SR790)	
Savin 4045E	122841	819	PED(PS530) PC(TYPE 2045E) FN(SR790)	
Savin 4045E	122842	686	PU(TYPE 1045) PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880) FAX(TYPE 2045E) E(PT330)	
Savin 4045E	122848	241	PED(PS530) PC(TYPE 2045E) FN(SR880)	
Savin 4045E	122856	550	PU(TYPE 1045) PED(PS530) FN(SR880)	
Ricoh AFICIO 2045E	123144	266	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Finisher will not align with machine- not tested; yellowed panels
Ricoh AFICIO 2045E	123966	522	ST() PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2045E	124085	838	ST() PC(TYPE 2045E) P(RT45) FAX(TYPE 2045E)	
Ricoh AFICIO 2045E	124114	520	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	Finisher left side lower panel caved in & top tray cracked- in false jam code & trays will not cycle
Savin 4045E	124721	437	PED(PS530) PC(TYPE 2045E) FN(SR790)	
Ricoh AFICIO 2045E	124806	472	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Broken paper tray #1 handle; offcolored panels; stapler jams
Ricoh AFICIO 2045E	124964	414	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	Broken bridge unit access door; cracked top finisher tray
Ricoh AFICIO 2045E	124965	801	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	Broken finisher tray; yellowed top finisher panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2045E	124966	813	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	Yellowed & dirty panels; RADF jams when duplexing; warped top finisher access door
Ricoh AFICIO 2045E	124967	227	PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Ricoh AFICIO 2051	121412	372	PU(TYPE 1045) PC(TYPE 2075) FN(SR850)	
Ricoh AFICIO 2051	123133	242	P(RT43) FN(SR850)	
Ricoh AFICIO 2051	124893	424	PC(TYPE 2075) P(RT43) FN(SR850)	
Ricoh AFICIO 2051	124894	957	PC(TYPE 2075) P(RT43) FN(SR850)	
Ricoh AFICIO 2051	125077	1294	PU(TYPE 1075) PC(TYPE 2075) FN(SR850)	
Savin 4060	123306	450	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	
Ricoh AFICIO 2060	123640	246	PC(TYPE 2075) FN(SR850)	Gouged back panel
Ricoh AFICIO 2060	123674	1810	PC(TYPE 2075) FN(SR850)	Bent lower finisher tray mount (still works)
Lanier LD160	124076	2477	FN(SR850)	Broken D2 handle off inside panel
Ricoh AFICIO 2060	124126	673	PU(TYPE 1075) P(RT43) FN(SR850)	
Savin 4060	124359	1233	PU(TYPE 1075) PS(TYPE 2075) PC(TYPE 2075) P(RT43) FN(SR861)	Finisher in error code SC740 (saddlestitch stapler motor problem)-grinds when running
Ricoh AFICIO 2060	124469	938	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	Finisher showing a false jam code in R1 & R3 (unable to test)
Ricoh AFICIO 2060	124744	671	PC(TYPE 2075) FN(SR850)	
Ricoh AFICIO 2060	124933	844	PS(TYPE 2075) PC(TYPE 2075) P(RT43) FN(SR850)	Finisher jams alot at R3
Ricoh AFICIO 2075	120723	998	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	
Ricoh AFICIO 2075	121406	572	PU(TYPE 1075) PC(TYPE 2075) FN(SR850)	
Ricoh AFICIO 2075	121428	860	PU(TYPE 1075) PC(TYPE 2075) FN(SR850)	Finisher is smashed- inop; broken RADF plug socket
Ricoh AFICIO 2075	123153	952	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR841)	
Ricoh AFICIO 2075	123661	4405	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR841)	
Ricoh AFICIO 2075	124671	1694	PC(TYPE 2075) FN(SR850)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 2075	124897	3048	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR861)	Has inserter unit type 1075
Gestetner DSM675	125016	718	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	
Gestetner DSM675	125017	949	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	Finisher tray mount smashed- finisher inop
Gestetner DSM675	125018	493	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	Broken finisher tray
Ricoh AFICIO 2090	122958	4749	PU(TYPE 1075) PC(TYPE 2105) P(RT46) FN(SR840)	Broken Q2 paper guide in finisher- can't test; error code SC870 (hard drive)- unable to fully test; has inserter unit type 1075
Savin 4090	123631	5427	PU(TYPE 1075) P(RT46) FN(SR840)	Broken wiring in paper deck- inop
Lanier LD0105	123601	4565	PU(TYPE 1075) PC(TYPE 2105) P(RT46) FN(SR840) B(TYPE 2105)	
Savin 40105	123706	6145	PU(TYPE 1075) PS(TYPE 2105) PC(TYPE 2105) P(RT46) FN(SR840) B(TYPE 2105)	Broken Q2 handle in finisher- unable to test
Savin 40105	124358	4437	PU(TYPE 1075) PS(TYPE 2105) PC(TYPE 2105) P(RT46) FN(SR90) FN(SR841) B(TYPE 2105)	Has Z-folding unit type 2105, BF90 book folder, TR90 trimmer unit, Type 1075 interposer tray & MicroPress System (w/ tower, monitor, mouse, keyboard & stand); broken RADF plug socket
Savin 9922 DP	122085	387	PED(PS440) DX(AD360)	
Savin 9922 DP	122087	231	PED(PS440) DX(AD360)	
Ricoh AFICIO 220	123037	351	ST() RADF(DF69) FAX(TYPE 270) E(TYPE 270) DX(AD360) B(TYPE 270)	Offcolored panels
Savin 9922 DP	124135	472	ST() SS(TYPE 270) RADF(DF69) DX(AD360) B(TYPE 270)	
Gestetner 3222	124952	184	ST() RADF(DF69) PC(TYPE 270) NIC(TYPE 185-E) FN(SR720) FAX(TYPE 270) DX(AD360)	Error code SC543 (high fuser temp); offcolored & dirty panels; missing printer button
Lanier LD228C	121733	431	ST() FAX(TYPE 2238) E(PT460)	Offcolored panels; color = 47k; B/W = 385k
Ricoh AFICIO 2228C	122357	294	ST() FAX(TYPE 2238) E(PT460)	Color = 42k; B/W = 253k
Ricoh AFICIO 2228C	124072	251	PED(PS550) E(PT460)	Color = 102k; B/W = 150k
Ricoh AFICIO 2228C	124409	708	PED(PS550) FN(SR910) E(PT460)	Color = 298k; B/W = 410k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD232C	119426	261	PED(PS550) FN(SR920) FAX(TYPE 2238) E(PT460)	Smashed back panel; color = 185k; B/W = 76k
Savin C3224	119736	1325	PU(TYPE 2238) PS(TYPE 2238) PED(PS540) FN(SR910) FAX(TYPE 2238) E(PT460)	Missing punch unit waste container (not tested); color = 750k; B/W = 576k
Ricoh AFICIO 2232C	119755	289	FAX(TYPE 2238) E(PT460)	Has a PS600 pedestal (works OK); jams every copy; color = 125k; B/W = 164k
Ricoh AFICIO 2232C	121210	262	ST() E(PT460)	Back panel broken; duplex panel dented; left side panel dented; Black meter = 91k; color meter = 171k
Gestetner DSC332	121314	763	ST() E(PT460)	Color = 17k; B/W = 747k
Ricoh AFICIO 2232C	121619	803	PED(PS560) FN(SR920) E(PT460)	Broken finisher trays; exit panel is pushed into machine; pedestal jams- inop; offcolored panels; color = 37k; B/W = 766k
Gestetner DSC332	122616	431	ST() E(PT460)	Color = 46k; B/W = 385k
Ricoh AFICIO 2232C	123046	254	PED(PS550) FN(SR920) E(PT460)	Color = 57k; B/W = 198k
Ricoh AFICIO 2232C	123923	650	PED(PS550) FN(SR910) FAX(TYPE 2238) E(PT460)	Color = 80k; B/W = 571k
Ricoh AFICIO 2232C	124113	278	FN(SR920) E(PT460)	Missing all toner cartridges causing error code 393-01 (toner density sensor); color = 75k; B/W = 203k
Ricoh AFICIO 2232C	124915	338	ST() FAX(TYPE 2238)	Needs new fuser oil unit to test; color = 57k; B/W = 281k; missing an exit tray
Ricoh AFICIO 2232C	124919	184	PU(TYPE 2238) PED(PS550) FN(SR910) FAX(TYPE 2238) E(PT460)	Offcolored panels; color = 116k; B/W = 69k
Ricoh AFICIO 2238C	119120	587	PED(PS540) FN(SR920) FAX(TYPE 2238) E(PT460)	Color = 76k; B/W = 511k
Ricoh AFICIO 2238C	119649	760	PU(TYPE 2238) PED(PS540) FN(SR920) FAX(TYPE 2238) E(PT460)	Dented & bent back panel; cracked internal exit tray; color = 153k; B/W = 607k
Ricoh AFICIO 2238C	120041	812	PU(TYPE 2238) PED(PS540) FN(SR910)	Color = 600k; B/W = 213k
Gestetner DSC338	120418	1019	PU(TYPE 2238) PED(PS550) FN(SR910)	Color = 385k; B/W = 635k
Ricoh AFICIO 2238C	120848	608	PU(TYPE 2238) PED(PS560) FN(SR920) FAX(TYPE 2238) E(PT460)	Paper tray #3 will not detect paper- inop; color = 79k; B/W = 530k
Ricoh AFICIO 2238C	123014	469	PU(TYPE 2238) PS(TYPE 2238) PED(PS540) FN(SR920) FAX(TYPE 2238) E(PT460)	Color = 237k; B/W = 233k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C3828	123620	450	PED(PS550) FN(SR910) FAX(TYPE 2238) E(PT460)	Color = 139k; B/W = 311k
Ricoh AFICIO 2238C	124053	692	PU(TYPE 2238) PED(PS550) FN(SR920) E(PT460)	Error code SC672 (unknown); controller area all bent up; cracked back panel; broken finisher interlock switch; color = 386k; B/W = 306k
Ricoh AFICIO 2238C	124054	1553	PU(TYPE 2238) PED(PS550) FN(SR920) E(PT460)	Color = 436k; B/W = 1117k
Ricoh AFICIO 2238C	124089	526	PU(TYPE 2238) PED(PS560) FN(SR920) FAX(TYPE 2238)	Missing an exit tray; color = 125k; B/W = 401k
Ricoh AFICIO 2238C	124890	686	PU(TYPE 2238) PED(PS550) FN(SR910) FAX(TYPE 2238) E(PT460)	Color = 183k; B/W = 503k
Ricoh AFICIO 2238C	124934	497	PS(TYPE 2238) PED(PS560) FN(SR910) FAX(TYPE 2238) E(PT460)	Color = 42k; B/W = 455k
Lanier LD238C	124943	296	PED(PS560) E(PT460)	Color = 199k; B/W = 97k
Ricoh AFICIO 2238C	124963	428	PU(TYPE 2238) PED(PS550) FN(SR920) FAX(TYPE 2238) E(PT460)	Broken finisher door; color = 82k; B/W = 346k
Savin 9925 DP	122093	320	RADF(DF65)	Has finisher brackets but missing finisher
Ricoh AFICIO 3025	119576	142	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	
Savin 8025	121709	24	ST() RADF(DF83) PC(TYPE 3030)	Broken bypass tray
Ricoh AFICIO 3025	121722	134	ST() SS(TYPE 1027) RADF(DF83) PC(TYPE 3030) FAX(TYPE 3030)	Dirty panels
Savin 8025	121859	71	ST() SS(TYPE 1027) RADF(DF83)	Missing drum unit- can't test
Ricoh AFICIO 3025	122325	258	ST() SS(TYPE 1027) RADF(DF83) PC(TYPE 3030) FAX(TYPE 3030)	
Ricoh AFICIO 3025	122527	18	RADF(DF83) PED(PS490) PC(TYPE 3030) FN(SR790) FAX(TYPE 3030)	Broken RADF plug socket
Ricoh AFICIO 3025	123152	79	ST() RADF(DF83) FN(SR820) FAX(TYPE 3030)	
Ricoh AFICIO 3025	123559	171	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	
Ricoh AFICIO 3025	123960	98	ST() RADF(DF83)	
Lanier LD225	124067	114	ST() RADF(DF83) PC(TYPE 3030) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(TYPE 3030) E(PT280)	
Ricoh AFICIO 3025	124116	34	ST() RADF(DF83)	Cracked & broken right side panel
Ricoh AFICIO 3025	124243	138	ST() RADF(DF83) PC(TYPE 3030) FAX(TYPE	
Ricoh AFICIO 3025	124635	45	ST() RADF(DF83) FN(SR820)	Broken bypass tray
Ricoh AFICIO 3025	124812	100	ST() RADF(DF83) FN(SR790)	Broken RADF plug socket
Ricoh AFICIO 3025	124827	56	ST() RADF(DF83)	Paper tray #1 in error code SC501
Ricoh AFICIO 3025	124846	124	ST() RADF(DF83) FAX(TYPE 3030)	Bypass tray broken off
Ricoh AFICIO 3025	124945	193	ST() RADF(DF83) FN(SR820)	
Ricoh AFICIO 3030	117504	156	ST() SS(TYPE 1027) RADF(DF83)	
Ricoh AFICIO 3030	121563	170	ST() RADF(DF83) PC(TYPE 3030) FAX(TYPE 3030) E(PT280)	
Savin 8030	122827	309	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030) FN(SR820) FAX(TYPE 3030) E(PT280)	
Ricoh AFICIO 3030	124746	37	RADF(DF83) PED(PS490) PC(TYPE 3030) FAX(TYPE (SR880) 3030) E(PT280)	Wrong finisher received with machine
Ricoh AFICIO 3035	118283	390	ST() PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO 3035	120054	208	ST() PC(TYPE 3045) FAX(TYPE 3045)	RADF is damaged- broken interlock actuator & bottom trim panel (RADF will not sit correctly)- inop
Ricoh AFICIO 3035	121401	524	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO 3035	121402	439	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO 3035	121407	340	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Lower finisher tray mount badly bent- inop
Ricoh AFICIO 3035	121408	411	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO 3035	121418	343	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3035	121423	191	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	
Savin 8035	122446	179	FN(SR790)	
Ricoh AFICIO 3035	123045	426	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Stapler jams- gate not functioning
Ricoh AFICIO 3035	123968	98	ST()	
Ricoh AFICIO 3035	124070	242	PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045) E(PT330)	
Gestetner DSM735	124490	126	ST() PC(TYPE 3045) FAX(TYPE 3045)	
Ricoh AFICIO 3035	124670	219	ST()	
Ricoh AFICIO 3035	124747	635	PED(PS530) PC(TYPE 3045) FN(SR790)	
Ricoh AFICIO 3035	124910	450	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO 3045	116682	222	ST() PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO 3045	118141	179	PED(PS530) FN(SR790) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO 3045	119003	1166	ST() PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045) E(PT330)	Yellowed & dirty panels; cracked exit tray
Savin 8045	121093	252	PED(PS530) FN(SR790)	Jams frequently in fuser; offcolored & dirty panels
Ricoh AFICIO 3045	121725	985	ST() PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Ricoh AFICIO 3045	121843	384	ST() PC(TYPE 3045) FAX(TYPE 3045) E(PT330)	
Savin 8045	122352	364	PED(PS530) PC(TYPE 3045)	Has wrong finisher (SR960)
Ricoh AFICIO 3045	122541	816	ST() P(RT45) FN(SR790)	Lower finisher tray mount bent (still works); missing paper tray #2 guide plate causing it to jam every copy; broken bridge unit exit extender
Gestetner DSM745	122611	726	PED(PS530) PC(TYPE 3045) FN(SR790)	Stapler inop
Gestetner DSM745	122612	615	PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790)	
Gestetner DSM745	122613	590	PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8045	122828	475	PU(TYPE 1045) PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045) E(PT330)	Stapler inop- cartridge jammed; scratched back panel
Savin 8045	122829	432	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) P(RT45) FN(SR880) FAX(TYPE 3045) E(PT330)	Cracked & bent back corner of paper deck
Ricoh AFICIO 3045	123012	405	ST() PC(TYPE 3045) P(RT45) FAX(TYPE 3045) E(PT330)	
Savin 8045	123301	156	PED(PS530) PC(TYPE 3045)	
Ricoh AFICIO 3045	123638	201	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Error code SC542 (low heat)
Ricoh AFICIO 3045	124702	387	PED(PS530) PC(TYPE 3045) FAX(TYPE 3045) E(PT330)	
Ricoh AFICIO 3045	124745	444	PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045) E(PT330)	Finisher in error code SC724 (stapler hammer motor)
Ricoh AFICIO 3045	124888	394	ST() PU(TYPE 1045) PC(TYPE 3045) P(RT45) FN(SR880) FAX(TYPE 3045)	
Gestetner DSC424	104472	115	ST() FN(SR790) FAX(TYPE C= 12k B/W= 104k 3232)	
Ricoh AFICIO 3224C	106644	143	SS(TYPE 3232) PED(PS510) FAX(TYPE 3232)	Cracked front door; missing fuser oil cover; color = 22k; B/W = 122k
Gestetner DSC424	116904	47	PED(PS520)	Color = 32k; B/W = 15k
Ricoh AFICIO 3224C	118394	125	PED(PS510) FN(SR790) FAX(TYPE 3232)	Control panel cracked; right side ped access door broken; right side upper panel missing; panel below control panel broken Tray #4 will not close; RADF plug broken; cracked RADF panel; Black meter =110k; colored meter =15k
Savin C2410	119398	149	PED(PS510)	Color = 29k; B/W = 121k
Ricoh AFICIO 3224C	119495	48	ST() FAX(TYPE 3232)	Broken left front interlock switch; color = 8k; B/W = 40k
Ricoh AFICIO 3224C	119832	138	PED(PS510) FAX(TYPE 3232) E(PT350)	Color = 134k; B/W = 4k
Ricoh AFICIO 3224C	122281	271	PED(PS510) FAX(TYPE 3232)	Color = 39k; B/W = 233k
Ricoh AFICIO 3224C	122282	291	PED(PS510) FAX(TYPE 3232)	Color = 29k; B/W = 263k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3224C	122326	186	ST() FAX(TYPE 3232)	Color = 57k; B/W = 130k
Ricoh AFICIO 3224C	122353	29	ST() FAX(TYPE 3232)	Touch screen not functioning- can't test machine; color = 7k; B/W = 22k
Ricoh AFICIO 3224C	122539	316	ST() FAX(TYPE 3232)	Color = 112k; B/W = 204k
Ricoh AFICIO 3224C	122651	81	ST() FAX(TYPE 3232)	Cracked upper front panel; missing all toner cartridges- can't test; color = 44k; B/W = 38k
Ricoh AFICIO 3224C	122970	40	ST() SS(TYPE 3232) FAX(TYPE 3232)	Cracked front door; broken front door interlock actuator; color = 2k; B/W = 39k
Ricoh AFICIO 3224C	122974	69	PED(PS510) FAX(TYPE 3232) E(PT350)	Cracked front door; color = 39k; B/W = 30k
Ricoh AFICIO 3224C	123863	196	PED(PS510) FAX(TYPE 3232)	Error code SC544 (fuser temp); color = 2k; B/W = 194k
Savin C2824	111840	178	PED(PS580) FAX(TYPE 3245) E(PT460)	Color = 28k; B/W = 150k
Ricoh AFICIO 3228C	112467	462	PED(PS590) FAX(TYPE 3245) E(PT460)	
Savin C2824	115761	347	ST() PU(TYPE 1045) FN(SR960) FAX(TYPE 3245) E(PT460)	Color = 167k; B/W = 181k
Savin C2824	116801	231	ST() FN(SR960) FAX(TYPE 3245) E(PT460)	Color = 56k; B/W = 176k
Ricoh AFICIO 3228C	117508	223	PED(PS590) FAX(TYPE 3245) E(PT460)	Color = 38k; B/W = 185k
Ricoh AFICIO 3228C	118279	142	PED(PS580) E(PT460)	Color = 70k; B/W = 73k
Ricoh AFICIO 3228C	120721	114	ST() FAX(TYPE 3245) E(PT460)	Color = 80k; B/W = 35k
Savin C2824	121127	162	ST() FN(SR960) FAX(TYPE 3245) E(PT460)	Cracked upper left side panel; missing a finisher tray; color = 9k; B/W = 153k
Savin C2824	124507	135	ST() FAX(TYPE 3245) E(PT460)	Color = 36k; B/W = 100k
Ricoh AFICIO 3228C	124636	132	PU(TYPE 2238) PS(TYPE 3245) PED(PS590) FN(SR950) E(PT460)	Color = 52k; B/W = 80k
Ricoh AFICIO 3228C	124944	148	ST() E(PT460)	Color = 35k; B/W = 114k
Gestetner DSC435	118180	635	ST() FN(SR960) FAX(TYPE 3245) E(PT460)	Shows black development unit not set properly- unable to resolve; color = 39k; B/W = 597k
Ricoh AFICIO 3235C	118772	375	PU(TYPE 1045) PED(PS590) FN(SR960) E(PT460)	Control panel will not power up- can't test; dented controller cover; dented fax port cover; scratched front door; color = 315k; B/W = 60k
Savin C3528	119185	594	PS(TYPE 3245) PED(PS600) FN(SR960)	Yellowed panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(TYPE 3245) E(PT460)	
Gestetner DSC435	119767	314	PED(PS580) FN(SR960) E(PT460)	Color = 104k; B/W = 210k
Lanier LD335C	120421	442	ST() PS(TYPE 3245) FN(SR950) FAX(TYPE 3245) E(PT460)	Color = 284k; B/W = 158k
Savin C3528	120690	324	PED(PS590) FN(SR960) FAX(TYPE 3245)	Cracked finisher tray; offcolored panels; color = 41k; B/W = 284k
Ricoh AFICIO 3235C	121414	384	PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Cracked back duplex panel; color = 178k; B/W = 206k
Ricoh AFICIO 3235C	121424	409	PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Cracked top duplex panel; color = 222k; B/W = 188k
Ricoh AFICIO 3235C	121543	310	ST() FN(SR960) FAX(TYPE 3245) E(PT460)	Color = 170k; B/W = 141k
Gestetner DSC435	121663	894	PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Offcolored panels; color = 87k; B/W = 807k
Savin C3528	121987	210	PU(TYPE 1045) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Error code SC733 - Stapler problem - not tested; black meter = 178k; colored meter =32k
Ricoh AFICIO 3235C	122540	330	ST() FN(SR950) FAX(TYPE 3245) E(PT460)	Color = 200k; B/W = 130k; broken internal exit tray
Ricoh AFICIO 3235C	122951	155	PED(PS590) FN(SR950) FAX(TYPE 3245) E(PT460)	Color = 107k; B/W = 48k
Ricoh AFICIO 3235C	122977	391	PU(TYPE 1045) PED(PS590) FN(SR950) FAX(TYPE 3245) E(PT460)	Cracked lower back panel; Color = 247k; B/W = 145k
Ricoh AFICIO 3235C	123376	430	PU(TYPE 2238) PS(TYPE 3245) PED(PS590) FN(SR950) E(PT460)	Missing all developer units & toner cartridges- tested with others
Ricoh AFICIO 3235C	123563	425	ST() FAX(TYPE 3245) E(PT460)	Color = 12k; B/W = 413k
Savin C3528	123616	344	PED(PS590) FAX(TYPE 3245) E(PT460)	Color = 260k; B/W = 84k
Ricoh AFICIO 3235C	123845	127	PS(TYPE 3245) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Broken finisher interlock actuator; color = 59k; B/W = 69k
Ricoh AFICIO 3235C	123958	124	PS(TYPE 3245) PED(PS590) FAX(TYPE 3245) E(PT460)	Color = 65k; B/W = 59k
Ricoh AFICIO 3235C	124223	285	PED(PS580) FN(SR960) FAX(TYPE 3245) E(PT460)	Color = 2k; B/W = 283k
Ricoh AFICIO 3235C	124571	368	ST() E(PT460)	Color = 294k; B/W = 75k
Ricoh AFICIO 3235C	124664	155	PS(TYPE 3245) PED(PS590) FAX(TYPE 3245) E(PT460)	Broken exit trays & inside exit door smashed; RADF out of alignment causing jams; Color = 128k; B/W = 27k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AFICIO 3235C	124852	144	PED(PS590) FAX(TYPE 3245) E(PT460)	Has a SR920 finisher (works OK); color = 65k; B/W = 80k
Ricoh AFICIO 3245C	114252	513	PED(PS590) E(PT460)	Color = 228k; B/W = 286k
Ricoh AFICIO 3245C	116031	645	PED(PS600) FN(SR960) E(PT460)	Front door scratched; black meter = 343k; colored meter = 303k
Ricoh AFICIO 3245C	121842	300	PED(PS590) FAX(TYPE 3245) E(PT460)	Broken bottom right side access door; color = 84k; B/W = 216k
Ricoh AFICIO 3245C	122218	244	PED(PS590) FN(SR960) E(PT460)	Hole in front door; color = 187k; B/W = 58k
Ricoh AFICIO 3245C	122354	773	PU(TYPE 2238) PED(PS580) FN(SR950) FAX(TYPE 3245) E(PT460)	Color = 145k; B/W = 628k
Ricoh AFICIO 3245C	122526	965	PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Color = 336k; B/W = 630k
Savin C4535	122837	447	PU(TYPE 2238) PED(PS590) FN(SR950)	Color = 57k; B/W = 391k
Ricoh AFICIO 3245C	122980	429	PED(PS580) FN(SR960) E(PT460)	Color = 299k; B/W = 131k
Ricoh AFICIO 3245C	124308	411	PU(TYPE 1045) PED(PS590) FN(SR960) E(PT460)	Color = 103k; B/W = 308k
Ricoh AFICIO 3245C	124911	106	PS(TYPE 3245) PED(PS600) FN(SR960) E(PT460)	Color = 58k; B/W = 49k
Toshiba E-STUDIO4500	123132	582	PC(FIERY E-7000) P(RT43) FN(SR980)	Color = 286k; B/W = 296k
Ricoh AFICIO 3260C	123954	401	PC(TYPE 3260) FN(SR970)	Color = 29k; B/W = 372k
Gestetner DSC460	124203	535	PU(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR970)	Color = 308k; B/W = 227k
Lanier 5625	119069	108	PED(PS380) PC(FIERY E310) E()	Error code SC385 (Drum ID sensor); toner spilled throughout machine
Ricoh AFICIO 4106	116037	183	RADF(DF64) PED(PS390) PC(FIERY E300) 20SS(ST32)	Color = 40k; B/W = 144k
Ricoh AFICIO 4506	118347	105	RADF(DF64) PED(PS380) PC(FIERY E310) FAX(TYPE 4000) E()	Error code SC385 (drum ID sensor); toner & fuser oil in duplex unit; yellowed RADF panels; color = 69k; B/W = 36k
Ricoh AFICIO 551	124857	1608	PC(EB-70) P(RT37) FN(SR740)	LCD contrast flickering
Gestetner CS555	125019	2083	PU(TYPE 3260) P(RT43) FN(SR980)	Paper deck jams at B4 every try- inop; color = 1499k; B/W = 585k; has interposer tray type 3260
Gestetner CS213D	111825	130	RADF(DF64) P(RT36) 20SS(ST33)	Color = 101k; B/W = 29k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin SDC413	118978	82	PC(E-710) E()	Broken exit tray; color = 63k; B/W = 20k
Savin SDC413	119388	256	RADF(DF64) P(RT36) 20SS(ST33)	Has a E-820 external print controller; sorter bins out of alignment & entrance guide bent- inop; missing controller cable
Savin SDC413	120205	192	PC(E-710) E()	Broken exit tray; color = 128k; B/W = 65k
Ricoh AFICIO 6513	120383	531	PC(E-820) E()	Color = 382k; B/W = 150k
Lanier 5813	122797	949	RADF(DF64) 20SS(ST33)	Print controller will not come to ready- inop; color = 623k; B/W = 327k
Ricoh AFICIO 850	122215	6664	PU(TYPE 850) PC(TYPE 850) P(RT42) NIC(TYPE 450-E) FN(SR810)	Paper deck jams
Lanier LD016	123605	47	PC(TYPE 161)	
Ricoh AFICIO MP 25	121224	29	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	RADF socket broken; bypass tray broken
Lanier LD325	123610	44	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Savin SLP38CS	109534	291	RADF(DF73) PU(TYPE 1045) FN(SR770) FAX(TYPE 3800C)	Color = 116k; B/W = 176k
Savin SLP38CS	113032	524	RADF(DF73) PU(TYPE 1045) FN(SR770) FAX(TYPE 3800C)	Color = 76k; B/W = 449k
Lanier 2138CMF	113096	346	RADF(DF73) FN(SR770)	Finisher jams when stapling; color = 145k; B/W = 201k
Ricoh AP3800CMF	113893	236	RADF(DF73) E()	Color = 73k; B/W = 164k
Lanier 2138CMF	114056	854	RADF(DF73) PU(TYPE 1045) FN(SR770) E()	Black meter = 662; colored meter = 192k
Ricoh AP3800CMF	114393	307	RADF(DF73) PU(TYPE 1045) FN(SR770)	Color = 67k; B/W = 241k
Ricoh AP3800CMF	114942	456	RADF(DF73) PU(TYPE 1045) FN(SR770) FAX(TYPE 3800C)	Color = 245k; B/W = 211k
Lanier 2138CMF	115974	379	RADF(DF73)	Black meter = 325k; color meter = 54k
Ricoh AP3800CMF	117212	567	RADF(DF73) FN(SR770)	Yellowed panels; color = 201k; B/W = 366k
Gestetner DSC38S	117671	431	RADF(DF73) FN(SR770) FAX(TYPE 3800C)	Missing R4 guide in finisher- inop; yellowed panels; broken exit tray; color = 91k; B/W = 340k
Ricoh AP3800CMF	117873	477	RADF(DF73) E()	Color = 38k; B/W = 450k; blurred color copies

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh AP3800CMF	118132	366	RADF(DF73) E()	Color = 79k; B/W = 287k
Savin SLP38CS	124386	469	RADF(DF73) E()	Needs a new fuser oil unit- can't test; yellowed panels; color = 213k; B/W = 256k
Ricoh AFICIO 3131	117043	87	RADF(DF81) PC(E-750) P(RT47) DX(AD470) C[1](PS570)	Missing finisher (has brackets); color = 40k; B/W = 48k
Ricoh AFICIO 3131	119350	255	RADF(DF81) PC(E-750) P(RT47) E() DX(AD470) C[1](PS570)	Print controller will not power up- inop; color = 228k; B/W = 28k
Ricoh AFICIO 3131	119673	83	RADF(DF81) P(RT47) FN(SR930) DX(AD470) C[1](PS570)	Missing all toner cartridges- tested with others; color = 73k; B/W = 10k
Ricoh AFICIO 3131	123286	190	RADF(DF81) PU(TYPE 3131) PC(E-750) FN(SR940) DX(AD470) C[1](PS570)	Color = 84k; B/W = 126k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.  
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.  
Please call our sales team for current availability.