

Wulff Enterprises

02/10/2012

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2513	192776	126	ADF(DF74)	Off color panels
Savin 2560	192777	1163	PU(TYPE 1045) PC(TYPE 1075) P(RT43) FN(SR850)	Very dirty panels, control panel quit functioning during testing - not fully tested
Savin 3515	192504	35		Error code SC120 - scanner home problem - not tested
Savin 3515	192505	25		
Savin 3515	192506	14		RADF feed tray broken
Savin 4015	189505	70	ST() PFU(PS450) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Yellowed panels; missing stand door
Savin 8016	179990	142	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Yellow panels
Savin 8020	191682	55	ST()	Has ADF- DF2000
Savin 8020D	191597	382	ST() PC(TYPE 2018) FAX(TYPE 2018)	Has ARDF DF2010
Savin 4022	183921	75	ST() RADF(DF75) FAX(TYPE 2027)	
Savin 4035E	192146	391	ST() FN(SR790)	Off color panels
Savin 4035E	192147	419	ST() FN(SR790)	Off color panels
Savin C3224	186162	443	PED(PS550) FAX(TYPE 2238) E(PT460)	Bent controller box; front door interlock out of alignment; missing fax button; yellowed panels; color = 195k; B/W = 249k
Savin 8025	179038	276	ST() RADF(DF83) PC(TYPE 3030 (S))	RADF and finisher yellow
Savin 8025	183075	625	RADF(DF83) PED(PS490) PC(TYPE 3030 (S))	Copies not fusing
Savin 8025	185108	399	ST() RADF(DF83) PC(TYPE 3030 (S))	Jamming in bypass - not tested
Savin 8025	188934	568	ST() RADF(DF83) PC(TYPE 3030 (S)) FAX(TYPE 3030) E(PT280)	
Savin 8025	191691	218	ST() RADF(DF83) PC(TYPE 3030 (S))	Cassette #2 not recognizing paper = not tested, bypass tray hinges broken
Savin 8030	182574	262	ST() RADF(DF83) PC(TYPE 3030 (S))	RADF yellow and finisher
Savin 8030	186734	310	ST() RADF(DF83) PC(TYPE 3030 (S))	Front door actuator broken, off color panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(TYPE 3030)	
Savin 8030	188511	250	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR820) FAX(TYPE 3030) E(PT280)	Missing cassette #1, right side access door broken, jamming in finisher - not tested, Yellow panels, broken bypass tray
Savin 8030	188512	455	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FN(SR820) FAX(TYPE 3030) E(PT280)	RADF yellow, jamming in duplexer
Savin 8030	190357	730	RADF(DF83) PS(TYPE 3030) PED(PS490) PC(TYPE 3030 (S)) FAX(TYPE 3030)	Missing finisher - has bridge unit and mount screws
Savin 8030	192213	457	RADF(DF83) PED(PS490) PC(TYPE 3030 (S)) FN(SR790) FAX(TYPE 3030) E(PT280)	Off color and dirty panels
Savin 8035	192465	95	PED(PS530) PC(TYPE 3045) FAX(TYPE 3045)	Off color panels
Savin 8045	183059	167	PED(PS530) PC(TYPE 3045) FN(SR790)	
Savin 8045	188933	154	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Error code SC870 - address book data error - hard-drive failure, looks like hard-drive was scrubbed, unable to fully test machine, hard-drive removed, off color, finisher yellow
Savin 8045	192301	585	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045) E(PT330)	Lower right side access panel missing, touch screen not responding - not fully tested
Savin 8045	192846	473	ST() FN(SR790)	Error code SC995 - machine type information error - not tested, very dirty, yellow
Savin C2410	184861	431	ST()	Black meter = 263k, color meter = 168k
Savin C4535	190850	418	PS(TYPE 3245) PED(PS600) FAX(TYPE 3245)	Missing finisher -has brackets, duplexer exit tray missing, yellow panels, black meter = 230k, color meter = 188k
Savin C6045	175378	685	PU(TYPE 3260) FN(SR970)	Black meter = 466k; color meter = 220k, finisher tray yellow
Savin C6045	189393	719	PC(TYPE 3260)	Came in with wrong finisher
Savin 2055 DP	191849	7087	FN(SR740)	Left side top cover cracked, yellow panels, has PC button - missing PC
Savin SGC 1506	191519	77		Has stand and 1C PFU, black meter = 46k, color meter = 32k, does not recognize toner installed - not tested, yellow panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 9016	182945	24	PC(TYPE 2000) FAX(TYPE 2000) ADF(DF2000)	
Savin 9016	182947	30	ST() PC(TYPE 2000) ADF(DF2000)	
Savin 9016	182948	28	ST() PC(TYPE 2000) ADF(DF2000)	Yellowed ADF panels
Savin 9016	182953	119	ST() ADF(DF2000)	
Savin 816F	186272	125		
Savin 816F	192514	29		
Savin 9021D	180203	26	ST() RADF(DF2010)	Dirty inside machine
Savin 9021D	182924	55	RADF(DF2010) PS(TYPE 2000) PC(TYPE 2000) FAX(TYPE 2000)	PFU harness broken, left side panel broken, jamming in duplexer, jamming out of cassette #2
Savin 9021D	182925	133	RADF(DF2010) PS(TYPE 2000) PC(TYPE 2000) FAX(TYPE 2000)	Lower right side access door out of alignment causing lower tray to jam; toner spilled in paper trays; yellowed RADF panels
Savin 9021D	186275	59	RADF(DF2010) PFU(PS450) FAX(TYPE 2000)	
Savin 9021D	190374	317	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	Skewing paper in RADF, right side panels yellow
Savin 9021D	191660	210	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Savin 7025	184865	287	ST() RADF(DF3020) PED(PB3030) PC(TYPE 2500) FAX(TYPE 2500) E(BN3020)	
Savin 7025	187549	77	ST() RADF(DF3020) PC(TYPE 2500) FN(SR3010) FAX(TYPE 2500) E(BN3020)	Off color panels
Savin 8025E	179041	136	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3010)	Touch screen loses calibration when power off; yellowed RADF panels
Savin 8025E	180681	106	ST() RADF(DF83) FN(SR820) FAX(TYPE 3030)	
Savin 8025E	181303	525	ST() RADF(DF83)	Bypass tray broken
Savin 8025E	182930	121	ST() RADF(DF83) PS(TYPE 3010) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	Bypass tray broken
Savin 8025E	183066	159	ST() RADF(DF83)	
Savin 8025E	186165	233	ST() RADF(DF83)	RADF off color, finisher bottom tray

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(TYPE 3010) FN(SR790)	cracked, bypass tray broken, jamming in duplexer - not tested
Savin 8025E	189027	30	ST() RADF(DF83)	
Savin 9025	179508	57	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350)	Finisher bracket bent - finisher not tested, off color panels, front door scratched, dirty
Savin 9025	182950	30	RADF(DF3030) FN(SR790)	
Savin 9025	182951	315	ST() RADF(DF3030) PC(TYPE 3350 (S))	Bypass not recognized - not tested
Savin 9025	183073	230	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Savin 9025	184862	251	ST() SS(SH3010) RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Error code SC671 - controller to operation panel communication error - not fully tested
Savin 9025	184895	323	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Savin 9025	186271	332	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Savin 9025	186273	207	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Savin 9025	187548	406	RADF(DF3030) PED(PS500) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Goes into error code 873 - email error or hard-drive; dirty panels
Savin 9025	190818	109	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	Error code SC723 - feed out belt motor error - stapler tested, yellow panels, finisher top access door broken
Savin 9025	191659	192	RADF(DF3030) PED(PB3030) PC(TYPE 3350 (S))	
Savin 9025	192148	198	ST() RADF(DF3030)	
Savin 8030E	181771	532	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	Touch screen not responding - not fully tested, hard-drive removed
Savin 8030E	182934	435	ST() RADF(DF83) PS(TYPE 3010) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Savin 9033	182944	438	ST() RADF(DF3030) PC(TYPE 3350 (S))	Control panel yellow, stand front left door broken off

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 9033	186181	183	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Savin 9033	189969	469	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	Very dirty, ground in dirt, yellow
Savin 8035E	181737	45	ST() PC(TYPE 4500)	Yellow panels
Savin 8035E	182957	244	ST() PU(TYPE 1045) PC(TYPE 4500) FN(SR880) FAX(TYPE 3045)	
Savin 8035E	187835	308	PU(TYPE 1045) PED(PS530) FN(SR880)	Yellow panels, jams in stapler - not tested
Savin 8035E	188064	1094	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Jamming in bypass - not tested
Savin 8035E	188219	483	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) FN(SR880)	
Savin 8035E	188965	723	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Jamming at finisher entranced - finisher not tested
Savin 8035E	190550	434	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Yellow panels
Savin 8035E	190821	213	PS(TYPE 4500) PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Finisher entrance guide missing
Savin 8035E	192099	566	ST() PS(TYPE 4500) PC(TYPE 4500) FAX(TYPE 3045)	Missing finisher - has bridge unit, off color panels
Savin 9040	180196	450	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9040	180204	74	ST() PC(TYPE 5000 (S)) FN(SR790)	
Savin 9040	182286	291	ST() FN(SR790)	Control panel panel cover yellow
Savin 9040	182287	373	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790)	Yellow panels, error code SC324 - LD drive current, yellow panels
Savin 9040	182288	447	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9040	182289	290	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9040	182290	220	ST() PC(TYPE 5000 (S))	
Savin 9040	182291	660	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 9040	182586	94	ST() FN(SR790)	
Savin 9040	183236	22	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Removed hard drive after testing; Finisher top access door broken, RADF yellow, finisher top panel yellow
Savin 9040	185537	283	ST() PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9040	187546	503	PED(PB3040)	Control panel yellow
Savin 9040	187547	244	PED(PB3050)	
Savin 9040	191681	323	ST() PC(TYPE 5000 (S)) FN(SR790)	
Savin 8045E	188966	1366	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Savin 8045E	190531	332	PU(TYPE 1045) PED(PS530) PC(TYPE 4500) P(RT45) FN(SR880) FAX(TYPE 3045) E(PT330)	
Savin 9050	182749	254	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Removed hard drive after testing; Does not recognize toner bottle installed - not tested
Savin 9050	182949	404	PU(TYPE 3260) PED(PB3040) PC(TYPE 5000 (S)) FN(SR3030)	
Savin 9050	184595	144	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790)	Removed hard drive after testing; Lower finisher tray missing, finisher entrance guide missing spring
Savin 9050	185939	190	PED(PB3050) FN(SR790)	
Savin 9050	190140	399	ST() PC(TYPE 5000 (S)) FN(SR790)	
Savin 9050	191018	473	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Control panel yellow, finisher tray missing
Savin 8055	192106	383	E()	
Savin 8060	178354	32	PU(TYPE 3260) FN(SR970) FAX(TYPE 7500)	Front door broken
Savin 9080	192515	3680	PC(TYPE 9001) FN(SR4030)	Jamming out of cassettes 1,2 - not tested
Savin C2020	185472	49	ST() FAX(TYPE MPC3000) E(BN3000)	Control panel broken on right side, control board broken - unable to fully test machine, left corner of PC dented, stand front doors missing, black meter = 48k, color meter = 16k
Savin C2525	184359	313	ST() FN(SR3010)	Black meter = 292k, color meter = 22k
Savin C2525	184370	259	PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 167k, color meter = 93k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C2525	184569	195 ST()	SS(SH3000)	Black meter = 139k, color meter= 57k
Savin C2525	185110	393 PED(PB3000)		Black meter = 369k, color meter = 24k
Savin C2525	186685	333 ST()	FAX(TYPE MPC3000) E(BN3000)	Control panels yellow, black meter = 290k, color meter = 44k
Savin C2525	186873	384 ST()	FN(SR3010)	Yellow panels
Savin C2525	187358	547 ST()		Black meter = 434k, color meter = 113k, off color and dirty
Savin C2525	192302	385 ST()	SS(SH3000) FAX(TYPE MPC3000) E(BN3000)	Black meter = 228k, color meter = 158k
Savin C2525	192495	N/A ST()	PED(PB3010) FN(SR3010) FAX(TYPE MPC3000)	Touch screen not responding - not fully tested, off color panels, hard-drive removed
Savin C2828	180180	46 ST()	FN(SR790)	Jamming in stapler - not tested, black meter = 44k, color meter = 3k
Savin C3030	184866	265 ST()	PED(PB3010) FAX(TYPE MPC3000)	Black meter = 191k. color meter = 75k
Savin C3030	186480	337 PED(PB3010)	FN(SR3010)	Yellow finisher panels, black meter = 263k, color meter = 75k
Savin C3030	189365	880 PED(PB3000)		Missing black and yellow toner- will not cycle toner (can't test), black meter = 120k, color meter = 761k
Savin C3030	190216	555 SS(SH3000)	PED(PB3000) FAX(TYPE MPC3000) E(BN3000)	PED right side access door broken, back right panel broken, RADF connector bent, black meter = 437k, color meter = 118k
Savin C3030	191552	305 PU(PU3000)	PED(PB3000) FN(SR3000) FAX(TYPE MPC3000)	Error code SC760 - finisher punch motor error - not tested, front door cracked, black meter = 245k, color meter = 61k
Savin C3535	179666	376 PU(PU3000)	PED(PB3010) FN(SR3030)	Ground in dirt, paper guides in top cassette not aligning, black meter = 351k, color meter = 26k
Savin C3535	182285	316 ST()	FN(SR790) FAX(TYPE MPC4500)	Finisher top access door broken, black meter - 271k, color meter = 45k
Savin C3535	183653	497 ST()	PS(TYPE C4500)	Black meter = 241k, color meter = 257k
Savin C3535	189967	379 ST()	FAX(TYPE MPC4500) E(BN3010)	Control panel cover yellow, black meter = 365k, color meter = 14k
Savin C3535	192793	223 ST()	FN(SR3020) FAX(TYPE MPC4500)	Bottom finisher tray and bracket missing, black meter = 92k, color meter = 131k
Savin C4540	185940	295 PED(PB3010)	FN(SR790)	Color = 77k; B/W = 219k
Savin C4540	187550	763 ST()	FN(SR790) FAX(TYPE MPC4500) E(BN3010)	Rear bypass paper guide missing, RADF actuator broken, black meter = 762k, color meter = 2k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C4540	187752	855	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Control panel cover yellow, finisher yellow, black meter = 825k, color meter = 31k
Savin C4540	189965	586	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Control panel cover very yellow, black meter = 460k, color meter = 126k
Savin C4540	189966	497	ST() FAX(TYPE MPC4500) E(BN3010)	Black meter = 344k, color meter = 153k
Savin C4540	190817	717	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Finisher off color, Finisher not deflecting paper to lower finisher tray - not tested, right side vent cracked, black meter = 567k, color meter = 150k
Savin C5050	181660	262	PS(TYPE C5000) PED(PB3040) FAX(TYPE C5000)	Hard drive removed after testing; Missing finisher causing error code SC792- communication problem with finisher; black meter = 213k, color meter = 50k
Savin C5050	189601	457	PED(PB3050)	Black meter = 407k, color meter = 51k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.