

Wulff Enterprises

01/07/2009

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-151	115313	116	ADF(AR-SP3)	Broken front door hinge; bypass jams
Sharp AR-157E	117428	149	ST()	Yellowed panels; missing bypass tray
Sharp AR-157E	117429	84	ST()	
Sharp AR-157E	120287	60		Very yellowed panels
Toshiba E-STUDIO150	122900	63	ADF(MR-2014)	Jams every copy- can't test; broken front door hinge; dirty & offcolored panels
Sharp AR-164	119538	76		
Sharp AR-168D	120278	40	NIC(AR-NB2N)	
Toshiba E-STUDIO162D	120635	48	RADF(MR-3017)	
Toshiba E-STUDIO162D	121114	22	ST() RADF(MR-3017) PC(GA-1170)	
Sharp AR-168D	122464	53	NIC(AR-NB2N) FAX(AR-FX9)	
Sharp AR-168D	122738	72		
Sharp AR-168D	124560	95	PFU(AR-D16)	Broken front door hinge
Toshiba E-STUDIO162	117843	62	PFU(MY-1026) PC(GA-1170) FAX(GD-1190) ADF(MR-2016)	Very dirty panels
Toshiba E-STUDIO162	119303	56	ST() PC(GA-1170) FAX(GD-1190) ADF(MR-2016)	
Toshiba E-STUDIO162	122272	76	ST() PFU(MY-1026) FAX(GD-1190) ADF(MR-2016)	
Sharp AR-168S	123280	12	FAX(AR-FX9)	
Sharp AR-200	115316	N/A	ADF(AR-SP2)	Goes into error codes F5 (exposure lamp) & E7 (laser); very dirty & discolored panels
Sharp AR-200S	122470	7	FAX(AR-FX2) ADF(AR-SP2)	Dirty & offcolored panels
Sharp AR-205	123123	117	ST() RADF(AR-RP1)	Broken registration switch causing a false jam code- can't test; yellowed & dirty panels
Sharp AR-235	119358	234	ST() RADF(AR-RP3)	
Sharp AR-235	122473	307	ST() RADF(AR-RP3)	Missing back left cover panel
Sharp AR-235	123354	N/A	SCAN(AR-NS2) RADF(AR-RP3)	Error code U2-40 (CROM communication error)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PFU(AR-D12) PC(AR-P11) NIC(AR-NC5J) FN(AR-FN5) FAX(AR-FX4)	
Sharp AR-235	124557	158 ST()	RADF(AR-RP3)	
Sharp AR-250	122472	101 ST()	FN(AR-FN2) ADF(AR-SP1)	Broken lower finisher tray
Sharp AR-275	114044	204 ST()	RADF(AR-RP3)	
Sharp AR-275	114754	67 RADF(AR-RP3)	PFU(AR-D12) FN(AR-FN5)	Very yellowed & dirty panels
Sharp AR-275	118254	134 ST()	RADF(AR-RP3) FN(AR-FN5)	Yellowed panels
Sharp AR-275	119320	180 ST()	RADF(AR-RP3) FN(AR-FN5)	Broken paper tray #1 (not tested)
Sharp AR-275	121756	310 ST()	RADF(AR-RP3) FN(AR-FN5) FAX(AR-FX4)	Missing top finisher tray
Sharp AR-285	114122	391 ST()	FN(AR-FN2)	Missing finisher paper entrance guide-inop; broken finisher brackets
Sharp AR-285	114123	453 ST()	FN(AR-FN2)	
Sharp AR-285	118445	839 PED(AR-DE1 [A])	E()	
Sharp AR-286	114121	398 ST()	FN(AR-FN2)	Touch screen not working well
Sharp AR-335	115305	406 PED(AR-DE1 [B])	FN(AR-FN1)	Needs toner to test; broken left side access door
Sharp AR-336	115306	256 ST()	P(AR-LC1) FN(AR-FN1N)	Stapler jams; broken finisher bracket
Sharp AR-336	115710	657 ST()	FN(AR-FN1N)	Broken finisher mounting bracket
Sharp AR-337	118415	441 ST()	FN(AR-FN2)	Ran OK, now touch screen will not respond; dented back panel
Sharp AR-405	123124	N/A ST()	P(AR-LC1) FN(AR-FN1N)	Ran OK, then went into error code H5-01 (exit sensor); broken fuser exit cover; yellowed RADF panels
Sharp AR-407	116614	697 ST()	PC(AR-PB2) NIC(AR-NC3D) E()	Double image on copies
Sharp AR-507	121915	756 ST()	P(AR-LC1N) FN(AR-FN3)	Finisher trays broken
Sharp AR-BC260	98978	77 PED(AR-D19N)		Color = 49k; B/W = 28k; bad left RADF hinge
Sharp AR-BC260	116110	21 PED(AR-D19N)	FN(AR-F13)	black meter = 17k; color meter = 4k
Sharp AR-C160	121146	39 RADF(AR-RF1)	PC(AR-PE2) DX(AR-DU2N) 20SS(AR-SS2)	Bottom paper tray will not feed-inop; color = 38k; B/W = 1k
Sharp AR-C160	121148	32 RADF(AR-RF1)	PC(AR-PE2) DX(AR-DU2N) 20SS(AR-SS2)	Broken sorter latch handle; color = 25k; B/W = 8k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-C160	121149	41	RADF(AR-RF1) PC(AR-PE2) DX(AR-DU2N) 1k 20SS(AR-SS2)	Yellowed panels; color = 40k; B/W =
Sharp AR-C160	121150	64	RADF(AR-RF1) PC(AR-PE2) DX(AR-DU2N) B/W = 6k 20SS(AR-SS2)	Yellowed RADF panels; color = 58k;
Sharp AR-C250	120976	228	RADF(AR-RF1) PC(AR-PE1) DX(AR-DU2) 20SS(AR-SS2)	Color = 56k; B/W = 173k
Sharp AR-C260M	115470	78	RADF(AR-RF3) PED(AR-D19) B(AR-RB1)	Jams every copy in fuser- rollers not turning; color = 44k; B/W = 34k
Sharp AR-C260M	119501	303	RADF(AR-RF3) PED(AR-D19)	Color = 88k; B/W = 216k
Sharp AR-C260M	122808	206	RADF(AR-RF3) PED(AR-D19)	Error code L3 (scanner); back panel smashed in; RADF panels badly scratched; yellowed & dirty panels; color = 191k; B/W = 15k
Sharp AR-C260M	122809	N/A	RADF(AR-RF3) PED(AR-D19) B(AR-RB1)	Control panel will not function- touch screen is loose; dented & bent upper back panel; dirty & yellowed panels
Sharp AR-C260M	122992	19	SCAN(AR-NS2) RADF(AR-RF3) PED(AR-D19) B(AR-RB1)	Color = 12k; B/W = 7k
Sharp AR-C260M	123010	11	SCAN(AR-NS2) RADF(AR-RF3) PED(AR-D19) B(AR-RB1)	Jams every copy in fuser- can't test; color = 9k; B/W = 3k
Sharp AR-C260M	123145	278	RADF(AR-RF3) PED(AR-D17)	Dirty & offcolored panels; color = 78k; B/W = 199k
Sharp AR-C270	116641	57	RADF(AR-RF1) DX(AR-DU2N)	Error code H6-00 (fuser); missing sorter; smashed back left corner panel; broken bottom paper tray panel; broken top left scanner panel; broken waste toner door
Sharp AR-C270	121757	144	RADF(AR-RF1) PC(AR-PE2) DX(AR-DU2N) 20SS(AR-SS2)	Color = 124k; B/W = 21k
Sharp AR-C270	122049	40	PC(AR-PE2) E()	Back panel dented; black meter =6k; colored meter =34k
Toshiba E-STUDIO161	113936	17	PFU(MY-1022) ADF(MR-2015)	
Toshiba E-STUDIO161	115746	89	ADF(MR-2015)	
Sharp AR-M205	123120	33	ST() RADF(AR-RP6)	
Toshiba E-STUDIO161	123929	28	ADF(MR-2015)	
Sharp AR-M207	123113	49	ST() RADF(AR-RP6N)	
Sharp AR-M208	120628	156	ST() PC(AR-P11)	Very yellowed panels; missing fax panel on control panel

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M208	121151	60	ST() SCAN(AR-NS2) PC(AR-P11) NIC(AR-NC5J) FN(AR-FN5N) FAX(AR-FX4)	Yellowed panels
Sharp AR-M208	124475	73	ST()	Duplex jams
Sharp AR-M208	124559	229	ST()	False jam code- will not clear; offcolored panels
Sharp AR-M237	124170	35	ST() PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M237	124171	136	ST() PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M237	124245	34	ST() FN(AR-FN5N)	
Sharp AR-M237	124288	58	ST() PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M237	124290	82	ST() PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M237	124643	94	ST() FAX(AR-FX7)	
Sharp AR-M277	122985	209	ST() PC(AR-P17) FN(AR-FN5N)	Needs toner to test; dirty & offcolored panels
Sharp AR-M277	123121	269	ST() SCAN(AR-NS2) PC(AR-P17) FAX(AR-FX7)	Bypass will not detect paper- inop
Sharp AR-M277	124156	55	ST() PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M277	124164	192	ST() PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M277	124172	29	ST() PC(AR-P17) FN(AR-FN5N)	
Sharp AR-M277	124540	222	ST() PC(AR-P17)	
Sharp AR-M277	124682	244	ST() FN(AR-FN5N)	
Sharp AR-M280	120746	512	RADF(AR-EF1) PED(AR-D13) FN(AR-FN6) DX(AR-DU4)	Error code L6-10 (laser problem)
Sharp AR-M280	121201	89	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	Finisher in error code F1-87 (stapler rotate motor)- finisher not tested; yellowed paper tray #1 panel; cracked right side exit tray
Sharp AR-M280	121202	58	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Finisher in error code F1-87 (stapler rotate motor)- finisher not tested
Sharp AR-M280	121203	204	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6)	Finisher in error code F1-87 (stapler rotate motor)- finisher not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(AR-FX5) DX(AR-DU4)	
Sharp AR-M280	121204	150	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	
Sharp AR-M280	121205	193	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	Finisher in error code F1-87 (stapler rotate motor)- finisher not tested
Sharp AR-M280	121206	184	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	
Sharp AR-M280	121207	103	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	Fax board in error code U-1 (battery problem)
Sharp AR-M280	124971	723	ST() RADF(AR-EF1) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5)	Error code F1-15 -finisher not tested
Sharp AR-M280	124972	392	RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	Version N; yellowed panels; RADF receiving tray broken; ; bottom finisher tray broken
Sharp AR-M350	117350	384	RADF(AR-EF1) PED(AR-D15) FN(AR-FN7) DX(AR-DU3)	LCD is dim
Sharp AR-M350	117682	N/A	RADF(AR-EF1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Machine will not come to ready- unable to test
Sharp AR-M350	117683	252	RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Missing drum unit- can't test; yellowed panels
Sharp AR-M350	118250	272	RADF(AR-EF1) PED(AR-D15) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Yellowed panels; made two copies and indicated to add toner
Sharp AR-M350	118253	307	RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Finisher tray mount damaged causing error code F1-15; Machine is showing change toner cartridge & will not clear- tried tetsing with another but error persists; dirty and off colored
Sharp AR-M350	118255	271	RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6)	Yellowed panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			DX(AR-DU4)	
Sharp AR-M350	118617	254	ST() RADF(AR-EF1) PFU(AR-MU1) FAX(AR-FX5) DX(AR-DU4)	
Sharp AR-M350	118939	298	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Yellowed panels
Sharp AR-M350	119855	951	SCAN(AR-NS2) RADF(AR-EF1) PU(AR-PN1B) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3)	
Sharp AR-M350	119856	550	SCAN(AR-NS2) RADF(AR-EF1) PU(AR-PN1B) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3)	
Sharp AR-M350	119857	198	SCAN(AR-NS2) RADF(AR-EF1) PU(AR-PN1B) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3)	Broken finisher door
Sharp AR-M350	119924	547	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M350	119926	834	RADF(AR-EF1) PFU(AR-MU1) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU4)	
Sharp AR-M350	120906	426	RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Pedestal in error code U6-02 (LCT tray lift problem)
Sharp AR-M350	121901	212	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Error code F1-87 - finisher error code
Sharp AR-M350	122230	484	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M350	122467	N/A	RADF(AR-EF1) PED(AR-D15) PC(AR-P14)	Machine will not boot- can't test

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	
Sharp AR-M350	122468	163	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D15) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4)	Dirty & offcolored panels
Sharp AR-M350	122490	563	RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Finisher trays out of alignment causing error code F1-15; missing RADF exit tray; yellowed & dirty
Sharp AR-M350	122986	136	RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU4)	Missing top finisher tray
Sharp AR-M350	123815	469	ST() RADF(AR-EF1) PFU(AR-MU1) PC(AR-P14) DX(AR-DU4)	Dirty & offcolored panels
Imagistics IM3511	116167	103	PED(9292) PC(ZB3500620) FAX(ZB3500590) DX(9246)	
Imagistics IM3511	119904	47	PED(9292) FN(9242) DX(9246)	
Sharp AR-M355	120284	185	RADF(AR-EF3) PED(AR-D27) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	120623	465	RADF(AR-EF3) PED(AR-D27) FN(AR-FN7) DX(AR-DU3)	Duplex jams when using finisher
Sharp AR-M355	122935	387	SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	123119	206	RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	123471	195	RADF(AR-EF3) PED(AR-D27) FN(AR-FN6) DX(AR-DU3)	
Sharp AR-M355	123472	149	SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	123888	113	SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	Jams very copy- will not pass paper
Sharp AR-M355	124539	561	RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M450	117430	729	RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M450	117431	712	RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4)	Yellowed panels
Sharp AR-M450	121153	205	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3)	
Sharp AR-M450	121154	872	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3)	
Sharp AR-M450	121156	436	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4)	Error code F1-87 (stapler rotate motor)- not tested; Error F1-15
Sharp AR-M450	121166	874	SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4)	
Sharp AR-M450	122231	888	STK(AR-MS1) SCAN(AR-NS2) RADF(AR-EF1) PU(AR-PN1B) PS(AR-PK1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU3)	
Sharp AR-M450	122271	1050	STK(AR-MS1) SCAN(AR-NS2) RADF(AR-EF1) PU(AR-PN1B) PS(AR-PK1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU3)	Yellowed & dirty panels
Sharp AR-M450	122462	751	RADF(AR-EF1) PED(AR-D14) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M450	122463	491	RADF(AR-EF1) PED(AR-D14) FN(AR-FN6) DX(AR-DU4)	Dirty & yellowed panels
Sharp AR-M450	122477	841	RADF(AR-EF1) PED(AR-D15) FN(AR-FN6) DX(AR-DU4)	Dirty & offcolored panels; broken finisher door latch

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M450	122478	299	RADF(AR-EF1) PED(AR-D15) FN(AR-FN6) DX(AR-DU4)	Missing RADF tray
Sharp AR-M450	122810	360	STK(AR-MS1) RADF(AR-EF1) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU3)	RADF smashed; duplex unit smashed; stacker bins cracked; offcolored & dirty panels
Sharp AR-M450	122811	248	STK(AR-MS1) RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU3)	Error code L4-02 (drum drive motor); stacker pulled free from machine & door broken off; missing RADF cover panel; dirty panels
Sharp AR-M450	122812	430	STK(AR-MS1) RADF(AR-EF1) PED(AR-D15) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU3)	Missing left side access door interlock actuator- unable to test machine; dirty & yellowed panels
Sharp AR-M450	122814	N/A	STK(AR-MS1) RADF(AR-EF1) PED(AR-D15) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU3)	Entire scanner section bent down; control panel inoperable- can't test; back panel smashed in; missing RADF panel; yellowed panels
Sharp AR-M450	122987	991	RADF(AR-EF1) PED(AR-D13) DX(AR-DU3)	Missing finisher (has brackets)
Imagistics IM4510	124329	516	SCAN(92NS) RADF(9240) PED(9247) PC(92HD) NIC(92NK) FN(9242) DX(9246)	Error code F1-19 (finisher problem); offcolored & dirty panels
Sharp AR-M450	124555	420	RADF(AR-EF1) PED(AR-D14) FN(AR-FN6)	
Sharp AR-M455	114447	417	ST() RADF(AR-EF3) PFU(AR-MU2)	Broken RADF tray
Sharp AR-M455	120624	641	SCAN(AR-NS3) RADF(AR-EF3) PU(AR-PN1B) PED(AR-D27) PC(AR-P21) FN(AR-FN7) DX(AR-DU3)	
Sharp AR-M455	123114	989	SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M455	124558	102	RADF(AR-EF3) PED(AR-D27) DX(AR-DU4)	
Sharp AR-M550	113920	527	FN(AR-F15)	
Sharp AR-M550	116093	358	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	116836	610	PC(AR-P19) FN(AR-F15)	Broken RADF tray
Sharp AR-M550	116872	487	FN(AR-F15)	Missing RADF tray
Sharp AR-M550	117351	N/A	PC(AR-P19) FN(AR-F15)	Missing toner cartridge- can't test

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M550	118427	1734	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	119586	1321	PC(AR-P19) P(AR-LC6) FN(AR-F15)	
Sharp AR-M550	119587	965	PC(AR-P19) P(AR-LC6) FN(AR-F15)	Bypass will not allow paper size to be selected
Sharp AR-M550	120256	1289	PC(AR-P19)	Missing finisher (has guide pin & missing knockouts)
Sharp AR-M550	120625	432	PU(AR-PN4B) P(AR-LC6) FN(AR-F15)	
Sharp AR-M550	121337	389	FN(AR-F15)	
Sharp AR-M550	122461	328	FN(AR-F15)	
Sharp AR-M550	122813	1150	SCAN(AR-NS3) PC(AR-P19)	Dented & bent back panel; dirty panels; duplex jams; missing exit tray
Sharp AR-M550	122984	1105	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	123188	584	PC(AR-P19) P(AR-LC6) FN(AR-F15)	
Sharp AR-M550	124165	391	PC(AR-P19) FN(AR-F15)	Machine will not come to ready- can't test; dirty & offcolored finisher panels
Sharp AR-M550	124166	770	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124167	790	PC(AR-P19) FN(AR-F15)	Broken finisher interlock switch
Sharp AR-M550	124169	271	PC(AR-P19) FN(AR-F15)	Error code C1-00
Sharp AR-M550	124188	220	PC(AR-P19) FN(AR-F15)	False jam code- will not clear
Sharp AR-M550	124190	1472	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124191	349	PC(AR-P19) FN(AR-F15)	Finisher in error code F1-02
Sharp AR-M550	124192	1058	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124194	205	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124247	446	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124248	347	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124258	664	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124289	1436	PC(AR-P19) FN(AR-F15)	
Sharp AR-M550	124291	795	PC(AR-P19) FN(AR-F15)	RADF jams- inop; stapler inop
Sharp AR-M620	116842	614	PC(AR-P19) FN(AR-F15)	Error code F2-31 (process control-drum reflection); toner mechanism not working; very dirty & discolored panels; missing RADF tray
Sharp AR-M620	118417	1415	SCAN(AR-NS3) PS(AR-PK5) PC(AR-P19) FN(AR-F15) FAX(AR-FX8)	
Sharp AR-M620	118614	1219	PC(AR-P19) P(AR-LC6) FN(AR-F15)	
Sharp AR-M620	118882	896	SCAN(AR-NS3) PU(AR-PN4B) PC(AR-P19)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(AR-F15) FAX(AR-FX8)	
Sharp AR-M700	117718	2535	SCAN(AR-NS3) PC(AR-P19) FN(AR-F15)	
Sharp AR-M700	117719	2555	SCAN(AR-NS3) PC(AR-P19) FN(AR-F15)	
Sharp AR-M700	117935	1213	SCAN(AR-NS3) PC(AR-P19) FN(AR-F15)	
Sharp AR-M700	117938	494	SCAN(AR-NS3) PC(AR-P19) FN(AR-F15) FAX(AR-FX8)	Dented & bent back panel; missing RADF tray
Sharp AR-M700	120084	819	PU(AR-PN4B) PC(AR-P19) P(AR-LC6) FN(AR-F16)	Error code L4-02 (drum driver motor)
Sharp AR-M700	124193	500	SCAN(AR-NS3) PC(AR-P19) FN(AR-F15)	Calling for toner cartridge to be installed & will not clear (can't test)

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.