

Wulff Enterprises

07/29/2010

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO120	149840	17	ADF(MR-2014)	
Toshiba E-STUDIO120	150163	67	ST() ADF(MR-2014)	Missing bypass tray
Toshiba E-STUDIO120	150164	61	ST() ADF(MR-2014)	
Toshiba E-STUDIO120	152566	26		Toner spilled throughout machine; cracked platen top hinges
Toshiba E-STUDIO150	149449	91		
Toshiba E-STUDIO150	149450	81	ST()	
Toshiba E-STUDIO150	154702	73		
Toshiba E-STUDIO150	155961	45	PFU(MY-1019) ADF(MR-2014)	Yellowed panels
Toshiba E-STUDIO150	156372	47	ADF(MR-2014)	Off color panels
Toshiba E-STUDIO150	157178	33	ADF(MR-2014)	Jams in fuser every copy- can't test; ADF not latching properly; yellowed panels
Toshiba E-STUDIO162D	155864	61	RADF(MR-3017) FAX(GD-1190)	Yellowed & dirty panels; RADF & duplex jam
Toshiba E-STUDIO162D	155866	N/A	RADF(MR-3017) FAX(GD-1190)	Error code H4-00 (fuser temp too low)
Toshiba E-STUDIO162D	155867	17	RADF(MR-3017) FAX(GD-1190)	Error code F4-00 (low fuser temp); offcolor & dirty panels
Toshiba E-STUDIO162D	155868	26	RADF(MR-3017) FAX(GD-1190)	Offcolor panels
Toshiba E-STUDIO162D	155874	52	RADF(MR-3017) FAX(GD-1190)	Duplex jams; missing toner cartridge- tested with another
Toshiba E-STUDIO162D	155875	36	RADF(MR-3017) FAX(GD-1190)	Blurred streak in center of copies
Toshiba E-STUDIO162D	156044	97	RADF(MR-3017) FAX(GD-1190)	
Toshiba E-STUDIO162D	157240	20	RADF(MR-3017) PFU(MY-1026) PC(GA-1170) FAX(GD-1190)	Missing lower right access panel- unable to test PFU tray
Toshiba E-STUDIO162	152801	38	ADF(MR-2016)	
Sharp AR-168S	153480	33		
Toshiba E-STUDIO162	154219	9	FAX(GD-1190) ADF(MR-2016)	
Toshiba E-STUDIO162	156687	71	ST() PFU(MY-1026) PC(GA-1170) ADF(MR-2016)	Yellowed panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO162	156688	41	PC(GA-1170) ADF(MR-2016)	Will not feed- makes a loud clicking noise; will not detect paper in tray
Toshiba E-STUDIO162	156848	25	FAX(GD-1190) ADF(MR-2016)	Copies feed to registration roller too quickly
Toshiba E-STUDIO162	157502	N/A	FAX(GD-1190) ADF(MR-2016)	Machine is smashed- total loss
Sharp AR-BC320	156456	547	PED(AR-D19N) FN(AR-F13)	Has duplexer bypass and inverter
Sharp AR-C330	151880	44	RADF(AR-RF1) PC(AR-PE3N) 20SS(AR-SS2)	Error code C1-11 (cyan charge corona, image density sensor or transfer belt problem); color = 44k; B/W = 1k
Sharp AR-C330	152914	122	RADF(AR-RF1) PC(AR-PE3N)	Broken left side panel; bowed back & right side panels; missing exit tray; offcolor & dirty panels; color = 102k; B/W = 21k
Sharp AR-C330	153406	N/A	RADF(AR-RF1) PC(AR-PE3N) E()	Missing a terminal on power plug- can't test
Sharp AR-C330	155302	133	RADF(AR-RF1) PC(AR-PE3N)	Error code E-7-10 (black correction shading problem); dirty panels; missing exit tray; color = 126k; B/W = 8k
Sharp AR-C330	157107	120	PC(AR-PE3N)	Missing exit tray; color = 81k; B/W = 40k
Sharp AR-M162	156879	164	NIC(AR-NB3)	
Toshiba E-STUDIO161	156446	N/A	ADF(MR-2015)	Error code CH - side cover open - not tested; left side frame bent
Sharp AR-M237	154800	28	ST() FN(AR-FN5N)	
Sharp AR-M237	154801	32	ST() FN(AR-FN5N) FAX(AR-FX7)	
Sharp AR-M237	157264	120	ST()	
Sharp AR-M257	157285	265	ST() FAX(AR-FX7)	
Sharp AR-M257	157286	346	PC(AR-P27) FAX(AR-FX7)	
Sharp AR-M257	157295	270	ST()	
Sharp AR-M317	157287	308	ST() PC(AR-P27) FAX(AR-FX7)	
Sharp AR-M317	157288	168	ST() FAX(AR-FX7)	
Sharp AR-M355	152068	369	ST() RADF(AR-EF3) PFU(AR-MU2) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12)	
Sharp AR-M355	152069	485	ST() RADF(AR-EF3) PFU(AR-MU2) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12)	Missing left side access door & top turnaround bracket- tested with another

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M355	152874	443	ST() RADF(AR-EF3) PFU(AR-MU2) DX(AR-DU4)	
Sharp AR-M355	153866	489	SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12)	
Sharp AR-M355	154240	429	SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	154335	540	RADF(AR-EF3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	155505	264	SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	155542	393	RADF(AR-EF3) PED(AR-D27) FN(AR-FN7) DX(AR-DU3)	Broken RADF access door annd missing paper feed pads- inop
Sharp AR-M355	155754	243	SCAN(AR-NS3) RADF(AR-EF3) PU(AR-PN1B) PS(AR-PK6) PED(AR-D27) PC(AR-P21) FN(AR-FN7) FAX(AR-FX12)	Offcolor panels
Sharp AR-M355	155756	659	SCAN(AR-NS3) RADF(AR-EF3) PU(AR-PN1B) PS(AR-PK6) PED(AR-D27) PC(AR-P21) FN(AR-FN7)	
Imagistics IM3511	155857	82	PED(9291) FN(9242) DX(9246)	Broken exit tray
Sharp AR-M355	155884	406	RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN7) DX(AR-DU3)	
Sharp AR-M355	156526	374	RADF(AR-EF3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	157230	368	RADF(AR-EF3) PED(AR-D27) PC(AR-P21) DX(AR-DU4)	
Sharp AR-M355	157248	193	RADF(AR-EF3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M355	157265	263	ST() SCAN(AR-NS3) RADF(AR-EF3) PFU(AR-MU2) PC(AR-P21) DX(AR-DU4)	Dented back panel above PFU on left side

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M355	157267	354	ST() SCAN(AR-NS3) RADF(AR-EF3) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4)	
Sharp AR-M455	153202	546	RADF(AR-EF3) PED(AR-D28) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M455	153203	445	RADF(AR-EF3) PED(AR-D28) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M455	153204	491	RADF(AR-EF3) PED(AR-D28) FN(AR-FN6) DX(AR-DU4)	
Imagistics IM4511	156685	210	SCAN(ZB3500610) PED(9292) PC(ZB3500620) FN(9242) FAX(ZB3500590) DX(9246)	Very dirty & offcolor panels; unable to print a fax report
Sharp AR-M455	157206	1065	SCAN(AR-NS3) RADF(AR-EF3) PS(AR-PK6) PED(AR-D27) PC(AR-P21) FN(AR-FN6) DX(AR-DU4)	
Sharp AR-M455	157289	427	RADF(AR-EF3) PU(AR-PN1B) PED(AR-D28) PC(AR-P21) FN(AR-FN7) FAX(AR-FX12)	
Sharp AR-M550	154972	74	FN(AR-F15)	Missing toner cartridge (tested with another)
Sharp AR-M550	154973	73	PC(AR-P19) FN(AR-F15)	Missing toner cartridge (tested with another); scratched right side panels
Sharp AR-M550	154974	26	PC(AR-P19) FN(AR-F15)	Cracked back panel; lower finisher tray out of alignment & broken back rail cover- inop; missing toner cartridge (tested with another)
Sharp AR-M550	154975	47	FN(AR-F15)	Missing toner cartridge (tested with another)
Sharp AR-M550	154976	45	FN(AR-F15)	Missing toner cartridge (tested with another)
Sharp AR-M550	154977	138	FN(AR-F15)	Missing toner cartridge (tested with another)
Sharp AR-M550	154980	15	FN(AR-F15)	Missing toner cartridge (tested with another); missing RADF tray
Sharp AR-M550	156424	375	FN(AR-F15)	Jamming in duplexer - not tested
Sharp AR-M550	157193	443	SCAN(AR-NS3) PC(AR-P19) FN(AR-F15)	Yellowed finisher rails

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Sharp AR-M620	156602	532	PC(AR-P19) FN(AR-F15) FAX(AR-FX8)	Trim bent on back upper left side panel
Oce CM2510	156976	159	PED(9502) FAX(CM2510030)	All functions tested fine, then went into error code L4-11 (shift motor trouble); color = 27k; B/W = 133k
Sharp MX-3501N	156529	1495	ST() PS(MX-PKX1) FN(MX-FNX2)	Black meter = 72k; color meter = 779k
Oce CM4010	150736	133	PS(CM2510020) PED(9511) P(9503) FN(9504) FAX(CM2510040) USB ports FAX(CM2510030)	Dented back paper deck panel; Color = 16k; B/W = 118k; has work tray w/4
Oce CM4010	156977	185	PED(9511) FN(9504) FAX(CM2510030)	Color = 81k; B/W = 105k
Oce CM4010	156978	286	PU(9507) PED(9511) FN(9504) FAX(CM2510030)	Color = 38k; B/W = 248k
Sharp MX-5500N	144411	1218	PU(MX-PNX2B) PS(MX-PKX1) FN(MX-FNX4)	Missing rear finisher wheels; Black meter = 967k; color meter = 251k
Sharp MX-5500N	154200	1445	PS(MX-PKX1) FN(MX-FNX4)	RADF shows a false jam occasionally; color = 188k; B/W = 1257k
Sharp MX-M450	139591	393	RADF(MX-EFX1) PED(AR-D27) PC(MX-NBX3) FN(AR-FN6) DX(AR-DU4)	
Sharp MX-M450	141693	489	RADF(MX-EFX1) PED(AR-D28) FN(AR-FN6) DX(AR-DU4)	Broken finisher tray
Sharp MX-M450	152167	948	ST() RADF(MX-EFX1) PC(MX-NBX3) FN(AR-FN6) DX(AR-DU4)	
Sharp MX-M450	152168	1416	ST() RADF(MX-EFX1) PFU(AR-MU2) PC(MX-NBX3) DX(AR-DU4)	
Sharp MX-M450	152169	897	ST() RADF(MX-EFX1) PFU(AR-MU2) PC(MX-NBX3) DX(AR-DU4)	
Sharp MX-M620	152070	925	PC(MX-NBX1) FN(AR-F15)	Error code H2-00 (fuser thermistor)-will not clear
Sharp MX-M620	157290	1391	PU(AR-PN4B) PC(MX-NBX1) FN(AR-F15)	
Sharp MX-M700	153599	1111	PS(MX-PKX1) PC(MX-NBX1) FN(AR-F15)	

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.