

Wulff Enterprises

01/07/2009

OH Inventory for Sale

Page:1

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|----------------------|--------|-------|---|---|
| Sharp AR-157E | 119099 | 173 | | |
| Sharp AR-157E | 121877 | 119 | ST() | |
| Sharp AR-157E | 122289 | 50 | | Offcolored panels |
| Sharp AR-162S | 124582 | 36 | ST() ADF(AR-SP2) | |
| Sharp AR-162S | 124583 | 65 | ST() ADF(AR-SP2) | |
| Sharp AR-164 | 123988 | 67 | | |
| Toshiba E-STUDIO162D | 120540 | 43 | RADF(MR-3017) PC(GA-1170) | |
| Sharp AR-168D | 121539 | 62 | NIC(AR-NB2N) | |
| Sharp AR-168D | 122650 | 136 | NIC(AR-NB2N) FAX(AR-FX9) | |
| Toshiba E-STUDIO162D | 123757 | 41 | RADF(MR-3017) | Duplex jams |
| Sharp AR-168D | 124778 | 31 | | |
| Toshiba E-STUDIO162 | 124527 | 13 | ADF(MR-2016) | |
| Sharp AR-235 | 116168 | 276 | ST() RADF(AR-RP3) | |
| Sharp AR-235 | 116708 | 309 | ST() RADF(AR-RP3) | Top right side access panel won't stay closed |
| Sharp AR-235 | 120499 | 105 | ST() RADF(AR-RP3) | Yellowed panels |
| Sharp AR-235 | 121560 | N/A | ST() RADF(AR-RP3) FN(AR-FN5) | Missing upper right side panel- can;t test; yellowed panels |
| Sharp AR-235 | 124577 | 554 | ST() RADF(AR-RP3) | |
| Sharp AR-275 | 115779 | 330 | ST() RADF(AR-RP3) | Missing finisher & print controller |
| Sharp AR-275 | 122997 | 115 | ST() RADF(AR-RP3) PFU(AR-D12) | Yellowed panels |
| Sharp AR-287 | 112973 | 1192 | ST() P(AR-LC1) FN(AR-FN2) | Paper deck inop; finisher makes a clicking noise |
| Sharp AR-337 | 122956 | 341 | PED(AR-DE1N [A]) P(AR-LC1) FN(AR-FN2) | Offcolored & dirty panels |
| Sharp AR-507 | 115968 | 772 | PED(AR-DE7 [B]) PC(AR-PB2) NIC(AR-NC3D) FN(AR-FN3) | Print controller in error code F9-00 (ICU-PRT problem); duplex causes error code E7-03 (hard drive) |
| Sharp AR-507 | 121635 | 225 | ST() PC(AR-PB2) NIC(AR-NC3D) FN(AR-FN3) | Broken finisher handle; stapler inop |
| Sharp AR-507 | 123807 | 164 | PED(AR-DE7 [B]) PC(AR-PB2) NIC(AR-NC3D) | Broken RADF tray hinge |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|--|---|
| | | | FN(AR-FN3) | |
| Sharp AR-5316 | 123906 | 14 | ADF(AR-SP6N) | |
| Sharp AR-BC260 | 114869 | 299 | PED(AR-D19N) | Color = 170k; B/W = 130k |
| Sharp AR-BC260 | 117784 | 129 | PED(AR-D19N) FN(AR-F13) | Color = 49k; B/W = 80k |
| Sharp AR-BC260 | 119472 | 159 | PED(AR-D19N) | Color = 35k; B/W = 125k |
| Sharp AR-BC260 | 119768 | 174 | PED(AR-D19N) FN(AR-F13) | Color = 26k; B/W = 148k |
| Sharp AR-BC260 | 121886 | 75 | PED(AR-D19N) | Needs black toner- unable to test; color = 16k; B/W = 60k |
| Sharp AR-BC260 | 122013 | 355 | PED(AR-D19N) FN(AR-F13) FAX(AR-FX10) | Black meter = 117k; colored meter =238k |
| Sharp AR-BC260 | 122602 | 140 | PED(AR-D17N) FAX(AR-FX10) | Color = 64k; B/W = 76k |
| Sharp AR-BC260 | 123001 | 10 | PED(AR-D19N) | Color = 8k; B/W = 2k |
| Sharp AR-BC260 | 123222 | 99 | PED(AR-D19N) FAX(AR-FX10) | Color = 59k; B/W = 40k; scratched front door; missing duplex exit tray |
| Sharp AR-BC260 | 123708 | 478 | PED(AR-D19N) FN(AR-F13) | Corrupted color copies; color = 93k; B/W = 386k |
| Sharp AR-BC260 | 123914 | 285 | PED(AR-D19N) FAX(AR-FX10) | Color = 57k; B/W = 228k |
| Sharp AR-BC260 | 124205 | 47 | PS(AR-PK4) PED(AR-D19N) | Color = 22k; B/W = 25k |
| Sharp AR-BC260 | 124570 | 86 | PED(AR-D19N) FAX(AR-FX10) | Color = 16k; B/W = 71k |
| Sharp AR-BC320 | 118911 | 173 | PED(AR-D19N) FN(AR-F13) | Machine will not detect finisher- can't test; color = 34k; B/W = 140k |
| Sharp AR-BC320 | 119469 | 525 | PED(AR-D19N) | Color = 82k; B/W = 444k |
| Sharp AR-BC320 | 122006 | 549 | PU(AR-PN1B) PED(AR-D19N) FN(AR-F13) | Has AR-RB1 Inverter; Black meter = 500k; colored meter =50k |
| Sharp AR-C160 | 119927 | 53 | RADF(AR-RF1) PC(AR-PE2) DX(AR-DU2N) 20SS(AR-SS2) | Sorter bins out of alignment- inop; dented & bent back panel; broken front door interlock actuator; color = 23k; B/W = 30k |
| Sharp AR-C160 | 121638 | 169 | RADF(AR-RF1) PC(AR-PE2) E() | Goes into error code H6-00 (fuser oil)- unable to fully test; color = 142k; B/W = 28k |
| Sharp AR-C160 | 124568 | 51 | RADF(AR-RF1) PC(AR-PE2) E() DX(AR-DU2N) | Duplex jams; print controller will not come top ready- inop; broken front door interlock actuator; broken waste toner door; color = 14k; B/W = 38k |
| Sharp AR-C250 | 120842 | 59 | E() | Missing external print controller (has cable); broken used toner door; color = 57k; B/W = 3k |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|---|--|
| Sharp AR-C260M | 103473 | 86 | SCAN(AR-NS2) RADF(AR-RF3) PED(AR-D18) E(AR-TE3) | Jams every copy in fuser- will not pass paper; yellowed front panels; color =53k; B/W = 34k |
| Sharp AR-C260M | 120821 | 241 | RADF(AR-RF3) PED(AR-D19) B(AR-RB1) | Broken exit tray; print controller will not come to ready- inop; color = 74k; B/W = 167k |
| Sharp AR-C260M | 124153 | 104 | RADF(AR-RF3) PED(AR-D19) B(AR-RB1) | Unable to test color copies- machine is calling for yellow toner; color = 2k; B/W = 102k |
| Sharp AR-C260M | 124569 | 67 | RADF(AR-RF3) PED(AR-D19) | Color = 28k; B/W = 40k |
| Sharp AR-C270 | 116339 | 148 | RADF(AR-RF1) PC(AR-PE2) FN(AR-FN4) DX(AR-DU2N) | Stapler inop; color = 122k; B/W = 26k |
| Sharp AR-C330 | 121550 | 46 | PC(AR-PE3N) E() | Color = 20k; B/W = 26k |
| Sharp AR-F152 | 118678 | 48 | | |
| Sharp AR-F152 | 118679 | 27 | | |
| Sharp AR-M160 | 119623 | N/A | ADF(AR-SP6) | Error code H-2-00 (fuser thermistor); missing toner unit & drum appears to have been swapped out |
| Sharp AR-M160 | 121089 | N/A | | Error code L4-1 (main motor); toner spilled throughout machine |
| Sharp AR-M160 | 122288 | 83 | PFU(AR-D24) ADF(AR-SP6) | |
| Sharp AR-M160 | 123969 | 20 | | |
| Sharp AR-M160 | 123970 | 29 | | |
| Sharp AR-M160 | 123971 | 16 | | |
| Sharp AR-M160 | 123972 | 139 | ADF(AR-SP6) | |
| Sharp AR-M160 | 123973 | 76 | ADF(AR-SP6) | |
| Sharp AR-M160 | 123974 | 40 | ADF(AR-SP6) | |
| Sharp AR-M160 | 123975 | 20 | | |
| Sharp AR-M162 | 122456 | 90 | ES(AR-EB9) ADF(AR-SP6N) | |
| Sharp AR-M162 | 123634 | 180 | PFU(AR-D24) NIC(AR-NB3) FAX(AR-FX11) ES(AR-EB9) | Dirty panels |
| Toshiba E-STUDIO161 | 105994 | 34 | | |
| Toshiba E-STUDIO161 | 107332 | N/A | ADF(MR-2015) | Error code L4 (main motor); toner spilled throughout machine |
| Sharp AR-M205 | 120888 | 94 | ST() RADF(AR-RP6) | |
| Sharp AR-M205 | 122290 | 203 | ST() RADF(AR-RP6) PFU(AR-D24) | |
| Sharp AR-M207 | 122681 | 47 | ST() RADF(AR-RP6N) | Expansion cover dented in |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|----------|---|--|
| | | | NIC(AR-NB3) FAX(AR-FX11) ES(AR-EB9) | |
| Sharp AR-M207 | 122682 | 77 ST() | RADF(AR-RP6N) NIC(AR-NB3) ES(AR-EB9) | |
| Sharp AR-M207 | 123907 | 71 | RADF(AR-RP6N) | |
| Sharp AR-M208 | 120539 | 118 ST() | | Broken right side access door; yellowed paper trays |
| Sharp AR-M208 | 120612 | 77 ST() | FAX(AR-FX4) | Yellowed panels |
| Sharp AR-M208 | 122097 | 88 ST() | FN(AR-FN5N) | Yellowed panels |
| Sharp AR-M208 | 122679 | 348 ST() | | Yellowed panels; cracked right side panel |
| Sharp AR-M208 | 122685 | 191 ST() | PC(AR-P11) FAX(AR-FX4) | Duplex jams |
| Sharp AR-M208 | 123636 | 137 ST() | | |
| Sharp AR-M208 | 123976 | 164 ST() | | |
| Sharp AR-M208 | 123977 | 113 ST() | | |
| Sharp AR-M208 | 123978 | 130 ST() | FN(AR-FN5N) | |
| Sharp AR-M208 | 123979 | 15 ST() | | Missing standard RADF |
| Sharp AR-M208 | 123980 | 136 ST() | FN(AR-FN5N) | |
| Sharp AR-M208 | 123981 | 104 ST() | FN(AR-FN5N) | |
| Sharp AR-M208 | 123982 | 134 ST() | FN(AR-FN5N) | |
| Sharp AR-M208 | 123983 | 147 ST() | | |
| Sharp AR-M208 | 123984 | 383 ST() | FN(AR-FN5N) | |
| Sharp AR-M208 | 123985 | 265 ST() | FN(AR-FN5N) | |
| Sharp AR-M208 | 123986 | 441 ST() | | |
| Sharp AR-M208 | 124414 | 180 ST() | PC(AR-P11) NIC(AR-NC5J) | |
| Sharp AR-M208 | 124415 | 157 ST() | PC(AR-P11) NIC(AR-NC5J) | |
| Sharp AR-M208 | 124565 | 40 ST() | FN(AR-FN5N) | Yellowed panels |
| Sharp AR-M237 | 121973 | 131 ST() | | NIC is missing - (has print meter count) |
| Sharp AR-M237 | 122458 | 218 ST() | | |
| Sharp AR-M237 | 122773 | 123 ST() | | Paper tray #2 motor missing; loose fuser section; duplex jams |
| Sharp AR-M237 | 123564 | 191 ST() | | Broken RADF access door; gouged RADF panels |
| Sharp AR-M237 | 123642 | 116 ST() | FAX(AR-FX7) E(AR-TR3) | |
| Sharp AR-M237 | 123908 | 322 ST() | SCAN(AR-NS2) | Duplex copies are unfused |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|---|---|
| | | | PC(AR-P17) | |
| Sharp AR-M237 | 124588 | 485 | PS(AR-PK1N) PFU(AR-D22) PC(AR-P17) E(AR-TR3) | |
| Sharp AR-M237 | 124589 | 291 | PFU(AR-D22) PC(AR-P17) NIC(AR-NC5J) FAX(AR-FX7) | Scanner will not move into position when testing RADF- can't test RADF |
| Sharp AR-M237 | 124590 | 197 | PS(AR-PK1N) PFU(AR-D22) PC(AR-P17) FAX(AR-FX7) E(AR-TR3) | |
| Sharp AR-M277 | 116868 | 460 | ST() FN(AR-FN5N) | |
| Sharp AR-M277 | 124457 | 239 | ST() PC(AR-P17) FAX(AR-FX7) | |
| Sharp AR-M277 | 124473 | 397 | ST() PC(AR-P17) FAX(AR-FX7) | |
| Sharp AR-M277 | 124491 | 267 | ST() FN(AR-FN5N) | |
| Sharp AR-M277 | 124580 | 334 | ST() SCAN(AR-NS2) PC(AR-P17) FN(AR-FN5N) | Missing lower finisher tray |
| Sharp AR-M280 | 115665 | 191 | RADF(AR-EF1) PFU(AR-MU1) PED(AR-D14) FN(AR-FN6) DX(AR-DU4) | Needs toner to test; yellowed panels |
| Sharp AR-M280 | 119387 | 316 | SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M280 | 119464 | 179 | ST() RADF(AR-EF1) PFU(AR-MU1) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M280 | 119632 | 1075 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Broken lower finisher tray; broken upper duplex tray; yellowed & dirty panels |
| Sharp AR-M280 | 120590 | 290 | SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU4) | |
| Sharp AR-M350 | 117018 | 894 | ST() RADF(AR-EF1) PFU(AR-MU1) FN(AR-FN6) DX(AR-DU4) | Yellowed panels |
| Sharp AR-M350 | 117569 | 716 | RADF(AR-EF1) PED(AR-D14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Yellowed panels |
| Sharp AR-M350 | 118204 | 338 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) FN(AR-FN6) DX(AR-DU4) | Dirty & yellowed panels; broken finisher door |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|--|---------------------------------|
| Sharp AR-M350 | 119727 | 442 | ST() RADF(AR-EF1) PFU(AR-MU1) PC(AR-P14) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4) | Yellowed panels |
| Sharp AR-M350 | 120812 | 571 | RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M350 | 121315 | 582 | RADF(AR-EF1) PED(AR-D14) FN(AR-FN7) DX(AR-DU3) | Broken front door hinge pin |
| Sharp AR-M350 | 121548 | 977 | ST() RADF(AR-EF1) PFU(AR-MU1) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) DX(AR-DU3) | Broken finisher door tab |
| Sharp AR-M350 | 121887 | 359 | RADF(AR-EF1) PED(AR-D14) PC(AR-P14) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M350 | 121975 | 933 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | Yellowed panels |
| Sharp AR-M350 | 122453 | 350 | SCAN(AR-NS2) RADF(AR-EF1) PS(AR-PK1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Yellowed panels |
| Sharp AR-M350 | 122649 | 412 | RADF(AR-EF1) PED(AR-D20) PC(AR-P14) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M350 | 122819 | 845 | SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Missing RADF tray; dirty panels |
| Sharp AR-M350 | 123057 | 1739 | SCAN(AR-NS2) RADF(AR-EF1) PS(AR-PK1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M350 | 124202 | 488 | SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Missing RADF exit tray |
| Sharp AR-M350 | 124591 | 360 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4) | Yellowed & dirty panels |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|---|--|
| Sharp AR-M350 | 124592 | 1192 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) E(AR-TE3) DX(AR-DU4) | |
| Sharp AR-M350 | 124593 | 802 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) E(AR-TE3) DX(AR-DU4) | |
| Sharp AR-M355 | 121968 | 350 | SCAN(AR-NS3) RADF(AR-EF3) PS(AR-PK6) PED(AR-D28) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4) | |
| Sharp AR-M355 | 122042 | 430 | RADF(AR-EF3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) | Right side exit tray broken |
| Sharp AR-M355 | 122454 | 73 | ST() RADF(AR-EF3) PFU(AR-MU2) DX(AR-DU4) | |
| Sharp AR-M355 | 122676 | 134 | SCAN(AR-NS3) RADF(AR-EF3) PS(AR-PK6) PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4) | Finisher inop- makes a thumping noise & missing all trays |
| Sharp AR-M355 | 122684 | 321 | RADF(AR-EF3) PED(AR-D27) DX(AR-DU4) | |
| Sharp AR-M355 | 123635 | 472 | RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FAX(AR-FX12) DX(AR-DU4) | |
| Sharp AR-M355 | 123672 | 219 | SCAN(AR-NS3) RADF(AR-EF3) PED(AR-D28) PC(AR-P21) FN(AR-FN6) DX(AR-DU4) | Dirty panels |
| Sharp AR-M355 | 124036 | 546 | RADF(AR-EF3) PED(AR-D28) PC(AR-P21) DX(AR-DU4) | |
| Sharp AR-M355 | 124068 | 515 | ST() RADF(AR-EF3) PFU(AR-MU2) DX(AR-DU4) | Missing fuser unit- can't test; offcolored & dirty panels; broken exit trays |
| Sharp AR-M355 | 124638 | 176 | RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) | Missing developer unit & toner cartridge- tested with others |
| Imagistics IM3511 | 124712 | 601 | PED(9291) FN(9242) DX(9246) | Missing an exit tray |
| Sharp AR-M450 | 117567 | 661 | RADF(AR-EF1) | Yellowed panels |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|--|---|
| | | | PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M450 | 118710 | 714 | RADF(AR-EF1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | model N+ |
| Sharp AR-M450 | 119524 | 961 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M450 | 119907 | 441 | SCAN(AR-NS2) RADF(AR-EF1) PU(AR-PN1B) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3) | Yellowed panels |
| Sharp AR-M450 | 120541 | 1224 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M450 | 120693 | 125 | RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU3) | Yellowed panels; missing duplex exit tray |
| Sharp AR-M450 | 121051 | 643 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Missing toner cartridge- tested with another; duplex jams- inop |
| Sharp AR-M450 | 121180 | 463 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M450 | 121473 | 721 | SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Bent back panel |
| Sharp AR-M450 | 121982 | 703 | STK(AR-MS1) SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3) | Yellowed panels |
| Sharp AR-M450 | 122095 | 607 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) E(AR-TE3) DX(AR-DU3) | Yellowed panels |
| Sharp AR-M450 | 122096 | N/A | RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) DX(AR-DU3) | No power |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|---|--|
| Imagistics IM4510 | 122901 | 678 | RADF(9240) PU() PED(9248) FN(9242) E(925T) DX(9245) | |
| Imagistics IM4510 | 122902 | 213 | RADF(9240) PED(9248) FN(9242) DX(9246) | |
| Sharp AR-M450 | 122999 | 494 | SCAN(AR-NS2) RADF(AR-EF1) PU(AR-PN1B) PS(AR-PK1) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) FAX(AR-FX5) DX(AR-DU3) | |
| Sharp AR-M450 | 123702 | 952 | SCAN(AR-NS2) RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN7) DX(AR-DU4) | Dirty & offcolored panels |
| Sharp AR-M450 | 123911 | 1573 | RADF(AR-EF1) PED(AR-D13) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M450 | 123987 | 854 | RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M450 | 124566 | 1008 | RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M450 | 124567 | 780 | RADF(AR-EF1) PED(AR-D14) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) DX(AR-DU4) | Error code L6-10 (laser problem) |
| Sharp AR-M450 | 124594 | 1250 | RADF(AR-EF1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) E(AR-TE3) DX(AR-DU4) | Shows false change toner message & will not clear- can't test |
| Sharp AR-M450 | 124595 | 1148 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M450 | 124596 | 2110 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | Missing RADF tray |
| Sharp AR-M450 | 124597 | 938 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4) | |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|---|---|
| Sharp AR-M450 | 124598 | 937 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M450 | 124599 | 363 | SCAN(AR-NS2) RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M450 | 124600 | 1942 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M450 | 124601 | 893 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M450 | 124602 | 1819 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU4) | Registration off on copies |
| Sharp AR-M450 | 124603 | 1564 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FAX(AR-FX5) DX(AR-DU3) | Ran OK, the went into error coed L4-02 (drum drive motor); copies are blurred |
| Sharp AR-M450 | 124604 | 971 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4) | Missing an exit tray |
| Sharp AR-M450 | 124605 | 654 | RADF(AR-EF1) PS(AR-PK1) PED(AR-D20) PC(AR-P14) NIC(AR-NC5J) FN(AR-FN6) FAX(AR-FX5) DX(AR-DU4) | |
| Sharp AR-M455 | 120784 | 392 | RADF(AR-EF3) PED(AR-D27) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M455 | 121980 | 210 | STK(AR-MS1) SCAN(AR-NS3) RADF(AR-EF3) PU(AR-PN1B) PS(AR-PK6) PED(AR-D27) PC(AR-P21) FN(AR-FN7) FAX(AR-FX12) | Finisher front panel cracked |
| Sharp AR-M455 | 122451 | 329 | STK(AR-MS1) RADF(AR-EF3) PED(AR-D28) PC(AR-P21) FAX(AR-FX12) DX(AR-DU4) | |
| Sharp AR-M455 | 122674 | 134 | ST() RADF(AR-EF3) PFU(AR-MU2) PC(AR-P21) | Finisher in error code F1-15 (lift |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|---|--|
| | | | FN(AR-FN6) DX(AR-DU4) | |
| Imagistics IM4511 | 122962 | 351 | PED(9291) PC(ZB3500620) FN(9244) FAX(ZB3500590) DX(9245) | |
| Sharp AR-M455 | 123204 | 241 | RADF(AR-EF3) PED(AR-D27) FN(AR-FN6) DX(AR-DU4) | |
| Sharp AR-M455 | 123221 | 662 | RADF(AR-EF3) PED(AR-D27) PC(AR-P21) FN(AR-FN7) DX(AR-DU3) | |
| Sharp AR-M455 | 123910 | 317 | SCAN(AR-NS3) RADF(AR-EF3) PU(AR-PN1B) PED(AR-D28) PC(AR-P21) FN(AR-FN7) DX(AR-DU3) | |
| Sharp AR-M455 | 124431 | 24 | RADF(AR-EF3) PED(AR-D27) FN(AR-FN6) DX(AR-DU4) | Missing developer unit & toner cartridge- tested with others; cracked finisher tray |
| Sharp AR-M455 | 124436 | 78 | SCAN(AR-NS3) RADF(AR-EF3) PS(AR-PK6) PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4) | Missing developer unit & toner cartridge- tested with others |
| Sharp AR-M455 | 124439 | 37 | SCAN(AR-NS3) RADF(AR-EF3) PS(AR-PK6) PED(AR-D27) PC(AR-P21) FN(AR-FN6) FAX(AR-FX12) DX(AR-DU4) | Missing developer unit & toner cartridge- tested with others |
| Sharp AR-M455 | 124440 | 42 | SCAN(AR-NS3) RADF(AR-EF3) PS(AR-PK6) PC(AR-P21) FN(AR-FN6) DX(AR-DU4) | Missing developer unit & toner cartridge- tested with others; lower finisher tray out of alignment- inop |
| Imagistics IM4511 | 124776 | 1127 | PED(9291) FN(9242) DX(9246) | |
| Sharp AR-M550 | 115785 | 707 | SCAN(AR-NS3) PS(AR-PK5) PC(AR-P19) | Missing finisher (has brackets); missing RADF tray |
| Sharp AR-M550 | 117990 | 96 | FN(AR-F15) | |
| Sharp AR-M550 | 117999 | 17 | FN(AR-F15) | Passes blanks; broken front door at left hinge; badly dented & bent left side panel |
| Sharp AR-M550 | 118003 | 251 | FN(AR-F15) | Dented & bent back panel |
| Sharp AR-M550 | 118004 | 353 | FN(AR-F15) | |
| Sharp AR-M550 | 118013 | 116 | FN(AR-F15) | Cracked lower front trim panel |
| Sharp AR-M550 | 118020 | 99 | FN(AR-F15) | Back & left side panels smashed in |
| Sharp AR-M550 | 118021 | 112 | FN(AR-F15) | Dented & bent back panel |

| Manufacturer/Model# | CTRL # | Meter | Accessories | Comments |
|---------------------|--------|-------|---|--|
| Sharp AR-M550 | 118022 | 160 | FN(AR-F15) | Bad fuser roller |
| Sharp AR-M550 | 118023 | 75 | FN(AR-F15) | |
| Sharp AR-M550 | 118025 | 109 | FN(AR-F15) | Missing RADF exit tray |
| Sharp AR-M550 | 118026 | 201 | FN(AR-F15) | |
| Sharp AR-M550 | 118032 | 193 | FN(AR-F15) | Scratched top finisher door |
| Sharp AR-M550 | 118033 | 92 | FN(AR-F15) | |
| Sharp AR-M550 | 118288 | 569 | PC(AR-P19) P(AR-LC6) FN(AR-F15) | |
| Sharp AR-M550 | 119652 | 1404 | FN(AR-F15) | |
| Sharp AR-M550 | 120571 | 512 | PC(AR-P19) FN(AR-F15) | |
| Sharp AR-M550 | 123002 | 1059 | PC(AR-P19) FN(AR-F15) | Broken finisher interlock actuator; yellowed & dirty panels; grease on finisher panels |
| Sharp AR-M550 | 123377 | 1170 | SCAN(AR-NS3) PC(AR-P19) FN(AR-F15) | Missing toner cartridge- can't test |
| Sharp AR-M550 | 124101 | 528 | PU(AR-PN4B) PC(AR-P19) FN(AR-F15) | |
| Sharp AR-M550 | 124438 | 126 | PU(AR-PN4B) FN(AR-F15) | Missing toner cartridge- can't test |
| Sharp AR-M620 | 118270 | 1120 | PC(AR-P19) FN(AR-F15) FAX(AR-FX8) | |
| Sharp AR-M620 | 118934 | 1326 | SCAN(AR-NS3) PS(AR-PK5) PC(AR-P19) P(AR-LC6) FN(AR-F15) | |
| Sharp AR-M620 | 119470 | 1443 | SCAN(AR-NS3) PU(AR-PN4B) FN(AR-F16) | |
| Sharp AR-M620 | 122437 | 1942 | PU(AR-PN4B) PC(AR-P19) FN(AR-F16) | Paper tray #3 in error code F3-32 |
| Sharp AR-M700 | 117086 | 913 | FN(AR-F15) | |
| Sharp AR-M700 | 117087 | 1066 | FN(AR-F15) | |
| Sharp AR-M700 | 120865 | 2207 | PU(AR-PN4B) PC(AR-P19) P(AR-LC6) FN(AR-F15) | |
| Sharp AR-M700 | 122014 | 8024 | PS(AR-PK5) PC(AR-P19) P(AR-LC6) FN(AR-F15) | Finisher connector cover broken |
| Sharp AR-651 | 121272 | 642 | PU(AR-PN3B) FN(AR-F11) | Scratched front paper tray panel; cracked platen glass |
| Sharp AR-651 | 124564 | 898 | FN(AR-F11) | |
| Sharp AR-651 | 124585 | 913 | PC(AR-P15) P(AR-LC4) FN(AR-F11) | |
| Sharp AR-810 | 124586 | 2860 | PC(AR-P15) P(AR-LC4) FN(AR-F11) | |

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.