

# Wulff Enterprises

07/29/2010

## GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO4500	157173	289	PC(FIERY E-7000) FN(SR4000)	Cracked front door in lower left corner; broken bottom left side panel; broken finisher tray; color = 383k; B/W = 7k
Toshiba E-STUDIO5500	151753	219	PU(TYPE 3260) FN(SR4000)	Missing print controller (cover missing & print count = 18,341); missing magenta toner- can't test color copies; color = 196k; B/W = 23k
Toshiba E-STUDIO5500	152741	1222		Black meter = 265k; color meter = 957k
Toshiba E-STUDIO162	154774	72	PC(GA-1170) FAX(GD-1190) ADF(MR-2016)	Bypass will not detect paper- inop; offcolor & dirty panels
Toshiba E-STUDIO162	157171	10	ST() PFU(MY-1026) ADF(MR-2016)	
Toshiba E-STUDIO160	153064	528	ST() RADF(MR-3011) PFU(MY-1015) DX(MD-0101)	Off color panels
Toshiba E-STUDIO160	153322	184	ST() RADF(MR-3011) PFU(MY-1015) DX(MD-0101)	Yellow panels
Toshiba E-STUDIO160	157111	107	ST() ADF(MR-2012)	Off color panels
Toshiba E-STUDIO163	150962	9	ADF(MR-2017)	
Toshiba E-STUDIO163	155085	23	ST() PFU(MY-1027) ADF(MR-2017)	
Toshiba E-STUDIO165	155074	N/A	RADF(MR-3019) PC(GA-1190) FAX(GD-1220)	Right paper tray rail broken off in paper tray causing machine to jam every copy; bypass tray broken off; offcolor & dirty panels; unable to print reports or get meter due to jamming; missing back paper stop in paper tray
Toshiba E-STUDIO200	151465	409	ST() PFU(MY-1015) ADF(MR-2012)	
Toshiba E-STUDIO200	153019	326	ST() B(MY-1016)	Off color
Toshiba E-STUDIO200	153389	235	ST() PFU(MY-1015) ADF(MR-2012)	Off color and dirty panels
Toshiba E-STUDIO200	155662	441	ST()	Needs toner to test; offcolor & dirty panels; cracked fuser cover
Toshiba E-STUDIO200L	157269	322	ST()	Paper tray will not recognize paper & jams from bypass every try- can't test; offcolor & dirty panels
Toshiba E-STUDIO200L	157614	68	ST() RADF(MR-3016) PFU(MY-1021)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO202L	156136	118 ST()	RADF(MR-3020) PC(GM-2080) FAX(GD-1150) E(MJ-5004)	
Toshiba E-STUDIO202L	157059	191 ST()	RADF(MR-3020) PC(GM-2080) FAX(GD-1150) E(MJ-5004) DX(MD-0102)	
Toshiba E-STUDIO205	148444	149 ST()	SCAN(GA-1200) RADF(MR-3019) PFU(MY-1027) PC(GA-1190) FAX(GD-1220) DX(MD-0103)	
Toshiba E-STUDIO205	153996	51 ST()	RADF(MR-3019) PFU(MY-1027) FAX(GD-1220) DX(MD-0103)	
Toshiba E-STUDIO205	155431	32 ST()	RADF(MR-3019) DX(MD-0103)	RADF shows a constant jam & will not clear- inop; offcolor & dirty panels
Toshiba E-STUDIO207	154870	17 ST()	PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO2100	141309	242	RADF(MR-3006A) PC(GA-1121) FN(MJ-1019) DX(MD-5007)	Yellowed panels; color = 189k; B/W = 54k
Toshiba E-STUDIO211C	145296	220	RADF(MR-3006A) PC(GA-1121) FN(MJ-1020) DX(MD-5007) C[1]()	Black meter = 91k; color meter = 129k; yellow panels
Toshiba E-STUDIO211C	150957	497	RADF(MR-3006A) PC(GA-1121) P(MP-1503LT) FN(MJ-1020) DX(MD-5007) C[1]()	Black meter = 307k; color meter = 190k
Toshiba E-STUDIO211C	151011	207	RADF(MR-3006A) PC(GA-1121) E() DX(MD-5007)	Black meter = 82k; color meter = 125k
Toshiba E-STUDIO211C	152154	215	RADF(MR-3006A) PC(GA-1121) FN(MJ-1020) DX(MD-5007) C[1]()	Black meter = 41k; color meter = 175k; off color and dirty panels; right side panel cracked
Toshiba E-STUDIO230	151475	35 ST()	RADF(MR-3016)	Error code C440 - fuser problem after warmup - not tested; RADF tray broken
Toshiba E-STUDIO230	153021	286 ST()	RADF(MR-3016) PC(GM-2020)	Control panel smashed; Jamming in fuser; duplexer latch broken
Toshiba E-STUDIO230	154052	97 ST()	RADF(MR-3016) FN(MJ-1022)	
Toshiba E-STUDIO230	156648	5 ST()	RADF(MR-3016) PC(GM-1020) FAX(GD-1150)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO230	156649	91	ST() RADF(MR-3016) PC(GM-1020) FAX(GD-1150)	
Toshiba E-STUDIO230	156650	54	ST() RADF(MR-3016) PC(GM-1020) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO230	156651	50	ST() RADF(MR-3016) PC(GM-1020) FAX(GD-1150)	Off color panels
Toshiba E-STUDIO230	156652	41	ST() PC(GM-1020) FAX(GD-1150)	Jamming in machine
Toshiba E-STUDIO230	156945	125	ST() RADF(MR-3016)	
Toshiba E-STUDIO232	151399	81	RADF(MR-3020)	
Toshiba E-STUDIO232	151545	96	ST() RADF(MR-3020) E(MJ-5004)	
Oce IM2330	151938	263	RADF(9255) PED(9281) PC(IM2300060) FN(9284) FAX(CM4530110)	Cracked slit glass; cracked lower left panel
Oce IM2330	152233	160	RADF(9255) PED(9281) PC(IM2300060) FN(9284) FAX(CM4530110)	Appears to be a shot in the finisher- makes a loud popping noise when powerd up (not tested); cracked slit glass; bypass mount is cracked & broken
Toshiba E-STUDIO232	152481	193	RADF(MR-3020) PED(KD-1011 [A]) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	152743	36	ST() RADF(MR-3020) FN(MJ-1022)	
Oce IM2330	152788	94	RADF(9255) PED(9281) PC(IM2300060) FN(9284) FAX(CM4530110)	
Toshiba E-STUDIO232	153423	240	ST() RADF(MR-3020) PC(GM-1070)	
Toshiba E-STUDIO232	155724	322	ST() RADF(MR-3020) PC(GM-2070) FAX(GD-1150)	Broken top tray paper stopper & door sensor switch tab broken
Toshiba E-STUDIO232	155834	79	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022)	Jams every copy- will not pass paper
Toshiba E-STUDIO237	141346	7	ST() RADF(MR-3019) PFU(MY-1027) FAX(GD-1220) DX(MD-0103)	Jams in fuser
Toshiba E-STUDIO237	142218	124	SCAN(GA-1200) RADF(MR-3019) PFU(MY-1027) PC(GA-1190) FAX(GD-1220)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			DX(MD-0103)	
Toshiba E-STUDIO2500	142558	N/A	RADF(MR-3018) FN(MJ-1030)	No power; cracked LCD
Toshiba E-STUDIO2500	142859	215	ST() RADF(MR-3018)	Black meter = 179k; color meter = 37k
Toshiba E-STUDIO2500	144959	286	RADF(MR-3018) PED(KD-1019) FN(MJ-1030)	Black meter = 279k; color meter = 7k
Toshiba E-STUDIO2500	144960	129	RADF(MR-3018) PU(MJ-6004) PED(KD-1019) FN(MJ-1101)	Fuser exit guide hinge pin broken; rip in transfer belt; front door of hole punch broken; black meter = 33k; color meter = 96k
Toshiba E-STUDIO2500	146429	300	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 184k; color meter = 117k
Toshiba E-STUDIO2500	147616	161	ST() RADF(MR-3018) FN(MJ-1101)	Stand front door bent in severely; duplexer cover scratched; error code CB31 - unkown; black meter = 61k; color meter 101k
Toshiba E-STUDIO2500	149853	314	ST() RADF(MR-3018) FAX(GD-1210)	Black meter = 279k; color meter = 35k
Toshiba E-STUDIO2500	150365	7	ST() RADF(MR-3018)	Keeps on coding different fuser codes - fuser has deep cuts in it; front door has hole in it
Toshiba E-STUDIO2500	151678	37	RADF(MR-3018) PED(KD-1018 [A]) FAX(GD-1210)	Error code CD40 (test pattern problem)- tried to clear and went into error code CD70 (unknown); broken RADF access door latch
Toshiba E-STUDIO2500	152165	328	RADF(MR-3018) PED(KD-1019) FN(MJ-1030)	Error code C390 - unknown
Toshiba E-STUDIO2500	152424	366	RADF(MR-3018) PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	Black meter = 314k; color meter = 52k
Toshiba E-STUDIO2500	152728	144	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Black meter = 129k; color meter = 16k
Toshiba E-STUDIO2500	152899	152	ST() RADF(MR-3018) FN(MJ-1101)	Black meter = 139k; color meter = 13k
Toshiba E-STUDIO2500	152901	57	ST() RADF(MR-3018)	Black meter = 30k; color meter = 27k
Toshiba E-STUDIO2500	153386	318	ST() RADF(MR-3018) FAX(GD-1210)	Black meter = 287k; color meter = 31k; jamming in fuser - not tested; control panel cover bent
Toshiba E-STUDIO2500	153396	156	ST() RADF(MR-3018) FN(MJ-1101)	Black meter = 113k; color meter = 43k
Toshiba E-STUDIO2500	153439	73	RADF(MR-3018) PED(KD-1019)	Finisher top access door latch broken; bypass paper sensor broken - not

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1101)	tested; black meter = 17k; color meter = 57k
Toshiba E-STUDIO2500	153641	206 ST()	RADF(MR-3018) PU(MJ-6101) FN(MJ-1101)	Black meter = 150k; color meter = 56k
Toshiba E-STUDIO2500	154038	187 ST()	RADF(MR-3018) FN(MJ-1030)	Offcolor panels; stapler inop; color = 55k; B/W = 132k
Toshiba E-STUDIO2500	154047	216	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Offcolor panels; color = 39k; B/W = 178k
Toshiba E-STUDIO2500	154048	169	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Broken LCT paper feed plate; bridge unit jams every try- can't test finisher; offcolor panels; color = 123k; B/W = 46k
Toshiba E-STUDIO2500	154053	173 ST()	RADF(MR-3018) FN(MJ-1101)	Error code F100 (hard drive); bypass tray broken; hole in back panel by
Toshiba E-STUDIO2500	154102	157 ST()	RADF(MR-3018)	Color = 109k; B/W = 49k
Toshiba E-STUDIO2500	154113	203 ST()	RADF(MR-3018) FAX(GD-1210)	Deep scratch in platen glass; offcolor panels; color = 77k; B/W = 127k
Toshiba E-STUDIO2500	154878	9 ST()	RADF(MR-3018) FAX(GD-1210)	Color = 3k; B/W = 6k
Toshiba E-STUDIO2500	155678	185	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Color = 82k; B/W = 104k
Toshiba E-STUDIO2500	156811	251	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Jams in fuser every copy- can't test
Toshiba E-STUDIO2500	156939	258 ST()	RADF(MR-3018)	
Toshiba E-STUDIO2500	157097	189	RADF(MR-3018) PED(KD-1018 [A]) FAX(GD-1210)	Waste toner container missing; black meter = 162k; color meter = 27k
Toshiba E-STUDIO2500	157161	236 ST()	RADF(MR-3018) FAX(GD-1210)	Color = 20k; B/W = 216k
Toshiba E-STUDIO2500	157394	219 ST()	RADF(MR-3018) FN(MJ-1101) FAX(GD-1210)	Jams in fuser very copy- can't test; color = 151k; B/W = 68k; offcolor front door
Toshiba E-STUDIO2500	157486	248 ST()	RADF(MR-3018)	Black meter = 236k; color meter = 12k
Toshiba E-STUDIO2500	157488	360	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Off color panels; black meter = 322k; color meter = 39k
Toshiba E-STUDIO2500	157489	62	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101)	Black meter = 55k; color meter = 68k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO280	156927	55 ST()	RADF(MR-3016) PC(GM-2020)	
Toshiba E-STUDIO281C	139151	144 ST()	RADF(MR-3018)	Back panel cracked; Black meter = 90k; color meter = 55k
Toshiba E-STUDIO281C	143361	48 ST()	RADF(MR-3018) FN(MJ-1022)	Finisher back panel broken; Black meter = 49k; color meter = 3k;
Toshiba E-STUDIO281C	143734	104	RADF(MR-3018) PED(KD-1011 [A]) FAX(GD-1200)	Error code CEE0 - transfer belt position at normal speed problem - color could not be tested
Toshiba E-STUDIO281C	144570	346	RADF(MR-3018) PED(KD-1012) FN(MJ-1024)	Black meter = 313k; color meter = 33k; appears fax was removed - knockout missing; black meter = 313k; color meter = 33k
Toshiba E-STUDIO281C	145763	343 ST()	RADF(MR-3018) FAX(GD-1200)	Black meter = 293k; color meter = 50k
Toshiba E-STUDIO281C	148849	315 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Color = 22k; B/W = 293k
Toshiba E-STUDIO281C	149667	214 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Missing lower back finisher tray cover; color = 1k; B/W = 213k
Toshiba E-STUDIO281C	150859	204 ST()	RADF(MR-3018)	Black meter = 163k; color meter = 42k
Toshiba E-STUDIO281C	151677	213	RADF(MR-3018) PED(KD-1012)	Color = 57k; B/W = 157k
Toshiba E-STUDIO281C	152160	89 ST()	RADF(MR-3018) FN(MJ-1022)	Black meter = 84k; color meter = 5k
Toshiba E-STUDIO281C	152510	256 ST()	RADF(MR-3018) FAX(GD-1200)	Black meter = 220k; color meter = 36k
Toshiba E-STUDIO281C	153993	52 ST()	RADF(MR-3018)	Black meter = 51k; color meter = 1k
Toshiba E-STUDIO281C	154042	255	RADF(MR-3018) PED(KD-1011 [A]) FN(MJ-1022)	Jamse every copy in fuser- can't test; Color = 26k; B/W = 229k
Toshiba E-STUDIO281C	154044	61	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Bottom finisher tray out of alignment - finisher not tested; black meter = 53k; color meter = 8k
Toshiba E-STUDIO281C	154658	19 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Black meter - 18k; color meter = 1k
Toshiba E-STUDIO281C	155599	356 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Missing lower finisher tray back cover panel; color = 29k; B/W = 327k
Toshiba E-STUDIO281C	156162	28 ST()	RADF(MR-3018) FN(MJ-1101)	Color = 9k; B/W = 19k
Toshiba E-STUDIO281C	156936	352 ST()	RADF(MR-3018)	Black meter = 347k; color meter = 5k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO281C	156942	295	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Black meter = 271k; color meter = 24k
Toshiba E-STUDIO281C	157099	72	RADF(MR-3018) PED(KD-1012) FAX(GD-1200)	Color = 7k; B/W = 66k
Toshiba E-STUDIO282	155711	238	RADF(MR-3020) PED(KD-1012) PC(GM-2070) FAX(GD-1150)	
Toshiba E-STUDIO282	155712	202	RADF(MR-3020) PED(KD-1012) FAX(GD-1150)	Has a GM-2071 print/scan enabler
Oce IM2830	156428	212	RADF(9255) PED(9283) PC(IM2300060) FAX(CM4530110) E(IM2300030)	Jamming in fuser
Toshiba E-STUDIO282	156809	145	ST() RADF(MR-3020)	
Toshiba E-STUDIO282	157089	219	RADF(MR-3020) PED(KD-1012) FN(MJ-1022)	
Toshiba E-STUDIO3100	143575	201	RADF(MR-3006A) PC(GA-1121) P(MP-1503LT) FN(MJ-1019) DX(MD-5007)	Deep scratches on paperdeck cover; back panel dented; RADF plug socket severly bent; Finisher plug broken; black meter = 9k; color meter = 192k
Toshiba E-STUDIO3100	144170	141	RADF(MR-3006A) PC(GA-1121) P(MP-1503LT) E() DX(MD-5007)	Black meter = 7k; color meter = 134k
Toshiba E-STUDIO3100	145712	56	RADF(MR-3006A) PC(GA-1121) FN(MJ-1020) DX(MD-5007)	Broken finisher tray; yellowed panels; broken & bent wheel cover; bottom paper tray will not lift- inop; color = 42k; B/W = 15k
Toshiba E-STUDIO3100	149494	569	RADF(MR-3006A) PC(GA-1121) FN(MJ-1019) DX(MD-5007)	Saddlestitch exit tray broken; black meter = 367k; color meter = 203k
Toshiba E-STUDIO3100	149636	160	RADF(MR-3006A) PC(GA-1121) FN(MJ-1019)	Broken finisher trays; offcolor panels; color = 3k; B/W = 157k
Toshiba E-STUDIO3100	149880	333	RADF(MR-3006A) DX(MD-5007)	Has finisher brackets but missing finisher; fuser gears grinding causing jam; black meter = 183k; color meter = 150k
Toshiba E-STUDIO3100	149892	N/A	RADF(MR-3006A) PU(MJ-6001N) PC(GA-1121) FN(MJ-1020) DX(MD-5007) C[1]()	Power cord completely destroyed - not tested
Toshiba E-STUDIO3100	154493	466	RADF(MR-3006A) PU(MJ-6001N) PC(GA-1121)	Off color panels; Black meter = 241k; color meter = 226k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO3100	154691	1150	P(MP-1503LT) FN(MJ-1020) DX(MD-5007) RADF(MR-3006A) PU(MJ-6001N) PC(GA-1121) P(MP-1503LT) FN(MJ-1020) DX(MD-5007)	Broken RADF plug socket; machine shows close large capacity feeder & will not clear- can't test; color = 904k; B/W = 247k
Toshiba E-STUDIO310C	154306	401	RADF(MR-3006A) PC(FIERY X3E+) FN(MJ-1020) E() DX(MD-5007)	Off color panels; black meter = 152k; color meter = 250k
Ricoh AFICIO 3131	145299	94	RADF(DF81) PC(E-750) DX(AD470)	Error code CE4 - test pattern problem; has finisher brackets - missing finisher; rear panel bent; front lable missing
Toshiba E-STUDIO311C	151674	716	RADF(MR-3006A) PC(GA-1121) FN(MJ-1020) DX(MD-5007) C[1]()	Top paper tray jammed in machine & will not release; color = 222k; B/W = 495k
Toshiba E-STUDIO311C	151709	549	RADF(MR-3006A) PC(GA-1121) P(MP-1503LT) FN(MJ-1020) DX(MD-5007) C[1]()	Broken bottom finisher tray; offcolor panels; color = 360k; B/W = 190k
Toshiba E-STUDIO311C	153489	785	PC(GA-1121) E() DX(MD-5007) C[1]()	Jams in fuser every copy- can't test; offcolor panels; color = 774k; B/W = 12k
Toshiba E-STUDIO350	156146	117	ST() RADF(MR-3015) FN(MJ-1022)	
Toshiba E-STUDIO350	156420	235	RADF(MR-3015) PED(KD-1011 [A]) PC(GM-2010) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO3500	144961	229	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 181k; color meter = 49k
Toshiba E-STUDIO3500	145143	557	RADF(MR-3018) PU(MJ-6004) PED(KD-1019) FN(MJ-1030)	Black meter = 193k; color meter = 365k
Toshiba E-STUDIO3500	146819	292	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 129k; color meter = 163k;
Toshiba E-STUDIO3500	146982	418	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Scratched back panel; Black meter = 400k; color meter = 18k
Toshiba E-STUDIO3500	148199	224	RADF(MR-3018) PED(KD-1018 [A]) FN(MJ-1101) FAX(GD-1210)	Black meter = 125k; color meter = 100k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO3500	150875	302	RADF(MR-3018) PED(KD-1018 [A]) FN(MJ-1030)	Black meter = 243k; color meter = 60k
Toshiba E-STUDIO3500	153742	97	RADF(MR-3018) PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	Bent back finisher panel; bent finisher entrance guides causing it to jam every copy- inop; color = 58k; B/W = 40k
Toshiba E-STUDIO3500	154172	297	RADF(MR-3018) PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	Jamming in finisher - not tested; black meter = 217k; color meter = 80k
Toshiba E-STUDIO3500	154648	318	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Finisher trays out of alignment causing error code CB31 (removable tray paper-full detection error); color = 171k; B/W = 147k
Toshiba E-STUDIO3500	154889	53	RADF(MR-3018) PU(MJ-6004) PED(KD-1018 [A])	Front door will not close correctly; offcolor panels; color = 37k; B/W = 17k
Toshiba E-STUDIO3500	156909	180	ST() RADF(MR-3018) FN(MJ-1101)	Constant jamming in fuser - not tested; black meter = 54k; color meter = 126k
Toshiba E-STUDIO3500	156937	222	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 161k; color meter = 62k
Toshiba E-STUDIO3500	156938	252	RADF(MR-3018) PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	Color = 77k; B/W = 175k
Toshiba E-STUDIO3500	157095	344	RADF(MR-3018) FN(MJ-1030)	Error code CBAO - saddlestitch front stitcher motor; error code C380 - unknown; black meter = 149k; color meter = 195k
Toshiba E-STUDIO3500	157172	207	RADF(MR-3018) PED(KD-1019) FN(MJ-1030)	Bad front door interlock switch- shows open door & will not clear (can't test); back panel smashed in & broken; broken filter cover & filter jammed in; cracked & scratched bypass panel
Toshiba E-STUDIO3500	157417	444	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Missing all toner cartridges & waste toner box- tested with others; color = 84k; B/W = 360k
Toshiba E-STUDIO3500	157418	524	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Missing all toner cartridges & waste toner box- tested with others
Toshiba E-STUDIO3500	157419	363	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Missing all toner cartridges & waste toner box- tried testing with others; shows a false open bridge cover- appear to be a bad sensor (unable to test machine)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO3500	157420	368	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Missing all toner cartridges & waste toner box- tested with others; offcolor panels; color = 90k; B/W = 278k
Toshiba E-STUDIO3510	152474	421	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Scratched LCD; color = 205k; B/W = 216k
Toshiba E-STUDIO3510	154494	335	RADF(MR-3018) PED(KD-1019) PC(GA-1210) FN(MJ-1030)	Black meter = 47k; color meter = 289k; cassettes # 1 & 2 not recognizing
Toshiba E-STUDIO3510	154692	336	RADF(MR-3018) PED(KD-1019) FN(MJ-1030)	Color = 332k; B/W = 5k
Toshiba E-STUDIO3510	155963	114	RADF(MR-3018) PED(KD-1018 [A]) FN(MJ-1101)	Color = 49k; B/W = 66k
Toshiba E-STUDIO3510	156941	680	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Constant jam in finisher - not tested; black meter = 648k; color meter = 33k
Toshiba E-STUDIO3511	151397	59	ST() RADF(MR-3015) FN(MJ-1022)	Off color panels; Black meter = 51k; color meter = 9k
Toshiba E-STUDIO3511	152152	994	RADF(MR-3015) PED(KD-1012) FN(MJ-1024)	Black meter = 982k; color meter = 13k
Toshiba E-STUDIO3511	152153	79	ST() RADF(MR-3015)	Black meter = 65k; color meter = 15k; off color panels
Toshiba E-STUDIO3511	152414	340	RADF(MR-3015) PED(KD-1011 [B]) FAX(GD-1150)	Black meter = 275k; color meter = 26k; off color panels
Toshiba E-STUDIO3511	152855	389	RADF(MR-3015) PU(MJ-6004) PED(KD-1012) FN(MJ-1023) FAX(GD-1150)	Offcolor & dirty panels; color = 8k; B/W = 382k
Toshiba E-STUDIO3511	153234	168	ST() RADF(MR-3015) FN(MJ-1022) FAX(GD-1150)	Off color panels; black meter = 130k; color meter = 38k
Toshiba E-STUDIO3511	153775	281	RADF(MR-3015) PED(KD-1011 [A]) FN(MJ-1022) FAX(GD-1150)	Finisher latch missing; off color panels; front door indicator broken - not tested
Toshiba E-STUDIO3511	154045	311	ST() RADF(MR-3015) FN(MJ-1022) FAX(GD-1150)	Cracked top finisher tray; Black meter = 307k; color meter = 5k
Toshiba E-STUDIO3511	154475	824	RADF(MR-3015) PED(KD-1012)	Off color and dirty panels; black meter = 746k; color meter = 79k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(MJ-1022)	
Toshiba E-STUDIO3511	154487	385 ST()	RADF(MR-3015) FN(MJ-1022) FAX(GD-1150)	Black meter = 314k; color meter = 72k
Toshiba E-STUDIO3511	154620	481 ST()	RADF(MR-3015) FN(MJ-1022)	Missing fax board; offcolor & dirty panels; color = 3k; B/W = 479k
Toshiba E-STUDIO3511	155067	706 ST()	RADF(MR-3015) FN(MJ-1022)	Finisher latch broken; off color and dirty panels; finisher trays out of alignment - not tested; black meter = 661k; color meter = 46k
Toshiba E-STUDIO3511	155333	114	RADF(MR-3015) PED(KD-1012) FN(MJ-1023) FAX(GD-1150)	Bypass tray mounts bent & lower cover broken off; scratched & scraped right side panels; color = 14k; B/W = 101k
Toshiba E-STUDIO3511	156438	169 ST()	RADF(MR-3015) FAX(GD-1150)	Error code F100- hard drive format error
Toshiba E-STUDIO3511	157098	472 ST()	RADF(MR-3015) FN(MJ-1024)	Color = 4k; B/W = 469k
Toshiba E-STUDIO351C	150764	108 ST()	RADF(MR-3018) FN(MJ-1023) FAX(GD-1200)	Black meter = 107k; color meter = 1k
Toshiba E-STUDIO351C	152255	430 ST()	RADF(MR-3018) FN(MJ-1022)	Black meter = 406k; color meter = 24k
Toshiba E-STUDIO351C	153214	223	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Broken lower back finisher tray cover; color = 59k; B/W = 165k
Toshiba E-STUDIO351C	154776	45 ST()	RADF(MR-3018)	Color = 18k; B/W = 27k
Toshiba E-STUDIO351C	155471	190 ST()	RADF(MR-3018) FN(MJ-1022)	Error code CC90 - finisher upper stack tray lift problem - not tested; black meter = 182k; color meter = 9k
Toshiba E-STUDIO351C	155747	477	RADF(MR-3018) PED(KD-1011 [B]) FN(MJ-1022)	Error code E724 (doc feeder jam)- will not clear; missing right top corner panel; machine not detecting finisher; color = 76k; B/W = 401k
Toshiba E-STUDIO352	155705	175	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	Broken paper guides in tray #1; duplex jams when stapling
Toshiba E-STUDIO352	155728	129 ST()	RADF(MR-3018) PC(GM-2060)	
Toshiba E-STUDIO352	157091	557	RADF(MR-3018) PED(KD-1012) FN(MJ-1023)	
Toshiba E-STUDIO352	157092	208	RADF(MR-3018) PED(KD-1012) FN(MJ-1023)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO352	157093	502	RADF(MR-3018) PED(KD-1012) FN(MJ-1023)	Offcolor panels
Toshiba E-STUDIO352	157109	158	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	Finisher tray broken
Toshiba E-STUDIO353	144328	161	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO451C	154171	265	RADF(MR-3018) FN(MJ-1023) FN(MJ-1101)	Needs black toner - not tested; black meter = 194k; color meter = 72k
Toshiba E-STUDIO451C	155821	146	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1200)	Color = 19k; B/W = 128k
Toshiba E-STUDIO451C	156439	861	RADF(MR-3018) PED(KD-1012) FN(MJ-1023) FAX(GD-1200)	Black meter = 818k; color meter = 43k
Toshiba E-STUDIO451C	157146	238	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1200)	Color = 24k; B/W = 215k
Toshiba E-STUDIO452	151379	119	RADF(MR-3018) PED(KD-1012) PC(GM-1060) FN(MJ-1101)	
Toshiba E-STUDIO452	154779	217	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2060) FN(MJ-1101) FAX(GD-1200)	Jams when duplexing & stapling at the same time
Toshiba E-STUDIO452	155080	205	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1101) FAX(GD-1200)	Underside finisher frame is all bent up & wheels damaged- unable to test
Toshiba E-STUDIO452	155835	134	RADF(MR-3018) PC(GM-1060)	
Toshiba E-STUDIO452	155845	234	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1101)	
Toshiba E-STUDIO452	157090	319	RADF(MR-3018) PED(KD-1012) FN(MJ-1023)	
Toshiba E-STUDIO452	157487	464	RADF(MR-3018) PED(KD-1012) PC(GM-1060) FN(MJ-1101)	
Toshiba E-STUDIO520	153994	166	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO520T	147976	126	PC(GM-2040) FN(MJ-1027)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO520T	154156	327	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	Off color and dirty panels
Toshiba E-STUDIO520T	154157	70	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	LCT paper guide bent - not tested; rear panel dented; enabler cover cracked
Toshiba E-STUDIO523T	156132	783	PU(MJ-6003) PC(GM-2041) FN(MJ-1027)	Offcolor panels
Toshiba E-STUDIO550	157117	70	FN(MJ-1017)	Off color panels
Toshiba E-STUDIO600	148369	408	PU(MJ-6003N) PC(GM-2040) P(MP-4004) FN(MJ-1027)	Front door scratched
Toshiba E-STUDIO600	156654	298	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO603T	156133	891	PC(GM-2041) FN(MJ-1027)	Offcolor & dirty panels
Toshiba E-STUDIO720	149409	274	PC(GM-1050) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO720	151679	349	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO720	155675	685	SCAN(GM-4010) PU(MJ-6003N) PC(GM-1050) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.  
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.  
Please call our sales team for current availability.