

# Wulff Enterprises

07/29/2010

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO4500	156672	670	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR4000)	Jams every copy at transfer belt- can't test; color = 128k; B/W = 542k
Toshiba E-STUDIO5500	126366	639	PU(TYPE 3260) PC(FIERY E-7000) P(RT43) FN(SR4000)	Finisher in false jam code at R8 & R12- will not clear; print controller will not come to ready- inop; color = 481k; B/W = 158k
Toshiba E-STUDIO5500	153945	1501	PC(FIERY E-7000) P(RT43) FN(SR4000)	toner spilled throughout machine; black meter = 230k; color meter = 1272k
Toshiba E-STUDIO5500	154418	644	PU(TYPE 3260) PC(TYPE 3260) P(RT43) FN(SR970)	Color = 296k; B/W = 349k
Toshiba E-STUDIO120	149840	17	ADF(MR-2014)	
Toshiba E-STUDIO120	150163	67	ST() ADF(MR-2014)	Missing bypass tray
Toshiba E-STUDIO120	150164	61	ST() ADF(MR-2014)	
Toshiba E-STUDIO120	152566	26		Toner spilled throughout machine; cracked platen top hinges
Toshiba E-STUDIO150	149449	91		
Toshiba E-STUDIO150	149450	81	ST()	
Toshiba E-STUDIO150	154702	73		
Toshiba E-STUDIO150	155961	45	PFU(MY-1019) ADF(MR-2014)	Yellowed panels
Toshiba E-STUDIO150	156372	47	ADF(MR-2014)	Off color panels
Toshiba E-STUDIO150	157178	33	ADF(MR-2014)	Jams in fuser every copy- can't test; ADF not latching properly; yellowed panels
Toshiba E-STUDIO162D	155864	61	RADF(MR-3017) FAX(GD-1190)	Yellowed & dirty panels; RADF & duplex jam
Toshiba E-STUDIO162D	155866	N/A	RADF(MR-3017) FAX(GD-1190)	Error code H4-00 (fuser temp too low)
Toshiba E-STUDIO162D	155867	17	RADF(MR-3017) FAX(GD-1190)	Error code F4-00 (low fuser temp); offcolor & dirty panels
Toshiba E-STUDIO162D	155868	26	RADF(MR-3017) FAX(GD-1190)	Offcolor panels
Toshiba E-STUDIO162D	155874	52	RADF(MR-3017) FAX(GD-1190)	Duplex jams; missing toner cartridge- tested with another
Toshiba E-STUDIO162D	155875	36	RADF(MR-3017) FAX(GD-1190)	Blurred streak in center of copies
Toshiba E-STUDIO162D	156044	97	RADF(MR-3017)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(GD-1190)	
Toshiba E-STUDIO162D	157240	20	RADF(MR-3017) PFU(MY-1026) PC(GA-1170) FAX(GD-1190)	Missing lower right access panel- unable to test PFU tray
Toshiba E-STUDIO162	152801	38	ADF(MR-2016)	
Toshiba E-STUDIO162	154219	9	FAX(GD-1190) ADF(MR-2016)	
Toshiba E-STUDIO162	156687	71	ST() PFU(MY-1026) PC(GA-1170) ADF(MR-2016)	Yellowed panels
Toshiba E-STUDIO162	156688	41	PC(GA-1170) ADF(MR-2016)	Will not feed- makes a loud clicking noise; will not detect paper in tray
Toshiba E-STUDIO162	156848	25	FAX(GD-1190) ADF(MR-2016)	Copies feed to registration roller too quickly
Toshiba E-STUDIO162	157502	N/A	FAX(GD-1190) ADF(MR-2016)	Machine is smashed- total loss
Toshiba E-STUDIO161	156446	N/A	ADF(MR-2015)	Error code CH - side cover open - not tested; left side frame bent
Toshiba E-STUDIO160	156788	81	ST() RADF(MR-3011) PC(GA-1031) NIC(GF-1110) FAX(GD-1061)	Yellowed panels; broken fuser cover
Toshiba E-STUDIO163	157308	83	ST()	
Toshiba E-STUDIO165	156178	42	FAX(GD-1220) ADF(MR-2017)	Dirty & yellowed panels
Toshiba E-STUDIO167	141287	20	ST() RADF(MR-3019) DX(MD-0103)	
Toshiba E-STUDIO167	152511	86	ST() RADF(MR-3019) FAX(GD-1220) DX(MD-0103)	Bypass tray holding arms (tray will not stay closed)
Toshiba E-STUDIO167	156695	10	ST() PFU(MY-1027) ADF(MR-2017)	
Toshiba E-STUDIO200	150165	299	ST() RADF(MR-3011) PFU(MY-1015) PC(GA-1031) NIC(GF-1110) FN(MJ-1011) FAX(GD-1061) DX(MD-0101)	Broken front door
Toshiba E-STUDIO200	150166	218	ST() RADF(MR-3011) PFU(MY-1015) NIC(GF-1110) FN(MJ-1011) FAX(GD-1061)	Broken rear finisher tray cover
Toshiba E-STUDIO200	150167	289	ST() RADF(MR-3011) PFU(MY-1015) PC(GA-1031) NIC(GF-1110) FN(MJ-1011) FAX(GD-1061)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			DX(MD-0101)	
Toshiba E-STUDIO200	150168	282	ST() RADF(MR-3011) PFU(MY-1015) PC(GA-1031) NIC(GF-1110) FN(MJ-1011) FAX(GD-1061) DX(MD-0101)	
Toshiba E-STUDIO200	150169	324	ST() RADF(MR-3011) PFU(MY-1015) PC(GA-1031) NIC(GF-1110) FN(MJ-1011) FAX(GD-1061) DX(MD-0101)	Wrinkles copies
Toshiba E-STUDIO200	150171	192	ST() RADF(MR-3011) PFU(MY-1015) PC(GA-1031) NIC(GF-1110) FAX(GD-1061)	
Toshiba E-STUDIO200	150172	310	ST() RADF(MR-3011) PFU(MY-1015) DX(MD-0101)	
Toshiba E-STUDIO200	150173	334	ST() RADF(MR-3011) PFU(MY-1015) FN(MJ-1011) DX(MD-0101)	Broken lower back finisher tray cover
Toshiba E-STUDIO200	150174	288	ST() RADF(MR-3011) PFU(MY-1015) FN(MJ-1011) DX(MD-0101)	
Toshiba E-STUDIO200	150758	361	ST() B(MY-1016)	Very dirty panels
Toshiba E-STUDIO200	153458	389	ST() B(MY-1016)	Very dirty & offcolor panels
Toshiba E-STUDIO200	156168	542	ST() B(MY-1016)	Very dirty & offcolor panels; bypass frame broken off; cracked back panel
Toshiba E-STUDIO200L	155008	340	ST() RADF(MR-3016) PFU(MY-1021) DX(MD-0101)	
Toshiba E-STUDIO200L	156528	207	ST()	Off color and dirty panels; left side front corner cracked
Toshiba E-STUDIO200L	156614	69	ST() RADF(MR-3016) DX(MD-0101)	
Toshiba E-STUDIO202L	153459	179	ST()	Cracked & broken platen top; very dirty panels
Toshiba E-STUDIO202L	153769	142	ST() RADF(MR-3020) PFU(MY-1021) FN(MJ-1022) DX(MD-0102)	Error code C430 (fuser?); smashed stand door; cracked & broken back panel; scuffed front door
Toshiba E-STUDIO202L	156689	12	ST() RADF(MR-3020) PFU(MY-1021)	
Toshiba E-STUDIO202L	156735	103	ST() RADF(MR-3020) PFU(MY-1021) PC(GM-2080) FAX(GD-1150)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			DX(MD-0102)	
Toshiba E-STUDIO203L	150138	100	ST() RADF(MR-3020) PFU(MY-1021) PC(GM-2081) FN(MJ-1022) DX(MD-0102)	
Toshiba E-STUDIO203L	156849	304	ST() RADF(MR-3020) PFU(MY-1021) PC(GM-2081) FN(MJ-1022) FAX(GD-1150) DX(MD-0102)	
Toshiba E-STUDIO205	145833	35	ST() SCAN(GA-1200) PC(GA-1190)	LCD keeps fading in & out with lines through it; chipped slit glass; deep nick in ADF access door
Toshiba E-STUDIO205	150710	168	ST() RADF(MR-3019) PFU(MY-1027) PC(GA-1190) DX(MD-0103)	Config & NIC reports not generated- shows 'network initializing' message
Toshiba E-STUDIO205	152048	31	ST() RADF(MR-3019) PFU(MY-1027)	Missing toner cartridge- can't test
Toshiba E-STUDIO205	152559	92	ST() RADF(MR-3019) PFU(MY-1027) DX(MD-0103)	Dirty panels inside & out
Toshiba E-STUDIO205	152890	207	ST() RADF(MR-3019) DX(MD-0103)	
Toshiba E-STUDIO205	152987	72	ST() FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO205	153720	77	ST() RADF(MR-3019) PFU(MY-1027)	
Toshiba E-STUDIO207	147699	16	ST() PC(GA-1190) FAX(GD-1220) ADF(MR-2017)	
Toshiba E-STUDIO207	154213	130	ST() SCAN(GA-1200) RADF(MR-3019) PFU(MY-1027) PC(GA-1190)	
Toshiba E-STUDIO207	154214	188	SCAN(GA-1200) RADF(MR-3019) PFU(MY-1027) PC(GA-1190) FAX(GD-1220) DX(MD-0103)	PFU will not feed- inop
Toshiba E-STUDIO207	156180	44	RADF(MR-3019)	
Toshiba E-STUDIO207	156922	80	ST() SCAN(GA-1200) RADF(MR-3019) PFU(MY-1027) PC(GA-1190) FAX(GD-1220)	
Toshiba E-STUDIO20S	150751	543	ST() B(MY-1016)	Missing toner cartridge- can't test; dirty & offcolor panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO2100	137593	155	RADF(MR-3006A) PC(GA-1121) DX(MD-5007)	Bottom paper tray will not lift- inop; color = 128k; B/W = 27k
Toshiba E-STUDIO2100	153596	328	RADF(MR-3006A) PC(GA-1121) P(MP-1503LT) E() DX(MD-5007)	Fuser exit access gate missing springs causing jams; color = 267k; B/W = 62k
Toshiba E-STUDIO2100	156370	139	RADF(MR-3006A) PC(GA-1121) E() DX(MD-5007)	Color = 125k; B/W = 14k
Toshiba E-STUDIO210C	151239	362	RADF(MR-3006A) PC(FIERY X3E+) FN(MJ-1019) DX(MD-5007) C[1]()	Grinds when cycling; color = 310k; B/W = 52k; yellowed panels
Toshiba E-STUDIO211C	151727	281	RADF(MR-3006A) PC(GA-1121) E() DX(MD-5007) C[1]()	Paper tray #1 out of order; Color = 269k; B/W = 12k
Toshiba E-STUDIO211C	156009	465	RADF(MR-3006A) PU(MJ-6002) PC(GA-1121) FN(MJ-1020) DX(MD-5007) C[1]()	Yellowed panels; color = 358k; B/W = 107k
Toshiba E-STUDIO230	155949	211	ST() RADF(MR-3016) PC(GM-2020) FN(MJ-1022)	
Toshiba E-STUDIO230	155950	347	ST() RADF(MR-3016) PC(GM-2020) FN(MJ-1022)	Missing small rear top finishe rflap cover
Toshiba E-STUDIO230	155951	223	ST() RADF(MR-3016) PC(GM-2020) FN(MJ-1022)	
Toshiba E-STUDIO230	155952	506	ST() RADF(MR-3016) PC(GM-2020) FN(MJ-1022)	
Toshiba E-STUDIO230	155954	237	ST() RADF(MR-3016) PC(GM-2020) FN(MJ-1022)	
Toshiba E-STUDIO230	155955	695	ST() RADF(MR-3016) FN(MJ-1022)	Missing back finisher tray wiring cover
Toshiba E-STUDIO230	155956	444	ST() RADF(MR-3016) FN(MJ-1022)	
Toshiba E-STUDIO230	156369	374	ST() RADF(MR-3016) PC(GM-1020) FN(MJ-1022)	Finisher tray out of alignment - not tested
Toshiba E-STUDIO230	156857	204	RADF(MR-3016) PED(KD-1011 [A])	RADF jams
Toshiba E-STUDIO230	156858	710	ST() RADF(MR-3016) FAX(GD-1150)	Broken back paper guide & end stopper in tray #1
Toshiba E-STUDIO230	157010	317	RADF(MR-3016) PED(KD-1012) PC(GM-2020) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO230	157106	389	RADF(MR-3016) PED(KD-1012) PC(GM-2020)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO230	157277	395	ST()	Broken front door; very dirty panels inside & out
Toshiba E-STUDIO230	157378	131	ST() RADF(MR-3016) FN(MJ-1022)	Jams from bottom paper tray due to toner spillage
Toshiba E-STUDIO232	152856	43	ST() RADF(MR-3020)	
Toshiba E-STUDIO232	153799	66	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	154181	51	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022)	Deep gouges in front door; missing serial/model tag on finisher; missing lower back finisher tray cover
Toshiba E-STUDIO232	154274	34	ST() RADF(MR-3020) FAX(GD-1150)	
Toshiba E-STUDIO232	154411	202	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	154723	63	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	154728	173	ST() RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO232	154730	496	ST() RADF(MR-3020) PC(GM-1070) FN(MJ-1022)	
Toshiba E-STUDIO232	155381	66	ST()	
Toshiba E-STUDIO232	155382	47	ST()	
Toshiba E-STUDIO232	155534	75	RADF(MR-3020) PED(KD-1012) PC(GM-1070) FN(MJ-1022) FAX(GD-1150)	RADF skews copies; offcolor & dirty panels
Toshiba E-STUDIO232	155939	106	ST() RADF(MR-3020)	
Toshiba E-STUDIO232	155960	141	RADF(MR-3020) PED(KD-1012) PC(GM-2070) FN(MJ-1022)	Lower control panel housing out of alignment; scuffed front door
Toshiba E-STUDIO232	156041	76	ST() RADF(MR-3020)	
Toshiba E-STUDIO232	156043	143	ST() RADF(MR-3020)	Has a GM-2071 print/scan enabler (works OK)
Toshiba E-STUDIO232	156357	559	RADF(MR-3020) PED(KD-1011 [B]) PC(GM-1070) FAX(GD-1150)	
Toshiba E-STUDIO232	156675	212	ST() RADF(MR-3020) FN(MJ-1022) FAX(GD-1150)	Has a GM-2071 print/scan enabler (works OK)
Toshiba E-STUDIO232	156676	164	ST() RADF(MR-3020) FN(MJ-1022)	Has a GM-2071 print/scan enabler (works OK)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(GD-1150)	
Toshiba E-STUDIO232	156677	128 ST()	RADF(MR-3020) FN(MJ-1022) FAX(GD-1150)	Has a GM-2071 print/scan enabler (works OK); both paper trays lift but will not detect paper (tested from bypass only- unable to generate reports)
Toshiba E-STUDIO232	156678	37 ST()	RADF(MR-3020) PC(GM-2070)	
Toshiba E-STUDIO232	156680	2 ST()	RADF(MR-3020)	Has a GM-2071 print/scan enabler (works OK)
Toshiba E-STUDIO232	156863	102 ST()	RADF(MR-3020) PC(GM-2070) FN(MJ-1022) FAX(GD-1150)	Error code CA10 (laser motor); finisher trays out of alignment- inop; scratched front panels; broken finisher latching handle
Toshiba E-STUDIO233	150339	17	RADF(MR-3020) FN(MJ-1022)	Finisher in error code CC90 (tray movement problem)
Toshiba E-STUDIO2500	141860	305	RADF(MR-3018) PED(KD-1018 [A]) FN(MJ-1101)	Color = 166k; B/W = 139k
Toshiba E-STUDIO2500	146907	178	RADF(MR-3018) PED(KD-1018 [B]) FN(MJ-1030)	Color 102k; B/W = 77k
Toshiba E-STUDIO2500	147658	1204	RADF(MR-3018) PU(MJ-6004) PED(KD-1018 [B])	Broken pedestal plug socket; color = 146k; B/W = 1059k
Toshiba E-STUDIO2500	147693	323	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Color = 130k; B/W = 194k
Toshiba E-STUDIO2500	148679	221	RADF(MR-3018) PU(MJ-6004) PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	Top finisher tray is out of alignment (Still works); color = 174k; B/W = 48k
Toshiba E-STUDIO2500	149526	103 ST()	RADF(MR-3018)	Color = 57k; B/W = 46k
Toshiba E-STUDIO2500	149527	662 ST()	RADF(MR-3018) FN(MJ-1101)	Dirty panels; color = 63k; B/W = 599k
Toshiba E-STUDIO2500	150045	124	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Yellowed front door; finisher jams every try at entrance- inop; color = 33k; B/W = 92k
Toshiba E-STUDIO2500	150049	151	PED(KD-1018 [A])	Color = 133k; B/W = 19k
Toshiba E-STUDIO2500	150051	186 ST()	RADF(MR-3018)	Color = 77k; B/W = 109k
Toshiba E-STUDIO2500	152084	N/A	RADF(MR-3018) PED(KD-1019)	Machine has a short in it and trips circuit breaker- can't test
Toshiba E-STUDIO2500	152320	197	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Color = 111k; B/W = 87k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO2500	152512	200	RADF(MR-3018) PED(KD-1018 [A]) FN(MJ-1101)	Finisher not jogging correctly when stapling; color = 39k; B/W = 161k
Toshiba E-STUDIO2500	153803	182	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1210)	Color = 30k; B/W = 153k
Toshiba E-STUDIO2500	153938	191	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Color = 64k; B/W = 127k
Toshiba E-STUDIO2500	154138	145	RADF(MR-3018) PED(KD-1018 [A])	Color 132k; B/W = 14k
Toshiba E-STUDIO2500	154729	114	RADF(MR-3018) PED(KD-1018 [B]) PC(GA-1210)	Color = 91k; B/W = 23k
Toshiba E-STUDIO2500	155010	N/A	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Showing HDD mount failed- unable to test
Toshiba E-STUDIO2500	155624	126	ST() RADF(MR-3018)	Error code CE20 (image quality sensor)
Toshiba E-STUDIO2500	156010	209	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Finisher goes into error code CB31 (movable tray paper full detection error)- inop; dirty & yellowed panels; color = 31k; B/W = 178k
Toshiba E-STUDIO2500	156352	88	ST() RADF(MR-3018)	Yellow panels; black meter = 44k; color meter = 44k
Toshiba E-STUDIO2500	156924	133	ST() RADF(MR-3018) FAX(GD-1210)	Color = 11k; B/W = 123k
Toshiba E-STUDIO2500	157012	189	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Color = 54k; B/W = 136k
Toshiba E-STUDIO2500	157013	307	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Unable to print a config page; color = 105k; B/W = 203k
Toshiba E-STUDIO2500	157293	180	ST() RADF(MR-3018) FAX(GD-1210)	RADF reverse gate will not flip properly causing it to jam; color = 78k; B/W = 103k
Toshiba E-STUDIO2500	157365	493	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	RADF jams at times; scratched front door; yellowed & dirty panels; color = 91k; B/W = 402k
Toshiba E-STUDIO2500	157368	493	ST() RADF(MR-3018)	Offcolor & dirty panels; color = 85k; B/W = 64k
Toshiba E-STUDIO280	156310	137	ST() RADF(MR-3016) PC(GM-2020) FN(MJ-1022)	
Toshiba E-STUDIO281C	135688	361	ST() RADF(MR-3018)	Color 71k; B/W = 290k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO281C	143471	138 ST()	RADF(MR-3018) FN(MJ-1022)	Color = 10k; B/W = 129k; broken left side access door
Toshiba E-STUDIO281C	143472	235 ST()	RADF(MR-3018) FN(MJ-1022)	Dented back panel; Color = 15k; B/W = 221k
Toshiba E-STUDIO281C	144513	280	RADF(MR-3018) PED(KD-1011 [B])	Color = 13k; B/W = 268k
Toshiba E-STUDIO281C	145119	315 ST()	RADF(MR-3018) FN(MJ-1022)	Color = 27k; B/W = 288k
Toshiba E-STUDIO281C	145516	146	RADF(MR-3018) PED(KD-1012) FN(MJ-1024)	Black meter = 126k; color meter = 21k
Toshiba E-STUDIO281C	146162	183 ST()	RADF(MR-3018)	Color = 2k; B/W = 181k
Toshiba E-STUDIO281C	146296	394 ST()	RADF(MR-3018) FAX(GD-1200)	Color = 70k; B/W = 325k
Toshiba E-STUDIO281C	147694	310 ST()	RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Color = 18k; B/W = 293k; unable to print NIC & config report
Toshiba E-STUDIO281C	147846	318 ST()	RADF(MR-3018)	Color = 50k; B/W = 269k
Toshiba E-STUDIO281C	150050	361	RADF(MR-3018) PED(KD-1011 [A]) FN(MJ-1022) FAX(GD-1200)	Color = 162k; B/W = 200k
Toshiba E-STUDIO281C	150335	131	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Color = 29k; B/W = 102k
Toshiba E-STUDIO281C	150848	400	RADF(MR-3018) PED(KD-1012) FAX(GD-1200)	RADF jams- inop; Color = 50k; B/W = 351k
Toshiba E-STUDIO281C	150922	115 ST()	RADF(MR-3018) FAX(GD-1200)	Color = 22k; B/W = 936k
Toshiba E-STUDIO281C	151137	140 ST()	RADF(MR-3018)	Black meter = 25k; color meter = 115k
Toshiba E-STUDIO281C	151508	254 ST()	RADF(MR-3018)	Color = 35k; B/W = 220k
Toshiba E-STUDIO281C	151526	328	RADF(MR-3018) PED(KD-1012)	Broken access panel under duplex unit; color = 5k; B/W = 323k
Toshiba E-STUDIO281C	152028	207	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Color = 36k; B/W = 171k
Toshiba E-STUDIO281C	152030	191	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101)	Smashed left side finisher frame; cracked back punch unit panel; color = 50k; B/W = 141k
Toshiba E-STUDIO281C	152031	165	RADF(MR-3018) PU(MJ-6101) PED(KD-1012)	Finisher frame smashed below paper entrance- passes paper but punch & staple not tested; cracked finisher

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO281C	152032	229	FN(MJ-1101) RADF(MR-3018) PU(MJ-6101) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	door; color = 27k; B/W = 138k Finisher tray out of alignment and shows false jam- inop; color = 53k; B/W = 176k
Toshiba E-STUDIO281C	152569	306	RADF(MR-3018) PED(KD-1012) FAX(GD-1200)	Color = 46k; B/W = 260k
Toshiba E-STUDIO281C	152676	152	ST() RADF(MR-3018)	Missing bridge unt cover panel; color = 50k; B/W = 102k
Toshiba E-STUDIO281C	152688	54	RADF(MR-3018) PED(KD-1011 [B]) FN(MJ-1022)	Color = 27k; B/W = 27k
Toshiba E-STUDIO281C	152886	261	RADF(MR-3018) PU(MJ-6004) PED(KD-1012) FN(MJ-1023)	Error code CE40 (image quality control test pattern abnormality); very dirty panels
Toshiba E-STUDIO281C	153268	114	ST() RADF(MR-3018) FN(MJ-1022)	Top finisher tray out of alignment causing error code CC90; color = 17k; B/W = 98k
Toshiba E-STUDIO281C	153625	60	ST() RADF(MR-3018) FN(MJ-1022)	Scratched control panel in front; color = 1k; B/W = 50k
Toshiba E-STUDIO281C	153700	715	RADF(MR-3018) PED(KD-1012)	Color = 69k; B/W = 646k
Toshiba E-STUDIO281C	154182	116	ST() RADF(MR-3018) FN(MJ-1022)	Color = 1k; B/W = 116k
Toshiba E-STUDIO281C	154287	388	RADF(MR-3018) PED(KD-1011 [B])	Broken fuser press roller release lever; color = 49k; B/W = 340k
Toshiba E-STUDIO281C	154435	321	ST() RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Missing finisher plastic entrance guide; color = 32k; B/W = 289k
Toshiba E-STUDIO281C	154451	293	RADF(MR-3018) PED(KD-1011 [B])	Color = 46k; B/W = 248k
Toshiba E-STUDIO281C	156045	388	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	Color = 56k; B/W = 333k
Toshiba E-STUDIO281C	156373	43	ST() RADF(MR-3018)	Black meter = 38k; color meter = 5k
Toshiba E-STUDIO281C	156682	279	ST() RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Color = 62k; B/W = 218k
Toshiba E-STUDIO281C	156698	184	ST() RADF(MR-3018) FAX(GD-1200)	Lower control panel housing out of alignment; color = 24k; B/W = 160k
Toshiba E-STUDIO281C	156699	155	ST() RADF(MR-3018) FAX(GD-1200)	Lower control panel housing out of alignment- control panel will not rotate; broken front door; partial image on copies; broken cap on cyan toner; color = 15k; B/W = 140k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO281C	157351	279	ST() RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Broken back finisher tray cover; color= 42k; B/W = 237k
Toshiba E-STUDIO282	154130	73	ST() RADF(MR-3020) FN(MJ-1022)	
Toshiba E-STUDIO282	155460	112	ST() RADF(MR-3020) PC(GM-1070) FN(MJ-1022)	
Toshiba E-STUDIO282	156374	55	ST() RADF(MR-3020) FN(MJ-1022)	Missing enabler; finisher bracket bent
Toshiba E-STUDIO282	156690	76	ST() RADF(MR-3020) PC(GM-1070) FN(MJ-1022)	Dirty & offcolor panels
Toshiba E-STUDIO283	155944	96	ST() RADF(MR-3020) PC(GM-2071) FAX(GD-1150) E(MJ-5004)	
Toshiba E-STUDIO3100	137507	251	RADF(MR-3006A) PU(MJ-6001N) PC(GA-1121) FN(MJ-1019) DX(MD-5007)	Paper tray #3 is out of order- inop; color = 234k; B/W = 18k
Toshiba E-STUDIO3100	137591	401	RADF(MR-3006A) PU(MJ-6001N) PC(GA-1121) P(MP-1503LT) FN(MJ-1020) DX(MD-5007)	Finisher in false jam code- inop; broken gears & feed tires in bottom paper tray- inop; color = 331k; B/W = 51k
Toshiba E-STUDIO3100	156365	275	RADF(MR-3006A) PU(MJ-6001N) PC(GA-1121) FN(MJ-1019) DX(MD-5007)	Black meter = 28k; color meter = 248k
Ricoh AFICIO 3131	150502	212	RADF(DF81) PU(TYPE 3131) PC(E-750) FN(SR930) DX(AD470) C[1](PS570)	Color = 29k; B/W = 184k
Toshiba E-STUDIO311C	151136	218	RADF(MR-3006A) PC(GA-1121) P(MP-1503LT) FN(MJ-1019) DX(MD-5007)	Black meter = 40k; color meter = 179k
Toshiba E-STUDIO311C	151511	48	RADF(MR-3006A) PC(GA-1121) E() DX(MD-5007) C[1]()	Color = 43k; B/W = 6k
Toshiba E-STUDIO35	157516	421	ST() RADF(MR-3012) FN(MJ-1011)	
Toshiba E-STUDIO350	155518	182	ST() RADF(MR-3015) FAX(GD-1150)	RADF in false jam code
Toshiba E-STUDIO350	156361	566	RADF(MR-3015) PED(KD-1012) PC(GM-1010) FN(MJ-1022) FAX(GD-1150)	
Toshiba E-STUDIO350	156923	311	ST() RADF(MR-3015) PC(GM-2010) FN(MJ-1022) FAX(GD-1150)	Print controller will not initialize- inop

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO350	157362	265	ST() RADF(MR-3015)	
Toshiba E-STUDIO350	157377	190	RADF(MR-3015) PED(KD-1012) PC(GM-1010) FN(MJ-1023)	Unable to print reports- shows list print reserved
Toshiba E-STUDIO3500	140228	534	PED(KD-1019)	Needs toner to test color copies; color = 462k; B/W = 72k
Toshiba E-STUDIO3500	145076	508	RADF(MR-3018) PED(KD-1018 [B]) PC(GA-1210) FN(MJ-1030)	Color = 467k; B/W = 42k
Toshiba E-STUDIO3500	145174	246	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Broken top front door hinge on finisher and chunk out of door frame; broken finisher interlock actuator; color = 49k; B/W = 198k
Toshiba E-STUDIO3500	146836	614	RADF(MR-3018) PED(KD-1019) FN(MJ-1030) FAX(GD-1210)	Stapler jogger not aligning properly; color = 296k; B/W = 319k
Toshiba E-STUDIO3500	147163	428	RADF(MR-3018) PED(KD-1019) PC(GA-1210) FN(MJ-1101)	Copier skew when using RADF; back bypass cover panel out of alignment; Color = 392k; B/W = 37k
Toshiba E-STUDIO3500	147703	189	ST() RADF(MR-3018) FN(MJ-1030)	Color = 91k; B/W = 99k
Toshiba E-STUDIO3500	149070	211	ST() RADF(MR-3018)	Color = 197k; B/W = 15k
Toshiba E-STUDIO3500	149397	182	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Black meter = 4k; color meter = 178k
Toshiba E-STUDIO3500	151696	254	ST() RADF(MR-3018) FN(MJ-1101)	Color = 174k; B/W = 80k
Toshiba E-STUDIO3500	151729	461	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Color = 198k; B/W = 263k
Toshiba E-STUDIO3500	152076	329	RADF(MR-3018) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Color = 281k; B/W = 49k
Toshiba E-STUDIO3500	152524	312	RADF(MR-3018) PED(KD-1018 [B]) FN(MJ-1030) FAX(GD-1210)	Color = 166k; B/W = 146k
Toshiba E-STUDIO3500	152532	514	RADF(MR-3018) PED(KD-1019)	Error code CF90 (unknown); laser motor is not functioning properly- copies are 1/2 blank and corrupted; reports print blank; color = 57k; B/W = 457k
Toshiba E-STUDIO3500	152685	222	ST() RADF(MR-3018) FN(MJ-1101)	Machine will not detect paper in trays #1 & #2- ran through bypass only (unable to generate reports); color = 66k; B/W = 156k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO3500	152977	652 ST()	RADF(MR-3018) FN(MJ-1030)	Scuffed front door; color = 354k; B/W = 299k
Toshiba E-STUDIO3500	153255	223	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101) FAX(GD-1210)	Color = 137k; B/W = 86k
Toshiba E-STUDIO3500	153709	302	RADF(MR-3018) PU(MJ-6004) PED(KD-1019) FN(MJ-1030)	Finisher not jogging correctly when stapling; color = 230k; B/W = 72k
Toshiba E-STUDIO3500	153710	276	RADF(MR-3018) PU(MJ-6004) PED(KD-1019) FN(MJ-1030)	Cracked back finisher pane; trays #1 & #2 will not detect paper- inop; stapler inop; copies exiting finisher crooked; color = 209k; B/W = 68k
Toshiba E-STUDIO3500	154135	214	RADF(MR-3018) PED(KD-1019) FAX(GD-1210)	Deep cut in LCD; color = 123k; B/W = 91k
Toshiba E-STUDIO3500	154142	508	RADF(MR-3018) PED(KD-1019) FAX(GD-1210)	Color = 130k; B/W = 379k
Toshiba E-STUDIO3500	154945	276	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101)	Color = 148k; B/W = 12k
Toshiba E-STUDIO3500	155610	283	RADF(MR-3018) PU(MJ-6004) PED(KD-1018 [A])	Color = 224k; B/W = 59k
Toshiba E-STUDIO3500	155903	314 ST()	RADF(MR-3018) FN(MJ-1030)	Color = 102k; B/W = 213k
Toshiba E-STUDIO3500	155936	247	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Color = 174k; B/W = 74k
Toshiba E-STUDIO3500	155945	247 ST()	RADF(MR-3018)	Color = 160k; B/W = 87k
Toshiba E-STUDIO3500	156351	387	RADF(MR-3018) PED(KD-1018 [B]) FAX(GD-1210)	Black meter = 273k; color meter = 114k
Toshiba E-STUDIO3500	156353	534	PED(KD-1018 [A]) PC(GA-1210)	Black meter = 37k; color meter = 497k
Toshiba E-STUDIO3500	156612	107	RADF(MR-3018) PED(KD-1018 [B]) FN(MJ-1030)	Color = 50k; B/W = 58k
Toshiba E-STUDIO3500	156664	129	RADF(MR-3018) PU(MJ-6101) PED(KD-1018 [B])	Color = 31k; B/W = 98k
Toshiba E-STUDIO3500	156673	N/A ST()	RADF(MR-3018) PU(MJ-6004) FN(MJ-1030)	Control panel shows "cannot start application"; missing hard drive

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO3500	156692	435	RADF(MR-3018) PED(KD-1018 [B]) FN(MJ-1101) FAX(GD-1210)	Error code CE40 (test pattern problem)
Toshiba E-STUDIO3500	156861	245	RADF(MR-3018) PED(KD-1019) FAX(GD-1210)	Color = 211k; B/W = 34k
Toshiba E-STUDIO3500	156882	177	RADF(MR-3018) PED(KD-1019) FAX(GD-1210)	Color = 110k; B/W = 67k
Toshiba E-STUDIO3500	157297	30	ST() FAX(GD-1210)	Error code C449 (fuser unit heater abnormality)
Toshiba E-STUDIO3500	157310	496	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1210)	Color = 74k; B/W = 422k
Toshiba E-STUDIO3510	146755	440	RADF(MR-3018) PED(KD-1019) FN(MJ-1030)	Goes into intermittent SC-CA00 & 445 codes (unknown); was able to run all functions; color = 112k; B/W = 328k
Toshiba E-STUDIO3510	147691	410	RADF(MR-3018) PED(KD-1019) FN(MJ-1030)	Finisher tray out of alignment causing error code CB30 (lift motor); broken top finisher tray; deep scratches in back panel; color = 58k; B/W = 353k
Toshiba E-STUDIO3510	150337	829	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	RADF jams at antrance when duplexing; wrinkled RADF mat; color = 65k; B/W = 765k
Toshiba E-STUDIO3510	151498	438	RADF(MR-3018) PED(KD-1019) FN(MJ-1101)	Finisher jams at entrance every try-inop; broken bridge unit handle; missing toner cartridges & waste toner bottle; cracked back panel by vent cover; waste toner actuator cover will not stay on; color = 177k; B/W = 261k
Toshiba E-STUDIO3510	152652	636	RADF(MR-3018) PED(KD-1019)	Color = 32k; B/W = 605k
Toshiba E-STUDIO3510	153946	130	RADF(MR-3018) PU(MJ-6004) PED(KD-1019) FN(MJ-1030)	Copies not aligning properly in staple mode; color = 105k; B/W = 25k
Toshiba E-STUDIO3510	155989	N/A	RADF(MR-3018) PED(KD-1018 [B])	Missing hard drive
Toshiba E-STUDIO3510	156860	407	RADF(MR-3018) PU(MJ-6101) PED(KD-1019) FN(MJ-1101)	Color = 106k; B/W = 301k
Toshiba E-STUDIO3511	150834	151	RADF(MR-3015) PED(KD-1012) FN(MJ-1023)	Color = 43k; B/W = 108k
Toshiba E-STUDIO3511	151073	223	RADF(MR-3015) PED(KD-1012) FN(MJ-1023)	Print controller is missing; color = 47k; B/W = 177k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(GD-1150)	
Toshiba E-STUDIO3511	151206	299 ST()	RADF(MR-3015) FAX(GD-1150)	Color = 22k; B/W = 278k
Toshiba E-STUDIO3511	151413	296 ST()	RADF(MR-3015)	Color = 87k; B/W = 209k
Toshiba E-STUDIO3511	151771	194 ST()	RADF(MR-3015) FAX(GD-1150)	Contrast dial missing on left side of control panel (LCD is dark); color = 24k; B/W = 171k
Toshiba E-STUDIO3511	151794	166 ST()	RADF(MR-3015) FN(MJ-1023) FAX(GD-1150)	Right side access door jammed shut & unable to open- machine shows a false jam code in this area & will not clear; dirty panels inside & out
Toshiba E-STUDIO3511	151954	403	RADF(MR-3015) PED(KD-1011 [A]) FN(MJ-1023)	Broken finisher door interlock switch actuator; color = 60k; B/W = 343k
Toshiba E-STUDIO3511	152879	387 ST()	RADF(MR-3015) FN(MJ-1024) FAX(GD-1150)	Color = 37k; B/W = 350k
Toshiba E-STUDIO3511	152971	256	RADF(MR-3015) PED(KD-1011 [A]) FN(MJ-1022) FAX(GD-1150)	Color = 9k; B/W = 247k
Toshiba E-STUDIO3511	154133	594	RADF(MR-3015) PED(KD-1011 [B]) FN(MJ-1024) FAX(GD-1150)	Color = 67k; B/W = 527k
Toshiba E-STUDIO3511	154197	287	RADF(MR-3015) PED(KD-1012) FAX(GD-1150)	Color = 29k; B/W = 259k
Toshiba E-STUDIO3511	155009	134	RADF(MR-3015) PED(KD-1012) FN(MJ-1022)	Makes a gidning & clicking noise when running; color = 35k; B/W =
Toshiba E-STUDIO3511	155484	404	RADF(MR-3015) PU(MJ-6004) PED(KD-1012) FN(MJ-1023) FAX(GD-1150)	Copies are coming out crooked at exit; color = 32k; B/W = 372k
Toshiba E-STUDIO3511	156920	423	RADF(MR-3015) PED(KD-1012) FN(MJ-1022) FAX(GD-1150)	Dirty & offcolor panels; color = 46k; B/W = 378k
Toshiba E-STUDIO351C	146248	282 ST()	RADF(MR-3018) FN(MJ-1023)	Error code CE40 (test pattern problem); missing cyan toner; toner rotation assembly making a thumping noise
Toshiba E-STUDIO351C	149964	1071	RADF(MR-3018) PU(MJ-6004) PED(KD-1012) FN(MJ-1024) FAX(GD-1200)	Stapler/punch not jogging properly; color = 23k; B/W = 1048k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO351C	150837	414	ST() RADF(MR-3018) FN(MJ-1023) FAX(GD-1200)	Duplex jams; Color = 98k; B/W = 317k
Toshiba E-STUDIO351C	150844	425	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Scratched front platen glass frame; color = 10k; B/W = 416k
Toshiba E-STUDIO351C	151414	354	RADF(MR-3018) PU(MJ-6101) PED(KD-1011 [B])	Color = 12k; B/W = 342k
Toshiba E-STUDIO351C	151488	405	RADF(MR-3018) PU(MJ-6004) PED(KD-1012) FN(MJ-1023) FAX(GD-1200)	RADF jams at turnaround every try- inop; dirty panels
Toshiba E-STUDIO351C	151512	324	RADF(MR-3018) PED(KD-1011 [A]) FN(MJ-1022) FAX(GD-1200)	Broken slit glass frame; color = 23k; B/W = 302k
Toshiba E-STUDIO351C	151663	218	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Very light color copies (almost no image); color = 47k; B/W = 171k
Toshiba E-STUDIO351C	152077	282	RADF(MR-3018) PED(KD-1012) FN(MJ-1023)	Color = 146k; B/W = 137k
Toshiba E-STUDIO351C	152889	417	RADF(MR-3018) PED(KD-1012) FN(MJ-1023) FAX(GD-1200)	Color = 29k; B/W = 388k
Toshiba E-STUDIO351C	153167	439	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Color = 48k; B/W = 391k
Toshiba E-STUDIO351C	153345	584	ST() RADF(MR-3018) FN(MJ-1022)	Color = 146k; B/W = 439k
Toshiba E-STUDIO351C	153723	398	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Color = 12k; B/W = 386k
Toshiba E-STUDIO351C	153724	748	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Color = 20k; B/W = 273k
Toshiba E-STUDIO351C	154086	118	ST() RADF(MR-3018) FN(MJ-1022) FAX(GD-1200)	Very dirty & greasy panels; color = 41k; B/W = 77k
Toshiba E-STUDIO351C	154220	125	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	Color = 5k; B/W = 121k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO351C	154797	203	PED(KD-1011 [A])	Color = 21k; B/W = 183k
Toshiba E-STUDIO351C	155384	272	RADF(MR-3018) PED(KD-1012) FAX(GD-1200)	Color = 35k; B/W = 238k
Toshiba E-STUDIO351C	155536	484	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	Color = 1k; B/W = 484k
Toshiba E-STUDIO351C	156349	198	ST() RADF(MR-3018) FN(MJ-1023)	RADF jams- inop; color = 37k; B/W = 162k
Toshiba E-STUDIO351C	156371	319	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Black meter = 287k; color meter = 32k
Toshiba E-STUDIO351C	156625	184	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	Color = 8k; B/W = 177k
Toshiba E-STUDIO351C	157350	379	RADF(MR-3018) PED(KD-1012) FN(MJ-1022) FAX(GD-1200)	Color = 13k; B/W = 367k
Toshiba E-STUDIO351C	157359	233	RADF(MR-3018) PED(KD-1011 [A]) FN(MJ-1024) FAX(GD-1200)	
Toshiba E-STUDIO352	148098	110	RADF(MR-3018) PED(KD-1011 [B]) PC(GM-2060) FN(MJ-1101)	
Toshiba E-STUDIO352	149083	264	ST() RADF(MR-3018) FN(MJ-1022)	
Toshiba E-STUDIO352	151256	122	RADF(MR-3018) PED(KD-1012) PC(GM-1060) FN(MJ-1022)	
Toshiba E-STUDIO352	151447	177	ST() RADF(MR-3018) PC(GM-1060) FN(MJ-1101)	Finisher jams when stapling
Toshiba E-STUDIO352	151524	227	RADF(MR-3018) PED(KD-1011 [A]) PC(GM-2060)	Offcolor & dirty panels (inside too)
Toshiba E-STUDIO352	152558	227	ST() RADF(MR-3018) FN(MJ-1101) FAX(GD-1200)	1/2 of copies are blank
Toshiba E-STUDIO352	152690	114	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	
Toshiba E-STUDIO352	152870	164	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	
Toshiba E-STUDIO352	152894	269	RADF(MR-3018) PED(KD-1012)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(GM-1060)	
Toshiba E-STUDIO352	153863	239	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	RADF jams when fed 11" side; RADF mat is torn; broken panel around controller
Toshiba E-STUDIO352	153887	30	ST() RADF(MR-3018) FN(MJ-1022)	Broken finisher handle; jams in fuser frequently
Toshiba E-STUDIO352	154018	225	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO352	154421	114	ST() RADF(MR-3018)	
Toshiba E-STUDIO352	155497	403	RADF(MR-3018) PED(KD-1012) PC(GM-1060) FN(MJ-1022)	
Toshiba E-STUDIO352	155865	359	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	Missing print enabler (has print meter count of 30,322); stapler inop
Toshiba E-STUDIO352	155933	342	RADF(MR-3018) PED(KD-1012) FN(MJ-1022)	
Toshiba E-STUDIO352	156011	232	RADF(MR-3018) PU(MJ-6101) PED(KD-1012) PC(GM-2060) FN(MJ-1101)	Finisher in error code CB31 (movable tray paper full detection error)- inop; offcolor & very dirty panels
Toshiba E-STUDIO352	156177	234	RADF(MR-3018) PED(KD-1011 [A]) PC(GM-2060) FN(MJ-1022)	
Toshiba E-STUDIO352	156303	211	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1022) FAX(GD-1200)	Duplex jams in fuser every try- broken access door #1 in duplex unit
Toshiba E-STUDIO352	157309	587	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1101) FAX(GD-1200)	Cracked lower back finisher panel
Toshiba E-STUDIO353	145102	241	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1022)	
Toshiba E-STUDIO353	152514	293	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	
Toshiba E-STUDIO353	152515	29	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101)	Finisher doesn't jog properly when stapling
Toshiba E-STUDIO353	155937	118	RADF(MR-3018) PED(KD-1012) PC(GM-1061) FN(MJ-1101)	
Toshiba E-STUDIO450	155621	181	ST() RADF(MR-3015)	Broken front paper guide in tray #2

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(GM-1010)	
Toshiba E-STUDIO450	156368	212	RADF(MR-3015) PU(MJ-6004) PED(KD-1012) FN(MJ-1024) FAX(GD-1150)	Pedestal trays not releasing cleanly
Toshiba E-STUDIO4511	152367	861	RADF(MR-3015) PU(MJ-6004) PED(KD-1012) FN(MJ-1024) FAX(GD-1150)	Color = 15k; B/W = 846k
Toshiba E-STUDIO4511	152368	1085	RADF(MR-3015) PU(MJ-6004) PED(KD-1012) FN(MJ-1024) FAX(GD-1150)	Color = 12k; B/W = 1074k
Toshiba E-STUDIO4511	152763	N/A	ST() RADF(MR-3015) FN(MJ-1024) FAX(GD-1150)	Machine will not come to ready- can't test
Toshiba E-STUDIO4511	153963	92	RADF(MR-3015) PED(KD-1012) FAX(GD-1150)	Color = 51k; B/W = 41k
Toshiba E-STUDIO4511	155689	589	RADF(MR-3015) PED(KD-1012) FN(MJ-1023) FAX(GD-1150)	Color = 78k; B/W = 512k
Toshiba E-STUDIO4511	156164	355	RADF(MR-3015) PED(KD-1012) FN(MJ-1023) FAX(GD-1150)	LCT will not lift- makes a loud grinding noise; cracked slit glass; color = 132k; B/W = 224k
Toshiba E-STUDIO4511	156661	406	RADF(MR-3015) PED(KD-1011 [A]) FN(MJ-1023) FAX(GD-1150)	Error code CF40 (test pattern problem)
Toshiba E-STUDIO4511	156697	526	RADF(MR-3015) PU(MJ-6004) PED(KD-1012) FN(MJ-1023)	Error code F-105 (hard drive error)
Toshiba E-STUDIO4511	156917	450	RADF(MR-3015) PED(KD-1012) FN(MJ-1023)	Color = 29k; B/W = 422k
Toshiba E-STUDIO451C	152967	754	RADF(MR-3018) PU(MJ-6004) PED(KD-1011 [B]) FN(MJ-1023)	Finisher not jogging correctly when stapling; Color = 114k; B/W = 640k
Toshiba E-STUDIO451C	154328	281	RADF(MR-3018) PU(MJ-6004) PED(KD-1012) FN(MJ-1023) FAX(GD-1200)	Missing small back finisher cover panel; color = 2k; B/W = 279k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO451C	154697	355	RADF(MR-3018) PED(KD-1012) FN(MJ-1024)	Broken lower control panel housing- tab broken off & won't mesh; color = 99k; B/W = 257k
Toshiba E-STUDIO451C	155463	375	RADF(MR-3018) PU(MJ-6004) PED(KD-1012) FN(MJ-1024) FAX(GD-1200)	Color = 27k; B/W = 349k
Toshiba E-STUDIO451C	156298	260	RADF(MR-3018) PED(KD-1011 [B]) FAX(GD-1200)	Offcolor & dirty panels; print controller will not initialize- inop; color = 29k; B/W = 232k
Toshiba E-STUDIO451C	156921	462	RADF(MR-3018) PU(MJ-6004) PED(KD-1012) FN(MJ-1024)	Color = 36k; B/W = 427k
Toshiba E-STUDIO451C	157122	306	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	Color = 2k; B/W = 304k
Toshiba E-STUDIO451C	157340	36	RADF(MR-3018) PED(KD-1012)	Scuffed control panel; color = 3k; B/W = 33k
Toshiba E-STUDIO452	151520	211	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO452	154019	300	RADF(MR-3018) PED(KD-1012) PC(GM-2060) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO452	154222	196	ST() RADF(MR-3018) PU(MJ-6101) FN(MJ-1101)	
Toshiba E-STUDIO452	154297	337	ST() RADF(MR-3018) PC(GM-2060) FN(MJ-1101)	
Toshiba E-STUDIO452	155872	302	RADF(MR-3018) PED(KD-1012) PC(GM-2060)	
Toshiba E-STUDIO452	155934	295	RADF(MR-3018) PED(KD-1012) FN(MJ-1024)	
Toshiba E-STUDIO452	156052	263	ST() RADF(MR-3018) PC(GM-1060) FN(MJ-1101)	
Toshiba E-STUDIO452	156053	176	ST() RADF(MR-3018) FN(MJ-1101)	
Toshiba E-STUDIO452	156202	166	RADF(MR-3018) PED(KD-1012) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO452	157239	345	RADF(MR-3018) PED(KD-1012) PC(GM-1060) FN(MJ-1101)	Broken lower control panel housing- control panel will not rotate

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO453	152526	498	RADF(MR-3018) PED(KD-1012) PC(GM-2061) FN(MJ-1101) FAX(GD-1160) FAX(GD-1200)	Cracked finisher panel behind finisher tray
Toshiba E-STUDIO453	154127	421	RADF(MR-3018) PED(KD-1011 [B]) PC(GM-2061) FN(MJ-1101) FAX(GD-1200)	
Toshiba E-STUDIO453	155938	106	RADF(MR-3018) PED(KD-1012) FN(MJ-1101)	Missing print enabler (has print meter count of 52,091); missing an exit claw causing LCT to jam
Toshiba E-STUDIO520	154215	527	PU(MJ-6003N) PC(GM-2040) P(MP-4004) FN(MJ-1027)	Broken paper deck lift cables- inop; paper deck actuator pin broken off
Toshiba E-STUDIO520	154791	645	PC(GM-2040) P(MP-4004) FN(MJ-1027) FAX(GD-1170)	Copies creasing in corner at finisher exit
Toshiba E-STUDIO520	154947	584	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	Tray #2 will not lift- inop
Toshiba E-STUDIO520	155959	674	PC(GM-2040) P(MP-4004) FN(MJ-1027)	
Toshiba E-STUDIO520	156363	761	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO520	156367	624	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO520	156375	237	FN(MJ-1027)	Has papder deck brackets - missing paperdeck; missing enabler
Toshiba E-STUDIO520	156527	207	P(MP-4004) FN(MJ-1027)	Finisher trays out of alignment causing error code CB30 (tray lift motor); top tray mount is bent and sitting at an angle
Toshiba E-STUDIO520	156580	511	FN(MJ-1027)	Missing print enabler (has print meter count of 64,301)
Toshiba E-STUDIO520	156684	248	PC(GM-2040) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO520	156870	598	PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO523	152516	739	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO523	152517	418	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO523	152518	271	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO523	152519	318	PC(GM-2041) FN(MJ-1027)	
Toshiba E-STUDIO523T	145517	144	PU(MJ-6003) PC(GM-2041) FN(MJ-1027) FAX(GD-1170)	
Toshiba E-STUDIO523T	147595	48	PC(GM-2041) FN(MJ-1027)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Toshiba E-STUDIO550	156442	320	PU(MJ-6003N) PC(GL-1020) FN(MJ-1017)	
Toshiba E-STUDIO550	157500	1219	PU(MJ-6003N) PC(GL-1020) FN(MJ-1017)	
Toshiba E-STUDIO600	149940	174	P(MP-4004)	Missing finisher (has brackets)
Toshiba E-STUDIO600	153342	287	PU(MJ-6003N) PC(GM-2040) FN(MJ-1027)	
Toshiba E-STUDIO600	155489	277	FN(MJ-1027)	
Toshiba E-STUDIO600T	149518	98	FN(MJ-1027)	
Toshiba E-STUDIO720T	154912	909	PU(MJ-6003N) PC(GM-2040) P(MP-4004) FN(MJ-1027)	Cracked top paper deck panel

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.  
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.  
Please call our sales team for current availability.