

Wulff Enterprises

02/10/2012

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Canon COLORPRINTER	186311	N/A		IR LBP5360; has 1C with PC and NIC, and 1C PED, PED back panel broken, lower back panel off color, does not recognize color cartridges installed - not tested
Hewlett Packard	185886	33		Color Laserjet 2840; Has 1C, PC and NIC, fax and ADF, black meter = 24k, color meter = 9k, off color
Hewlett Packard	188902	405		Color laserjet 5550DN; has PC and NIC and 1C and 2C PED, black meter = 134k, color meter = 271k, off color panels
Hewlett Packard	192606	247		Laserjet P3005; Has 1C and PC and nIC
Hewlett Packard	188492	728		M4345MFP; w/ RADF, duplex, NIC, fax, scan; missing an exit tray
Hewlett Packard	192604	90		Laserjet P3005x; Has 1C and PC and NIC, and PFU
Hewlett Packard	192605	39		Laserjet P3005x; Has 1C and PC and NIC and PFU
Hewlett Packard	192602	116		Laserjet P3005x; Has 1C and PC and NIC and PFU
Hewlett Packard	192603	149		Laserjet P3005x; Has 1C and PC and NIC, and PFU, on switch not work - could not powerdown the machine
KonicaMinolta	191611	N/A		Magicolor 2490MF, missing imaging unit - not tested, has 1C and PC and NIC and fax, bypass cassette missing, Missing PFU cover
KonicaMinolta	190995	20		Magicolor 2480MF; 1C and ADF and PFU, black meter = 7k, color meter = 14k, front panel missing from cassette #1
KonicaMinolta	190994	14		Magicolor 2480MF; has 1C and ADF and PFU, black meter = 10k, color meter = 5k
Konica FORCE 75	188897	1686 FN(FS-108)		Has a Ricoh model G-150-17 label; jams every try; off color panels
Konica FORCE 75	188896	1687 FN(FS-108)		Has a Ricoh model G-150-17 label; off color panels
Konica FORCE 75	188899	27 FN(FS-108)		Has a Ricoh model G-150-17 label; jams every try; off color panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera COLORPRINTER	191860	27		FS-C5030N; Has 1C and PC and NIC and duplexer, black meter = 6k color meter = 21k
Kyocera COLORPRINTER	189995	5		FS-C5030N; 1C PC and NIC nad FPU, and duplexer, black meter = 1k, color meter = 5k
Kyocera COLORPRINTER	192013	57		FS-C5030N; Has 1C and PC and NIC, black meter = 15k, color meter = 43k
Kyocera COLORPRINTER	189417	8		FS-C5030N; has PC and NIC and 1C, black meter = 5k, color meter = 3k
Kyocera COLORPRINTER	190997	68		FS-C5020N; has PC and NIC and 1C, black meter = 25k, color meter = 43k, has duplexer
Kyocera COLORPRINTER	189997	3		FS-C5030N; Has PC and NIC and 1C, has PF-60 PFU, black meter = 1k, color meter = 3k
Kyocera LASERPRINTER	190998	56		FS-1030D; has 1C and PC and NIC, off color
Kyocera LASERPRINTER	190999	107		FS-1030D; Off color panels
Kyocera LASERPRINTER	184625	5		FS-1030d; has 1C w/ port
Kyocera LASERPRINTER	184647	N/A		FS-1030D; has 1C
Kyocera LASERPRINTER	184626	N/A		FS-1030D; has 1C
Kyocera LASERPRINTER	184649	N/A		FS-1030D; 1C Missing imaging unit and toner, fuser gear missing
Kyocera LASERPRINTER	184648	N/A		FS-1030D; has 1C,
Kyocera LASERPRINTER	191120	N/A		FS-1920; 1C and PCa nd NIC, blank images
Kyocera LASERPRINTER	178624	1292		FS-9520DN; has PC w/NIC and PED, jamming in exit roller - not tested, yellow panels
Kyocera LASERPRINTER	192012	104		FS-3530N; Has PC and NIC and 1C
Kyocera LASERPRINTER	187456	1347		FS-9520DN; has 2C and PC and NIC, and duplexer, has DF-71U, finisher and PED PF-75, off color panels
Kyocera LASERPRINTER	186584	417		FS-9530DN; has PC and NIC and 2C, fuser vent yellow
Kyocera LASERPRINTER	186583	304		FS-9530DN; has PC and NIC and 2C, yellow panels
Kyocera LASERPRINTER	191863	729		FS-9530DN; has 2C and PC and NIC and PED PF-750 and FN DF710
Kyocera LASERPRINTER	186204	1858		FS-9530DN; has PC and NIC and duplexer, 2C, has PF750 PED, back panel dented
Lexmark COLORPRINTER	183809	558		X945E; has RADF and NIC and port, black meter = 354k, colormeter =

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lexmark LASERPRINTER	192518	847		204k, left side interlock broken, jamming in bypass tray x646e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192519	485		X646e; Missing imaging unit
Lexmark LASERPRINTER	192394	455		x644e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192517	150		x646e; Has 1C and PC and NIC and fax
Lexmark LASERPRINTER	192395	221		x644e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192516	127		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192521	567		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192524	220		x646e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192528	167		x646e; Has 1C and PC and NIC and RADF with duplexing, missing imaging unit - no tested
Lexmark LASERPRINTER	192529	107		x646e; Has 1C and PC and NIC and fax
Lexmark LASERPRINTER	192527	973		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192525	681		T644; Has 1C and PC and NIC and finisher and duplexer
Lexmark LASERPRINTER	192526	62		T644; Has 1C and PC and NIC and RADF and duplexer and finisher
Lexmark LASERPRINTER	192523	491		x646e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192393	154		x644e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192522	326		x646e; Has PC and NIC and 1C
Lexmark LASERPRINTER	192388	503		x644e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192380	252		x854e; Has PC and NIC and RADF 2C and finisher, missing photo conductor unit and toner - not tested
Lexmark LASERPRINTER	192381	338		x854e; Has 2c and PC and NIC and finisher, missing photo conductor unit and toner - not tested
Lexmark LASERPRINTER	192379	268		x854e; Has PC and 2C and Fax and NIC and finisher, missing Photo conductor unit and toner - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lexmark LASERPRINTER	192378	645		x945e; Has 1C and PC and NIC, has PED and finisher, black meter = 443k, color meter = 202k
Lexmark LASERPRINTER	191637	318		X854e; 2C 1K LCT, PC and NIC and Fax and ADF
Lexmark LASERPRINTER	192377	582		x945e; Has 1C and PC and NIC and PED with finisher, black meter = 522k, color meter = 61k
Lexmark LASERPRINTER	192382	547		x854e; Has 2C and PC and NIC, missing imaging unit - not tested
Lexmark LASERPRINTER	192384	807		x646e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192383	1117		X646e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192389	150		x644e; Has 1C and PC and NIC and fax, missing imaging unit - not tested
Lexmark LASERPRINTER	192390	215		x644e; Has 1C and PC and NIC missing imaging unit
Lexmark LASERPRINTER	192530	867		x646e; Has 1C and PC and NIC and fax
Lexmark LASERPRINTER	192387	486		x644e; Has 1C and PC and NIC,
Lexmark LASERPRINTER	192385	119		x644e; Has 1C and PC and NIC
Lexmark LASERPRINTER	192386	N/A		x644e; Has 1C and PC and NIC, error code 935.00 - service printhead error, missing imaging unit
Lexmark LASERPRINTER	192391	187		x644e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192392	334		x644e; Has 1C and PC and NIC and 1C, missing imaging unit - not tested
Lexmark LASERPRINTER	192531	1023		T644; Has 1C and PC and NIC and fax and finisher
Lexmark LASERPRINTER	192544	227		x646e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	190398	251		XM642E; has 1C PC and NIC and fax, toner spilled in cassette, bypass tray broken, toner door broken
Lexmark LASERPRINTER	192543	349		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192545	272		x646e; Has 1C and PC and NIC
Lexmark LASERPRINTER	192548	549		X644e; Has PC and NIC and and fax and RADf with duplexer, missing toner and developer units
Lexmark LASERPRINTER	192550	317		x646e; Has 1C and PC and NIC and fax, missing imaging unit

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lexmark LASERPRINTER	192532	79		x644e; Has 1C and PC and NIC and fax
Lexmark LASERPRINTER	192549	113		X644e; Has PC and NIC and fax and 1C, Missing toner and developer units
Lexmark LASERPRINTER	192542	803		x646e; Has 1C and PC and NIC, missing imaging unit
Lexmark LASERPRINTER	192541	474		T644; has 1C and PC and NIC and fax, and finisher, missing toner and developer units
Lexmark LASERPRINTER	192551	317		T644; Has 1C and PC and NIC and fax, has Finisher and duplexer
Lexmark LASERPRINTER	192535	512		x646e, Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192536	736		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192534	493		x644e; Has PC and NIC and 1C, missing imaging unit
Lexmark LASERPRINTER	192537	554		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192533	341		x644e; Has PC and NIC and fax and 1C
Lexmark LASERPRINTER	192538	243		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Lexmark LASERPRINTER	192540	256		T644; Has 1C and PC and NIC and fax, missing finisher, missing developer and toner units, RADF feed tray broken
Lexmark LASERPRINTER	192539	233		x646e; Has 1C and PC and NIC and fax, missing imaging unit
Mita COLORPRINTER	188006	115		FS-C5030N; has PC and NIC, and PF-60 PFU, and duplexer, black meter = 67k, color meter = 49k
Mita LASERPRINTER	188435	6		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188437	71		FS-1030d; Has 1C PC and NIC and 1C PFU
Mita LASERPRINTER	186355	164		FS-4000DN; has PC and NIC and 1C PFU
Mita LASERPRINTER	188438	35		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188434	18		FS-1030D; Has PC and NIC and 1C, has PF-17 PFU
Mita LASERPRINTER	188433	45		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188432	28		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188431	4		FS-1030D; has 1C + PFU(PF-17),

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Mita LASERPRINTER	188429	84		FS-1030D; has 1C PC and NIC and PF17 PFU
Mita LASERPRINTER	188428	99		FS-1030D; has PC and NIC and 1C w/ PF 17PFU
Mita LASERPRINTER	188423	53		FS-1030D; has CP and NIC and 1C with PF-17 PFU
Mita LASERPRINTER	188421	48		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188422	19		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188417	56		FS-1030D; has 1C PC and NIC and PF17 PFU
Mita LASERPRINTER	188420	89		FS-1030D; has PC and NIC and 1C w/ PF17 PFU
Mita LASERPRINTER	188418	48		FS-1030D; has 1C w/ PF17 PFU, and PC and NIC
Mita LASERPRINTER	188416	48		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188419	92		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188415	10		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188426	130		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188430	166		FS-1030D; has PC and NIC and 1C and PF-17 PFU
Mita LASERPRINTER	188424	38		FS-1030D; has PC and NIC and 1C and PF-17 PFU
Mita LASERPRINTER	188427	38		FS-1030D; w/ NIC & PFU
Mita LASERPRINTER	188425	60		FS-1030D; hs 1C PC and NIC, and PFU PF17
Okidata COLORPRINTER	184560	28		ES1624MFP; Black meter = 4k, color meter = 25k, has Fax scan and port
Okidata COLORPRINTER	185766	46		C9600; has PC and NIC and 1C, black meter = 5k, color meter = 42k
Okidata COLORPRINTER	187459	36		CX2032MFP; has 1C Fax and NIC, black meter = 29k, color meter = 7k
Gestetner COLORPRINTER	192676	55		C7425DN; Has 1C and PC and NIC, black meter = 21k, color meter = 34k, yellow panels
Ricoh COLORPRINTER	183175	5		SP C410DN; has 1C PC and NIC, black meter= 3k, color meter = 3k
Ricoh COLORPRINTER	188800	56		SPC410DN; w/ NIC & PS
Ricoh COLORPRINTER	191927	N/A		Aficio SPC811DN; has 2C and PC and NIC and 2C PED, error code SC681-121 - RFID communication error - not tested
Ricoh COLORPRINTER	191926	240		Aficio SPC811DN; has 2C and PC and NIC and 2C PED, has PS3, black meter = 47k, color meter = 194k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh COLORPRINTER	192243	3		GX3050; has 1C and PC and NIC, black meter = 1k, color meter = 3k, top panel scratched
Ricoh COLORPRINTER	184997	N/A		Aficio SP C222DN; has PC and NIC - not tested
Ricoh COLORPRINTER	190408	N/A		SP C211N; Needs CYan toner - not tested, has 1C and PC and NIC
Ricoh COLORPRINTER	184998	N/A		Aficio sp C222DN; has PC and NIC - not tested
Ricoh COLORPRINTER	185514	14		Aficio SP C222SF; has fax and scan and ADF and PC, black meter = 12k, color meter = 2k
Ricoh COLORPRINTER	189264	87		Aficio sp C4100N; left side access door interlock broken, black meter = 79k, color meter = 9k
Ricoh COLORPRINTER	192239	N/A		Aficio SP C410DN; has 1C and PC and NIC, missing toner - not tested
Ricoh COLORPRINTER	192228	N/A		Aficio SP C410DN; Has PC and NIC and 1C, off color panels, tab broken, side door interlock broken
Ricoh COLORPRINTER	187433	303		AFICIO SP C410DN; w/ NIC & PS; color =130k; B/W = 173k
Ricoh COLORPRINTER	183174	25		SP C410DN; has Pc and NIC and 1C, black meter = 14k, color meter = 12k
Ricoh COLORPRINTER	189583	N/A		Aficio SP C222SF; error code sc300 - AC charge output error, has ADF and 1C and PC and NIC
Ricoh COLORPRINTER	186004	1		Aficio SP C221SF; has PC and NIC and Scan, ADF, 1C black meter = 1k, color meter = 1k
Ricoh COLORPRINTER	187144	20		Aficio SP C411DN; has PC and NIC and 1C
Ricoh COLORPRINTER	183476	108		SC-C811DN; has PC and NIC and port, has SR-3030 finisher not tested, black meter = 20k, color meter = 88k
Ricoh COLORPRINTER	192245	8		GX3050N; has PC and NIC and duplexer, black meter = 3k, color meter = 6k
Lanier COLORPRINTER	188029	65		LP331CN; has Pc and NIC and 1C, black meter = 22k, color meter = 43k
Lanier COLORPRINTER	188027	63		LP331CN; has PC and NIC and 1C, black meter = 15k, color meter = 48k
Lanier COLORPRINTER	188028	45		LP331CN; has PC and NIC and 1C black meter = 9k, color meter = 36k
Lanier COLORPRINTER	188030	94		LP311CN; has 1C and PC and NIC, black meter = 11k, color meter = 84k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier COLORPRINTER	192590	650		LP440C; Has 2C and PC and NIC and finisher and PED, finisher not tested, black meter = 511k, color meter = 140k
Lanier COLORPRINTER	186086	333		LP440C; has 2C with PC and NIC, has stand and 1C PFU, black meter = 15k, color meter = 318k
Lanier COLORPRINTER	188024	84		LP331CN; has PC and NIC and 1C, black meter = 16k, color meter = 69k
Lanier COLORPRINTER	188026	92		LP331CN; has PC and NIC and 1C black meter = 15k, color meter = 77k
Lanier COLORPRINTER	188025	135		LP331CN; has PC and NIC and 1C, black meter = 42k, color meter = 93k
Lanier COLORPRINTER	191937	47		LP440c; Has 2C and PC and NIC and LCT, black meter = 12k, color meter = 36k
Lanier COLORPRINTER	188031	130		LP311CN; has 1C and Pc and NIC, black meter = 39k, color meter = 91k
Lanier COLORPRINTER	188032	101		LP331CN; has PC and NIC and 1C, black meter = 23k, color meter = 78k
Lanier COLORPRINTER	184939	263		LP440C; has PC and NIC, black meter = 101k, color meter = 163k
Lanier COLORPRINTER	188035	112		LP331CN; has 1C and PC and NIC, black meter = 67k, color meter = 45k
Lanier COLORPRINTER	188033	24		LP331CN; has 1C and PC and NIC, black meter = 13k, color meter = 11k
Lanier COLORPRINTER	188034	125		LP331CN; has 1C and Pc and NIC, black meter = 47k, color meter = 79k
Savin COLORPRINTER	181784	76		CLP128; has PC and NIC and duplexerBlack meter = 48k, color meter = 28k
Savin COLORPRINTER	181785	71		CLP22; has PC and NIC and duplexer and PS, black meter = 47k, color meter = 24k
Gestetner LASERPRINTER	182736	1		DSM516MF; has Fax and ADF, 1C, jamming in ADF
Savin LASERPRINTER	189263	N/A		MLP31N; Grinding noise in machine
Ricoh LASERPRINTER	188488	N/A		AFICIO AP610N; w/ NIC & PFU; needs toner to test
Ricoh LASERPRINTER	190682	1089		Aficio SP 9100DN, has 2C + 2K LCT, has PC and NIC
Ricoh LASERPRINTER	192230	6		GX3050; has 1C and PC and NIC
Ricoh LASERPRINTER	192244	10		GX3050N; Has 1C and PC and NIC, error code sc990 - software performance error - not tested, black meter = 5k, color meter = 5k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh LASERPRINTER	192247	65		Aficio SP 4100N; Has 1C and NIC and PC
Ricoh LASERPRINTER	192246	457		Aficio SP 4100N; Has 1C and PC and NIC
Ricoh LASERPRINTER	187157	8		Aficio sp 4100N; has 1C, PC and NIC, rear access door broken
Ricoh LASERPRINTER	192229	10		GX3050; Has PC and NIC and 1C, black meter = 9k, color meter = 1k
Ricoh LASERPRINTER	192225	18		Aficio BP20N; Has 1C and PC and NIC
Ricoh LASERPRINTER	192227	5		Aficio BP20N; Has 1C and PC and NIC, missing developer unit and toner
Ricoh LASERPRINTER	192226	17		Aficio BP20N; Has PC and NIC and 1C
Ricoh LASERPRINTER	192248	23		Aficio SP 4100N; has PC and NIC and 1C
Ricoh LASERPRINTER	192249	20		Aficio SP 4100N; Has 1C and PC and NIC
Ricoh LASERPRINTER	181442	2		SP 4100N; has 1C w PC and NIC and PS3
Ricoh LASERPRINTER	185512	N/A		Aficio BP20; has 1C and bypass, has PFU type 20, PFU communication cable crushed - not tested
Ricoh LASERPRINTER	185513	8		Aficio BP20; 1C port, yellow panels
Ricoh LASERPRINTER	192254	54		Aficio SP4100N; Has 1C and PC and NIC, yellowing panels
Ricoh LASERPRINTER	192253	66		Aficio SP 4100N; has PC and NIC and 1C, yellow panels
Ricoh LASERPRINTER	192250	35		Aficio SP 4100N; Has PC and NIC and 1C
Ricoh LASERPRINTER	192252	92		Aficio SP 4100N; Has PC and NIC 1C
Ricoh LASERPRINTER	192251	39		Aficio SP 4100N; Has PC and NIC and 1C
Ricoh LASERPRINTER	192224	6		Aficio BP20DN; Has PC and NIC and 1C, missing developer and toner units
Ricoh LASERPRINTER	192242	N/A		GX3050N; Has 1C and PC and NIC, error code SC990 - software performance error - not tested, ink cover broken
Ricoh LASERPRINTER	192221	56		Aficio BP20N; Has 1C and PC and NIC, off color panels
Ricoh LASERPRINTER	192219	4		Aficio BP20N; Has 1C and PC and NIC

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Ricoh LASERPRINTER	192220	8		Aficio BP20N; Has PC and NIC and 1C, missing developer and toner units
Ricoh LASERPRINTER	192223	22		Aficio BP20N; Has PC and NIC and 1C, missing developer and toner units
Ricoh LASERPRINTER	192222	26		Aficio BP20N; Has PC and NIC and 1C
RISO HC5000	188799	1243		Won't come to ready- can't test; Has external controller PS7R-9000
RISO HC5000	187014	725		Error code S98-320K1 - ink spilled all over left side of machine, exit tray bracket bent
RISO LASERPRINTER	184498	201		Model P620; has PC and NIC and scanner, has finisher, dirty and off color panels
RISO LASERPRINTER	184633	6		G752; has 2C and fax and scan, has PC, black meter = 1k, color meter =
Sharp AR-P350	187671	575	PED(AR-D14) NIC(AR-NC5J)	Off color panels
Sharp AR-P350	187672	593	PED(AR-D14) NIC(AR-NC5J)	
Sharp AR-P450	180064	721	STK(AR-MS1) PED(AR-D20) NIC(AR-NC5J) DX(AR-DU4)	
Sharp AR-P450	187673	600	PED(AR-D14) NIC(AR-NC5J)	Has stacker - ar-ms1
Sharp AR-P450	180065	511	STK(AR-MS1) PED(AR-D20) NIC(AR-NC5J) DX(AR-DU4)	Off color panels
Toshiba COLORPRINTER	184326	N/A		E-studio360CP; has PC and NIC and 1C, PFU, needs yellow toner
Toshiba COLORPRINTER	187434	N/A		E-STUDIO205cp; w/ NIC; needs magenta toner to test
Xerox COLORPRINTER	186036	N/A		Phaser 8560MFP; has PC and NIC and ADF with Duplexer, has fax and 1c, off color panels
Xerox COLORPRINTER	186038	N/A		Phaser 8560MFP; has PC and NIC and 1c with fax, needs toner - not tested, off color
Xerox COLORPRINTER	186033	290		Phaser 8560MFP; has PC and NIC and ADF and duplexer, off color panels, black meter = 258k, color meter = 34k
Xerox COLORPRINTER	186034	N/A		Phaser 8560MFP; has PC and NIC and RADF and duplexer, needs toner - not tested, off color panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox LASERPRINTER	191756	3		Phaser 3600; Has 1C and Pc and NIC and PFU
Xerox LASERPRINTER	191759	113		Phaser 3600; Has 1C and PC and NIC, top panel yellow
Xerox LASERPRINTER	191760	9		Phaser 3600; Has 1C and PC and NIC, Back access door broken
Xerox LASERPRINTER	191758	167		Phaser 3600; Has 1C and PC and NIC and 1C PFU, top panel yellow
Xerox LASERPRINTER	191757	106		Phaser 3600; Has 1C and PC and NIC, top panel yellow, fuser cover will not latch
Xerox LASERPRINTER	191761	13		Phaser 3600; has 1C and PC and NIC an PFU
Xerox LASERPRINTER	191755	124		Phaser 3600; Has 1C and PC and NIC, top panel yellow
Xerox LASERPRINTER	191762	92		Phaser 3600; Has 1C and PC and NIC and 1C PFU and duplexer
Xerox LASERPRINTER	191764	13		Phaser 3600; has 1C and PC and NIC, rear access door broken

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.