

Wulff Enterprises

01/07/2009

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner 1302	117312	95		Yellowed panels
Gestetner 1302	117313	154		Jams frame cassette- ran through bypass only
Gestetner 1302	117317	136		Missing pin & drive sprocket on cassette feed shaft- tested with another
Gestetner 1302F	119168	187		
Gestetner 1302F	121261	92		
Gestetner 1802	121258	391	RADF(DF72)	
Gestetner 1802	121259	198	ST() RADF(DF72)	Cassette handle cracked; fax knockout missing
Gestetner 1802	124629	93	ST() RADF(DF72)	
Gestetner 1802D	117314	44	ST() RADF(DF71) FAX(TYPE 1018)	Top tray paper sensor broken loose; needs toner (unable to test all functions)
Gestetner 1802D	117537	256	ST() RADF(DF71)	
Gestetner 1802D	119253	71	ST() RADF(DF71) PFU(PS450)	
Gestetner 1802D	121257	141	RADF(DF71) PC(TYPE 1018) NIC(TYPE 1018)	Right side panel broken
Gestetner 2712	122308	197	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	Tray #2 will not detect paper & tray #1 jams every copy (unable to test); has wrong finisher (SR830); broken RADF plug socket; broken bypass tray & panel; broken right side panel
Gestetner 2712	122617	501	ST() RADF(DF75) DX(AD420) B(TYPE 1027)	
Gestetner 3502	120814	710	ST() RADF(DF70) FAX(TYPE 1045) E(PT1045)	
Gestetner 3502	121672	390	ST() RADF(DF70) FN(SR720)	
Gestetner DSC224	118712	95	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Black meter =84k; colored meter =12k
Gestetner DSC224	121991	577	RADF(DF75) PED(PS510)	Yellowed and dirty panels; Black meter = 458k; colored meter =119k
Gestetner DSC224	123000	167	ST() RADF(DF75) PC(TYPE 1232)	Bypass tray broken off; color = 14k; B/W = 153k; blurred color copies; color = 14k; B/W = 153k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSC232	113493	829	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Yellowed panels
Gestetner DSC232	115679	280	RADF(DF75) PED(PS510) FN(SR830)	Color = 2k; B/W = 279k
Gestetner DSC232	119192	293	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR830)	Color = 18k; B/W = 275k
Gestetner DSC232	122978	585	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Color = 69k; B/W = 516k
Gestetner DSC232	123895	420	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830) = 46k; B/W = 374k FAX(TYPE 1232)	Yellowed panels; blurred copies; color
Gestetner DSC232	124627	242	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830) FAX(TYPE 1232) E(PT290)	Color = 7k; B/W = 235k
Gestetner 3218	120850	83	ST() PC(TYPE 185) NIC(TYPE 185) ADF(DF68)	
Gestetner DSM618	122196	88	ST() PFU(PS460) FAX(TYPE 2018) ADF(DF78)	
Gestetner DSM622	122449	108	ST()	Has a book platen
Gestetner DSM622	122450	119	ST()	Has a book platen
Gestetner DSM622	124204	254	RADF(DF75) PED(PS490) PC(TYPE 2027) FN(SR790)	Broken bypass tray
Gestetner 3532	120314	331	PS(TYPE 2045) PED(PS530) PC(TYPE 2045) FN(SR790)	
Gestetner 3532	120847	480	PED(PS360)	Broken inner exit panel
Gestetner 3532	120851	652	PED(PS530) PC(TYPE 2045) FAX(TYPE 2045) E(PT330)	
Gestetner 3532	121263	201	PU(TYPE 1045) PED(PS530) PC(TYPE 2045) FN(SR880)	
Gestetner 3532	121265	309	PED(PS530) PC(TYPE 2045) FN(SR890) FAX(TYPE 2045)	
Gestetner 3532	121266	540	ST() PU(TYPE 1045) PC(TYPE 2045) FN(SR880) FAX(TYPE 2045)	RADF plug wires pulled loose- inop; missing paper deck (tested with another)
Gestetner 3532	122769	173	ST()	
Gestetner 3532	123369	427	ST() P(RT45) FN(SR790)	Broken turn around guide in tray #2- inop
Gestetner DSM635	116909	626	ST() PC(TYPE 2045E) P(RT45) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM635	121678	578	PED(PS530) PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Gestetner DSM635	123042	549	ST()	
Gestetner DSM635	123149	349	ST() PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	RADF dogears copies on exit
Gestetner DSM635	124364	156	ST()	
Gestetner DSM635	124631	757	PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Gestetner DSM635	124814	172	ST() FAX(TYPE 2045E)	Missing paper deck & finisher (knockouts missing)
Gestetner 4532	122398	921	ST() PC(TYPE 2045)	
Gestetner 4532	123154	1010	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	Goes into error code SC542 (low fuser temp) during copying- unable to fully test; offcolored & dirty panels; double image on copies; broken lower back panel
Gestetner 4532	124630	1004	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045) E(PT330)	Broken R4 plate in finisher- stapler inop
Gestetner DSM645	121680	1111	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880) FAX(TYPE 2045E) E(PT330)	
Gestetner DSM645	121681	1084	PU(TYPE 1045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880) FAX(TYPE 2045E) E(PT330)	Broken paper deck door actuator
Gestetner DSM675	125016	718	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	
Gestetner DSM675	125017	949	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	Finisher tray mount smashed- finisher inop
Gestetner DSM675	125018	493	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	Broken finisher tray
Gestetner 3222	124952	184	ST() RADF(DF69) PC(TYPE 270) NIC(TYPE 185-E) FN(SR720) FAX(TYPE 270) DX(AD360)	Error code SC543 (high fuser temp); offcolored & dirty panels; missing printer button
Gestetner DSC332	121314	763	ST() E(PT460)	Color = 17k; B/W = 747k
Gestetner DSC332	122616	431	ST() E(PT460)	Color = 46k; B/W = 385k
Gestetner DSC338	120418	1019	PU(TYPE 2238) PED(PS550) FN(SR910)	Color = 385k; B/W = 635k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Gestetner DSM735	124490	126 ST()	PC(TYPE 3045) FAX(TYPE 3045)	
Gestetner DSM745	122611	726 PED(PS530)	PC(TYPE 3045) FN(SR790)	Stapler inop
Gestetner DSM745	122612	615 PED(PS530)	PC(TYPE 3045) P(RT45) FN(SR790)	
Gestetner DSM745	122613	590 PED(PS530)	PC(TYPE 3045) P(RT45) FN(SR790)	
Gestetner DSC424	104472	115 ST()	FN(SR790) FAX(TYPE C= 12k B/W= 104k 3232)	
Gestetner DSC424	116904	47 PED(PS520)		Color = 32k; B/W = 15k
Gestetner DSC435	118180	635 ST()	FN(SR960) FAX(TYPE 3245) E(PT460)	Shows black development unit not set properly- unable to resolve; color = 39k; B/W = 597k
Gestetner DSC435	119767	314 PED(PS580)	FN(SR960) E(PT460)	Color = 104k; B/W = 210k
Gestetner DSC435	121663	894 PED(PS600)	FN(SR960) FAX(TYPE 3245) E(PT460)	Offcolored panels; color = 87k; B/W = 807k
Gestetner DSC460	124203	535 PU(TYPE 3260)	PC(TYPE 3260) P(RT43) FN(SR970)	Color = 308k; B/W = 227k
Gestetner CS555	125019	2083 PU(TYPE 3260)	P(RT43) FN(SR980)	Paper deck jams at B4 every try- inop; color = 1499k; B/W = 585k; has interposer tray type 3260
Gestetner CS213D	111825	130 RADF(DF64)	P(RT36) 20SS(ST33)	Color = 101k; B/W = 29k
Gestetner DSC38S	117671	431 RADF(DF73)	FN(SR770) FAX(TYPE 3800C)	Missing R4 guide in finisher- inop; yellowed panels; broken exit tray; color = 91k; B/W = 340k
Gestetner CS331	112825	168 RADF(DF81)	PC(E-850) E() DX(AD470)	Duplex jams; color = 120k; B/W = 48k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.