

Wulff Enterprises

01/07/2009

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB C350	103299	323	ST() RADF(DF-601) DX(AD-501)	Bypass in error code C-0960 (manual tray lift up); color = 230k; B/W = 93k
Imagistics CM3520	116288	656	RADF(DF-601) PED(PC-401) FN(FS-601) DX(AD-501)	Color = 365k; B/W = 291k
KonicaMinolta BIZHUB C350	117685	226	ST() RADF(DF-601) DX(AD-501)	Color = 161k; B/W = 66k
KonicaMinolta BIZHUB C350	120117	1226	RADF(DF-601) PED(PC-201) FN(FS-501) DX(AD-501)	Color = 116k; B/W = 1110k
KonicaMinolta BIZHUB C350	121773	301	RADF(DF-601) PED(PC-201) DX(AD-501)	Color = 88k; B/W = 213k
Kyocera KM-C2230	122883	279	ST() RADF(DP-621)	Color = 18k; B/W = 261k
KonicaMinolta BIZHUB C350	122921	250	RADF(DF-601) PED(PC-401) PC(IC-401) FN(FS-501) DX(AD-501)	Color = 233k; B/W = 17k
KonicaMinolta BIZHUB C350	123104	932	ST() RADF(DF-601) PU(PK-501) PC(IC-401) FN(FS-601) DX(AD-501)	Color = 512k; B/W = 421k
Kyocera KM-C2230	124383	424	ST() RADF(DP-621) FN(DF-621)	Needs a new imaging unit to test; broken RADF plug socket; color = 88k; B/W = 337k
KonicaMinolta BIZHUB C350	124445	558	ST() RADF(DF-601) DX(AD-501)	Broken front door; color = 115k; B/W = 444k
KonicaMinolta BIZHUB C450	121381	365	PED(PC-402) FN(FS-603)	Missing yellow imaging unit; missing finisher bridge unit assembly; black meter = 189k; colored meter = 176k
Konica 7022	119790	208	ST() RADF(DF-314) E()	
Konica 7022	122147	151	PED(DB-210)	Paper will not feed through machine - not tested
Konica 7022	124695	180	ST() RADF(DF-314) E()	Dirty & offcolored panels; duplex jams
Konica 7025	120016	316	RADF(DF-314) PED(DB-209)	Went into error code F-28-2 (transfer corona) during copying; very dirty panels; makes a clicking noise; duplex jams
Konica 7030	119297	138	ST() RADF(DF-314) PC(IP-421) NIC(KN-303) FAX(FK-101)	Missing exit tray
Konica 7030	120642	610	ST() RADF(DF-314) E()	
Konica 7030	120776	427	ST() RADF(DF-314) PC(IP-011) NIC(KN-304)	Finisher skews copies when stapling

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(FS-107)	
Konica 7030	123883	278	RADF(DF-314) PED(DB-210) E()	
Konica 7030	124321	328	ST() RADF(DF-314) E()	
Konica 7035	116645	491	RADF(DF-314) PED(DB-210) FN(FS-107)	Broken front door; broken RADF panel; stapler inop
Konica 7035	118622	N/A	RADF(DF-314) PED(DB-210) FN(FS-107)	Error code F-28-3 (separation corona)
Mita VI7360	119781	1855	FN(FS-8330)	Scanner not working- can't test machine; broken finisher door
Mita VI7360	123855	2908	FN(FS-8330)	Broken finisher door hinges
Mita VI7360	123856	3941	FN(FS-8330)	Dirty & offcolored panels; cracked & dented front door
Minolta DI 850	121777	1389	PC(PI8500) P(C-403) FN(FN-115)	Error code E90-01 (duplex drive board problem); james every copy at registration rollers; paper deck not detected by machine
Konica 7130	124696	N/A	ST() RADF(DF-314) E()	Error code F-28-3; dirty & offcolored panels
Konica 7130	124697	401	ST() RADF(DF-314) E()	Dirty & offcolored panels
Konica 7145	120260	289	PED(DB-411) PC(IP-432) FN(FS-114)	
Konica 7145	121331	1492	PED(DB-411) PC(IP-432) FN(FS-112)	Finisher trays out of alignment causing error code F-77-2 (up/down motor); memory is full- unable to fully
Konica 7145	121333	1275	PED(DB-411) PC(IP-432) FN(FS-112)	LCD locked up after testing; cracked finisher trays
Konica 7145	122926	336	PED(DB-411) FN(FS-112)	
Konica 7145	122936	563	PED(DB-211) FN(FS-114)	
Konica 7145	124687	755	PED(DB-211) PC(IP-432) FN(FS-114)	Finisher trays out of alignment causing error code F-77-02
Konica 7145	124688	684	PED(DB-211) PC(IP-432) FN(FS-114)	
Konica 7145	124689	257	PED(DB-211) PC(IP-432) FN(FS-114)	False jam code- will not clear
Konica 7145	124690	350	PED(DB-211) PC(IP-432) FN(FS-114)	False jam code- will not clear
Konica 7145	124698	1144	PED(DB-411) PC(IP-432) FN(FS-112)	RADF in false jam code & will not clear- can't test; offcolored panels
Minolta DI 551	122989	489	FN(FN-6)	
Hewlett Packard 9065MFP	120215	243	PU(PK-110) PC(IP-511) FN(FS-110)	Stapler jams
Hewlett Packard 9065MFP	120216	450	PU(PK-110) PC(IP-511) FN(FS-110)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Minolta DI 650	123477	493	FN(FN-113)	
Konica 7222	110128	184	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	
Konica 7222	110325	148	ST() RADF(DF-320) FAX(FK-103) E()	Bypass will not feed- unable to test; Blurry copies
Konica 7222	113616	216	ST() RADF(DF-320) FAX(FK-103) E()	
Konica 7222	114031	180	ST() RADF(DF-320) E()	Has wrong controller installed (IP-432); missing toner cartridge- can't test
Konica 7222	115124	195	ST() RADF(DF-320) E()	Needs toner to test
Konica 7222	116877	102	ST() RADF(DF-320) E()	
Konica 7222	121644	119	ST() RADF(DF-320) E()	
Konica 7222	122243	37	RADF(DF-320) PED(DB-211) PC(IP-424) FN(FS-114)	
Konica 7228	115726	72	ST() RADF(DF-320) E()	Blurred copies
Konica 7228	120029	516	ST() RADF(DF-320)	Error code F-28-3 (separation corona)
Konica 7235	114310	154	ST() RADF(DF-320) E()	
Konica 7235	118535	577	PED(DB-211) PC(IP-424) FN(FS-114) FAX(FK-103)	
Konica 7235	119591	464	ST() RADF(DF-320) FN(FS-114)	Blurred copies
Konica 7235	124691	352	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	False jam code- will not clear
Konica 7235	125029	312	RADF(DF-320) PED(DB-411) FN(FS-114)	
Minolta DI 5510	117522	286	FN(FN-121)	Missing RADF drive assembly parts- inop (unable to test finisher)
Konica 7255	121894	526	PC(IP-511) FN(FS-110)	
Minolta DI 5510	122920	787	PC(PI7200E) E()	
Konica 7272	120451	1677	PU(PK-120) PC(IP-511) FN(FS-110)	
Konica 7272	124692	1458	FN(FS-110)	
Konica 8020	113503	134	RADF(DF-332) PFU(PF-232 [B]) PC(FIERY 15k X3E+) FN(FS-135)	Black meter = 120K; colored meter =
Konica 8050	112881	146	RADF(DF-319) PC(IP-921) FN(FS-115)	Dented & bent left side panel; broken waste toner door; color = 95k; B/W = 51k
Konica 8050	113458	667	RADF(DF-319) PC(IP-901) P(LT-211) FN(FS-215)	Paper deck will not feed- inop; Color = 245k; B/W = 643k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 8050	121800	913	RADF(DF-319) PC(IP-901) FN(FS-115)	Color = 852k; B/W = 62k
Konica 7115	122757	20		

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.