

Wulff Enterprises

07/29/2010

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB 160	153981	27	ADF(DF-501)	Missing paper tray rear cover & bypass cover; torn ADF mylar strip
KonicaMinolta BIZHUB 160	153982	18	PFU(PF-501) ADF(DF-501)	Missing rear paper tray cover; missing toner cartridge (tested with another)
KonicaMinolta BIZHUB 160	157278	24	ADF(DF-501)	Missing toner cartridge- tested with another; missing an exit tray
KonicaMinolta BIZHUB 160	157279	7	ADF(DF-501)	
KonicaMinolta BIZHUB 161F	152638	N/A	PFU(PF-501) NIC(NC-501)	No power; broken paper tray hinge; broken ADF tray
KonicaMinolta BIZHUB 161F	154407	N/A		Machine will not come to ready- can't test
KonicaMinolta BIZHUB 161F	154408	65		
KonicaMinolta BIZHUB 250	153967	238	ST() RADF(DF-605) E(JS-502)	
KonicaMinolta BIZHUB 250	153969	312	ST() RADF(DF-605) E(JS-502)	Jams every copy at registration roller
KonicaMinolta BIZHUB 250	154554	646	RADF(DF-605) PED(PC-202)	
KonicaMinolta BIZHUB 250	155978	496	RADF(DF-605)	
KonicaMinolta BIZHUB 250	157126	194	ST() RADF(DF-605) FN(FS-508)	Cracked front finisher panel
KonicaMinolta BIZHUB 350	156014	357	RADF(DF-605) PED(PC-202) FN(FS-508)	
Muratec MFX-2850D	156170	227	FN(2850FN)	Has one tray pedestal
KonicaMinolta BIZHUB 420	149046	248	PU(PU-501) PED(PC-202) P(LU-201) FN(FS-510) FAX(FK-502)	
KonicaMinolta BIZHUB 420	150619	221	PED(PC-402) FN(FS-510)	Makes a thumping noise when running; scuffed back left RADF panel
KonicaMinolta BIZHUB 420	151316	442	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	Missing front right side panel (tested with another)
KonicaMinolta BIZHUB 420	151557	244	ST() FN(FS-510) FAX(FK-502)	Cracked back right corner panel
KonicaMinolta BIZHUB 420	152386	209	PED(PC-402) PC(IC-204) FAX(FK-502) E(JS-502)	
KonicaMinolta BIZHUB 420	152821	242	PC(IC-204) FN(FS-510)	
KonicaMinolta BIZHUB 420	153039	285	PED(PC-202) PC(IC-204) FN(FS-510) FAX(FK-502)	Stapler jogger not aligning sheets properly & tears paper when trying to staple

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB 420	153711	320	PED(PC-402) PC(IC-204) FN(FS-510)	
KonicaMinolta BIZHUB 420	154397	189	PED(PC-202) FN(FS-510) FAX(FK-502)	Broken top back finisher bracket
KonicaMinolta BIZHUB 420	154501	569	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	
KonicaMinolta BIZHUB 420	154705	198	PED(PC-202) PC(IC-204) FN(FS-510)	Right finisher bin rail is broken loose from rack- finisher inop
KonicaMinolta BIZHUB 420	154788	226	PED(PC-202)	
KonicaMinolta BIZHUB 420	154833	688	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	Cracked trim plate above LCT
KonicaMinolta BIZHUB 420	155324	387	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	
KonicaMinolta BIZHUB 420	155767	581	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	
KonicaMinolta BIZHUB 420	156443	463	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	
KonicaMinolta BIZHUB 420	156520	217	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	Cassette #3 front panel bent
KonicaMinolta BIZHUB 420	157323	1336	PU(PU-501) PED(PC-402) PC(IC-204) FN(FS-510)	Tray #1 & bypass will not detect paper- inop
KonicaMinolta BIZHUB 420	157384	958	PED(PC-402) FN(FS-510)	Registration roller needs replaced- machine jams every copy
KonicaMinolta BIZHUB 500	153179	277	PU(PU-501) PED(PC-402) PC(IC-204) FN(FS-510)	
KonicaMinolta BIZHUB 500	153368	292	PED(PC-402) PC(IC-204) FN(FS-510) FAX(FK-502)	Error code C-C183 (overall control board); *electronic meter has been cleared
KonicaMinolta BIZHUB 500	153570	300	PU(PU-501) PED(PC-202) PC(IC-204) FN(FS-510)	Broken top finisher tray bracket corner
KonicaMinolta BIZHUB 500	153628	260	PED(PC-202) PC(IC-204) FN(FS-510)	
KonicaMinolta BIZHUB 500	153667	166	PED(PC-202) FN(FS-510)	
KonicaMinolta BIZHUB 500	153670	440	PED(PC-202) FN(FS-510)	
KonicaMinolta BIZHUB 500	155066	192	PU(PU-501) PED(PC-402) PC(IC-204) FN(FS-510)	
KonicaMinolta BIZHUB 500	155612	267	PU(PU-501) PED(PC-402) PC(IC-204) FN(FS-511)	Bypass will not detect paper- inop
KonicaMinolta BIZHUB 500	156965	696	PED(PC-402) FN(FS-510)	
KonicaMinolta BIZHUB 500	157196	153	PED(PC-402) FN(FS-511)	Cracked left side & back finisher panels
KonicaMinolta BIZHUB 500	157202	461	ST() FN(FS-510)	Torn RADF platen mat
KonicaMinolta BIZHUB 500	157357	621	PU(PU-501) PED(PC-402)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(IC-204) FN(FS-510)	
KonicaMinolta BIZHUB 500	157385	1588	PED(PC-402) FN(FS-510)	
KonicaMinolta BIZHUB 600	151789	1090	FN(FS-504)	
KonicaMinolta BIZHUB 600	151790	1284	FN(FS-504)	
KonicaMinolta BIZHUB 600	153666	232	PU(PK-505) FN(FS-504)	Offcolor & dirty panels
KonicaMinolta BIZHUB 600	153674	157	PC(IC-202) FN(FS-504)	Deep scratches in right front door
KonicaMinolta BIZHUB 600	154183	531	PC(IC-202) FAX(FK-502) E()	Control panel functioning intermittently
KonicaMinolta BIZHUB 600	154488	1027	PC(IC-202) FN(FS-504)	
KonicaMinolta BIZHUB 600	154489	1305	PC(IC-202) FN(FS-504)	
Imagistics IM6020	154932	845	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-504)	Machine not detecting punch unit- inop; paper guides out of alignment in tray #3- will not detect paper
KonicaMinolta BIZHUB 600	154988	245	PC(IC-202) FN(FS-504)	Tray #1 set to statement size and will not change
KonicaMinolta BIZHUB 600	154989	170	FN(FS-504)	Control panel & LCD is smashed- can't test machine; broken finisher trays; back finisher panel dented & bent
KonicaMinolta BIZHUB 600	154990	73	PC(IC-202) FN(FS-504)	Cracked finisher tray; deneted & bent back finisher panel; inside front door panel cracked by mounting pin
KonicaMinolta BIZHUB 600	154991	12	PC(IC-202) FN(FS-504)	Cracked lower finisher tray; dented & bent back & side finisher panel
KonicaMinolta BIZHUB 600	154992	28	PC(IC-202) FN(FS-504)	Finisher exit area frame bent causing paper actuator to stick and jams; deep scratch in back panel missing RADF exit tray; broken paper tray #3 handle;
KonicaMinolta BIZHUB 600	154996	96	PC(IC-202) FN(FS-504)	Smashed finisher trays; transport tire broken off finisher feed- can't test; dented & bent back panel
KonicaMinolta BIZHUB 600	154999	132	PC(IC-202) FN(FS-504)	Broken finisher tray; paper tray #1 handle broken off & missing; dented & bent back panel; bent back finisher panel; cracked & scuffed front door
KonicaMinolta BIZHUB 600	155000	36	PC(IC-202) FN(FS-504)	Broken finisher wiring harness connector & one wire broken- inop; smashed finisher trays; dented & bent back finisher panel
Imagistics IM6020	155849	1040	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-504)	
Imagistics IM6020	156115	924	PU(PK-505) PC(IC-202) FN(FS-602)	Bent back finisher panel; scratched front door
KonicaMinolta BIZHUB 600	156441	744	PC(IC-202) FN(FS-504)	
KonicaMinolta BIZHUB 600	156562	260	PC(IC-202) FN(FS-504)	Dented & bent back finisher panel; broken paper tray #2 handle; jams at

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				finisher entrance frequently; stapler inop
KonicaMinolta BIZHUB 600	156564	35	PC(IC-202) FN(FS-504)	Finisher tray mount bent - inop; missing finisher wheel; dented & bent left side finisher panel
KonicaMinolta BIZHUB 600	156566	66	PC(IC-202) FN(FS-504)	Finisher in error code C-1137 (FS abnormality gate home sensor); broken bottom paper tray
KonicaMinolta BIZHUB 600	156567	46	FN(FS-504)	Machine will not come to ready- can't test; dented & bent back finisher panel; cracked bottom finisher rail & extension missing
KonicaMinolta BIZHUB 600	156568	243	FN(FS-504)	Dented & bent back finisher panel; finisher tray is smashed; stapler inop
KonicaMinolta BIZHUB 600	156569	583	PC(IC-202) FN(FS-504)	Bottom paper tray panel broken off; scratched front door; dented & bent back finisher panel
KonicaMinolta BIZHUB 600	156570	172	PC(IC-202) FN(FS-504)	Finisher in error code C1139 (registration shutter home sensor)
KonicaMinolta BIZHUB 600	156571	67	PC(IC-202) FN(FS-504)	Finisher trays out of alignment- inop; finisher trays broken off & wheels broken
KonicaMinolta BIZHUB 600	156572	468	PC(IC-202) FN(FS-504)	Broken handle on tray #1
KonicaMinolta BIZHUB 600	156573	142	PC(IC-202) FN(FS-504)	Broken bypass tray & cover; missing finisher wheels; broken paper tray #2 handle; deep scratches in control panel; jams constantly in vertical transport- unable to run reports
KonicaMinolta BIZHUB 600	156623	284	PU(PK-505) PC(IC-202) FN(FS-504) FAX(FK-502)	Bowed back finisher panel
KonicaMinolta BIZHUB 600	156969	974	FN(FS-602)	Dented back finisher panel
KonicaMinolta BIZHUB 600	157022	749	PC(IC-202) FN(FS-504) FAX(FK-502)	Deep scratch in right side panel
KonicaMinolta BIZHUB 600	157050	409	PC(IC-202) FN(FS-504)	
KonicaMinolta BIZHUB 600	157125	1291	PU(PK-505) PC(IC-202) FN(FS-504)	
KonicaMinolta BIZHUB 600	157128	801	PU(PK-505) PC(IC-202) FN(FS-504)	
KonicaMinolta BIZHUB 600	157298	928	FN(FS-504)	
KonicaMinolta BIZHUB 600	157375	2485	PU(PK-505) FN(FS-504)	Unable to clear admin password- only able to run counter list; dented back finisher panel
KonicaMinolta BIZHUB 600	157376	2477	PU(PK-505) FN(FS-504)	Unable to clear admin password- was only able to generate a counter list; dented back panel
KonicaMinolta BIZHUB 750	150919	636	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-504)	Punch unit inop; makes a clicking noise when copying

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB 750	151313	1350	PC(IC-202) P(LU-401) FN(FS-504)	
KonicaMinolta BIZHUB 750	151902	1498	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-505)	Missing paper deck attaching brackets & hardware
KonicaMinolta BIZHUB 750	152218	2942	PC(IC-202) FN(FS-504)	Finisher not jogging properly when stapling
KonicaMinolta BIZHUB 750	152641	545	PC(IC-202) FN(FS-504)	Scuffed front door
KonicaMinolta BIZHUB 750	153677	670	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-602) FAX(FK-502)	Dented & bent back finisher panel; front door of finisher out of alignment (not actuating); staple, punch & duplex cannot be selected together
KonicaMinolta BIZHUB 750	153840	1547	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-602)	Finisher jams when stapling
KonicaMinolta BIZHUB 750	154688	531	PC(IC-202) FN(FS-504)	Cracked left front door at pivot; noisy finisher
Imagistics IM7520	154931	1129	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-504)	
KonicaMinolta BIZHUB 750	155065	521	PU(PK-505) PC(IC-202) P(LU-401) FN(FS-505)	Bent upper left side paper deck panel
KonicaMinolta BIZHUB 750	155862	1304	PU(PK-505) PC(IC-202) P(LU-402) FN(FS-504) FAX(FK-502)	Missing mounting pin for paper deck entrance guide- can't test; scuffed front door & finisher door; loose top finisher door hinge
KonicaMinolta BIZHUB 750	155916	1438	PU(PK-505) FN(FS-504)	
KonicaMinolta BIZHUB 750	156966	1567	FN(FS-504)	
KonicaMinolta BIZHUB 750	157108	562	PC(IC-202) P(LU-401) FN(FS-504)	Paper deck door dented in
KonicaMinolta BIZHUB 750	157294	1003	PC(IC-202) FN(FS-504)	
KonicaMinolta BIZHUB C250	151287	189	RADF(DF-601) PED(PC-403) FN(FS-501) DX(AD-503)	Duplex jams; color = 81k; B/W = 108k
KonicaMinolta BIZHUB C250	152148	149	RADF(DF-601) PED(PC-203) FN(FS-501) FAX(FK-502) DX(AD-503)	Dirty front door; color = 29k; B/W = 121k
KonicaMinolta BIZHUB C250	154405	223	ST() RADF(DF-601) PU(PK-501) FN(FS-603) FAX(FK-502) DX(AD-503)	Finisher jams every copy; missing punch waste container; color = 8k; B/W = 65k
KonicaMinolta BIZHUB C250	154933	99	RADF(DF-601) PED(PC-403) DX(AD-503)	COlor = 45k; B/W = 55k
KonicaMinolta BIZHUB C250	155475	299	ST() RADF(DF-601) DX(AD-503)	Color = 28k; B/W = 35k
KonicaMinolta BIZHUB C250	155608	188	RADF(DF-601) PED(PC-403) FN(FS-501) DX(AD-503)	Color = 21k; B/W = 167k; stapler inop; bypass will not detect paper- inop
KonicaMinolta BIZHUB C250	155797	195	ST() RADF(DF-601)	Color = 59k; B/W = 136k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FN(FS-603) DX(AD-503)	
KonicaMinolta BIZHUB C250	156542	96 ST()	RADF(DF-601) DX(AD-503)	Bypass not feeding paper; control panel broken; black meter = 63k; color meter = 34k
KonicaMinolta BIZHUB C250	156733	316 ST()	RADF(DF-601) FAX(FK-502) DX(AD-503)	Color = 19k; B/W = 297k
KonicaMinolta BIZHUB C250	157127	62 ST()	RADF(DF-601) FN(FS-501) FAX(FK-502) DX(AD-503)	Missing bridge unit- can't test finisher; unable to print a config page; color = 4k; B/W = 58k
KonicaMinolta BIZHUB C252	149711	135 ST()	RADF(DF-601) FN(SD-503) FN(FS-514) FAX(FK-502)	Color = 27k; B/W = 109k
KonicaMinolta BIZHUB C252	151495	171 ST()	RADF(DF-601) FN(FS-514)	Color = 99k; B/W = 72k
KonicaMinolta BIZHUB C252	153929	101 ST()	RADF(DF-601) FAX(FK-502)	Error code CD010 - hard disk unformat error - screen frozen; black meter = 20k; color meter = 81k
KonicaMinolta BIZHUB C252	154502	57	RADF(DF-601) PED(PC-103) FN(FS-514) FAX(FK-502)	Color = 15k; B/W = 17k
KonicaMinolta BIZHUB C252	156535	132	RADF(DF-601) PU(PK-501) PED(PC-203) FN(FS-603) FAX(FK-502)	Black meter = 66k; color meter = 66k; finisher front throat bent
KonicaMinolta BIZHUB C300	147155	64	RADF(DF-608) PED(PC-203)	Color = 45k; B/W = 19k
KonicaMinolta BIZHUB C300	147925	232	RADF(DF-608) PED(PC-203) FN(FS-514) FAX(FK-502)	Missing fax board PCB causing error code C-B003; broken stapler cable & cracked plastic base panel- stapler unit is detached; color = 148k; B/W = 85k
KonicaMinolta BIZHUB C300	147926	224	ST() RADF(DF-608)	Color = 36k; B/W = 189k
KonicaMinolta BIZHUB C300	152328	50	ST() PC(IC-406)	Color = 44k; B/W = 6k
KonicaMinolta BIZHUB C300	153928	315	ST() RADF(DF-608)	Bypass tray front cover broken; black meter = 168k; color meter = 147k
KonicaMinolta BIZHUB C300	155941	517	RADF(DF-608) PU(PK-510) PED(PC-403) PC(IC-406) FN(FS-514) FAX(FK-502)	Color = 268k; B/W = 250k
KonicaMinolta BIZHUB C350	152913	220	ST() RADF(DF-601) DX(AD-501)	Color = 81k; B/W = 140k
KonicaMinolta BIZHUB C350	153103	300	ST() RADF(DF-601) FN(FS-501) DX(AD-501)	Color = 27k; B/W = 274k
KonicaMinolta BIZHUB C350	153583	277	ST() RADF(DF-601) DX(AD-501)	Cracked back panel; broken duplex hook- will not stay closed; color = 177k; B/W = 100k
KonicaMinolta BIZHUB C350	153678	109	RADF(DF-601) PED(PC-101) FN(FS-501) DX(AD-501)	Broken finisher tray; cracked back panel; color = 90k; B/W = 19k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB C350	153837	137 ST()	RADF(DF-601) DX(AD-501)	Color = 27k; B/W = 111k
KonicaMinolta BIZHUB C350	153943	364	RADF(DF-601) PED(PC-101) FN(FS-501) DX(AD-501)	Big hole in pedestal storage tray panel; Color = 41k; B/W = 323k
KonicaMinolta BIZHUB C350	153959	374	RADF(DF-601) PED(PC-101) FN(FS-601) DX(AD-501)	Black meter = 190k; color meter = 184k
KonicaMinolta BIZHUB C350	154151	150	RADF(DF-601) PED(PC-101) PC(IC-401) FN(FS-501) DX(AD-501)	Color = 59k; B/W = 91k
KonicaMinolta BIZHUB C350	154152	287	RADF(DF-601) PED(PC-101) PC(IC-401) FN(FS-501) DX(AD-501)	Broken bottom paper tray handle; color = 44k; B/W = 243k
KonicaMinolta BIZHUB C350	154190	306	RADF(DF-601) PED(PC-101) PC(IC-401) FN(FS-501) DX(AD-501)	Missing NIC; color = 121k; B/W = 185k
KonicaMinolta BIZHUB C350	154191	481	RADF(DF-601) PED(PC-101) PC(IC-401) FN(FS-501) DX(AD-501)	Missing NIC; Color = 351k; B/W = 131k
KonicaMinolta BIZHUB C350	154192	262	RADF(DF-601) PED(PC-101) PC(IC-401) FN(FS-501) DX(AD-501)	Color = 129k; B/W = 133k
KonicaMinolta BIZHUB C350	154503	212	RADF(DF-601) PED(PC-201) FN(FS-603) DX(AD-501)	Color = 161k; B/W = 52k
KonicaMinolta BIZHUB C350	154900	220	RADF(DF-601) PU(PK-501) PC(IC-401) FN(FS-601) DX(AD-501)	Color = 45k; B/W = 176k
KonicaMinolta BIZHUB C350	155036	200 ST()	RADF(DF-601) DX(AD-501)	Color = 67k; B/W = 134k
KonicaMinolta BIZHUB C350	155455	692	RADF(DF-601) PED(PC-401) FN(FS-501) DX(AD-501)	Black meter = 662k; color meter = 30k
KonicaMinolta BIZHUB C350	155765	212	RADF(DF-601) PED(PC-401) FN(FS-501) DX(AD-501)	Chipped left side control panel; color = 86k; B/W = 127k
KonicaMinolta BIZHUB C350	155792	395	RADF(DF-601) PED(PC-401) DX(AD-501)	Cracked back panel by power plug; color = 4k; B/W = 392k
Copystar KM-C2230	156171	442 ST()	RADF(DP-621) FN(DF-626) DX(DU-621)	Color = 181k; B/W = 261k
KonicaMinolta BIZHUB C350	156172	410	RADF(DF-601) PU(PK-501) PED(PC-401) FN(FS-603) DX(AD-501)	Color = 139k; B/W = 271k
KonicaMinolta BIZHUB C350	156210	434 ST()	RADF(DF-601) PC(IC-401) FN(FS-501) DX(AD-501)	RADF jams; color = 234k; B/W = 201k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB C350	156301	153	RADF(DF-601) PED(PC-201) PC(IC-401) FN(FS-501) DX(AD-501)	Yellowed panels; color = 58k; B/W = 96k
KonicaMinolta BIZHUB C350	156327	318	RADF(DF-601) PED(PC-401) FN(FS-501) DX(AD-501)	Missing bride unit gears- can't test finisher; color = 131k; B/W = 188k
KonicaMinolta BIZHUB C350	156347	296	ST() RADF(DF-601) FN(FS-501) DX(AD-501)	Black meter = 139k; color meter = 157k
KonicaMinolta BIZHUB C350	156423	489	ST() RADF(DF-601) DX(AD-501)	Black meter = 466k; color meter = 24k
KonicaMinolta BIZHUB C350	156534	162	ST() RADF(DF-601) FN(FS-501) DX(AD-501)	Missing bridge unit - finisher not tested; black meter = 74k; color meter = 89k
Kyocera KM-C2230	156957	623	RADF(DP-621) PED(PF-621) FN(DF-626) DX(DU-621)	Bent finisher tray mount (still works); color = 557k; B/W = 66k
KonicaMinolta BIZHUB C350	156958	201	RADF(DF-601) PU(PK-501) PED(PC-101) FN(FS-601) DX(AD-501)	Lamp problem- blank image down side of copies; color = 61k; B/W = 140k
KonicaMinolta BIZHUB C350	157027	505	RADF(DF-601) PU(PK-501) PED(PC-401) FN(FS-601) DX(AD-501)	Color = 146k; B/W = 359k
KonicaMinolta BIZHUB C350	157133	286	ST() RADF(DF-601) DX(AD-501)	Bridge unit is smashed; received wrong finisher with machine (FS-507); missing yellow & cyan toner cartridges; color = 80k; B/W = 206k
KonicaMinolta BIZHUB C350	157232	284	ST() RADF(DF-601) PC(IC-401) FN(FS-501) DX(AD-501)	Port for IC-401 connection was removed from machine (IC-401 not tested); cracked front bridge unit hook; color = 80k; B/W = 204k
KonicaMinolta BIZHUB C350	157343	508	RADF(DF-601) PU(PK-501) PC(IC-401) FN(FS-601) DX(AD-501)	Broken trim panel on tray #3; color = 70k; B/W = 439k
KonicaMinolta BIZHUB C350	157374	291	ST() RADF(DF-601) DX(AD-501)	Imaging units and fuser units need replaced- can't test; color = 82k; B/W = 209k
KonicaMinolta BIZHUB C351	156967	700	RADF(DF-601) PED(PC-402) FN(FS-507)	Missing bridge unit securing clip; color = 207k; B/W = 493k
KonicaMinolta BIZHUB C352	149333	404	RADF(DF-608) PU(PK-510) PED(PC-403) FN(FS-514)	Finisher socket broken; finisher trays out of alignment; missing finisher base; black meter = 310k; color meter = 95k
KonicaMinolta BIZHUB C352	151333	267	ST() RADF(DF-608) FAX(FK-502)	Color = 36k; B/W = 232k
KonicaMinolta BIZHUB C352	152534	191	RADF(DF-608) PED(PC-103) FAX(FK-502)	Color = 21k; B/W = 170k
KonicaMinolta BIZHUB C352	152539	232	RADF(DF-608) PED(PC-403) PC(IC-406)	Print controller will not come to ready-inop; missing controller cable (tested)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB C352	152912	325	FN(FS-514) RADF(DF-608) PED(PC-403) PC(IC-406) FN(FS-514) FN(SD-503)	with another); color = 180k; B/W = 53k Finisher trays out of alignment causing error code C-1183 (elevator drive); broken finisher plug socket; color = 287k; B/W = 38k
KonicaMinolta BIZHUB C352	153407	265	ST() RADF(DF-608) PC(IC-406)	Color = 196k; B/W = 70k
KonicaMinolta BIZHUB C352	153468	323	RADF(DF-608) PED(PC-403) FN(FS-514)	Color = 61k; B/W = 262k
KonicaMinolta BIZHUB C352	153471	342	RADF(DF-608) PED(PC-103)	Color = 35k; B/W = 308k
KonicaMinolta BIZHUB C352	153632	219	RADF(DF-608) PED(PC-403) FAX(FK-502)	Color = 85k; B/W = 135k
KonicaMinolta BIZHUB C352	153635	203	ST() RADF(DF-608) FAX(FK-502)	Color = 27k; B/W = 177k
KonicaMinolta BIZHUB C352	153673	194	RADF(DF-608) PED(PC-403) PC(IC-406) FN(FS-514)	Touch screen is working intermittently; Color = 168k; B/W = 26k
KonicaMinolta BIZHUB C352	153795	612	RADF(DF-608) PED(PC-403) FN(FS-514) FAX(FK-502)	Color = 156k; B/W = 456k
KonicaMinolta BIZHUB C352	153941	324	ST() RADF(DF-608) PU(PK-510) FN(FS-514) FAX(FK-502)	Color = 192k; B/W = 133k
KonicaMinolta BIZHUB C352	154433	559	RADF(DF-608) PED(PC-403)	Bypass tray broken off & wiring loose (still works); color =
KonicaMinolta BIZHUB C352	155396	730	RADF(DF-608) PED(PC-203) FN(FS-514) FN(SD-503)	Color = 153k; B/W = 577k
KonicaMinolta BIZHUB C352	155647	193	RADF(DF-608) PU(PK-510) PED(PC-403) PC(IC-406) FN(FS-514)	Finisher came in completely disassembled- appears that some rear assembly pieces are missing (not tested); color = 165k; B/W = 28k; no printer report available
KonicaMinolta BIZHUB C352	155907	218	RADF(DF-608) PED(PC-403) FN(SD-503) FN(FS-514) FAX(FK-502)	Touch screen inoperable- cannot test machine; shows error code C-D0101 (hard drive); color = 65k; B/W = 154k
KonicaMinolta BIZHUB C352	155908	213	RADF(DF-608) PED(PC-403) FN(FS-514) FN(SD-503)	Bottom finisher tray mount dented & bent (still works); color = 91k; B/W = 122k
KonicaMinolta BIZHUB C352	155909	288	RADF(DF-608) PED(PC-403) FN(FS-514) FN(SD-503)	Touch screen inoperable- cannot test machine; color = 182k; B/W = 106k
KonicaMinolta BIZHUB C352	155913	543	RADF(DF-608) PU(PK-510) PED(PC-203) PC(IC-406) FN(FS-514)	Missing SD-503 saddlestitch option (knockouts missing); color = 455k; B/W = 88k
KonicaMinolta BIZHUB C352	156294	215	ST() RADF(DF-608) FN(FS-514) FAX(FK-502)	Goes into error code C-2253 (4 color PC motor) when trying to test color

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				copies; color = 81k; B/W = 135k
KonicaMinolta BIZHUB C352	156348	457	RADF(DF-608) PED(PC-403) FN(FS-514) FAX(FK-502)	Touch screen inoperable- unable to fully test machine; finisher trays out of alignment
Oce CM3521	156686	273	PED(PC-403) FN(FS-514) FAX(FK-502)	Color = 158k; B/W = 114k
KonicaMinolta BIZHUB C352	156700	159	RADF(DF-608) PU(PK-510) PED(PC-203) FN(FS-514)	Cracked back right side panel; color = 50k; B/W = 109k
KonicaMinolta BIZHUB C352	156701	542	RADF(DF-608) PU(PK-510) PED(PC-203) FN(FS-514)	Color = 164k; B/W = 378k
KonicaMinolta BIZHUB C352	157356	550	RADF(DF-608) PED(PC-403) FN(FS-514) FAX(FK-502)	Color = 113k; B/W = 438k
KonicaMinolta BIZHUB C450	153363	439	PED(PC-402) FN(FS-507)	Color = 11k; B/W = 429k
KonicaMinolta BIZHUB C450	154695	328	PED(PC-402) FN(FS-507)	Broken finisher trays; missing yellow, cyan and black toner cartridges; color = 104k; B/W = 224k
KonicaMinolta BIZHUB C450	155473	504	PED(PC-202) FN(FS-603)	Color = 115k; B/W = 390k
KonicaMinolta BIZHUB C450	155732	445	PED(PC-202) FN(FS-507)	Color = 125k; B/W = 320k
KonicaMinolta BIZHUB C450	155796	701	PED(PC-402) FN(FS-507) FAX(FK-502)	Broken inside bridge unit alignment pin; color = 11k; B/W = 691k
KonicaMinolta BIZHUB C450	156017	192	PED(PC-402) FN(FS-507)	Dented back panel; color = 56k; B/W = 137k
KonicaMinolta BIZHUB C450	156018	567	PED(PC-402) FN(FS-507)	Color = 97k; B/W = 471k
KonicaMinolta BIZHUB C450	156496	618	PU(PK-501) PED(PC-402) FN(FS-507) FAX(FK-502)	False jam in bridge unit - not tested; black meter = 608k; color meter = 11k
KonicaMinolta BIZHUB C450	156826	527	PU(PK-501) PED(PC-402) FN(FS-603) FAX(FK-502)	Color = 122k; B/W = 406k
KonicaMinolta BIZHUB C500	155761	1285	RADF(DF-319)	Has a FN-9 finisher (works OK); also Fiery X3E embedded controller; color = 345k; B/W = 940k
KonicaMinolta BIZHUB C500	157123	3456	RADF(DF-319) PU(PK-507) PC(IP-921) P(LT-211) INSU(PI-110) FN(FS-606)	Paper deck will not detect paper- inop; punch unit jams; color = 1840k; B/W = 1616k
KonicaMinolta DI 1610FP	153486	4	NIC(NC-5)	
KonicaMinolta DI 1610FP	154278	42		Broken front paper tray panel; broken receiving tray
Konica 7145	157327	194	PU(PK-114) PED(DB-411) PC(IP-432) FN(FS-114) FAX(FK-102A)	Very dark copies; offcolor & dirty panels
Minolta DI 650	157370	1160	PC(PI6500E) P(C-403) FN(FN-6)	Jams every copy in section 11B when finisher is attached- unable to test finisher; dented back finisher panel; jams frequently at drum area- unable to run reports; missing duplex unit knob

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7222	153025	192	ST() RADF(DF-320) PC(IP-424) FN(FS-114) FAX(FK-103)	
Konica 7222	153461	119	STK(IT-101) ST() RADF(DF-320) PC(IP-424) FAX(FK-103)	Went into error code F-26-1 (auto toner detect problem) during testing
Konica 7222	153661	188	RADF(DF-320) PED(DB-211) PC(IP-424) FN(FS-114) FAX(FK-103)	
Konica 7222	154184	147	ST() RADF(DF-320) PC(IP-424) FAX(FK-103) E()	
Konica 7222	154193	111	ST() RADF(DF-320) PC(IP-424) FAX(FK-103) E()	Blurred copies; tray #2 will not lift-
Konica 7222	155226	63	ST() RADF(DF-320) E()	
Konica 7222	155236	145	RADF(DF-320) PED(DB-211) FN(FS-114)	Blurred & streaky copies
Konica 7222	155240	179	RADF(DF-320) PED(DB-211)	
Konica 7222	155247	189	RADF(DF-320) PED(DB-211) FN(FS-114)	
Konica 7222	155291	156	RADF(DF-320) PED(DB-211) PC(IP-424) FN(FS-114) FAX(FK-103)	
Konica 7222	155325	131	ST() RADF(DF-320) E()	
Konica 7222	155398	186	ST() RADF(DF-320) E()	
Konica 7222	155400	187	RADF(DF-320) PED(DB-211) FN(FS-114)	
Konica 7222	155402	197	ST() RADF(DF-320) FN(FS-114) FAX(FK-103)	
Konica 7222	156106	66	ST() RADF(DF-320) PC(IP-424) FAX(FK-103) E()	Blurred copies
Konica 7222	157129	136	STK(IT-101) ST() RADF(DF-320) PC(IP-424)	
Konica 7228	156955	129	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	
Konica 7235	155234	388	RADF(DF-320) PED(DB-211) FN(FS-114) FAX(FK-103)	Blurred copies
Konica 7235	155364	466	RADF(DF-320) PED(DB-211) PC(IP-424) FN(FS-114)	
Minolta DI 5510	153485	219	PU(PK-5) PC(PI7200E) FN(FN-122)	Finisher trays out of alignment causing error code SC77-02; broken

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7255	155399	175 FN(FS-110)		lower finisher tray Finisher back panel dented

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.