

Wulff Enterprises

01/07/2009

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB 160	120088	14	ADF(DF-501)	Broken exit tray
KonicaMinolta BIZHUB 161F	120087	49	PFU(PF-501) NIC(NC-501)	ADF in false jam code- inop; missing exit tray
KonicaMinolta BIZHUB 161F	120092	4		Bent exit tray hinge
KonicaMinolta BIZHUB 161F	120093	19		Broken paper tray at hinges
KonicaMinolta BIZHUB 161F	120094	20	PFU(PF-501)	Missing bottom paper tray & cover (has feed unit); broken exit tray; broken top paper tray sensor (inop); missing top paper tray extender & bypass cover
KonicaMinolta BIZHUB 161F	120115	29	PFU(PF-501) NIC(NC-501)	Scanner out of alignment on right side; broken top paper tray; missing lower paper tray cover
KonicaMinolta BIZHUB 161F	123234	22		Broken exit tray; missing NIC (port cover missing)
KonicaMinolta BIZHUB 161F	123236	10		
KonicaMinolta BIZHUB 161F	123237	16	NIC(NC-501)	Broken paper tray
KonicaMinolta BIZHUB 161F	123243	8		
KonicaMinolta BIZHUB 161F	123244	4		Jams every copy- can't test
KonicaMinolta BIZHUB 161F	123246	49	PFU(PF-501)	Missing paper tray cover
KonicaMinolta BIZHUB 161F	123247	5	PFU(PF-501) NIC(NC-501)	
KonicaMinolta BIZHUB 161F	123248	31		ADF jams- inop; broken exit tray
KonicaMinolta BIZHUB 200	124609	265	ST() RADF(DF-605)	
KonicaMinolta BIZHUB 250	124338	94	RADF(DF-605) PED(PC-102)	
KonicaMinolta BIZHUB 250	124728	317	ST() RADF(DF-605) FN(FS-508) FAX(FK-503)	
KonicaMinolta BIZHUB 350	119527	292	RADF(DF-605) PED(PC-202) FAX(FK-503) E(JS-502)	Paper tray #3 will not lift- inop
KonicaMinolta BIZHUB 350	120675	206	RADF(DF-605) PED(PC-202) FN(FS-508) FAX(FK-503)	
KonicaMinolta BIZHUB 350	120678	212	RADF(DF-605) PED(PC-202) FN(FS-508) FAX(FK-503)	
KonicaMinolta BIZHUB 350	122165	175	RADF(DF-605) PED(PC-202)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB 350	122687	338	ST() RADF(DF-605) FAX(FK-503)	Broken platen glass; tray #2 will not detect paper- inop; RADF inop; deep scratches on RADF panels
KonicaMinolta BIZHUB 350	123486	256	ST() RADF(DF-605) FAX(FK-503)	
KonicaMinolta BIZHUB 350	124740	338	RADF(DF-605) PED(PC-402) FN(FS-508)	
KonicaMinolta BIZHUB 420	121107	367	PED(PC-402) PC(IC-204) FN(FS-510)	Finisher tray mounts badly bent & trays broken- inop
KonicaMinolta BIZHUB 500	120209	183	PED(PC-202) PC(IC-204) FN(FS-510)	
KonicaMinolta BIZHUB 500	122163	177	PED(PC-202) PC(IC-204) P(LU-201) FN(FS-510)	Finisher in error code C-1102 (lift motor or sensor)
KonicaMinolta BIZHUB 500	123242	210	PU(PU-501) PED(PC-402) PC(IC-204) FN(FS-511)	Broken front door hinge
KonicaMinolta BIZHUB 600	116307	329	FN(FS-602)	
KonicaMinolta BIZHUB 600	117760	220	FN(FS-504)	Damaged finisher tray mounts- trays out of alignment (inop)
Imagistics IM6020	120960	385		Error code C-2105 (corona problem?); missing finisher (has brackets); dented & bent back panel
KonicaMinolta BIZHUB 600	122603	896	FN(FS-504)	Dented back finisher panel
KonicaMinolta BIZHUB 750	120676	438	PU(PK-505) PC(IC-202) FN(FS-602)	Dented & bent back finisher panel; cracked saddlestitch tray; blurry copies
KonicaMinolta BIZHUB C350	116301	473	RADF(DF-601) PED(PC-401) DX(AD-501)	
KonicaMinolta BIZHUB C350	117070	204	ST() RADF(DF-601) FN(FS-501) DX(AD-501)	Has Peerless ZR print controller version UAB-330 w/ enabler; color = 76k; B/W = 128k; cracked duplex panel
KonicaMinolta BIZHUB C350	117503	245	RADF(DF-601) PED(PC-401) FN(FS-501) DX(AD-501)	Damaged bridge unit solenoid- wiring sliced & broken attaching hook (can't test finisher); color = 63k; B/W = 182k
KonicaMinolta BIZHUB C350	118455	294	ST() RADF(DF-601) DX(AD-501)	Black meter = 230k; color meter = 54k
KonicaMinolta BIZHUB C350	119316	567	RADF(DF-601) PED(PC-401) FN(FS-501) DX(AD-501)	Color = 18k; B/W = 550k
KonicaMinolta BIZHUB C350	119880	166	ST() RADF(DF-601) PC(IC-401) DX(AD-501)	Has a FS-603 finisher (works OK); color = 149k; B/W = 17k
KonicaMinolta BIZHUB C350	120416	499	ST() RADF(DF-601) DX(AD-501)	Color = 113k; B/W = 386k
KonicaMinolta BIZHUB C350	120475	311	RADF(DF-601) PED(PC-201) DX(AD-501)	Has Peerless ZR controller w/ fax port; Color = 30k; B/W = 281k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB C350	120694	86	RADF(DF-601) PED(PC-201) FN(FS-501) DX(AD-501)	Error code SC-C1260 (hard drive error); dented & bent back panel; color = 66k; B/W = 21k
KonicaMinolta BIZHUB C350	120711	404	ST() RADF(DF-601) DX(AD-501)	Color = 214k; B/W = 191k
KonicaMinolta BIZHUB C350	120836	230	RADF(DF-601) PED(PC-201) FN(FS-501) DX(AD-501)	Bridge unit gears broken off- can't test finisher; broken right side access door handle; RADF jams when duplexing; color = 109k; B/W = 121k
KonicaMinolta BIZHUB C350	121302	246	ST() RADF(DF-601) DX(AD-501)	Color = 11k; B/W = 236k
KonicaMinolta BIZHUB C350	121304	444	RADF(DF-601) PED(PC-201) PC(IC-401) DX(AD-501)	Color = 50k; B/W = 395k
KonicaMinolta BIZHUB C350	121488	197	RADF(DF-601) PED(PC-201) FN(FS-501) DX(AD-501)	Broken actuator switch on left side access door- can't test machine (shows open door); broken RADF plug socket; broken bridge unit plug socket; color = 110k; B/W = 88k
KonicaMinolta BIZHUB C350	121639	563	RADF(DF-601) PED(PC-401) FN(FS-501) DX(AD-501)	Missing top finisher tray
KonicaMinolta BIZHUB C350	122207	136	ST() PC(IC-401)	Missing front scanner post cover panel; color = 124k; B/W = 13k
KonicaMinolta BIZHUB C350	122409	386	RADF(DF-601) PED(PC-101) DX(AD-501)	Missing finisher; broken front door handle; color = 117k; B/W = 270k
KonicaMinolta BIZHUB C350	122504	195	RADF(DF-601) PED(PC-401) DX(AD-501)	Color = 63k; B/W = 133k
KonicaMinolta BIZHUB C350	122505	160	RADF(DF-601) PED(PC-401) DX(AD-501)	Color = 56k; B/W = 105k
Kyocera KM-C2230	122566	50	ST() RADF(DP-621) PC(FIERY X3E22C) DX(DU-621)	Color = 41k; B/W = 10k
KonicaMinolta BIZHUB C350	122904	76	RADF(DF-601) PED(PC-201) FN(FS-501) DX(AD-501)	Left back panel smashed in causing fan to click; cracked top back panel; cracked left side back panel & lower right side panel; front door handle broken off; color = 41k; B/W = 36k
KonicaMinolta BIZHUB C350	122913	245	RADF(DF-601) PED(PC-101) FN(FS-501) DX(AD-501)	Color = 47k; B/W = 198k
KonicaMinolta BIZHUB C350	123167	594	RADF(DF-601) PU(PK-501) PED(PC-201) FN(FS-601) DX(AD-501)	Color = 142k; B/W = 453k
KonicaMinolta BIZHUB C350	123216	210	ST() RADF(DF-601) PC(IC-401) FN(FS-601) DX(AD-501)	Color = 99k; B/W = 112k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta BIZHUB C350	123273	348	RADF(DF-601) PU(PK-501) PED(PC-401) FN(FS-601) DX(AD-501)	Color = 168k; B/W = 180k
KonicaMinolta BIZHUB C350	123310	210	ST() RADF(DF-601) PC(IC-401) FN(FS-501) DX(AD-501)	Color = 56k; B/W = 154k
KonicaMinolta BIZHUB C350	123647	246	ST() RADF(DF-601) PC(IC-401) FN(FS-501) DX(AD-501)	Color = 127k; B/W = 120k
KonicaMinolta BIZHUB C350	123943	148	ST() RADF(DF-601) DX(AD-501)	Color = 34k; B/W = 115k
KonicaMinolta BIZHUB C350	124100	390	RADF(DF-601) PED(PC-401) FN(FS-501) DX(AD-501)	Color = 25k; B/W = 366k
KonicaMinolta BIZHUB C350	124296	689	ST() RADF(DF-601) FN(FS-501) DX(AD-501)	Color = 12k; B/W = 677k
KonicaMinolta BIZHUB C350	124304	244	RADF(DF-601) PU(PK-501) PED(PC-101) FN(FS-601) DX(AD-501)	Finisher trays out of alignment causing error code C0B4C; needs a new image transfer belt to test; color = 109k; B/W = 135k
KonicaMinolta BIZHUB C350	124306	217	ST() RADF(DF-601) DX(AD-501)	Color = 46k; B/W = 171k
KonicaMinolta BIZHUB C350	124404	277	RADF(DF-601) PU(PK-501) PED(PC-101) FN(FS-601) DX(AD-501)	Punch unit inop; broken finisher right side access door; color = 98k; B/W = 179k
KonicaMinolta BIZHUB C350	124723	782	PED(PC-201) PC(IC-401) DX(AD-501)	Broken lower right side panel; color = 702k; B/W = 80k
KonicaMinolta BIZHUB C350	124976	177	ST() RADF(DF-601) DX(AD-501)	Color = 100k; B/W = 77k
KonicaMinolta BIZHUB C351	123550	216		Broken bridge unit plug socket; broken handles on trays #2 & #3; color = 33k; B/W = 183k; broken access panel below bypass
KonicaMinolta BIZHUB C351	124387	335	RADF(DF-601) PED(PC-202) FN(FS-507)	Broken bridge unit housing & gear assembly- can't test finisher; dented & bent lower back panel; RADF jams when duplexing; color = 219k; B/W = 117k
KonicaMinolta BIZHUB C351	124399	323	RADF(DF-601) PED(PC-102) FN(FS-507)	Dented & bent back panel; color = 91k; B/W = 233k
KonicaMinolta BIZHUB C450	115636	220	PED(PC-202)	LCD panel scratched; Black meter = 141k; colored meter = 79k
KonicaMinolta BIZHUB C450	118865	681	PED(PC-402) FN(FS-507)	Touch screen inop; broken finisher interlock actuator; broken bottom finisher tray; color = 266k; B/W = 416k
KonicaMinolta BIZHUB C450	119407	309	PED(PC-402) PC(IC-402)	Color = 304k; B/W = 6k
Imagistics CM4520	120959	409	PED(PC-402) PC(IC-402)	Missing finisher (has brackets);

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				mising service reset board inside front door; broken platen glass; dented & bent back panel; color = 39k; B/W = 370k
KonicaMinolta BIZHUB C450	122208	514	PED(PC-202) FN(FS-507)	Color = 288k; B/W = 226k
KonicaMinolta BIZHUB C450	123140	682	PU(PK-501) PED(PC-402) FN(FS-603)	Color = 43k; B/W = 640k
KonicaMinolta BIZHUB C450	123328	821	PU(PK-501) PED(PC-202) FN(FS-507)	Error code E002 (control board); bridge unit front brokn; deep scratch in front door; color = 146k; B/W =
KonicaMinolta BIZHUB C450	123370	338	ST()	Color = 93k; B/W = 245k
KonicaMinolta BIZHUB C450	123435	875	PU(PK-501) PED(PC-402) FN(FS-603)	Color = 87k; B/W = 788k
KonicaMinolta BIZHUB C450	123899	423	PU(PK-501) PED(PC-402) FN(FS-603)	Color = 90k; B/W = 333k
KonicaMinolta BIZHUB C450	124360	486	PED(PC-402) PC(IC-402) FN(FS-603)	IC-402 will not come to ready- inop; broken right side access door
KonicaMinolta BIZHUB C450	124736	596	PED(PC-402) FN(FS-603)	Broken lower right access door causing pedestal to jam; color = 101k; B/W = 496k
KonicaMinolta BIZHUB C450	124907	152	ST() FN(FS-603)	Broken top bridge unit panel at mounting post; blurred B/W copies; broken finisher interlock pin; color = 38k; B/W = 8k
KonicaMinolta BIZHUB C450	124951	128	ST() PU(PK-501) FN(FS-603)	Color = 45k; B/W = 83k
KonicaMinolta BIZHUB C500	118866	566	RADF(DF-319) PU(PK-507) P(LT-211) FN(FS-513)	Lower finisher tray out of alignment causing machine to show paper in tray; color = 468k; B/W = 99k
KonicaMinolta BIZHUB C500	120228	492	RADF(DF-319) PC(IP-901) FN(FS-606)	Has inserter unit PI-110 & trimmer unit TU-109; trimmer unit is badly damaged at attaching points- frame bent
KonicaMinolta BIZHUB C500	122838	709	PC(IP-921) FN(FS-606)	Color = 187k; B/W = 522k
KonicaMinolta BIZHUB C500	124102	493	RADF(DF-319) PU(PK-507) PC(IP-921) P(LT-211) FN(FS-606)	Color = 429k; B/W = 65k
KonicaMinolta DI 1610FP	123250	18		
KonicaMinolta DI 1610FP	123251	25		Will not detect paper- can't test; broken feed tray & exit tray
KonicaMinolta DI 1610FP	123252	64		Broken exit tray & feed tray
KonicaMinolta DI 1610FP	123253	13	PFU(PF-125)	Cracked ADF panel
KonicaMinolta DI 1610FP	123254	15	PFU(PF-125)	Broken ADF tray
KonicaMinolta DI 1610FP	123255	7		Broken exit tray & feed tray; missing NIC (port cover missing)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
KonicaMinolta DI 1610FP	123256	32	PFU(PF-125)	Broken paper tray
Konica 7020	118328	278	ST() RADF(DF-314) E()	
Konica 7020	120708	127	ST() RADF(DF-314)	Needs toner to test; dirty & offcolored panels
Konica 7020	122499	265	ST() RADF(DF-314) E()	Bypass jams- roller not turning
Konica 7020	123889	256	RADF(DF-314) PED(DB-209) PC(IP-011) NIC(KN-304) FAX(FK-101)	Pedestal paper guides broken- inop; duplex jams
Konica 7020	124055	528	RADF(DF-314) PED(DB-209) FN(FS-107)	Yellowed & dirty panels; missing left side pedestal panel
Konica 7022	114502	223	ST() RADF(DF-314) FAX(FK-102) E()	Broken RADF plug socket
Konica 7022	115344	170	ST() RADF(DF-314) FAX(FK-102) E()	Blurred copies
Konica 7022	115594	112	ST() RADF(DF-314) E()	
Konica 7022	116771	168	ST() RADF(DF-314) FAX(FK-102) E()	
Konica 7022	116774	345	ST() RADF(DF-314) FAX(FK-102) E()	Broken RADF plug socket
Konica 7022	116776	117	ST() RADF(DF-314) E()	
Konica 7022	117206	328	ST() RADF(DF-314) FAX(FK-102) E()	
Konica 7022	117491	163	ST() RADF(DF-314) E()	
Konica 7022	117962	14	ST() RADF(DF-314) E()	Dirty panels
Konica 7022	118332	224	ST() RADF(DF-314) E()	
Konica 7022	119305	273	ST() RADF(DF-314) E()	
Konica 7022	119306	117	ST() RADF(DF-314) E()	
Konica 7022	119342	117	ST() RADF(DF-314) E()	
Konica 7022	119869	82	RADF(DF-314) PED(DB-210) FN(FS-107)	Finisher tray mounts bent causing error code F-77-2; broken RADF plug socket; offcolored & dirty panels
Konica 7022	120036	228	ST() RADF(DF-314) FN(FS-107)	
Konica 7022	120295	780	ST() RADF(DF-314) E()	
Konica 7022	120331	226	ST() RADF(DF-314) E()	
Konica 7022	120474	457	ST() RADF(DF-314) FAX(FK-102) E()	
Konica 7022	120740	7	RADF(DF-314) PED(DB-210) FN(FS-107)	
Konica 7022	120753	334	ST() RADF(DF-314) PC(IP-423) FN(FS-107)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7022	120759	215	ST() RADF(DF-314) E()	
Konica 7022	121448	172	ST() RADF(DF-314) FAX(FK-102) E()	Broken left side panel on RADF
Konica 7022	121449	109	ST() RADF(DF-314) E()	
Konica 7022	121453	93	ST() RADF(DF-314) FN(FS-107)	Broken RADF plug socket
Konica 7022	122412	166	ST() RADF(DF-314) FN(FS-107) FAX(FK-102)	
Konica 7022	122413	465	ST() RADF(DF-314) E()	
Konica 7022	122955	186	ST() RADF(DF-314) PC(IP-422) FAX(FK-102) E()	
Konica 7022	123406	86	ST() RADF(DF-314) FN(FS-107)	
Konica 7022	123484	132	ST() RADF(DF-314) E()	
Konica 7022	123492	290	ST() RADF(DF-314) FN(FS-107)	
Konica 7022	123755	109	ST() RADF(DF-314) FAX(FK-102) E()	
Konica 7022	123942	274	ST() RADF(DF-314) PC(IP-423) FAX(FK-102) E()	
Konica 7022	124295	87	ST() RADF(DF-314) FN(FS-107)	Broken RADF plug socket
Konica 7022	124340	98	ST() RADF(DF-314) PC(IP-422) E()	
Konica 7022	124724	256	ST() RADF(DF-314) E()	
Konica 7022	124725	173	ST() RADF(DF-314) FN(FS-107) FAX(FK-102)	
Konica 7022	124742	64	ST() RADF(DF-314) E()	
Konica 7022	125145	65	ST() RADF(DF-314) E()	
Konica 7030	123900	346	RADF(DF-314) PED(DB-409) FN(FS-107)	
Konica 7030	124401	436	RADF(DF-314) PED(DB-209) PC(IP-421) NIC(KN-303) FN(FS-107) FAX(FK-101)	Error code 26-3 (auto-toner detect problem); broken toner bottle cover; broken finisher door at hinges; broken finisher trays; broken RADF plug socket
Konica 7033	116423	347	PED(DB-208) E()	
Konica 7033	117082	502	PED(DB-608) FN(FS-105)	
Konica 7033	119170	333	PED(DB-608) E()	Broken RADF plug socket
Konica 7033	124108	952	PED(DB-208) E()	Broken RADF plug socket
Konica 7033	124342	1068	PED(DB-608) FN(FS-105)	Offcolored panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7035	120595	155	ST() RADF(DF-314) PC(IP-421) NIC(KN-303) FN(FS-107) FAX(FK-101)	Broken RADF tray guide; yellowed panels
Konica 7035	121193	322	RADF(DF-314) PED(DB-210) FN(FS-107)	Finisher trays out of alignment, internal cable unwound & top finisher tray cracked- inop
Konica 7045	116699	437	PED(DB-608) PC(IP-431) FN(FS-109)	
Konica 7045	116704	491	PED(DB-208) FN(FS-109)	
Konica 7045	116705	771	PED(DB-208) FN(FS-109)	
Konica 7045	119745	568	PED(DB-208) PC(IP-431) FN(FS-109)	Duplex jams; distorted copies
Konica 7045	123281	1603	PED(DB-608) PC(IP-431) FN(FS-109)	
Konica 7045	124402	562	PED(DB-608) FN(FS-109)	LCT jams
Konica 7065	116316	598	FN(FS-106)	
Konica 7065	116317	961	FN(FS-106)	Scratched front door
Konica 7065	118717	1255	FN(FS-106)	
Konica 7075	117818	5317	PC(IP-601) P(LT-401) NIC(KN-302) FN(FS-108B)	Missing cable & power cord for print controller (tested with another)
Konica 7075	120844	3731	PC(IP-601) P(LT-411) NIC(KN-302) FN(FS-108)	Dented & bent paper deck door; dented & bent back finisher panel; print controller will not come to ready-inop; broken fuser cover
Konica 7075	120845	8041	PC(IP-601) P(LT-401) NIC(KN-302) FN(FS-108B)	
Konica 7075	121191	2286	FN(FS-108)	Error code SC42-04 (DC drive board or cooling fans); dented & bent left side & back panels
Konica 7075	121637	1954	PC(IP-601) P(LT-401) FN(FS-108)	Missing controller cable; paper deck inop- will not feed; offcolored panels; registration off on copies
Konica 7075	124332	2731	PC(IP-601) P(LT-411) NIC(KN-302) FN(FS-108B)	Mising print controller (has print meter of 1,351,299); scratched top front finisher panel; has inserter unit; print controller will not come to ready-inop
Minolta DI 750	124950	2434	PU(PK-1) PC(PI7500) P(C-305) FN(FN-4)	
Minolta DI 850	122861	1857	FN(FN-7)	Bent finisher panel at brackets & brackets all bent up; missing finisher tray; missing paper deck (knockouts missing)
Mita KM-8530	122971	629	P(LT-402) FN(DF-635)	Paper deck in false jam code- inop; has inserter unit

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7085	123495	2960	PC(IP-602) P(LT-402) NIC(KN-306) FN(FS-211)	Cracked top paper deck panel & dented paper deck door; dented & bent left side panel; dented & bent back finisher panel
Konica 7085	123496	3379	PC(IP-602) P(LT-402) NIC(KN-306) FN(FS-211)	Cracked finisher tray; has inserter unit
Minolta DI 850	124058	2104	P(C-403) FN(FN-7)	Has PZ-109 folding unit; broken finisher wheels- unable to align finisher to test
Minolta DI 850	124462	4306	PU(PK-7) PC(PI8500) P(C-404) FN(FN-115)	Dented & bent paper deck door
Konica 7085	124849	5906	P(LT-402) FN(FS-211)	Bypass inop- sensor not detecting paper
Konica 7130	123052	194	RADF(DF-314) PED(DB-210) PC(IP-422) FN(FS-107) FAX(FK-102)	
Konica 7130	123491	48	ST() RADF(DF-314) E()	
Konica 7135	118333	164	ST() RADF(DF-314) FN(FS-107)	
Konica 7135	122131	182	RADF(DF-314) PED(DB-410) E()	Broken RADF plug socket
Konica 7135	123215	947	ST() RADF(DF-314) PC(IP-423) FN(FS-107)	Dirty & offcolored panels
Konica 7135	123543	175	RADF(DF-314) PED(DB-210) PC(IP-423) FN(FS-107) FAX(FK-102)	Error code F26-3 (auto toner detect)
Konica 7135	124733	227	ST() RADF(DF-314) E()	
Konica 7135	125076	286	RADF(DF-314) PED(DB-210) PC(IP-423) FN(FS-107)	Broken lower finisher tray; went into error code F-26-1 (auto-toner detect) during testing
Konica 7145	118653	191	PED(DB-411) PC(IP-432) FN(FS-114)	
Konica 7145	118875	112	PS(PS-344) PED(DB-411) PC(IP-432) FN(FS-114)	Blurred copies
Konica 7145	119729	667	PED(DB-411) PC(IP-432) FN(FS-114) FAX(FK-102A)	
Konica 7145	121452	495	PED(DB-211) PC(IP-432) FN(FS-114) FAX(FK-102A)	Finisher trays damaged causing error code F-77-2 (up/down motor)
Konica 7145	121592	620	PED(DB-411) PC(IP-432) FN(FS-112)	Pedestal jams- inop
Konica 7145	121880	133	PED(DB-211) FN(FS-114)	Missing counter button; dirty & offcolored panels
Konica 7145	121881	187	PED(DB-211) FN(FS-114)	Broken front finisher rail; offcolored & dirty panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7145	121883	508	PED(DB-211) FN(FS-114)	RADF jams- inop
Konica 7145	121884	349	PED(DB-211) FN(FS-114)	Offcolored panels
Konica 7145	121924	273	PED(DB-411) FN(FS-114)	
Konica 7145	122135	385	PED(DB-411) FN(FS-114)	
Konica 7145	122370	901	PED(DB-211) PC(IP-432) FN(FS-112) FAX(FK-102A)	Could not print config page
Konica 7145	122410	692	PED(DB-411) FN(FS-114)	
Konica 7145	122560	288	PED(DB-211) FN(FS-112)	Offcolored & dirty panels
Konica 7145	122561	203	PED(DB-211) FN(FS-112)	
Konica 7145	122562	331	PED(DB-211) PC(IP-432) FN(FS-112)	Broken front door hinge; RADF jams- inop; print controller will not come to ready- inop
Konica 7145	122865	432	PED(DB-411) PC(IP-432) FN(FS-113)	Cracked finisher tray
Konica 7145	123206	1274	PED(DB-211) PC(IP-432) P(LT-203) FN(FS-112) FAX(FK-102A)	Finisher trays out of alignment- inop
Konica 7145	123482	528	PED(DB-411) FN(FS-114)	
Konica 7145	123494	229	PED(DB-411) FN(FS-114)	Machine will not recognize finisher- inop; broken finisher jam lever #3
Konica 7145	123789	1043	PED(DB-411) PC(IP-432) FN(FS-112)	
Konica 7145	123903	533	PED(DB-411) PC(IP-432) FN(FS-114) FAX(FK-102A)	Broken top finisher tray
Konica 7145	124042	554	PED(DB-211) FN(FS-112)	
Konica 7145	124046	560	PU(PK-114) PED(DB-211) PC(IP-432) FN(FS-114) FAX(FK-102A)	Broken upper finisher tray & tray mount out of alignment-inop; cracked finisher door;
Konica 7145	124048	517	PED(DB-211) FN(FS-112)	Trays #1 & #2 will not feed
Konica 7145	124050	164	PED(DB-211) E()	
Konica 7145	124057	141	PED(DB-411) PC(IP-432) FN(FS-113)	
Konica 7145	124151	506	PED(DB-211) FN(FS-112)	
Konica 7145	124335	246	PED(DB-411) PC(IP-432) FN(FS-114)	
Konica 7145	124336	383	PED(DB-411) PC(IP-432) FN(FS-114)	Finisher trays out of alignment causing error code SC77-2; broken top finisher tray
Konica 7145	124339	698	PED(DB-211) PC(IP-432) FN(FS-114)	
Konica 7145	124394	270	PED(DB-211) FN(FS-112)	
Konica 7145	124425	188	PED(DB-211) PC(IP-432) FN(FS-112)	Broken finisher inner access door

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7145	124665	575	PS(PS-344) PED(DB-411) PC(IP-432) FN(FS-112)	
Konica 7145	124737	455	PED(DB-211) PC(IP-432) FN(FS-114) FAX(FK-102A)	Finisher trays out of alignment causing error code SC-77-02
Konica 7145	124779	378	PED(DB-411) FN(FS-114)	
Konica 7145	124789	429	PED(DB-411) FN(FS-112)	Finisher trays cracked & out of alignment- finisher inop; broken top finisher door
Konica 7145	124793	299	PED(DB-411) FN(FS-114)	Broken RADF tray
Konica 7145	124794	461	PS(PS-344) PED(DB-411) PC(IP-432) FN(FS-114)	Broken RADF tray
Konica 7145	124810	248	PED(DB-411) PC(IP-432) FN(FS-113)	
Konica 7145	124850	439	PED(DB-411) FN(FS-112)	Only copies 1/2 of image from platen
Konica 7145	124851	1111	PED(DB-411) FN(FS-112)	
Konica 7145	124853	155	PU(PK-114) PED(DB-411) PC(IP-432) FN(FS-114)	
Konica 7145	124968	531	PED(DB-211) E()	
Konica 7155	116733	462	E()	
Konica 7155	116734	327	PU(PK-110) FN(FS-110)	Punch unit inop
Konica 7155	116735	204	FN(FS-110)	
Konica 7155	117814	783	PS() PC(IP-511) FN(FS-210)	
Konica 7155	117815	2393	P(LT-402) FN(FS-110)	Finisher in error code SC77-02 (up/down motor)
Konica 7155	117816	2911	P(LT-402) FN(FS-110)	
Konica 7155	117945	563	PS() PC(IP-511) FN(FS-110)	Dented lower left side panel
Konica 7155	118324	590	P(LT-402) FN(FS-110)	
Konica 7155	118327	445	E()	
Konica 7155	118449	1804	PU(PK-110) PC(IP-511) FN(FS-110)	Will not recognize tray 1(not tested); dent on rear finisher panel
Konica 7155	118659	719	PC(IP-511) FN(FS-110)	Rear panel on finisher dented
Konica 7155	118660	2133	PC(IP-511) FN(FS-110)	PC will not come to ready error code 49-01; knob for finisher jam removal missing; small dent in finisher rear panel
Konica 7155	118661	1662	PU(PK-110) PC(IP-511) P(LT-402) FN(FS-110)	
Konica 7155	118662	495	FN(FS-110)	finisher upper exit assembly does not lower; control panel not functioning properly

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7155	119103	688	PU(PK-110) PS() PC(IP-511) FN(FS-210)	Goes into error code SC49-01 (unknown) but still able to fully test; offcolored panels
Konica 7155	120180	3848	PU(PK-110) PC(IP-511) FN(FS-210)	Loose control panel- broken mounting tab; RADF jams when duplexing
Konica 7155	120379	1373	PC(IP-511) FN(FS-110)	Dented & bent upper back finisher panel
Konica 7155	120469	1455	FN(FS-110)	
Minolta DI 551	120793	1037	PU(PK-5) PC(PI6500E) FN(FN-113)	
Minolta DI 551	120830	508	PU(PK-5) FN(FN-113)	Jams every copy at registration roller- can't test
Minolta DI 551	120992	534	PU(PK-5) FN(FN-113)	
Konica 7155	121044	1302	FN(FS-210)	
Konica 7155	121045	866	PC(IP-511) FN(FS-210)	
Konica 7155	121441	2343	FN(FS-110)	RADF jams- inop
Konica 7155	121629	618	PC(IP-511) FN(FS-210)	
Konica 7155	121748	394	PC(IP-511) FN(FS-110)	
Konica 7155	121978	2453	PC(IP-511) P(LT-402) FN(FS-110)	Off colored panels
Konica 7155	122137	515	PS() PC(IP-511) FN(FS-110)	
Minolta DI 551	122383	760	PU(PK-5) FN(FN-113)	
Konica 7155	123212	407	PC(IP-511) FN(FS-110)	Cracked finisher door handle; dirty & offcolored panels
Konica 7155	123213	585	PC(IP-511) FN(FS-110)	Dented & bent back & left side panels
Minolta DI 551	123274	2140	PU(PK-5) PC(PI6500 PRO) FN(FN-113)	Missing print controller cables- not tested
Minolta DI 551	123275	1794	PU(PK-5) PC(PI6500 PRO) FN(FN-113)	Error codes E56-02 & SC46-40 (image control board); controller will not power up & missing cables; big hole in right side panel
Minolta DI 551	123276	1852	PU(PK-5) FN(FN-113)	Finisher not aligning with machine & missing bracket (not tested)
Minolta DI 551	123277	1807	PU(PK-5) FN(FN-113)	
Konica 7155	123282	360	FN(FS-110)	Stapler inop; rray #2 will not detect paper- inop
Minolta DI 551	123490	488	PU(PK-5) PC(PI6500 PRO) FN(FN-113)	Finisher entrance guide bent causing finisher to jam every copy; back finisher wheel badly bent; broken finisher door
Konica 7155	123780	932	FN(FS-110)	
Minolta DI 551	123801	589	PU(PK-5) FN(FN-113)	Dented & bent back panel

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Minolta DI 551	123939	814	PU(PK-5) PC(PI6500E) FN(FN-113)	Finisher in error code 77-02; dented & bent back panel
Konica 7155	124047	1757	PU(PK-110) FN(FS-210)	Cracked finisher handle
Konica 7155	124673	2165	PU(PK-110) PS() PC(IP-511) FN(FS-210)	Has PI-110 inserter unit
Konica 7155	124720	1138	PU(PK-110) PC(IP-511) FN(FS-210)	
Konica 7155	124788	982	PS() PC(IP-511) FN(FS-210)	Has PI-110 inserter unit
Konica 7165	116736	869	FN(FS-110)	Has inserter unit PI-110
Konica 7165	121184	917	PU(PK-110) PC(IP-511) P(LT-402) FN(FS-210)	Broken RADF tray
Minolta DI 650	121289	1206	PU(PK-5) PC(PI6500E) FN(FN-6)	Dented & bent back finisher panel; finisher grinds; has inserter unit B
Konica 7165	122563	840	FN(FS-110)	
Minolta DI 650	124816	742	PU(PK-5) FN(FN-113)	Broken finisher tray; missing paper deck (knockouts missing)
Konica 7165	124941	1813	PC(IP-511) FN(FS-210)	Has inserter unit PI-110
Konica 7222	113661	178	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	Finisher damaged- bottom tray mount badly bent; blurred copies; RADF top panel has 4 cuts in it
Konica 7222	114006	151	ST() RADF(DF-320) FAX(FK-103) E()	
Konica 7222	114260	19	ST() RADF(DF-320) E()	
Konica 7222	114705	87	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	Blurred copies
Konica 7222	115326	130	RADF(DF-320) PED(DB-211) FN(FS-114)	No image on half of copies
Konica 7222	115991	252	ST() RADF(DF-320) E()	
Konica 7222	115992	116	ST() RADF(DF-320) E()	
Konica 7222	116245	101	ST() RADF(DF-320) PC(IP-424) E(IT-101)	Jams every copy at pre-transfer roller-roller not turning
Konica 7222	116769	169	ST() RADF(DF-320) PC(IP-424) FN(FS-114) FAX(FK-103)	Finisher is smashed- inop; blurred copies
Konica 7222	116777	241	ST() RADF(DF-320) FN(FS-114)	
Konica 7222	117073	269	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	Blurred copies
Konica 7222	117958	109	ST() RADF(DF-320) PC(IP-424) E()	Dented & bent controller box
Konica 7222	118164	452	STK(IT-101) RADF(DF-320) PED(DB-211) PC(IP-424)	Blurred spot in copies

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(FK-103)	
Konica 7222	118168	181 ST()	PC(IP-424) E()	Has wrong RADF (DF-318)
Konica 7222	119008	38 ST()	RADF(DF-320) E()	
Konica 7222	119187	351 RADF(DF-320)	PED(DB-211) PC(IP-424) FN(FS-114)	
Konica 7222	119870	97 RADF(DF-320)	PED(DB-211) FN(FS-114) FAX(FK-103)	
Konica 7222	120206	69 STK(IT-101)	RADF(DF-320) PED(DB-211)	
Konica 7222	120294	68 ST()	RADF(DF-320) PC(IP-424) E()	
Konica 7222	120606	356 RADF(DF-320)	PED(DB-211) FN(FS-114)	
Konica 7222	121109	92 ST()	RADF(DF-320) E()	
Konica 7222	121918	14 ST()	RADF(DF-320) FN(FS-114)	Broken back corner on finisher rail
Konica 7222	122222	257 ST()	RADF(DF-320) FN(FS-114)	
Konica 7222	122888	162 ST()	RADF(DF-320) PC(IP-424) E()	
Konica 7222	123040	219 RADF(DF-320)	PED(DB-211) PC(IP-424) FN(FS-114) FAX(FK-103)	Broken switch in paper tray #3- inop
Konica 7222	123224	129 ST()	RADF(DF-320) E()	
Konica 7222	123233	130 ST()	RADF(DF-320) E()	
Konica 7222	123235	33 ST()	RADF(DF-320) E()	
Konica 7222	123241	123 RADF(DF-320)	PED(DB-411) E()	
Konica 7222	123283	249 ST()	RADF(DF-320) FN(FS-114)	
Konica 7222	123295	157 ST()	RADF(DF-320) PC(IP-424) E()	
Konica 7222	123488	81 ST()	RADF(DF-320) FN(FS-114)	
Konica 7222	123489	163 ST()	RADF(DF-320) FN(FS-114)	
Konica 7222	123498	169 ST()	RADF(DF-320) E()	
Konica 7222	123501	139 ST()	RADF(DF-320) PC(IP-424) FN(FS-113) FAX(FK-103)	
Konica 7222	123905	316 ST()	RADF(DF-320) PC(IP-424) FN(FS-114)	Blurred copies

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX(FK-103)	
Konica 7222	124039	288	ST() RADF(DF-320) FN(FS-114)	
Konica 7222	124201	166	ST() RADF(DF-320) PC(IP-424) FAX(FK-103) E()	Dirty & offcolored panels
Konica 7222	124343	135	ST() RADF(DF-320) E()	
Konica 7222	124388	155	ST() RADF(DF-320) FN(FS-114)	
Konica 7222	124389	156	ST() RADF(DF-320) FN(FS-114)	Blurred copies
Konica 7222	124390	192	ST() RADF(DF-320) FN(FS-114)	Machine will not detect finisher- inop; broken lower finisher tray mount; dirty & yellowed panels
Konica 7222	124391	173	ST() RADF(DF-320) FN(FS-114) FAX(FK-103)	Finisher trays out of alignment causing error code SC77-2; broken top finisher tray mount; blurred copies
Konica 7222	124392	131	ST() RADF(DF-320) FN(FS-114)	Blurred copies
Konica 7222	124734	115	ST() RADF(DF-320) E()	
Konica 7222	124780	21	ST() RADF(DF-320) FN(FS-114)	
Konica 7228	115637	262	ST() RADF(DF-320) FN(FS-114) FAX(FK-103)	Copies are blurry
Konica 7228	115638	254	ST() RADF(DF-320) FAX(FK-103) E()	Copies are blurry
Konica 7228	115990	186	ST() RADF(DF-320) FAX(FK-103) E()	
Konica 7228	119530	492	RADF(DF-320) PS(PS-346) PED(DB-211) PC(IP-424)	
Konica 7228	120476	201	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	Finisher trays out of alignment- inop; broken back finisher panel
Konica 7228	120681	456	STK(IT-101) ST() RADF(DF-320) PC(IP-424)	
Konica 7228	122133	242	ST() RADF(DF-320) PC(IP-424) FAX(FK-103) E()	
Konica 7228	122330	85	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	
Konica 7228	122867	159	ST() RADF(DF-320) FN(FS-114)	Dirty panels
Konica 7228	123033	84	ST() RADF(DF-320) FN(FS-114)	
Konica 7228	123058	99	ST() RADF(DF-320) FN(FS-114)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7228	123502	331	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	
Konica 7228	123950	186	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	
Konica 7235	113788	123	RADF(DF-320) PS(PS-346) PED(DB-411) PC(IP-424) FN(FS-114) FAX(FK-103)	Broken LCT panel; LCT will not feed
Konica 7235	113871	152	ST() RADF(DF-320) FAX(FK-103) E()	Error code F-26-3 (auto toner detect problem)
Konica 7235	113989	255	RADF(DF-320) PS(PS-346) PED(DB-211) PC(IP-424) FN(FS-114) FAX(FK-103)	Blurred copies in some areas; broken finisher latch
Konica 7235	116900	358	ST() RADF(DF-320) PC(IP-424) E()	Error code E-56-1 (communication problem between system control board & main control board)
Konica 7235	116988	172	ST() RADF(DF-320) FAX(FK-103) E()	Blurred copies
Konica 7235	119133	66	ST() RADF(DF-320) E()	
Konica 7235	120741	170	ST() RADF(DF-320) E()	Scanner is way out of position causing nearly black copies
Konica 7235	120755	335	ST() RADF(DF-320) PC(IP-424) FN(FS-114) FAX(FK-103)	Finisher trays out of alignment causing error code F-77-2 (tray motor); jams frequently- unable to fully
Konica 7235	121105	311	RADF(DF-320) PU(PK-114) PED(DB-211) PC(IP-424) FN(FS-114)	Dented & bent lower back panel; blurred copies
Konica 7235	121106	454	RADF(DF-320) PED(DB-211) PC(IP-424) FN(FS-114)	Finisher trays out of alignment- inop
Konica 7235	122407	498	RADF(DF-320) PED(DB-411) FN(FS-114)	
Konica 7235	122868	554	RADF(DF-320) PED(DB-411) PC(IP-424) FN(FS-114)	
Konica 7235	123141	161	ST() RADF(DF-320) E()	
Konica 7235	123223	40	ST() RADF(DF-320) E()	
Konica 7235	123226	48	ST() RADF(DF-320) E()	Missing access soor #6 for duplex unit- duplex inop
Konica 7235	123228	412	ST() RADF(DF-320) PC(IP-424) FN(FS-114)	Blurred copies
Konica 7235	123229	414	ST() RADF(DF-320) E()	Broken RADF tray; blurred copies
Konica 7235	123240	50	ST() RADF(DF-320) E()	RADF will not stay closed (still works); broken RADF tray
Konica 7235	123947	193	ST() RADF(DF-320) PC(IP-424) E()	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7235	124040	559	RADF(DF-320) PED(DB-411) FN(FS-114)	
Konica 7235	124341	412	RADF(DF-320) PED(DB-411) PC(IP-424) FN(FS-114)	
Konica 7255	116395	1603	PS() PC(IP-511) FN(FS-110)	Serial number on frame has been scratched out (sticker on outside of machine machines)
Konica 7255	119730	1577	PS() PC(IP-511) P(LT-402) FN(FS-110)	Paper tray #4 inop- machine will not detect it
Konica 7255	120296	1291	PS() PC(IP-511) FN(FS-110)	Dented & bent back finisher panel; noisy finisher
Konica 7255	120597	672	FN(FS-110)	Finisher in error code 77-04 (control board or motor)
Konica 7255	120743	299	PU(PK-110) PC(IP-511) FN(FS-110)	Machine in false jam code- will not clear; dented & bent back finisher panel; badly scratched front door
Konica 7255	120756	716	FN(FS-110)	Dented & bent back finisher panel; missing finisher tray; bent lower back panel in corner
Konica 7255	120757	1216	PC(IP-511) FN(FS-210)	
Konica 7255	121111	470	PU(PK-110) PC(IP-511) P(LT-402) FN(FS-110)	Print controller inop- hard drive will not initialize; dented finisher panels
Minolta DI 5510	121575	767	PC(PI7200E) FN(FN-10)	Finisher jams every copy- inop
Minolta DI 5510	121861	812	PC(PI7200E) FN(FN-10)	
Minolta DI 5510	121862	342	PC(PI7200E) FN(FN-10)	RADF jams when duplexing
Minolta DI 5510	122182	167	PU(PK-5) P(C-403) FN(FN-122)	False jam code in tray #4- unable to clear (cannot test)
Minolta DI 5510	122183	187	PU(PK-5) FN(FN-122)	Dented back panel
Minolta DI 5510	122211	1172	PU(PK-5) PC(PI7200E) FN(FN-122)	
Minolta DI 5510	122212	628	PU(PK-5) PC(PI7200E) FN(FN-122)	
Minolta DI 5510	122213	862	PU(PK-5) PC(PI7200E) FN(FN-122)	
Minolta DI 5510	122214	1056	PU(PK-5) PC(PI7200E) FN(FN-122)	Damaged finisher paper entrance guides causing it to jam
Konica 7255	122221	541	PS() PC(IP-511) P(LT-402) FN(FS-110)	
Minolta DI 5510	122276	195	PU(PK-5) PC(PI7200E) FN(FN-122)	
Minolta DI 5510	122673	953	PC(PI7200E) FN(FN-10)	Has inserter unit B
Minolta DI 5510	122905	212	PU(PK-5) PC(PI7200E) FN(FN-121)	Dented & bent back finisher panel

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 7255	122922	808	FN(FS-110)	
Konica 7255	122923	854	PC(IP-511) FN(FS-110)	Scratched back panel
Minolta DI 5510	123128	1275	PU(PK-5) PC(PI7200E) FN(FN-122)	
Minolta DI 5510	123138	460	PC(PI7200E) FN(FN-10)	
Konica 7255	123329	837	PC(IP-511) FN(FS-110)	
Konica 7255	123499	1085	PU(PK-120) FN(FS-110)	Broken LCT panel; lower finisher tray mount bent & tray will not cycle; broken finisher exit switch; dented & bent back finisher panel; cracked top finisher tray
Konica 7255	123898	1006	FN(FS-110)	
Konica 7255	123945	1016		
Konica 7255	124337	1553	PC(IP-511) P(LT-402) FN(FS-111)	
Konica 7255	124735	2013	PC(IP-511) FN(FS-110)	
Konica 7255	124738	1500	PU(PK-110) FN(FS-110)	
Konica 7255	124821	285	PU(PK-110) PC(IP-511) FN(FS-210)	Cracked saddlestitch tray
Konica 7255	124822	249	PU(PU-109) FN(FS-110)	
Minolta DI 7210	122046	754	PU(PK-5) PC(PI7200E) FN(FN-121)	Print controller in error code SC49-01 (PC Fault code)- not tested; stapler inop; dented & bent back finisher panel
Minolta DI 7210	122047	419	PU(PK-5) PC(PI7200E) FN(FN-121)	
Minolta DI 7210	122198	1231	PU(PK-5) FN(FN-121)	Has AHT Oncore external print controller
Konica 7272	122775	867	FN(FS-111)	Scratches on control panel
Konica 7272	122910	2418	PC(IP-511) P(LT-402) FN(FS-210)	Paper deck feed guide all bent up- can't test; bent back paper deck panel; Has inserter unit PI-110
Minolta DI 7210	122924	623	PU(PK-5) FN(FN-121)	
Konica 7272	124106	2421	PC(IP-511) P(LT-402) FN(FS-110)	Bent paper deck door; cracked lower finisher tray; dented & bent back finisher panel
Minolta DI 7210	124298	732	PU(PK-5) PC(PI7200E) FN(FN-122)	Broken finisher tray
Konica 8020	115251	99	RADF(DF-332) PFU(PF-232 [B]) PC(FIERY = 76k; B/W = 23k X3E+) DX(AD-231)	Missing finisher (has brackets); color
Konica 8020	116985	533	RADF(DF-332) PED(DB-432) PC(FIERY X3E+) DX(AD-231)	Print controller will not come to ready- inop; Color = 89k; B/W = 445k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Konica 8020	118451	194	ST() PC(FIERY X3E+) DX(AD-231)	Black meter = 40k; colored meter = 155k
Konica 8020	120134	32	ST() RADF(DF-332) PC(FIERY X3E+) FN(FS-231) DX(AD-231)	Color = 24k; B/W = 8k
Konica 8020	120671	26	ST() RADF(DF-332) PC(FIERY X3E+) FN(FS-135) DX(AD-231)	LCD is calling for key counter- unable to clear; duplex unit will not close properly; color = 17k; B/W = 9k
Konica 8020	120835	391	RADF(DF-332) PFU(PF-232 [B]) PC(FIERY X3E+) FN(FS-135)	Machine will not come to ready (bas canner cable?); was able to generate config pages; cracked finisher tray; color = 181k; B/W = 210k
Konica 8020	121948	24	ST() PC(FIERY X3E+)	Print controller inop- calling for setup; color = 24k; B/W = 1k
Konica 8020	122184	83	RADF(DF-332) PFU(PF-232 [B]) PC(FIERY X3E+) FN(FS-231)	Finisher in error code C0BA0 (elevator motor); color = 80k; B/W =
Konica 8020	122369	237	ST() PC(FIERY X3E+) FN(FS-135) DX(AD-231)	Bridge unit broken - finisher not tested; error code C-0500 -fuser belt (machine not tested); black meter =75k; colored meter =163k
Konica 8020	123503	149	RADF(DF-332) PED(DB-432) PC(FIERY X3E+) FN(FS-135) DX(AD-231)	Offcolored panels; color = 126k; B/W = 24k
Konica 8020	123788	155	ST() RADF(DF-332) PC(FIERY X3E+)	Color = 128k; B/W = 27k
Konica 8020	124424	45	RADF(DF-332) PFU(PF-232 [B]) PC(FIERY X3E+) FN(FS-231)	Color = 27k; B/W = 19k
Konica 8031	124787	16	RADF(DF-332) PFU(PF-232 [B]) FN(FS-135) DX(AD-231)	Error code C-0010 (cyan PC motor); broken lower finisher tray; color = 13k; B/W = 4k
Konica 8031	124795	73	RADF(DF-332) PED(DB-432) PC(FIERY X3E+) FN(FS-231) DX(AD-231)	Broken bottom finisher panel; color = 58k; B/W = 15k
Konica 8050	122327	678	RADF(DF-319) PC(IP-921) P(LT-211) FN(FS-115)	Error codes SC46-59 (CCD board), SC46-11 (unknown), & SC46-25 (image processing abnormality); color = 468k; B/W = 205k
Konica 8050	122857	438	RADF(DF-319) PC(IP-921) P(LT-211) E()	Control panel will not respond- can't test; color = 177k; B/W = 261k
Konica 8050	123285	939	RADF(DF-319) PC(IP-921) P(LT-211) FN(FS-215)	Color = 614k; B/W = 326k
Konica 8050	124240	669	RADF(DF-319) PC(IP-921) FN(FS-215)	Error code SC33-01 (fuser)

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.