

Wulff Enterprises

02/10/2012

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-1820	191606	16	FAX(K) ADF(DP-100)	Off color panels, Bypass not feeding paper - not tested, ADF left hinge broken, jamming in ADF - not tested
Kyocera KM-2050	185182	31	ST() RADF(DP-410)	Off color panels
Kyocera KM-2050	188444	70	ST() RADF(DP-410) DX(DU-410)	Does not allow duplex shows "cannot combine" - not tested
Kyocera KM-2050	189415	19	ST() SCAN(F) RADF(DP-410) FAX(L) E(JS-410) DX(DU-410)	Jamming in RADF when duplexing
Kyocera KM-2050	189431	130	ST() SCAN(F) RADF(DP-410) FAX(L) E(JS-410) DX(DU-410)	
Kyocera KM-2050	189571	69	ST() SCAN(F) RADF(DP-410) DX(DU-410)	
Copystar CS-2050	191319	119	RADF(DP-410)	
Kyocera KM-2050	192014	76	ST() RADF(DP-410) FAX(L) DX(DU-410)	Blurry copies
Kyocera KM-2550	188008	37	ST() SCAN(F) RADF(DP-410) FAX(L) E(JS-410) DX(DU-410)	Unable to duplex - cannot select
Kyocera KM-2550	188536	36	ST() RADF(DP-410) FN(DF-410) DX(DU-410)	
Kyocera KM-3040	173220	127	ST() RADF(DP-670)	Off color panels
Kyocera KM-3040	190044	351	ST() RADF(DP-670)	
Kyocera KM-3040	190046	373	ST() RADF(DP-670)	
Kyocera KM-3040	191859	109	ST() RADF(DP-670) FAX(P) E(JS-670)	
Kyocera KM-3050	188411	312	ST() FN(DF-730) DSPF(DP-700)	
Copystar CS-3050	189095	673	ST() FAX(M) DSPF(DP-700)	
Kyocera KM-3050	189434	358	ST() FAX(M) E(JS-700) DSPF(DP-700)	
Kyocera KM-3050	189435	837	ST() FAX(M) E(JS-700) DSPF(DP-700)	Bypass grinding - not tested
Kyocera KM-3050	189436	1278	ST() FAX(M) E(JS-700) DSPF(DP-700)	
Kyocera KM-3050	189437	481	ST() FAX(M) E(JS-700) DSPF(DP-700)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-3050	189438	1328	ST() FAX(M) E(JS-700) DSPF(DP-700)	Jamming in duplexer - not tested
Kyocera KM-3050	191726	330	ST() FN(DF-720) DSPF(DP-700)	
Kyocera KM-3060	178084	273	ST() RADF(DP-670)	
Copystar CS-3060	184808	244	ST() RADF(DP-670) FAX(M)	
Kyocera KM-3060	186612	632	ST() RADF(DP-670)	Jams in RADF - not tested
Kyocera KM-4050	190052	323	ST() FAX(M) DSPF(DP-700)	Stand frame bent, stand drawer not closed
Kyocera KM-4050	190806	498	ST() FN(DF-730) FAX(M) DSPF(DP-700)	
Kyocera KM-4050	191736	323	ST() FN(DF-730) DSPF(DP-700)	
Kyocera KM-4050	191929	803	PU(PH-5A) PED(PF-750) FN(DF-710) DSPF(DP-700)	
Kyocera KM-4050	191930	252	PU(PH-5A) PED(PF-750) FN(DF-710) DSPF(DP-700)	
Kyocera KM-4050	191931	494	ST() DSPF(DP-700)	
Kyocera KM-4050	191932	474	PU(PH-5A) PED(PF-750) FN(DF-710) DSPF(DP-700)	
Kyocera KM-4050	191993	305	ST() FN(DF-710) DSPF(DP-700)	
Kyocera KM-4050	192591	369	ST() DSPF(DP-700)	
NEC IT5050	185764	N/A	RADF(DP-700) PU(PH-5A) PED(PF-750) FN(DF-710)	Needs user ID - not able to access system menu- not tested
Kyocera KM-5050	189154	905	ST() FN(DF-730) FAX(M) DSPF(DP-700)	Cassette #1 not lifting paper - not tested
Kyocera KM-5050	189191	507	ST() FN(DF-730) DSPF(DP-700)	
Kyocera KM-5050	189441	1158	ST() FAX(M) E(JS-700) DSPF(DP-700)	
Kyocera KM-5050	192589	295	ST() DSPF(DP-700)	
Kyocera KM-6030	185663	612	PU(PH-4) FN(DF-650)	Error code C0330 - relay board problem - not tested, off color panels, has hardware for paper deck - missing paper deck
Kyocera KM-6030	185680	2243	PU(PH-4) FN(DF-650)	
Copystar CS-6030	189550	2468	FN(DF-650)	
Kyocera KM-6030	191008	2216	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	
Copystar CS-6030	191749	1263	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	Has mailbox - MT-1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-6030	191969	468	FN(DF-650)	Jamming in stapler - not tested
Kyocera KM-6030	192586	949	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	Cassette #3 not feeding - not tested, controller box dented
Kyocera KM-6030	192588	734	PU(PH-4) FN(DF-650)	Touch screen not responding - not fully tested, LCD panel blank
Kyocera KM-8030	182406	1113	PU(PH-4) FN(DF-650)	
Kyocera KM-8030	185187	1708	FN(DF-650)	
Kyocera KM-8030	191934	785	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	Jamming at registration during duplexing - not tested
Kyocera KM-8030	191935	910	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	
Copystar CS-8030	192657	184	SCAN(G) PU(PH-4) PC(V) FN(DF-650)	
Kyocera KM-C2520	180078	334	ST() RADF(DP-710) PU(PH-5A) FN(DF-710) E(JS-710)	Black meter = 163k, color meter = 171k
Kyocera KM-C2520	189200	144	ST() RADF(DP-710)	Off color panels, black meter = 114k, color meter = 31k
Copystar CS-C2520	190400	329	ST() RADF(DP-710) FAX(N) E(JS-710)	Off color panels, black meter = 262k, color meter - 68k
Kyocera KM-C2520	191139	296	ST() RADF(DP-710)	Jamming in bypass - not tested, void lines on copies, black meter = 280k, color meter = 17k
Kyocera KM-C2520	191725	147	ST() RADF(DP-710)	Black meter = 119k, color meter = 28k
Copystar CS-C2520	192621	260	ST() RADF(DP-710)	Jamming out of cassette #2, black meter = 158k, color meter = 102k
Kyocera KM-C2525E	188446	254	ST() RADF(DP-710) FAX(N) E(JS-710)	Black meter = 206k, color meter = 48k
Copystar CS-C2525E	189266	326	ST() RADF(DP-710)	Touch screen not responding - not fully tested; touch screen loose at left hinge
Copystar CS-C2525E	191516	161	ST() RADF(DP-710)	Black meter = 138k, color meter = 23k
Kyocera KM-C2525E	191729	85	ST() RADF(DP-710) FAX(N) E(JS-710)	Black meter = 80k, color meter = 6k
Kyocera KM-C2525E	191735	282	ST() RADF(DP-710) FN(DF-730)	Black meter = 188k, color meter = 94k
Kyocera KM-C3225	180898	545	RADF(DP-710) PED(PF-710) FN(DF-710) FAX(N) E(JS-710)	Finisher trays missing, black meter = 394k, color meter = 152k
Kyocera KM-C3225	181607	216	ST() RADF(DP-710) PU(PH-5A) FN(DF-710) FAX(N) E(JS-710)	Black meter = 171k, color meter = 45k
Copystar CS-C3225	183869	692	ST() RADF(DP-710)	Yellow and off color, black meter = 577k, color meter = 115k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C3225	186027	215	RADF(DP-710) PED(PF-750) FN(DF-730) FAX(N) E(JS-710)	Top finisher access door broken - finisher not tested, cassette #2 jamming, black meter = 210k, color meter = 6k
Kyocera KM-C3225	188531	248	ST() RADF(DP-710)	Color = 156k; B/W = 92k
Kyocera KM-C3225	190780	214	ST() RADF(DP-710) PU(PH-5A) FN(DF-710)	BLack meter = 91k, color meter = 123k, dark lines on black copies
Kyocera KM-C3225	191866	238	ST() RADF(DP-710) E(JS-710)	Black meter = 222k, color meter = 160k
Kyocera KM-C3225E	174887	185	ST() RADF(DP-710)	Color = 19k; B/W = 166k
Kyocera KM-C3225E	177271	277	ST() RADF(DP-710) FN(DF-730) FAX(N) E(JS-710)	Touch screen not responding - not tested, hard-drive removed
Copystar CS-C3225E	179722	160	ST() RADF(DP-710) FN(DF-730) E(JS-710)	Black meter = 80k, color meter = 80k
Kyocera KM-C3225E	180073	234	ST() RADF(DP-710) E(JS-710)	Black meter = 195k, color meter = 39k
Kyocera KM-C3225E	180321	234	ST() RADF(DP-710) FAX(N) E(JS-710)	Off color panels, black meter = 195k, color meter = 39k
Kyocera KM-C3225E	181604	160	ST() RADF(DP-710) FAX(N) E(JS-710)	Black meter = 105k, color meter = 54k
Kyocera KM-C3225E	186350	222	ST() RADF(DP-710) PU(PH-5A) FN(DF-710) FAX(N)	Touch screen not responding - not tested, hard-drive removed, yellow panels
Kyocera KM-C3225E	188010	225	ST() RADF(DP-710)	Black meter = 167k, color meter = 58k
Kyocera KM-C3225E	189870	73	ST() RADF(DP-710)	Black meter = 55k, color meter = 18k
Kyocera KM-C3232	180896	538	ST() RADF(DP-710)	Black meter = 516k, color meter = 23k
Kyocera KM-C3232	183409	N/A	RADF(DP-710) PED(PF-710) FN(DF-710)	Touch screen not responding - not tested - removed hard-drive
Copystar CS-C3232	183897	526	ST() RADF(DP-710) FN(DF-710)	Black meter = 466k, color meter = 61k
Kyocera KM-C3232	184704	185	RADF(DP-710) PU(PH-5A) FN(DF-710) E(JS-710)	Jamming in cassette #2 - not tested, black meter = 76k, color meter = 110k
Copystar CS-C3232	184728	322	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710) FAX(N) E(JS-710)	Duplex jams; Color = 72k; B/W = 250k; very light copies
Kyocera KM-C3232	185981	243	RADF(DP-710) PU(PH-5A) PED(PF-710) FN(DF-710) E(JS-710)	Black meter = 165k, color meter = 78k
Kyocera KM-C3232	190448	397	RADF(DP-710) PU(PH-5A) PED(PF-750) FN(DF-710) FAX(N)	Jamming in LCT - not tested, machine not fully tested- hard-drive bad
Kyocera KM-C3232E	174064	244	ST() RADF(DP-710) FN(DF-730) E(JS-710)	Duplex - inop not tested; black meter = 121k; color meter = 123k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Kyocera KM-C3232E	174065	193 ST()	RADF(DP-710) FN(DF-730) E(JS-710)	Black meter = 57k; color meter = 136k
Kyocera KM-C3232E	177643	117 ST()	RADF(DP-710)	Black meter = 111k, color meter = 6k
Kyocera KM-C3232E	179067	338 ST()	RADF(DP-710) FAX(N) E(JS-710)	Touch screen froze up during testing- unable to fully test
Kyocera KM-C3232E	179071	214 ST()	RADF(DP-710)	Color = 12k; B/W = 203k
Kyocera KM-C3232E	188355	489 ST()	RADF(DP-710) PU(PH-5A) FN(DF-710) FAX(N)	Falser paper indicator in RADF - not tested, partial image on copies, off color, black meter = 202k, color meter 287k
Kyocera KM-C4035E	172777	505 RADF(DP-710)	PU(PH-5A) PED(PF-750) FN(DF-710) FAX(N) E(JS-710)	Black meter = 239k; color meter = 267k
Kyocera KM-C4035E	174321	190 ST()	RADF(DP-710)	Black meter = 150k; color meter = 40k; bypass paper feed tire broken - not tested
Copystar CS-C4035E	175131	213 RADF(DP-710)	PED(PF-700)	Black meter = 159k; color meter = 55k
Copystar CS-C4035E	178837	350 RADF(DP-710)	PED(PF-700) FN(DF-710) E(JS-710)	False jam in finisher - not tested, black meter = 28k, color meter = 323k
Kyocera KM-C4035E	179070	365 ST()	RADF(DP-710) FAX(N) E(JS-710)	Color = 21k; B/W = 345k
Kyocera KM-C4035E	184705	111 RADF(DP-710)	PU(PH-5A) PED(PF-750) FN(DF-710) E(JS-710)	Jamming out of cassette #2, black meter = 60k, color meter = 52k
Kyocera KM-C4035E	186568	759 ST()	RADF(DP-710) FN(DF-710)	Black meter = 667k, color meter = 93k
Kyocera KM-C4035E	186571	385 ST()	RADF(DP-710) PU(PH-5A) FN(DF-710)	Color = 247k; B/W = 138k
Copystar CS-C4035E	187136	225 RADF(DP-710)	PU(PH-5A) PED(PF-700) FN(DF-710) E(JS-710)	Finisher trays missing - finisher not tested, black meter = 83k, color meter = 143k
Copystar CS-C4035E	187949	202 RADF(DP-710)	PU(PH-5A) PED(PF-750) FN(DF-710)	Jamming in bypass, black meter = 115k, color meter = 88k
Kyocera KM-C4035E	191862	416 RADF(DP-710)	PU(PH-5A) PED(PF-750) FN(DF-710) E(JS-710)	Black meter = 373k, color meter = 43k
Kyocera KM-C4035E	192666	902 RADF(DP-710)	PED(PF-700) FAX(N) E(JS-710)	Touch screen not responding - not fully tested
Kyocera KM-C850D	187200	155 SCAN(C)	RADF(SRDF-2) PFU(PF-35) PC(S) FAX(G)	Black meter 148k, color meter = 7k
Copystar CS 500CI	190799	433 RADF(DP-750)	PU(PH-5A) PED(PF-720) FN(DF-760)	Black meter = 299k, color meter = 135k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Copystar CS 500CI	190800	435	ST() RADF(DP-750) PU(PH-5A) PED(PF-720) FN(DF-760)	Error code C0630 - DMA transmission of compressed, decompressed, rotated, relocated, or blanked out image data - not tested, RADF socket bent, scanner bent
Kyocera TASKALFA 820	191730	1617	SCAN(H) PU(PH-4A) PC(W) FN(DF-650B)	Jamming in cassette #4 - not tested
Kyocera TASKALFA 820	191731	1621	SCAN(H) PU(PH-4A) PC(W) FN(DF-650B)	
Copystar CS-1500	183828	N/A	PFU(PF-17)	Only prints quarter of image on paper, yellow and off color panels
Copystar CS-2030	178816	160	ST() FAX(B) ADF(STDF-3)	Yellow panels
Copystar CS-2030	182692	N/A	ST() PFU(ST-12 [B]) FAX(B) ADF(STDF-3)	Yellow, password protected - not tested
Mita KM-3035	189924	24	ST()	Yellow panels
Copystar CS-3035	190444	1979	ST() RADF(SRDF-2)	
Mita KM-3035	192203	659	ST() RADF(SRDF-2) PC(U) FN(DF-73) FAX(J)	RADF plug socket broken
Mita KM-3035	192592	91	ST() RADF(SRDF-2)	
Copystar CS-4035	187772	185	ST() RADF(SRDF-2)	Almost blank copies
Mita KM-4035	192587	451	ST() RADF(SRDF-2)	
Mita KM-5035	187455	1411	RADF(SRDF-2) PED(PF-75) PC(U) FN(DF-71U) FAX(J)	Off color and dirty panels, jamming out of cassette #2 - not tested
Mita KM-5035	192015	736	ST() RADF(SRDF-2) PC(U) FN(DF-71U)	Error code C0240 - communication problem between main board and PC board - PC not tested, RADF plug socket broken, top finisher panel yellow
Mita KM-5035	192614	355	RADF(SRDF-2) PED(PF-75) FN(DF-73)	Back panel dented

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.