

Wulff Enterprises

02/10/2012

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD060	192034	3116	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Cassette #2 not feeding - not tested, jamming in stapler jogger - stapler not tested
Lanier LD060	192145	875	PU(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Hard-drive error - hard-drive missing - not fully tested
Lanier LD015SPF	190588	210	PFU(PS480)	
Lanier LD120	191550	174	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018)	Has ARDF - DF2010
Lanier LD127	183097	254	ST() RADF(DF75) PC(TYPE 2027)	Off color panels
Lanier LD127	190582	43	RADF(DF75) PED(PS500) PC(TYPE 2027) FAX(TYPE 2027)	Bypass tray broken - not tested, has bridge unit - missing finisher, bridge unit socket broken
Lanier 5222	162295	310	ST() RADF(RADF-527) DX(ADM-527)	Yellowed panels
Lanier LD232C	190186	567	PED(PS540) FAX(TYPE 2238) E(PT460)	Yellow panels, black meter = 414k, color meter = 154k
Lanier LD232C	192046	261	ST() E(PT460)	Yellow panels, Back panel dented, frame dented on left side, black meter = 185k, color meter = 76k
Lanier LD225	181843	212	ST() RADF(DF83) PC(TYPE 3030 (S))	Cassette #1 will not lift - error code SC501 - not tested
Lanier LD225	190589	490	ST() RADF(DF83) PC(TYPE 3030 (S)) FAX(TYPE 3030) E(PT280)	RADF yellow, off color panels, bypass tray broken
Lanier LD230	180399	393	ST() RADF(DF83)	Missing Doc server, printer and scan features - has buttons
Lanier LD245	190590	629	PED(PS530) FN(SR790)	
Lanier LD124C	183865	57	ST() FAX(TYPE 3232)	Jamming out of cassette #2, black meter = 49k, color meter = 9k
Lanier LD160C	172965	3655	PU(TYPE 3260) PS(TYPE 3260) PC(TYPE 3260) FN(SR970)	Unable to clear login code- ran in SP mode; color = 286k; B/W = 3369k; blurred color copies
Lanier LD160C	181851	627	PC(FIERY E-7000) FN(SR980)	Black meter = 115k, color meter = 513k
Lanier LD160C	182863	836	PU(TYPE 1075) PC(TYPE 3260) FN(SR970)	Finisher tray off color, black meter = 409k, color meter = 427k
Lanier LC155	191392	890	PC(TYPE 3260) FN(SR970)	Lower finisher tray yellow, black meter = 855k, color meter = 36k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD016SPF	191383	128		
Lanier LD117SPF	192036	95		
Lanier LD117SPF	192037	67		
Lanier LD320D	181335	266	ST() RADF(DF2010)	
Lanier LD320D	185778	106	ST() RADF(DF2010) FAX(TYPE 2000)	
Lanier LD320D	192086	84	ST() RADF(DF2010) FAX(TYPE 2000)	Registration off on copies
Lanier LD320D	192474	184	ST() RADF(DF2010) PC(TYPE 2000) FAX(TYPE 2000)	
Lanier LD320D	192779	55	ST() RADF(DF2010) FAX(TYPE 2000)	
Lanier LD125	181841	27	ST() RADF(DF3020) FN(SR3010)	
Lanier LD325	182826	123	ST() RADF(DF83)	Has PC and scanner buttons on control panel installed
Lanier LD325	182867	255	ST() RADF(DF83) PC(TYPE 3010)	RADF off color
Lanier LD325	182868	201	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	
Lanier LD325	182869	270	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030) E(PT280)	Bypass tray broken
Lanier LD325	182870	258	ST() RADF(DF83) PC(TYPE 3010)	Missing finisher - has bridge unit, not fusing to paper
Lanier LD325	185608	100	ST() RADF(DF83) FN(SR820)	
Lanier LD325	185699	286	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030)	
Lanier LD325	187738	1140	ST() RADF(DF83) PC(TYPE 3010)	Bypass hinge broken
Lanier LD325	187739	524	ST() RADF(DF83) PC(TYPE 3010)	Jamming out of cassette #1
Lanier LD325	187740	440	ST() RADF(DF83) PC(TYPE 3010)	
Lanier LD325	187741	364	ST() RADF(DF83) PC(TYPE 3010) FAX(TYPE 3030)	RADF yellow
Lanier LD325	187744	145	ST() RADF(DF83) PC(TYPE 3010)	
Lanier LD325	189466	43	ST() RADF(DF83) FN(SR820)	Touch screen not responding - not fully tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD325	192041	61	ST() RADF(DF83) PC(TYPE 3010) FN(SR820) FAX(TYPE 3030) E(PT280)	Not feeding in bypass - not tested
Lanier LD425	181831	148	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	
Lanier LD425	183100	31	ST() RADF(DF3030)	Dirty, yellow, jams in bypass - not tested
Lanier LD425	184612	311	ST() RADF(DF3030) PC(TYPE 3350 (S))	Jamming out of cassette #1 and bypass
Lanier LD425	184613	267	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350)	
Lanier LD425	184614	487	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350)	Duplexer deflector broken - not tested
Lanier LD425	186897	104	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	
Lanier LD425	186899	352	ST() RADF(DF3030) PC(TYPE 3350 (S)) FAX(TYPE 3350) E(BN3030)	
Lanier LD425	189976	32	ST() RADF(DF3030) FAX(TYPE 3350)	
Lanier LD425	191093	183	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	Control panel yellow
Lanier LD425	191104	118	ST() RADF(DF3030) FN(SR790)	Jamming in RADF - not tested, jamming in stapler unit - not tested
Lanier LD425	191983	82	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	Finisher covers yellow, false jam in fuser - not tested
Lanier LD425	192102	85	ST() RADF(DF3030) FAX(TYPE 3350) E(BN3030)	
Lanier LD330	179386	105	ST() RADF(DF83) PC(TYPE 3010) FN(SR790)	Yellow panels
Lanier LD330	181536	351	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030) E(PT280)	Missing finisher exit tray
Lanier LD330	185786	324	ST() RADF(DF83) PS(TYPE 3010) PC(TYPE 3010) FAX(TYPE 3030)	Bypass tray broken, RADF yellow
Lanier LD433	177258	226	RADF(DF3030) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD433	177259	88	ST() RADF(DF3030) FN(SR790)	
Lanier LD433	184615	262	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	#0748
Lanier LD433	184616	255	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790)	
Lanier LD433	184617	349	RADF(DF3030) PED(PS500) PC(TYPE 3350 (S)) FN(SR790)	Lower right side access door on PED broken
Lanier LD433	189342	163	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR790) FAX(TYPE 3350)	Missing finisher control board- finisher inop
Lanier LD335	182884	646	ST() PC(TYPE 4500) FN(SR790)	Off color and dirty panels
Lanier LD335	184670	594	PED(PS530) PC(TYPE 4500) FN(SR790)	
Lanier LD335	191094	242	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	Yellow panels
Lanier LD040	178247	512	ST() FN(SR790)	
Lanier LD040	178542	240	PED(PB3040) PC(TYPE 5000 (S))	
Lanier LD040	182570	368	ST() PC(TYPE 5000 (S)) E(BN3040)	
Lanier LD040	183667	86	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000) E(BN3040)	Control panel cover yellow
Lanier LD040	184143	525	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Lanier LD040	184478	635	PS(TYPE 5000) PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Lanier LD040	185782	418	ST() PS(TYPE 5000) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Control panel cover yellow
Lanier LD040	185785	559	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	
Lanier LD040	189341	333	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE	Yellowed control panel and finisher panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD040	189343	300	5000) ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Yellowed panel around touch screen; RADF will not feed- inop
Lanier LD040	191100	1241	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	PED not recognizing paper - not tested
Lanier LD040	191101	789	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	Dirty panels
Lanier LD040	191102	483	PED(PB3050) PC(TYPE 5000 (S)) FAX(TYPE 5000)	Missing finisher - has bridge unit
Lanier LD040	191103	426	PU(TYPE 3260) PED(PB3050) PC(TYPE 5000 (S)) FN(SR3030) FAX(TYPE 5000)	Finisher tray missing
Lanier LD040	192087	127	ST() FAX(TYPE 5000)	
Lanier LD345	184761	374	ST() PS(TYPE 4500) PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Lanier LD345	192162	157	PED(PS530) PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Lanier LD345	192210	672	PED(PS530) PC(TYPE 4500) FN(SR790)	Off color panels, Missing fax - has control panel button
Lanier LD345	192364	583	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045) E(PT330)	Off color panels, toner spilled in machine, jamming in bypass - not fully tested -shows false jam
Lanier LD050	184469	439	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Jamming out of cassette #1
Lanier LD050	185781	500	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Control panel yellow
Lanier LD050	185784	476	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	Control panel yellow
Lanier LD050	188399	686	PS(TYPE 5000) PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000) E(BN3040)	
Lanier LD050	189338	336	PED(PB3050) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Yellowed panel around touch screen

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD050	189340	427	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Yellowed panel around touch screen
Lanier LD255	192467	2489	PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	
Lanier LD255	192468	2642	PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	
Lanier LD260	189339	456	PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	
Lanier LD270	190043	874	PU(TYPE 3260) PC(TYPE 8000) FN(SR970)	
Lanier LD275	192157	2131	PC(TYPE 7500) FN(SR970)	
Lanier LD280	192829	890	PU(TYPE 3260) FN(SR970)	
Lanier LD420C	181199	71	ST() PS(TYPE C3000)	Color = 20k; B/W = 52k
Lanier LD420C	188339	248	ST()	Black meter = 173k, color meter = 75k
Lanier LD420C	192306	317	ST() FAX(TYPE MPC3000)	Front door cracked, black meter = 225k, color meter = 93k
Lanier LD520C	184666	54	ST()	Lower right side door broken, black meter = 32k, color meter = 22k
Lanier LD520C	184667	42	ST()	Yellow, ground in dirt, jamming in duplexer - deflector broken, error code SC536 - junction gate solenoid fan error - not fully tested, black meter = 37k, color meter = 6k
Lanier LD520C	192305	88	ST() FAX(TYPE C2550)	Black meter = 62k, color meter = 27k
Lanier LD425C	183666	396	PED(PB3000) FN(SR3000)	Black meter = 198k, color meter = 198k
Lanier LD425C	184141	334	PED(PB3000) FN(SR790)	Black meter = 330k, color meter = 4k
Lanier LD425C	184662	267	ST()	Black meter = 199k, color meter = 68k
Lanier LD425C	184663	247	PED(PB3000) FN(SR790) FAX(TYPE MPC3000)	Black meter = 231k, color meter = 17k
Lanier LD425C	185777	646	PED(PB3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	has wireless PC card, control panel yellow, front door cracked, black meter = 152k, color meter = 495k
Lanier LD425C	186631	362	PED(PB3000) FN(SR3010) FAX(TYPE MPC3000)	Finisher exit tray missing - finisher not tested, black meter = 273k, color meter = 90k
Lanier LD425C	186729	141	PED(PB3000) FAX(TYPE MPC3000)	Jamming in bypass - not tested, yellow panels, black meter = 103k, color meter = 39k
Lanier LD425C	186913	179	ST()	Black meter = 147k, color meter = 32k
Lanier LD425C	187745	219	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 198k, color meter = 22k
Lanier LD425C	188338	393	ST() FN(SR790) FAX(TYPE	Finisher tray missing, black meter =

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			MPC3000)	323k, color meter = 71k
Lanier LD425C	188714	223 ST()	FAX(TYPE MPC3000)	Color = 17k; B/W = 207k
Lanier LD425C	190585	184 ST()		Black meter = 131k, color meter = 54k
Lanier LD425C	191982	152 ST()	FAX(TYPE MPC3000)	Black meter = 90k, color meter = 63k
Lanier LD425C	192042	334 PED(PB3000)	FN(SR790) FAX(TYPE MPC3000)	Black meter = 284k, color meter = 51k, Finisher panels yellow
Lanier LD425C	192044	452 ST()		Black meter = 230k, color meter = 223k
Lanier LD425C	192304	190 ST()		Black meter = 160k, color meter = 30k
Lanier LD525C	184157	166 ST()	FAX(TYPE C2550)	Fuser lock mechanism missing - jamming at fuser
Lanier LD525C	192040	95 ST()	FAX(TYPE C2550)	Black meter = 73k, color meter = 23k
Lanier LD528C	190278	390 ST()	FN(SR3000) FAX(TYPE C5000)	Black meter = 230k, color meter = 161k
Lanier LD430C	181852	563 PED(PB3010)	FAX(TYPE MPC3000) E(BN3000)	Missing finisher - has bridge unit, black meter = 325k, color meter = 239k
Lanier LD430C	185589	640 ST()		Black meter = 420k, color meter = 221
Lanier LD430C	189600	564 PED(PB3000)	FAX(TYPE MPC3000) E(BN3000)	Black meter = 542k, color meter = 22k
Lanier LD430C	190270	556 ST()	FN(SR790) FAX(TYPE MPC3000)	Finisher yellow, black meter = 296k, color meter - 260k
Lanier LD435C	179128	435 PED(PB3000)	FN(SR3030)	Has fax option but missing control panel button, black meter = 341k, color 95k
Lanier LD435C	183542	483 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Black meter = 348k, color meter = 135k
Lanier LD435C	187746	422 PS(TYPE C4500)	PED(PB3000)	Black meter = 374k, color meter = 48k
Lanier LD435C	188974	112 ST()	PU(PU3000) FN(SR3020)	Missing external PC, has cable, black meter = 41k, color meter = 71k
Lanier LD435C	188976	N/A PED(PB3000)		Error code SC689 - IH inverter error - not tested, touch screen frozen, missing fax board- has control panel button, hard-drive removed
Lanier LD435C	190586	380 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Black meter = 338k, color meter = 43k
Lanier LD435C	190953	448 PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Has VM cardy type C, black meter = 119k, color meter = 329k
Lanier LD435C	191984	N/A PED(PB3000)	FN(SR790) FAX(TYPE MPC4500)	Error code SC750 - Finisher eprom, error code SC792 - does not recognize finisher - machine not tested, touch screen inoperable, finisher very yellow

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Lanier LD540C	192469	435	PED(PB3050) FN(SR790) FAX(TYPE C5000)	Black meter = 394k, color meter = 42k
Lanier LD445C	182526	855	PED(PB3000) FN(SR3030) FAX(TYPE MPC4500) E(BN3010)	yellow control panel cover, finisher tray yellow, black meter = 690k, color meter = 166k
Lanier LD445C	182877	530	PED(PB3010) FN(SR3020)	Black meter = 450k, color meter = 80k
Lanier LD445C	183098	428	PED(PB3000) FN(SR790)	Finisher top access door broken, black meter= 229k, color meter =
Lanier LD445C	183101	608	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	jamming at bridge unit - finisher not tested, jamming in RADF at slit glass - slit glass cracked, black meter = 598k, color meter = 11k
Lanier LD445C	184472	756	PS(TYPE C4500) PED(PB3010) FN(SR790) FAX(TYPE MPC4500)	Control panel yellow, black meter = 562k, color meter = 195k
Lanier LD445C	185744	N/A	PED(PB3000) FN(SR790) FAX(TYPE MPC4500)	Finisher tray missing, finisher top access door broken, error code SC860 - hard-drive format error - not tesetd
Lanier LD445C	187747	924	PED(PB3010) FN(SR790) FAX(TYPE MPC4500)	Black meter = 923k, color meter = 1k
Lanier LD445C	189117	785	PED(PB3010) FN(SR3020)	Color = 302k; B/W = 483k
Lanier LD445C	190190	456	PED(PB3000) FAX(TYPE MPC4500)	Missing finisher - has bridge unit, went into error code SC548 (fuser rotate error fuser belt sensor actuator sensor, IH inverter) during testing, black meter = 437k, color meter = 20k
Lanier LD445C	190591	596	PED(PB3000) FN(SR3020)	Black meter = 544k, color meter = 52k
Lanier LD445C	192475	916	PU(PU3000) PED(PB3000) FN(SR3020) FAX(TYPE MPC4500) E(BN3010)	Front door off color, black meter = 497k, color meter = 419k
Lanier LD550C	191384	794	PED(PB3050) FN(SR790) FAX(TYPE C5000)	Black meter = 114k, color meter = 681k
Lanier LD260C	178541	1269	FN(SR4020)	Yellow panels, dirty, black meter = 1185k, color meter = 84k
Lanier LD260C	180678	916	PU(TYPE 3260) PS(TYPE C7500) P(RT43) FN(SR4010)	Black meter = 394k, color meter = 522k
Lanier LD260C	181273	319	PU(TYPE 3260) FN(SR5000)	RADF smashed - not tested, RADF top panel broken, RADF frame bent - not tested, black meter = 197k, color meter = 122k
Lanier LD260C	189337	488	PU(TYPE 3260) FN(SR4010)	Color = 29k; B/W = 460k
Lanier LD275C	186749	936	PU(TYPE 3260) FN(SR4020) FAX(TYPE C7500)	Control panel cover yellow

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.