

Wulff Enterprises

02/10/2012

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-3030	191971	351	ST() FN(DA-FS300)	Error code E07-59 - stapler motor problem - finisher not tested
Panasonic DP-3530	180430	136	PED(DA-DS603) FN(DA-FS330)	Skewing paper out of cassette #3, stapler not working - not tested
Panasonic DP-3530	180590	524	ST() SCAN(DA-NS601) FAX(DA-FG600)	Yellow panels
Panasonic DP-3530	182669	201	SCAN(DA-NS601) FN(DA-FS330) FAX(DA-FG600)	Right access door on finisher broken, finisher disassembled - not tested
Panasonic DP-3530	183121	504	SCAN(DA-NS601) PED(DA-DS603) FN(DA-FS330) FAX(DA-FG600)	Font door scratched
Panasonic DP-3530	184418	236	ST()	Exit tray missing
Panasonic DP-3530	184419	321	ST() E()	
Panasonic DP-3530	184420	242	ST() SCAN(DA-NS601)	Off color panels, missing exit tray
Panasonic DP-3530	184566	186	ST() SCAN(DA-NS601) FN(DA-FS330)	
Panasonic DP-3530	186030	90	PED(DA-DS603) FN(DA-FS330)	Yellow panels
Panasonic DP-3530	186031	133	PED(DA-DS603) FN(DA-FS330)	Yellow panels
Panasonic DP-3530	186545	274	PED(DA-DS604) E()	Not recognizing PED - not tested
Panasonic DP-3530	186918	431	PED(DA-DS603) FN(DA-FS330)	Jamming at finisher entrance - not tested, missing punch unit disposal
Panasonic DP-3530	187665	812	ST() SCAN(DA-NS601) FN(DA-FS330) FAX(DA-FG600)	Right access door yellow, stand bottom panel dented
Panasonic DP-3530	188465	124	ST() FAX(DA-FG600)	Missing exit tray
Panasonic DP-3530	188466	71	ST() SCAN(DA-NS601) FAX(DA-FG600)	
Panasonic DP-4530	178525	258	FN(DA-FS600) FAX(DA-FG600)	Does not print - not tested, Yellow panels
Panasonic DP-4530	183543	471	ST() SCAN(DA-NS601) FN(DA-FS600)	Finisher button broken - does not recognize finisher - not tested
Panasonic DP-4530	191167	612	PED(DA-DS604)	False jam in RADF - not tested,
Panasonic DP-6030	183919	720	ST() E()	
Panasonic DP-6030	186546	783	PED(DA-DS604)	Error code E03-51 - corona wire cleaning problem - not tested, missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				corona assembly - not tested, PED connector broken, off color and dirty panels
Panasonic DP-6030	190261	1713	PED(DA-DS604) E()	Whining noise in machine, PED socket broken, bypass feed tires worn
Panasonic DP-8035	179377	331	ST() FN(DA-FS330) FAX(DA-FG600)	Finisher throat broken - not tested
Panasonic DP-8035	183067	745	ST() E(DA-XT600)	Jamming in bypass
Panasonic DP-8035	183985	189	ST() FN(DA-FS330) FAX(DA-FG600)	Finisher exit tray missing
Panasonic DP-8035	184311	220	ST() FAX(DA-FG600) E(DA-XT600)	Ground in dirt
Panasonic DP-8035	184360	32	PED(DA-DS604) FAX(DA-FG600)	Has wrong finisher, touch screen not responding - not fully tested, back panel dented
Panasonic DP-8035	184609	170	ST() FAX(DA-FG600) E(DA-XT600)	No power to machine - not tested
Panasonic DP-8035	184907	214	PED(DA-DS604) FN(DA-FS330) FAX(DA-FG600)	Finisher socket broken
Panasonic DP-8035	185207	326	ST() FN(DA-FS330)	Finisher entrance guide broken - finisher not tested, touch screen not responding
Panasonic DP-8035	185208	411	ST() FN(DA-FS330)	Missing fax - has count
Panasonic DP-8035	186887	502	PED(DA-DS603) FN(DA-FS330)	Clicking in finisher - not tested
Panasonic DP-8035	186889	396	PED(DA-DS603) FN(DA-FS330)	PED connector broken, finisher connection cracked, finisher tray missing
Panasonic DP-8035	186890	633	PED(DA-DS603) FN(DA-FS330)	Finisher not tested - interlock switch for punch unit disposal out of alignment, finisher trays missing, does not recognize cassette #3 installed
Panasonic DP-8035	186894	467	PED(DA-DS603) FN(DA-FS330) FAX(DA-FG600)	Something rubbing in finisher
Panasonic DP-8035	188614	195	ST() FN(DA-FS330) FAX(DA-FG600)	
Panasonic DP-8035	188948	563	ST() E(DA-XT600)	
Panasonic DP-8035	191181	323	ST() E(DA-XT600)	
Panasonic DP-8035	191517	183	ST() FAX(DA-FG600) E(DA-XT600)	Front panel scuffed
Panasonic DP-8035	191972	565	ST() E(DA-XT600)	
Panasonic DP-8045	173019	325	PED(DA-DS604) FN(DA-FS600)	Broken finisher release handle

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-8045	183505	682	PED(DA-DS603) FN(DA-FS600)	Touch screen not responding - not fully tested
Panasonic DP-8045	184505	668	PED(DA-DS604) FN(DA-FS600)	Jamming out of cassette #4
Panasonic DP-8045	186978	231	ST()	Missing finisher - has hardware; blurred copies
Panasonic DP-8045	188278	229	ST() FAX(DA-FG600)	Yellow panels, has wrong finisher (FS-330)
Panasonic DP-8045	188946	736	PED(DA-DS604) FN(DA-FS600) FAX(DA-FG600)	Jamming out of cassette #2,3 - not tested
Panasonic DP-8045	188949	896	PED(DA-DS603) FN(DA-FS600)	
Panasonic DP-8045	191970	599	PED(DA-DS603) E(DA-XT600)	
Panasonic DP-8060	188944	169	PED(DA-DS604) FN(DA-FS600)	Cassette #1 paper sensor broken - not tested
Panasonic DP-8060	189854	559	ST() FN(DA-FS600)	
Panasonic DP-8060	190144	366	ST() FN(DA-FS600)	Error code E3-21 - dust collection fan rotation error
Panasonic DP-8060	190267	662	ST() FN(DA-FS600)	Finisher back panel broken
Panasonic DP-C262	177334	N/A	ST() E(DA-XT320)	No power to control panel - not tested
Panasonic DP-C262	179628	238	ST() FN(DA-FS320)	Black meter = 155k, color meter = 83k, cassette #2 not recognizing paper - not tested, finisher exit tray yellow, black meter = 155k, color meter = 83k
Panasonic DP-C262	182891	89	ST() SCAN(DA-NS320) FN(DA-FS320)	Color = 31k; B/W = 58k
Panasonic DP-C262	183920	85	ST()	Black meter = 58k, color meter = 28k
Panasonic DP-C262	184361	89	PED(DA-DS321)	Black meter = 81k, color meter = 9k
Panasonic DP-C262	189033	286	PED(DA-DS321) FN(DA-FS320) FAX(DA-FG320)	Does not recognize PED - not tested, error code E07-59 - stapler motor problem - finisher not tested; color = 42k; B/W = 245k
Panasonic DP-C262	189385	N/A	PED(DA-DS321) FN(DA-FS325)	Touch screen not responding - password protected (can't test)
Panasonic DP-C264	179623	118	PED(DA-DS320)	Password protected - could not get config page, not recognizing paper deck, and cassette #2, bottom trim panel bent, black meter = 61k, color meter = 57k
Panasonic DP-C264	183506	560	PU(DA-SP41) PED(DA-DS320) FN(DA-FS356)	Error code E05-13 - not tested, finisher tray mount bent, black meter = 409k, color meter = 51k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-C264	186891	374	PED(DA-DS320) FN(DA-FS356)	Black meter = 15k, color meter = 249k, stapler not stapling
Panasonic DP-C322	174095	412	ST() E(DA-XT320)	Black meter = 405k; color meter 8k
Panasonic DP-C322	178490	414	PED(DA-DS321) FN(DA-FS320)	Finisher tray broken - finisher not tested, black meter = 146k, color meter = 268k
Panasonic DP-C322	178495	516	PU(DA-SP41) PED(DA-DS320) FN(DA-FS325)	Finisher top panel and door yellow, Black meter = 291k, color meter = 225k
Panasonic DP-C322	179526	533	ST() SCAN(DA-NS320) FAX(DA-FG320)	Black meter = 512k, color meter = 21k
Panasonic DP-C322	180385	N/A	PED(DA-DS321)	Error code E1-01 - scan sensor, scan motor board, SPC board, connector VPS, slit glass broken, control panel and front panels smashed, EXP lamp broken, back panel broken, left side panel bent, RADF panels broken
Panasonic DP-C322	182001	56	ST() FN(DA-FS325)	Black meter = 25k, color meter = 32k
Panasonic DP-C322	183556	503	SCAN(DA-NS320) PED(DA-DS321) FN(DA-FS325)	Black meter = 395k, color meter = 108k
Panasonic DP-C322	187360	25	SCAN(DA-NS320) PED(DA-DS321) FN(DA-FS320)	Finisher interlock broken, black meter = 10k, color meter = 16k
Panasonic DP-C322	191600	325	PED(DA-DS320) FAX(DA-FG320)	Black meter = 203k, color meter = 122k
Panasonic DP-C322	192009	530	ST() PU(DA-SP41) FN(DA-FS325) FAX(DA-FG320)	Error code E07-59 - stapler motor error - finisher not tested, finisher yellow, black meter = 484k, color meter = 47k
Panasonic DP-C354	186736	284	PED(DA-DS321) FN(DA-FS356) FAX(DA-FN350)	Black meter = 180k, color meter = 104k
Panasonic DP-C354	187071	386	PED(DA-DS321) FN(DA-FS356) FAX(DA-FN350)	Error code E07-59 - finisher shift tray error - not tested, finisher tray mount bent, Cassettes #3,4 not recognized - not tested, black meter = 288k, color meter = 98k
Panasonic DP-C354	191553	30	PED(DA-DS321) FN(DA-FS350)	Error code E07-59 - finisher upper limit sensor stack tray paper height detection sensor or paper hold lever detection sensor, missing finisher tray - finisher not tested, does not recognize pedestal - not tested, missing all toner cartridges- tested with others, black meter = 15k, color meter = 16k
Panasonic DP-C405	182602	617	ST()	Black meter = 478k, color meter = 140k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Panasonic DP-C405	182606	431 ST()		Black meter = 158k, color meter = 274k
Panasonic DP-C405	191169	215 PED(DA-DS321) FN(DA-FS405) FAX(DA-FG320)		Finisher tray mount bent & tray broken - finisher not tested, black meter = 185k, color meter = 31k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.