

Wulff Enterprises

01/07/2009

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2513	119841	39		Yellowed & dirty panels; scratched top panels
Savin 2513	121649	27	ADF(DF74)	
Savin 2515	118775	94	ST() RADF(DF72) PFU(PS460) PC(TYPE 1018) NIC(TYPE 1018)	Tray 2 inop
Savin 2518	125045	80	ST() RADF(DF72)	
Savin 2518D	124277	127	ST() RADF(DF71) PC(TYPE 1018) NIC(TYPE	
Savin 2518D	125049	285	ST() RADF(DF71)	
Savin 2518D	125053	100	ST() RADF(DF71) PFU(PS460) FAX(TYPE 1018)	
Savin 2522	119480	91	ST() RADF(DF75) DX(AD420)	Missing RADF access door
Savin 2522	121339	212	ST() RADF(DF75) DX(AD420)	
Savin 2522	121461	108	ST() RADF(DF75) DX(AD420)	
Savin 2522	124454	108	ST() RADF(DF75)	
Savin 2522	125046	247	RADF(DF75) FAX(TYPE 1027)	Error code SC548 - missing fuser section
Savin 2522	125050	116	RADF(DF75)	
Savin 2522	125054	302	ST() RADF(DF75) FAX(TYPE 1027) DX(AD420)	
Savin 2522	125055	187	ST() RADF(DF75) DX(AD420)	
Savin 2527	124279	197	RADF(DF75) PED(PS490) PC(TYPE 1027[S]) NIC(TYPE 1027) FAX(TYPE 1027)	
Savin 2527	124449	30	RADF(DF75) PED(PS490) FN(SR820)	SC542 code - fuser temperature low; front door interlock switch broken
Savin 2535	120269	751	ST() RADF(DF70) FN(SR720)	
Savin 2535	124451	285	ST() RADF(DF70)	
Savin 2545	125057	2652	RADF(DF70) PED(PS360) PC(TYPE 1045) P(RT36)	Dirty and off colored panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2575	125047	4144	PU(TYPE 1075) PS(TYPE 1075) PC(TYPE 1075[S]) FN(SR850)	Document feeder actuator broken; error code sc725 -problem with FN(SR850)
Savin C2408	117129	142	ST() RADF(DF75)	Bypass tray broken off; yellowed panels; color = 16k; B/W = 126k
Savin C2408	117399	21	ST() RADF(DF75)	Broken bypass trays; very light copies; color = 9k; B/W = 12k
Savin C2408	120027	133	RADF(DF75) PED(PS510) FN(SR830)	Yellowed top panels; color = 7k; B/W = 127k
Savin C2408	123316	474	RADF(DF75) PED(PS520) PC(TYPE 1232) FN(SR830)	Color = 144k; B/W = 331k
Savin C2408	123318	158	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790) = 158k FAX(TYPE 1232)	Broken bypass tray; color = 10k; B/W
Savin C3210	119483	150	ST() RADF(DF75) PC(TYPE 1232) FN(SR790) = 79k	Missing bypass tray; color= 71k; B/W
Savin C3210	124276	612	ST() RADF(DF75) PC(TYPE 1232) FN(SR790) = 598k FAX(TYPE 1232) E(PT290)	Finisher jams- inop; color = 15k; B/W
Savin 3515F	125044	76		
Savin 3515MF	124155	91		
Savin 3515MF	124163	984		Fuser broken at mounting point- can't test
Savin 3515MF	124187	149		Duplex jams
Savin 3515MF	124261	122		
Savin 3515MF	124281	97	PFU(PS480)	
Savin 4015	119810	91	ST() FAX(TYPE 2018) ADF(DF78)	
Savin 4015	120735	86	ST() PFU(PS450) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	
Savin 4015	124450	100	ADF(DF78)	
Savin 4015	124452	134	PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Right side panel broken
Savin 4018	124453	61	ST() PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	
Savin 4018D	117395	35	ST() RADF(DF79) FAX(TYPE 2018)	
Savin 4018D	117518	32	ST() RADF(DF79) PFU(PS460) PC(TYPE 2018) FAX(TYPE 2018)	Yellowed RADF panels; duplex unit not detected by machine- inop
Savin 4022	119813	104	ST() RADF(DF75) PC(TYPE 2027)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4022	119814	96	ST() RADF(DF75) PC(TYPE 2027)	
Savin 4022	119816	116	ST() RADF(DF75) PC(TYPE 2027)	Missing fax board (port cover missing); broken bypass tray catch
Savin 4022	119837	141	ST() RADF(DF75) FAX(TYPE 2027)	
Savin 4022	125048	228	ST() RADF(DF75) FAX(TYPE 2027)	
Savin 4035	120025	1129	PED(PS360) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Jams every copy in fuser; very yellowed panels; broken paper guide in tray #4
Savin 4035	122053	331	ST() FAX(TYPE 2045) E(PT330)	
Savin 4035	122054	330	ST() FAX(TYPE 2045) E(PT330)	Yellowed panels
Savin 4035	122226	35	ST() FN(SR790)	Yellowed & dirty panels; broken top finisher access door at hinge
Savin 4035	122642	198	PED(PS360) PED(PS530)	
Savin 4035	123881	235	ST() FN(SR790) FAX(TYPE 2045)	
Savin 4035E	117359	222	ST() P(RT45)	
Savin 4035E	117985	224	ST() FAX(TYPE 2045E)	
Savin 4035E	118401	146	ST() FAX(TYPE 2045E)	
Savin 4035E	119482	284	ST() P(RT45)	
Savin 4035E	119502	197	ST() FN(SR790) FAX(TYPE 2045E)	
Savin 4035E	119503	102	ST() FAX(TYPE 2045E)	Yellowed panels
Savin 4035E	119504	191	ST() FN(SR790) FAX(TYPE 2045E)	
Savin 4035E	119505	353	ST() FN(SR790) FAX(TYPE 2045E)	
Savin 4035E	124448	179	ST() FN(SR790)	Finisher not tested- jamming
Savin 4035E	124545	582	ST()	
Savin 4035E	124759	178	PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Stapler causes finisher to jam
Savin 4045	124446	709	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Error code SC302 (charge roller, HTV problem or fuse FU5 on power supply); dirty and off colored panels; passes blank copies; missing access panel where paper deck attaches
Savin 4045E	121022	225	PU(TYPE 1045) PED(PS530) PC(TYPE	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			2045E) FN(SR880)	
Savin 4051	120022	787 PC(TYPE 2075)	FN(SR850)	
Savin 4051	120272	636 FN(SR850)		
Savin 4060	124447	911 PU(TYPE 1075)	PC(TYPE 2075) FN(SR850)	
Savin 4060	125021	1765 PC(TYPE 2075)	P(RT43)	
Savin 4060	125022	1525 PC(TYPE 2075)	P(RT43)	
Savin 4075	124168	622 PU(TYPE 1075)	PC(TYPE 2075) FN(SR850)	
Savin 4075	124186	976 PU(TYPE 1075)	PC(TYPE 2075) FN(SR850)	
Savin 4075	124257	647 PU(TYPE 1075)	FN(SR850)	Error code SC304 (unknown); finisher paper entrance guide bent & broken
Savin C3224	117339	258 PS(TYPE 2238)	PED(PS550) FN(SR920)	Color = 114k; B/W = 144k
Savin C3224	118585	287 PED(PS550)	FAX(TYPE 2238) E(PT460)	Yellowed RADF; Black meter = 229k; colored meter = 59k
Savin C3224	119809	211 ST() FN(SR920)	FAX(TYPE 2238)	Color = 84k; B/W = 128k
Savin 9927 DP	125052	578 ST() RADF(DF69)	PC(TYPE 270) DX(AD360)	Dirty and off colored panels
Savin 8035	124278	140 ST()		
Savin 8035	124455	405 PED(PS530)	PC(TYPE 3045) FN(SR790)	Jamming in finisher
Savin 8035	124748	566 PS(TYPE 3045)	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124749	677 PS(TYPE 3045)	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124750	595 PS(TYPE 3045)	PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Savin 8035	124751	738 PS(TYPE 3045)	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124752	689 PS(TYPE 3045)	PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124753	828 PS(TYPE 3045)	PED(PS530) PC(TYPE	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124754	448	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124755	228	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124756	529	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Savin 8035	124757	727	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	Bad paper sensor switch- will not pass paper
Savin 8035	124760	554	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124761	610	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124762	462	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124763	467	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	Stapler jams
Savin 8035	124764	469	PU(TYPE 1045) PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Savin 8035	124765	300	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124766	238	PU(TYPE 1045) PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Savin 8035	124767	624	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8035	124769	629	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124770	587	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124771	540	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124772	652	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) P(RT45) FN(SR790) FAX(TYPE 3045)	
Savin 8035	124774	363	PU(TYPE 1045) PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	
Savin 8045	123194	388	PED(PS530) PC(TYPE 3045) FAX(TYPE 3045)	
Savin 8045	123813	822	PU(TYPE 1045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045)	Finisher in error code SC733; offcolored & dirty panels
Savin 8045	124758	273	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR790) FAX(TYPE 3045)	
Savin C2824	118437	156	ST() FN(SR960) FAX(TYPE 3245)	Black meter = 137k; color meter = 20k
Savin C3528	122000	175	PU(TYPE 1045) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	bypass interlock broken -not tested; dirty and yellowed panels; finisher trays broken; black meter =124k; colored meter =52k
Savin C3528	122144	1695	PED(PS580) FN(SR960) FAX(TYPE 3245) E(PT460)	Error- developer unit not setting properly (can't test); black meter = 952k; color meter =743k
Savin C3528	125026	175	ST()	Black meter = 148k; colored meter =27k
Savin 9955 DP	125051	1644	FN(SR730)	Error code SC120; Off colored panels; right side cover panel broken
Savin 9965 DP	123884	3128	FN(SR730)	Finisher jams; finisher tray broken; broken upper left side panel
Savin CLP28S	122266	568	FN(SR770)	Color = 212k; B/W = 356k
Savin SDC531	124773	69	PC(E-750) E() DX(AD470) C[1](PS570)	Color = 67k; B/W = 3k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.