

Wulff Enterprises

02/10/2012

GA Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2535	182851	433	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720)	Error code SC726 - finisher shift tray 1, lift motor error - not tested, off color panels
Savin 2535	190660	558	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FN(SR720) FAX(TYPE 1045)	Off color panels. void lines on copies
Savin 3515MF	176004	230		Off color panels
Savin 3515MF	181081	199		Very dirt - toner spilled on machine, yellow panels
Savin 3515MF	183385	77		RADF yellow, toner spilled in cassettes
Savin 3515MF	188895	141		
Savin 3515MF	190443	19		
Savin 8016	188779	10	ST() ADF(DF78)	Jams at fuer every copy; missing small access panel on left side; broken back panel on right side
Savin 4018D	186771	142	ST() RADF(DF79)	Off color panels
Savin 8020	184397	247	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Wireless PC card, has ADF DF2000
Savin 8020	184402	105	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Has wireless PC LAN card, exit tray broken
Savin 8020	184403	288	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Has ADF DF2000; ADF top access panel dented
Savin 8020	184404	352	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340) ADF(DF78)	Has wireless PC card, has ADF DF2000
Savin 8020	184406	178	ST() PC(TYPE 2018) FAX(TYPE 2018) E(PT340)	Has ADF DF2000, has wireless card
Savin 8020D	190615	81	ST() RADF(DF79) PC(TYPE 2018) FAX(TYPE	
Savin 8020D	192710	144	RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018)	Ground in dirt
Savin 4022	187974	1054	ST() RADF(DF75) PC(TYPE 2027) FAX(TYPE	Jamming at registration rollers - not tested, toner spilled throughout machine, off color panels, duplexers will not latch
Savin 4027	190397	608	ST() RADF(DF75)	RADF yellow, void lines on copies

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(TYPE 2027) FAX(TYPE 2027)	
Savin 4045E	191224	175 ST()	PC(TYPE 2045E) FN(SR790) FAX(TYPE 2045E)	Yellow panels
Savin 4075	187553	1142 PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)		Front door magnet bracket broken, finisher tray broken
Savin C3224	187869	416 PED(PS540) FN(SR910) FAX(TYPE 2238) E(PT460)		Yellow panels, trim panel below bypass tray missing, black meter = 326k, color meter = 90k
Savin C3224	187870	288 PED(PS540) FN(SR910) FAX(TYPE 2238) E(PT460)		Finisher front access door broken below finisher entrance guide, yellow panels, black meter = 109k, color meter = 179k
Savin C3828	180353	436 PED(PS540) FN(SR910)		Yellow panels, black meter = 308k, color meter = 128k
Savin 8025	177910	131 ST()		Off color panels
Savin 8025	182217	153 ST()	RADF(DF83)	Off color panels
Savin 8025	184754	77 ST()	SS(TYPE 1027) RADF(DF83) FAX(TYPE 3030)	
Savin 8025	187871	97 ST()	RADF(DF83) PC(TYPE 3030)	Off color panels
Savin 8025	191058	193 ST()	RADF(DF83) PC(TYPE 3030 (S))	
Savin 8030	187166	310 ST()	RADF(DF83) PC(TYPE 3030 (S))	Error code SC411 - separataion bias, HCT or discharge plate - not tested, off color panels
Savin 8035	179593	484 ST()	FAX(TYPE 3045)	Off color panels
Savin 8035	184025	517 ST()	FN(SR790) FAX(TYPE 3045) E(PT330)	
Savin 8035	185007	184 ST()	FN(SR790)	
Savin 8035	190612	595 ST()	FN(SR790)	Lower right side access door missing- tested with another; off color panels; void streaks in copies
Savin C2410	186494	232 ST()		Front door interlock switch not working - not tested, hole in front door, fuser oil spilled all throughout machine from being on its back, off color panels, black meter = 194k,
Savin C2824	188793	253 ST()	FN(SR960) FAX(TYPE 3245) E(PT460)	Finisher jams & grinds- inop; cannot access fax option; yellowed & very dirty panels; color = 48k; B/W = 206k
Savin C3528	187173	442 PED(PS580) FAX(TYPE 3245) E(PT460)		Error code SC820 - CPU, firmware or controller error - not tested, black meter = 358k, color meter = 84k, yellow panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C4535	190055	493	PED(PS590) FN(SR950) FAX(TYPE 3245)	Jamming in duplexer - not tested, yellow panels, Finisher rail top panel cracked, black meter= 233k, color meter = 261k
Savin C6045	180827	81	PC(TYPE 3260) E()	Black meter = 7k, color meter = 75k
Savin C6045	181336	1917	FN(SR4000)	Black meter = 1710k, color meter = 207k, has inverter type 3260
Savin C6045	183379	1594	PC(FIERY E-7000) FN(SR980)	Needs toner to test; color = 1534k; B/W = 61k
Savin C6045	185930	422	PU(TYPE 3260) PC(TYPE 3260) FN(SR4000)	Has cover interposer 3260, off color panels, black meter = 269k, color meter= 154k
Savin C6045	187554	275	PU(TYPE 3260) PC(FIERY E-7000) FN(SR970)	Black meter = 85k, color meter = 190k
Savin C6045	189179	965	FN(SR4000)	Missing PC has PC fiery decal on copier, black meter = 251k, color meter = 714k
Savin 7025	178865	139	ST() RADF(DF3020) PC(TYPE 2500NA) E(BN3020)	Off color panels, jamming in duplexer - not tested
Savin 7025	186565	36	ST() RADF(DF3020)	
Savin 8025E	177635	185	ST() RADF(DF83) FAX(TYPE 3030)	Off color panels
Savin 8025E	179294	309	ST() RADF(DF83)	Off color and very dirty, jamming in duplexer - not tested
Savin 8025E	184398	385	ST() RADF(DF83) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	Wireless PC card, front door scratched
Savin 8025E	186615	178	ST() RADF(DF83) PC(TYPE 3010)	Bypass tray not detecting paper - not tested
Savin 8025E	190445	52	ST() RADF(DF83)	
Savin 8025E	190613	44	ST() RADF(DF83)	Yellowed RADF panels
Savin 8025E	190637	133	ST() RADF(DF83) FAX(TYPE 3030) E(PT280)	RADF yellow
Savin 8025E	190638	185	ST() RADF(DF83)	Touch screen not responding -not fully tested, RADF yellow
Savin 9025	176046	52	ST() RADF(DF3030) FN(SR790) E(BN3030)	
Savin 9025	180062	208	ST() SCAN(TYPE 3350) E(BN3030)	
Savin 9025	180579	105	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350) E(BN3030)	Error code SC792 - finisher problem - not tested, yellow control panel
Savin 9025	180920	115	ST() RADF(DF3030)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(TYPE 3350 (S)) E(BN3030)	
Savin 9025	181453	757	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050) FAX(TYPE 3350)	Error code SC876-05 - hard-drive defective, hard-drive removed, duplexer internal parts missing, error code sc672 - controller to operation communication error, transfer roller falling apart
Savin 9025	184701	56	ST() RADF(DF3030) PC(TYPE 3350 (S))	
Savin 9025	185877	238	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050)	
Savin 9025	185878	211	ST() RADF(DF3030) PC(TYPE 3350 (S)) FN(SR3050)	Finisher top access door interlock broken - finisher not tested, needs toner - not fully tested,
Savin 8030E	191720	264	RADF(DF83) PED(PS490) PC(TYPE 3010) FN(SR790) FAX(TYPE 3030)	
Savin 8035E	178113	12	PED(PS530) FN(SR790) FAX(TYPE 3045)	Touch screen not responding - not fully tested, hard-drive removed
Savin 8035E	184756	80	ST() PC(TYPE 4500) FN(SR790) FAX(TYPE 3045)	
Savin 8035E	185083	142	ST() PC(TYPE 4500) FAX(TYPE 3045)	Jamming in fuser, jams in duplexer
Savin 8035E	185084	492	ST() PC(TYPE 4500) FAX(TYPE 3045)	
Savin 8035E	186040	302	ST() PU(TYPE 1045) FN(SR880)	Off color panels
Savin 8035E	190614	369	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Savin 8035E	192711	625	ST() PC(TYPE 4500) P(RT45) FN(SR790) FAX(TYPE 3045)	
Savin 9040	182407	308	PED(PB3040) FN(SR790)	
Savin 9040	184734	519	ST() PC(TYPE 5000 (S))	
Savin 9040	188391	237	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Savin 9040	191719	318	ST() PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	
Savin 8045E	180924	327	ST() PC(TYPE 4500) FN(SR880)	
Savin 8045E	188591	237	ST() PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	Missing lower right side access door- unable to test tray #2; off color panels

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 8045E	190436	388	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Savin 8045E	190446	429	PED(PS530) PC(TYPE 4500) FAX(TYPE 3045) E(PT330)	
Savin 8045E	190611	256	ST() PU(TYPE 1045) FN(SR880)	Yellowed panels
Savin 8045E	192615	234	PED(PS530) PC(TYPE 4500) FN(SR790)	
Savin 9050	182918	708	PED(PB3040) PC(TYPE 5000 (S)) FAX(TYPE 5000)	
Savin 9050	186397	854	PED(PB3040) PC(TYPE 5000 (S)) FN(SR790) FAX(TYPE 5000)	Top finisher panel interlock broken, jamming in stapler
Savin 9050	189248	441	PED(PB3040) PC(TYPE 5000 (S)) FN(SR3020)	Not fusing copies
Savin 8055	187872	1096	PU(TYPE 3260) FN(SR970)	Has NIC but no PC enablers
Savin 8065	189151	399	PU(TYPE 3260) PC(TYPE 7500) FN(SR970)	Touch screen working intermittedly - not fully tested
Savin 8065	191919	526	PU(TYPE 3260) PC(TYPE 7500) FN(SR970) FAX(TYPE 7500)	Front door has deep scratch
Savin 8080	191183	1331	PC(TYPE 8000) FN(SR970) FAX(TYPE 7500)	
Savin C9020	183546	27	ST()	Needs toner - not tested, black meter = 7k, color meter = 20k
Savin C2525	183466	181	PED(PB3000) FN(SR790) E(BN3000)	Black meter = 178k, color meter = 3k
Savin C2525	184750	253	ST() FN(SR790) FAX(TYPE MPC3000)	Jamming in stapler - not tested, off color and dirty panels, black meter = 193k, color meter 60k
Savin C2525	186391	212	PED(PB3000) FN(SR790) FAX(TYPE MPC3000) E(BN3000)	Jamming in stapler- not tested, hole in finisher shift tray, black meter = 148k, color meter = 65k
Savin C2525	187688	247	ST() FAX(TYPE MPC3000)	Black meter = 175k, color meter = 72k
Savin C2525	187776	261	PED(PB3000) FN(SR3010) FAX(TYPE MPC3000)	Color = 79k; B/W = 182k
Savin C2525	188117	156	ST()	Black meter = 78k, color meter = 78k
Savin C2525	188141	267	ST() FN(SR790) FAX(TYPE MPC3000)	Black meter = 206k, color meter = 61k, finisher panels yellow
Savin C3030	181401	275	ST() FAX(TYPE MPC3000) E(BN3000)	Black meter = 247k, color meter = 29k
Savin C3030	181458	505	ST() E(BN3000)	Black meter - 363k, color meter - 143k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C3535	189197	539	PU(PU3000) PED(PB3000) FN(SR3030)	Jamming in punch unit, black meter = 415k, color meter = 125k
Savin C3535	189249	499	PED(PB3000) FN(SR790)	Black meter = 261k, color meter = 238k
Savin C4040	189198	827	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Has USB/SD card reader, jamming in stapler, black meter = 424k, color meter = 404k
Savin C4040	189201	457	PED(PB3040) FN(SR790) FAX(TYPE C5000)	Has USB/SD card reader, black meter= 264k, color meter = 194k
Savin C4540	185641	403	PS(TYPE C4500) PED(PB3000) FN(SR3020)	Black meter = 243k, color meter = 161k, off color panels
Savin C4540	188589	764	PU(PU3000) PED(PB3010) FN(SR3030) FAX(TYPE MPC4500)	Color = 114k; B/W = 650k
Savin C4540	191920	298	PU(PU3000) PS(TYPE C4500) PED(PB3010) FN(SR3020) FAX(TYPE MPC4500)	Color meter - 182k, black meter = 116k
Savin C6055	176364	362	FN(SR4010) FAX(TYPE C7500)	Missing black toner bottle - not tested, black meter = 201k; color meter = 162k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.