

# Wulff Enterprises

01/07/2009

## OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2513	113696	80	ADF(DF74)	Loud clicking noise when copying
Savin 2513	120829	84	ADF(DF74)	Broken ADF hinges
Savin 2515	119277	97	RADF(DF72)	Has a DF78 RADF (works OK); yellowed RADF panels
Savin 2515	119992	215	ST() RADF(DF72) PFU(PS460) PC(TYPE 1018) NIC(TYPE 1018) FAX(TYPE 1018)	Dirty & yellowed panels; broken top paper tray handle
Savin 2515	120161	121	ST() RADF(DF72)	
Savin 2518	118545	105	ST() RADF(DF72)	
Savin 2518	118557	52	ST() RADF(DF72)	
Savin 2518	118558	101	ST() RADF(DF72) PC(TYPE 1018) NIC(TYPE	
Savin 2518	121746	217	ST() RADF(DF72)	Offcolored & dirty panels; broken paper guide in tray #1
Savin 2518	121747	339	ST() RADF(DF72)	Broken paper tray handles; yellowed & dirty panels
Savin 2518	122079	124	ST() RADF(DF72) PFU(PS460)	Yellowed panels; missing front name plate
Savin 2518D	115367	137	ST() RADF(DF71) PFU(PS460) PC(TYPE 1018) NIC(TYPE 1018)	Yellowed panels
Savin 2518D	120162	226	ST() RADF(DF71)	
Savin 2518D	120199	282	ST() RADF(DF71)	Yellowed panels
Savin 2518D	120200	159	ST() RADF(DF71) PFU(PS460)	Duplex jams; yellowed panels
Savin 2518D	120201	239	ST() RADF(DF71)	Duplex unit & transfer section will not latch properly causing jams; yellowed panels
Savin 2518D	120340	173	ST() RADF(DF71)	
Savin 2518D	120682	134	ST() RADF(DF71) PC(TYPE 1018) FAX(TYPE	Needs toner- unable to finish testing
Savin 2518D	124711	103	ST() RADF(DF71) FAX(TYPE 1018)	
Savin 2522	120189	141	ST() SS(TYPE 1027) RADF(DF75) DX(AD420) B(TYPE 1027)	Ripped platen mat
Savin 2522	120190	121	ST() SS(TYPE 1027) RADF(DF75) DX(AD420)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 2522	121318	226	ST() RADF(DF75) FN(SR790) DX(AD420) B(TYPE 1027)	
Savin 2522	122417	502	ST() SS(TYPE 1027) RADF(DF75) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	Yellowed panels
Savin 2522	122418	385	ST() SS(TYPE 1027) RADF(DF75) FAX(TYPE 1027) E(TYPE 1027) DX(AD420) B(TYPE 1027)	Broken bypass tray
Savin 2522	122423	153	RADF(DF75) FN(SR820)	Missing stand
Savin 2522	123004	144	ST() SS(TYPE 1027) RADF(DF75) DX(AD420) B(TYPE 1027)	Broken bypass tray
Savin 2527	124174	337	SS(TYPE 1027) RADF(DF75) PED(PS490) PC(TYPE 1027[S]) NIC(TYPE 1027) DX(AD420) B(TYPE 1027)	
Savin 2535	120164	734	RADF(DF70) PED(PS360) FN(SR720)	Broken bypass tray
Savin 2535	120165	585	RADF(DF70) PED(PS360) FN(SR720)	Yellowed panels
Savin 2535	120166	859	RADF(DF70) PED(PS360) FN(SR720)	
Savin 2535	120167	545	RADF(DF70) PED(PS360) FN(SR720)	
Savin 2535	120168	1419	RADF(DF70) PED(PS360) FN(SR720)	Yellowed panels
Savin 2535	120169	1196	RADF(DF70) PED(PS360) FN(SR720)	Offcolored panels
Savin 2535	120170	755	RADF(DF70) PED(PS360) FN(SR720)	
Savin 2535	122852	256	RADF(DF70) PU(TYPE 1045) PED(PS360) PC(TYPE 1045) P(RT36) NIC(TYPE 1045) FN(SR760)	Noisy machine when copying
Savin 2535	124132	465	RADF(DF70) PED(PS360) PC(TYPE 1045[S]) NIC(TYPE 1045) FAX(TYPE 1045)	
Savin 2535	124136	467	ST() RADF(DF70) PC(TYPE 1045[S]) NIC(TYPE 1045)	
Savin 2545	122939	966	RADF(DF70) PED(PS360) PC(TYPE 1045) P(RT36)	Offcolored & dirty panels; cracked paper tray #4 panel & lower right side

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			NIC(TYPE 1045) FN(SR720)	trim panel
Savin 2545	123131	833	RADF(DF70) PED(PS360) PC(TYPE 1045) P(RT36) NIC(TYPE 1045) FN(SR720)	
Savin 2545	124134	712	ST() RADF(DF70) PC(TYPE 1045) NIC(TYPE 1045) FAX(TYPE 1045)	Missing transfer belt section causing error code SC402; also error code SC501 (tray #1 lift problem); yellowed panels
Savin 2560	123304	824	PU(TYPE 1075) PC(TYPE 1075[S]) P(RT43) FN(SR850)	
Savin 2560	123305	942	PU(TYPE 1075) PC(TYPE 1075[S]) P(RT43) FN(SR850)	
Savin 2575	123630	881	PU(TYPE 1075) FN(SR850)	
Savin 2585	122252	3991	PU(TYPE 850) PC(TYPE 850) NIC(TYPE 450-E) FN(SR810)	Jams alot in sections D & Z; yellowed panels
Savin C2408	119872	336	ST() RADF(DF75) PC(TYPE 1232) FN(SR830)	Yellowed panels; color = 159k; B/W = 178k
Savin C2408	120060	253	RADF(DF75) PED(PS520) PC(TYPE 1232)	Color = 219k; B/W = 35k; bypass tray broken off
Savin C2408	120181	292	ST() SS(TYPE 1232) RADF(DF75)	Yellowed panels; broken top paper tray adjusting gear; color = 6k; B/W = 286k
Savin C2408	120585	131	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790) FAX(TYPE 1232) E(PT290)	Color = 20k; B/W = 112k
Savin C2408	120586	86	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR830)	Finisher damaged- tray broken off & tray mount bent (inop); yellowed panels; missing adjusting gear in tray #1; color = 12k; B/W = 74k
Savin C2408	124722	345	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790)	Color = 339k; B/W = 7k
Savin C2408	124856	197	SS(TYPE 1232) RADF(DF75) PED(PS520) PC(TYPE 1232)	Color = 24k; B/W = 174k
Savin C3210	116802	429	RADF(DF75) PED(PS510) PC(TYPE 1232) FAX(TYPE 1232)	Color = 4k; B/W = 425k
Savin C3210	120561	335	RADF(DF75) PED(PS510)	Bypass tray assembly broken off & missing
Savin C3210	121277	502	SS(TYPE 1232) RADF(DF75) PED(PS510) PC(TYPE 1232)	Color = 27k; B/W = 476k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin C3210	122547	542	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790)	Color = 127k; B/W = 416k; detached lower right side panel
Savin C3210	122822	398	RADF(DF75) PED(PS510) PC(TYPE 1232) E(PT290)	Yellowed panels; color = 61k; B/W = 338k
Savin C3210	122843	443	RADF(DF75) PED(PS510) PC(TYPE 1232) FN(SR790)	Color = 39k; B/W = 404k
Savin C3210	123967	505	ST() PC(TYPE 1232) FAX(TYPE 1232) E(PT290)	Color = 61k; B/W = 445k
Savin C3210	124855	677	SS(TYPE 1232) RADF(DF75) PED(PS520) PC(TYPE 1232)	Color = 23k; B/W = 654k
Savin 3515	121919	156		
Savin 3515	121920	30		
Savin 3515	124820	61	ST()	
Savin 3515F	119397	197		
Savin 3515F	122914	68		
Savin 4015	120377	101	PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	
Savin 4015	120683	181	PC(TYPE 2018) FAX(TYPE 2018) ADF(DF78)	Error code SC302 (charge roller or HVT); dirty panels
Savin 4015	122915	78	ST() FAX(TYPE 2018) ADF(DF78)	
Savin 4015	123622	34	ADF(DF78)	
Savin 4015	123623	67	ADF(DF78)	
Savin 4015	123624	73	ADF(DF78)	
Savin 4015	123627	223	ADF(DF78)	Error code SC301 (broken paper tray motor); broken ADF plug socket; broken right side front door hinge
Savin 8016	120687	32	ST() ADF(DF78)	
Savin 8016	120688	64	ST() ADF(DF78)	
Savin 8016	124400	84	ST() ADF(DF78)	
Savin 8016	124949	26	ST() PFU(PS450) ADF(DF78)	
Savin 4018	120684	109	PFU(PS460)	Broken lower right side access door; dirty & offcolored panels
Savin 4018	122839	104	ST() PFU(PS460)	
Savin 4018	123621	163	ST() PFU(PS460) ADF(DF78)	
Savin 4018D	122831	258	RADF(DF79)	Bent lower right side access door
Savin 4018D	122952	291	RADF(DF79) PC(TYPE 2018) FAX(TYPE 2018)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4018D	124361	11	ST()	
Savin 4022	119394	116	ST() SS(TYPE 1027) RADF(DF75) FAX(TYPE 2027)	Broken shift sort plug socket
Savin 4022	120197	399	ST() SS(TYPE 1027) RADF(DF75)	Broken bypass mounting bracket
Savin 4022	123625	193	ST() RADF(DF75) FN(SR790)	
Savin 4022	124704	95	ST() RADF(DF75) FAX(TYPE 2027)	
Savin 4027	121708	28	ST() RADF(DF75) FN(SR790)	Dirty panels; yellowed upper panels
Savin 4027	122853	162	ST() SS(TYPE 1027) RADF(DF75)	Offcolored RADF panels
Savin 4027	123626	434	ST() RADF(DF75) FN(SR790)	Missing bypass tray; offcolored finisher panels
Savin 4027	123628	288	ST() RADF(DF75) FN(SR790)	
Savin 4035	120241	302	ST() PC(TYPE 2045) FN(SR790)	Yellowed panels
Savin 4035	120532	702	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	
Savin 4035	120691	481	PS(TYPE 2045) PED(PS530) PC(TYPE 2045) FAX(TYPE 2045)	
Savin 4035	121094	161	ST() PC(TYPE 2045) FAX(TYPE 2045)	Offcolored panels
Savin 4035	121876	321	ST() PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	
Savin 4035	122080	271	PED(PS530) FAX(TYPE 2045)	Has finisher brackets but no finisher
Savin 4035	122081	542	PED(PS530)	Has finisher brackets but no finisher
Savin 4035	122982	245	PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	Error codes SC322 & SC326 (laser) was able to clear & run copies, but copy quality is very poor; bent controller panel frame; cracked lower finisher tray; top paper tray will not detect paper size
Savin 4035	124459	182	ST() FAX(TYPE 2045) E(PT330)	Yellowed panels
Savin 4035E	121099	574	PU(TYPE 1045) PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880)	Goes into error code SC863 (hard drive)

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4035E	122258	336	ST() PU(TYPE 1045) PC(TYPE 2045E) FN(SR880)	
Savin 4035E	122823	134	PED(PS530) FN(SR790) FAX(TYPE 2045E)	
Savin 4035E	122844	315	ST() FN(SR790)	
Savin 4035E	122847	165	PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	
Savin 4035E	122850	271	PED(PS530) PC(TYPE 2045E) FN(SR880)	Finisher jams every copy- inop
Savin 4035E	122851	656	PED(PS530) PC(TYPE 2045E) FN(SR880)	
Savin 4035E	122854	279	PU(TYPE 1045) PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) FN(SR880) FAX(TYPE 2045E)	
Savin 4035E	123043	553	PC(TYPE 2045E) P(RT45) FN(SR790) FAX(TYPE 2045E) E(PT330)	
Savin 4035E	123560	548	ST() PC(TYPE 2045E) FN(SR790)	
Savin 4035E	124133	654	ST() PC(TYPE 2045E)	
Savin 4035E	124463	179	ST() PC(TYPE 2045E) FAX(TYPE 2045E) E(PT330)	
Savin 4045	121634	168	PED(PS530) PC(TYPE 2045) FN(SR790)	
Savin 4045	122835	738	ST() P(RT45) FN(SR790) FAX(TYPE 2045)	
Savin 4045	123150	156	ST() P(RT45) FN(SR790)	Yellowed panels
Savin 4045	124179	755	PED(PS530) PC(TYPE 2045) FN(SR890)	Yellowed panels
Savin 4045	124444	360	PS(TYPE 2045) PED(PS530) PC(TYPE 2045) FN(SR790) FAX(TYPE 2045)	
Savin 4045	124572	150	PED(PS530) PC(TYPE 2045)	Yellowed panels
Savin 4045E	120501	237	ST() PC(TYPE 2045E) FAX(TYPE 2045E)	
Savin 4045E	122836	347	PED(PS530) PC(TYPE 2045E) FN(SR790)	
Savin 4045E	122841	819	PED(PS530) PC(TYPE 2045E) FN(SR790)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Savin 4045E	122842	686	PU(TYPE 1045) PS(TYPE 2045) PED(PS530) PC(TYPE 2045E) P(RT45) FN(SR880) FAX(TYPE 2045E) E(PT330)	
Savin 4045E	122848	241	PED(PS530) PC(TYPE 2045E) FN(SR880)	
Savin 4045E	122856	550	PU(TYPE 1045) PED(PS530) FN(SR880)	
Savin 4045E	124721	437	PED(PS530) PC(TYPE 2045E) FN(SR790)	
Savin 4060	123306	450	PU(TYPE 1075) PC(TYPE 2075) P(RT43) FN(SR850)	
Savin 4060	124359	1233	PU(TYPE 1075) PS(TYPE 2075) PC(TYPE 2075) P(RT43) FN(SR861)	Finisher in error code SC740 (saddlestitch stapler motor problem)-grinds when running
Savin 4090	123631	5427	PU(TYPE 1075) P(RT46) FN(SR840)	Broken wiring in paper deck- inop
Savin 40105	123706	6145	PU(TYPE 1075) PS(TYPE 2105) PC(TYPE 2105) P(RT46) FN(SR840) B(TYPE 2105)	Broken Q2 handle in finisher- unable to test
Savin 40105	124358	4437	PU(TYPE 1075) PS(TYPE 2105) PC(TYPE 2105) P(RT46) FN(SR90) FN(SR841) B(TYPE 2105)	Has Z-folding unit type 2105, BF90 book folder, TR90 trimmer unit, Type 1075 interposer tray & MicroPress System (w/ tower, monitor, mouse, keyboard & stand); broken RADF plug socket
Savin 9922 DP	122085	387	PED(PS440) DX(AD360)	
Savin 9922 DP	122087	231	PED(PS440) DX(AD360)	
Savin 9922 DP	124135	472	ST() SS(TYPE 270) RADF(DF69) DX(AD360) B(TYPE 270)	
Savin C3224	119736	1325	PU(TYPE 2238) PS(TYPE 2238) PED(PS540) FN(SR910) FAX(TYPE 2238) E(PT460)	Missing punch unit waste container (not tested); color = 750k; B/W = 576k
Savin C3828	123620	450	PED(PS550) FN(SR910) FAX(TYPE 2238) E(PT460)	Color = 139k; B/W = 311k
Savin 9925 DP	122093	320	RADF(DF65)	Has finisher brackets but missing finisher
Savin 8025	121709	24	ST() RADF(DF83) PC(TYPE 3030)	Broken bypass tray
Savin 8025	121859	71	ST() SS(TYPE 1027) RADF(DF83)	Missing drum unit- can't test
Savin 8030	122827	309	RADF(DF83) PS(TYPE 3030) PED(PS490)	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			PC(TYPE 3030) FN(SR820) FAX(TYPE 3030) E(PT280)	
Savin 8035	122446	179	FN(SR790)	
Savin 8045	121093	252	PED(PS530) FN(SR790)	Jams frequently in fuser; offcolored & dirty panels
Savin 8045	122352	364	PED(PS530) PC(TYPE 3045)	Has wrong finisher (SR960)
Savin 8045	122828	475	PU(TYPE 1045) PS(TYPE 3045) PED(PS530) PC(TYPE 3045) FN(SR880) FAX(TYPE 3045) E(PT330)	Stapler inop- cartridge jammed; scratched back panel
Savin 8045	122829	432	PS(TYPE 3045) PED(PS530) PC(TYPE 3045) P(RT45) FN(SR880) FAX(TYPE 3045) E(PT330)	Cracked & bent back corner of paper deck
Savin 8045	123301	156	PED(PS530) PC(TYPE 3045)	
Savin C2410	119398	149	PED(PS510)	Color = 29k; B/W = 121k
Savin C2824	111840	178	PED(PS580) FAX(TYPE 3245) E(PT460)	Color = 28k; B/W = 150k
Savin C2824	115761	347	ST() PU(TYPE 1045) FN(SR960) FAX(TYPE 3245) E(PT460)	Color = 167k; B/W = 181k
Savin C2824	116801	231	ST() FN(SR960) FAX(TYPE 3245) E(PT460)	Color = 56k; B/W = 176k
Savin C2824	121127	162	ST() FN(SR960) FAX(TYPE 3245) E(PT460)	Cracked upper left side panel; missing a finisher tray; color = 9k; B/W = 153k
Savin C2824	124507	135	ST() FAX(TYPE 3245) E(PT460)	Color = 36k; B/W = 100k
Savin C3528	119185	594	PS(TYPE 3245) PED(PS600) FN(SR960) FAX(TYPE 3245) E(PT460)	Yellowed panels
Savin C3528	120690	324	PED(PS590) FN(SR960) FAX(TYPE 3245)	Cracked finisher tray; offcolored panels; color = 41k; B/W = 284k
Savin C3528	121987	210	PU(TYPE 1045) PED(PS590) FN(SR960) FAX(TYPE 3245) E(PT460)	Error code SC733 - Stapler problem - not tested; black meter = 178k; colored meter = 32k
Savin C3528	123616	344	PED(PS590) FAX(TYPE 3245) E(PT460)	Color = 260k; B/W = 84k
Savin C4535	122837	447	PU(TYPE 2238) PED(PS590) FN(SR950)	Color = 57k; B/W = 391k
Savin SDC413	118978	82	PC(E-710) E()	Broken exit tray; color = 63k; B/W = 20k
Savin SDC413	119388	256	RADF(DF64) P(RT36) 20SS(ST33)	Has a E-820 external print controller; sorter bins out of alignment & entrance guide bent- inop; missing

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				controller cable
Savin SDC413	120205	192	PC(E-710) E()	Broken exit tray; color = 128k; B/W = 65k
Savin SLP38CS	109534	291	RADF(DF73) PU(TYPE 1045) FN(SR770) FAX(TYPE 3800C)	Color = 116k; B/W = 176k
Savin SLP38CS	113032	524	RADF(DF73) PU(TYPE 1045) FN(SR770) FAX(TYPE 3800C)	Color = 76k; B/W = 449k
Savin SLP38CS	124386	469	RADF(DF73) E()	Needs a new fuser oil unit- can't test; yellowed panels; color = 213k; B/W = 256k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators. While we make every effort to keep this list as current as possible, the list you are viewing may have already changed. Please call our sales team for current availability.