

Wulff Enterprises

02/10/2012

OH Inventory for Sale

Page:1

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC M20I	192202	130		
Xerox WC 4150	190832	79	PC() FAX()	Bypass not feeding - not tested
Xerox WC 4150X	191816	460	PFU()	Yellow panels
Xerox WC 4150X	191818	255	ST()	Off color and dirty panels
Xerox 416	170816	61	RADF(MR-3011) PED(KD-1009 [A]) PC(GA-1031) NIC(GF-1110) E(MJ-5001) DX(MD-0101) B(MY-1016)	Platen glass & slit glass smashed; line in copies due to no glass
Xerox 460DC	167514	650	P() FN()	
Xerox 470ST	170817	N/A		Missing drum unit and coronas- can't test; also shows a communication error on control panel
Xerox 470ST	171752	1482		Jams frequently; yellowed & dirty panels
Xerox 470ST	171753	2191		Machine will not print reports- can't test; finisher not functioning; yellowed panels
Xerox 535DC	170801	209	RADF() PED() PC() FN()	Unable to print a config page
Xerox 535DC	170802	396	RADF() PED() PC() FN()	Broken back panel; unable to print a config page
Xerox 535DC	170803	687	RADF() PED() PC() FN()	Broken back panel; broken rear finisher latch
Xerox 535DC	170804	596	RADF() PED() PC() FN()	Cracked finisher tray; broken rear finisher latch; broken back panel & internal filter holder; broken finisher interlock pin; unable to print a config page
Xerox 535DC	170805	1401	RADF() PED() PC() FN()	Cracked right side panel; broken paper tray #3 panel; unable to print a config page
Xerox 535DC	170806	1467	RADF() PED() PC() FN()	Broken back panel
Xerox 535DC	171746	312	ST() RADF() PC() FN()	Unable to print reports- network controller will not initialize; back left panel scraped & out of alignment; bypass jams
Xerox 535DC	178990	427	RADF() PED() PC() FN()	Rear fan cover broken
Xerox 535DC	178991	666	RADF() PED() PC() FN()	Finisher front latch hook broken, yellow panels
Xerox 545DC	170807	1551	RADF() PED() PC() FN()	Broken back panel; controller section not latching properly; unable to

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
				generate a config page
Xerox 545DC	170808	1527	RADF() PED() PC() FN()	
Xerox 545DC	171747	902	RADF() PED() PC() FN()	Missing fuser unit- unable to test; broken 3d/4d handle
Xerox 545DC	178992	993	RADF() PED() PC() FN()	Missing drum unit, yellow panels, rear panel shroud broken
Xerox 555DC	170813	1954	RADF() PED() PC() FN()	Broken back panel; unable to print a config page
Xerox 555DC	170814	730	RADF() PED() PC() FN()	Unable to print a config page- shows network controller unavailable; off color panels
Xerox 555DC	170815	1161	RADF() PED() PC() FN()	Print controller appears to be missing; off color & dirty panels
Xerox C123	188093	63	ST() FN()	Cassette #2 not recognizing paper size - not tesetd, drum needs replaced - unable to test
Xerox C123	189766	272	ST()	Yellow, ground in dirt
Xerox C65	171230	982	PC() P() FN()	Broken handle on RADF front; missing platen mat; broken front finisher panel; paper deck door not
Xerox WC 123	188188	98	PED()	Error code 016-454 - fax error - not tested
Xerox WC 123	190856	112	ST()	
Xerox WC 123	190873	304	ST()	
Xerox WC 123	190874	424	ST()	Yellow panels
Xerox WC 123	190875	208	ST()	Yellow panels
Xerox WC 123	190876	516	ST()	Off color panels
Xerox WC 123	190916	189	ST()	Yellow panels
Xerox WC 123	190917	221	ST()	Yellow, ground in dirt
Xerox WC 123	190918	233	ST()	Cassette #2 paper adjustment gear missing
Xerox WC 123	190919	205	ST()	Left side access door not latching - not fully tested
Xerox WC 123	190920	409	ST()	Yellow, ground in dirt, imaging unit missing
Xerox WC 123	190921	294	ST()	Yellow panels
Xerox WC 123	190922	191	ST()	Yellow panels
Xerox WC 123	190936	378	ST()	
Xerox WC 123	190937	316	ST()	Yellow panels
Xerox WC 123	190938	629	ST()	Yellow panels
Xerox WC 123	190939	580	ST()	False jam in duplexer - not fully tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 123	190940	940 ST()		Bypass tray broken, Falser paper sensing in RADF feed tray - not tested, off color
Xerox WC 123	190941	572 ST()		RADF not feeding - not tested
Xerox WC 123	190942	374 ST()		False jam in Duplexer - not tested, toner spilled in machine
Xerox WC 123	190943	322 ST()		
Xerox WC 123	190944	381 ST()		Jamming in bypass - not tested
Xerox WC 123	192487	46 PED() FN()		
Xerox WC 232	183090	533 ST() SCAN() PC() FAX()		Has OCT tray
Xerox WC 232	183836	331 ST() SCAN() PC() FN(BF0-1)		Exit tray missing
Xerox WC 232	189181	452 ST()		
Xerox WC 245	181768	134		Has FN BF0-1, has Fax, has PC w/ NIC and PED
Xerox WC 255	190542	348 PED() PC() FN(BF0-1) FAX()		Has user ID - not able to clear to test
Xerox WC 265	166263	803 SCAN() FN(BF0-1)		Missing lower finisher tray; Missing controller cable
Xerox WC 265	166275	N/A SCAN() FN(BF0-1)		Control panel is smashed- can't test machine; cracked right side panel; Missing controller cable; bottom back right side pedestal tray broken; cracked front pedestal panel
Xerox WC 265	166276	1868 SCAN() FN(BF0-1)		Finisher tray out of alignment; Missing controller cable
Xerox WC 265	166286	888 SCAN() FN(BF0-1)		
Xerox WC 35	171221	399 PED() FN(BF0-1)		Machine will not detect tray #2- inop; stapler causes finisher to jam
Xerox WC 35	171222	369 PED() FN(BF0-1)		Showing 'scanner has failed to initialize'- unable to test'
Xerox WC 35	171223	758 PED() FN(BF0-1)		Makes a loud clicking noise after copying
Xerox WC 35	171224	836 PED() FN(BF0-1)		Jams every copy in fuser; unable to print reports due to jamming
Xerox WC 35	171226	1429 PED() FN(BF0-1)		Finisher in false jam- will not clear; front corner of finisher out of alignment; jams constantly in areas 3 & 4
Xerox WC 35	171227	97 PED() FN(BF0-1)		
Xerox WC 35	171228	332 PED() FN(BF0-1)		
Xerox WC 35	171743	635 PED() FN()		Handle 3d/4d is broken off cuasing machine to jam every copy; shows RADF is unavailable; broken finisher

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 35	171751	N/A	PED() FN()	attaching hook and interlock actuator Control panel is cracked & broken; machine will not come to ready and LCD is blank
Xerox WC 4118	187407	27	ST() ADF()	
Xerox WC 4118	189228	31	ADF()	
Xerox WC 4118	190339	40		Has fax
Xerox WC 4118	190864	6	ADF()	Has fax
Xerox WC 4118	192197	59	ADF()	Has fax
Xerox WC 4118	192199	23	ADF()	Dirty, off color, bypass not feeding, Has fax
Xerox WC 4118	192211	43	ADF()	
Xerox WC 423	191715	179		Cassette 2.,3 front panels yellow, right side access door broken
Xerox WC 45	171225	1432	PED() FN(BF0-1)	Broken paper tray #3 panel
Xerox WC 45	171748	1138	FN()	mising handle 3d/4d causing machine to jam every copy - not tested
Xerox WC 45	176634	622	FN()	Has LCT pedestal
Xerox WC 5030	175524	209	PED()	
Xerox WC 5030	185962	301	PED() PC() FN()	Trays #1 & #2 jam
Xerox WC 5030	186634	124	PED() PC() FN()	Does not recognize finisher - not tested, could not access copier - not tested, finisher throat broken
Xerox WC 5030	190982	208	PED() PC() FN() FAX()	Fuser module warmup failure error - not tested, stapler missing
Xerox WC 5030	190983	321	PED() PC() FAX()	Off color panels
Xerox WC 5030	190984	200	PED() PC() FN() FAX()	Off color and dirty
Xerox WC 5030	190985	220	PED() PC() FAX()	Off color panels
Xerox WC 5030	190986	121	PED() PC() FN() FAX()	
Xerox WC 5030	191045	181	PED() PC() FAX()	
Xerox WC 5030	191562	261	PED() PC() FN() FAX()	Yellow and dirty, toner spilled in top cassette, finisher latches broken
Xerox WC 5030	192293	100	PED() PC() FN() FAX()	Needs fuser replaced - not fully tested
Xerox WC 5030	192294	87	PED() PC() FN() FAX()	Cassette #2 not recognizing paper size - nto tested, off color and dirty panels.
Xerox WC 5030	192295	137	PED() PC() FN() FAX()	Off color and dirty panels, grinding noise in finisher - stapler not tested
Xerox WC 5050	180754	103	PC() FN()	
Xerox WC 5050	192485	30	PC() FN() FAX()	

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 5225	187368	274	PED() PC(497K03580) FAX(498K17950)	
Xerox WC 5225	189229	179	PC(497K03580) FN(HFN-1) FAX(498K17950)	
Xerox WC 5225	189231	339	PED() PC(497K03580) FAX(498K17950)	
Xerox WC 5225	190853	57	PED() PC(497K03580) FN(HFN-1) FAX(498K17950)	Bypass guide plates bent, missing stapler cartridge - stapler not tested
Xerox WC 5225	192096	N/A	PED() PC(497K03580) FAX(498K17950)	Error code 124-373 - software module which controls printer operations has failed - not tesetd
Xerox WC 55	171235	934	PED() FN(BF0-1)	Cracked panel around platen glass in right corner; broken start button
Xerox WC 55	171236	1365	PED() FN(BF0-1)	
Xerox WC 55	171741	818	PED() FN()	Machine will not come to ready - not tested
Xerox WC 55	171742	1508	PED() FN()	Machine will not come to ready (scanner shows failed to initialize); broken finisher attaching hooks
Xerox WC 55	171744	590	PED() FN()	Finisher tray is twisted- inop; machine will not recognize paper in trays #1 & #2- unable to test; bypass will not feed
Xerox WC 55	171745	N/A	PED() FN()	Machine will not come to ready- unable to tes (LCD is blank); broken language button on control panel
Xerox WC 5632	188096	330	ST() FAX()	Has Exit tray
Xerox WC 5632	190024	86	PED() PC() FN(BF0-1) FAX()	Could not access fax - not tested
Xerox WC 5638	187284	238	ST() PC() FN(XXA-1)	
Xerox WC 5638	188094	168	PED() PC() FAX()	
Xerox WC 5638	190085	337	PED() PC() FAX()	Has OCT, cassette #2 out of service - will not raise paper - not tested
Xerox WC 5638	191342	1203	PU() PED() PC() FN(BF0-1) FAX()	Missing PC communication cable - not tested, scans originals but does not print
Xerox WC 5638	192097	379	PED() PC() FN(BF0-1) FAX()	
Xerox WC 5638	192201	319	PED() PC() FAX()	Yellow panels, grinding noise in machine
Xerox WC 5645	180684	765	PED() FN(BF0-1)	
Xerox WC 5645	181707	95	PED() PC()	Has hang on finisher
Xerox WC 5645	182161	579	PED() PC() FN(BF0-1) FAX()	Cassette #1 inop - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 5645	187223	256 PED()	PC() FN(BF0-1)	Stapler not tested -disabled
Xerox WC 5645	187500	204 PED()	PC() FAX()	Off color and dirty panels, front door cracked
Xerox WC 5645	187501	155 PED()	PC() FAX()	Missing PC cables, off color
Xerox WC 5645	188012	99 PED()	PC() FN(BF0-1) FAX()	Finisher door interlock pin broken, Jamming in RADF & also shows RADF unavailable, not jogging paper properly to staple - not test
Xerox WC 5645	188718	390 PED()		Unable to print reports- shows function disabled; yellowed panels
Xerox WC 5645	188721	52 ST()	PC() FN(XXA-1)	
Xerox WC 5645	190039	124 PED()	PC() FN(BF0-1) FAX()	Off color panels, ground out in dirt
Xerox WC 5645	190040	N/A PED()	PC() FN(BF0-1) FAX()	Machine will not come to ready - not tested
Xerox WC 5645	190877	126 PED()	PC() FN(BF0-1) FAX()	
Xerox WC 5645	191518	226 PED()	PC() FN(BF0-1) FAX()	
Xerox WC 5655	172356	429 PC()	FN(BF0-1) FAX()	
Xerox WC 5655	177179	446 PC()	FN() FAX()	
Xerox WC 5655	177180	620 PU()	PC() FN(SFN-3) FAX()	
Xerox WC 5655	178060	392 PU()	PC() FN(BF0-1)	
Xerox WC 5655	178061	188 PU()	PC() FN(BF0-1)	Jamming in duplexer,
Xerox WC 5655	179656	197 PC()	FN(BF0-1)	Machine frame bent - unable to test
Xerox WC 5655	183995	398 PU()	PC() FN(BF0-1)	Touch screen contrast very light
Xerox WC 5655	187279	619 PC()	FN(BF0-1) FAX()	Bypass not recognizing paper - not tesetd
Xerox WC 5655	187280	685 PC()	FN(BF0-1) FAX()	
Xerox WC 5655	187281	229 PC()	FN(BF0-1)	
Xerox WC 5655	187282	560 PC()	FN(BF0-1)	
Xerox WC 5655	187283	151 PC()	FN(BF0-1)	
Xerox WC 5655	187285	501 PU()	PC() FN(BF0-1) FAX()	Cassette #1 inop - not tested, RADF and control panel yellow
Xerox WC 5655	187626	N/A PC()	FN(BF0-1)	Will not come to ready, password protected
Xerox WC 5655	188097	1316 PC()	FN(BF0-1)	
Xerox WC 5655	188236	1 PC()	FN() FAX()	
Xerox WC 5655	188237	58 PC()	FN() FAX()	Deep Scratch on touch screen
Xerox WC 5655	188717	205 FN(BF0-1)		Unable to generate reports- shows function disabled

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 5655	188775	1250	PC() FN(BF0-1)	Jamming at fuser - not fully tested, yellow panels, missing PC cables, PC locking knob missing, finisher tray pin broken, left side panle cracked
Xerox WC 5655	188776	1016	PC() FN(BF0-1)	Missing PC cable; unable to generate a config page
Xerox WC 5655	190857	604	PU() PC() FN(BF0-1) FAX()	
Xerox WC 5655	190858	1501	PC() FN(BF0-1) FAX()	
Xerox WC 5655	190862	175	PC() FN(BF0-1)	Touch screen cut, scanner failed to initialize - not tested
Xerox WC 5655	191178	216	PU() PC() FN(BF0-1) FAX()	
Xerox WC 5655	191540	603	PU() PC() FN(BF0-1) FAX()	exit rollers clicking
Xerox WC 5655	192094	196	PC() FN(BF0-1) FAX()	Does not recognize fax - not tested
Xerox WC 5655	192098	411	PC() FN(BF0-1) FAX()	
Xerox WC 5665	178923	471	FN(BF0-1)	
Xerox WC 5665	180228	459	PU() PC() FN(BF0-1)	
Xerox WC 5665	182841	297	PC() FN(BF0-1)	Misisng PC to scanner cable- unable to bring up PC in menu or confirm scanning
Xerox WC 5665	188716	1452	PC() FN(BF0-1)	Jams every copy at finisher entrance; copies are unreadable; yellowed panels
Xerox WC 5665	188719	2101	PC() FN(BF0-1) FAX()	Finisher entrance guide broken causing finisher to jam (tested with another); duplex jams
Xerox WC 5665	188720	N/A	PC() FN(BF0-1)	Control panel is smashed- touch screen inop; yellowed panels
Xerox WC 5665	188722	597	PC() FN(BF0-1)	Finisher tray mount is bent (still works); unable to print a config page- shows feature disabled
Xerox WC 5665	188723	N/A	PC() FN(BF0-1)	Power supply is arcing when plugged in- can't test; dirty panels
Xerox WC 5665	188724	1654	PC() FN(BF0-1)	Finisher will not dock with machine correctly- unable to test machine; yellowed panels; missing PC cables
Xerox WC 5665	188725	1188	PC() FN(BF0-1)	Tray #2 out of service- makes a grinding noise; yellowed panels
Xerox WC 5665	188772	857	PC() FN()	Scanner vibrates at home position- can't test shows "scanner needs service"
Xerox WC 5665	188773	1328	PC() FN(BF0-1)	Missing controller cable- unable to test; cracked finisher tray
Xerox WC 5665	188774	1176	PC() FN(BF0-1)	Unable to generate a config page- missing both PC cabled; RADF makes a thumping noise when cycling

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 5665	190979	496	PC() FN(BF0-1) FAX()	
Xerox WC 5665	191539	54	PU() PC() FN(BF0-1) FAX()	PC cable missing
Xerox WC 5665	191950	655	PU() PC() FN(BF0-1)	Has SMX-3 LCT, yellow panels
Xerox WC 5665	192153	329	PC() FAX()	Has XW5 Finisher, missing left bottom cover
Xerox WC 5665	192209	2864	PC() FN(BF0-1)	Scanner not moving - not fully tested
Xerox WC 5675	178062	1260	PC() FN(BF0-1)	Paper deck copie are out of alignment
Xerox WC 5675	181774	1112	PC() FN(BF0-1)	Has LCT SMX-3 - not feeding
Xerox WC 5675	188238	12	PC() FN() FAX()	Jamming out of cassette #3
Xerox WC 5675	188239	52	PC() FN() FAX()	Finisher right side panel broken; gouged right side finisher panel
Xerox WC 5675	190861	685	PC() FN(BF0-1)	
Xerox WC 5675	192076	850	PC() FN(BF0-1) FAX()	Front stapler has vibrating noise when operating
Xerox WC 5675	192077	1090	PC() FN(BF0-1) FAX()	
Xerox WC 5687	187836	1479	PC() FN(YFW)	Finisher actuator broken, finisher communication error - false jam in finisher - not tested, cassette #5 not lifting properly - not tested
Xerox WC 65	170811	1055	FN()	Has a paper deck; broken bypass feed tires; loose frame around touch screen; RADF will not stay up (bad hinges); unable to generate a config page; scuffed front panels
Xerox WC 65	170812	3423	FN()	Has a paper deck; control panel shows a scanner fault and 'copier unavailable'- unable to clear (can't test machine)
Xerox WC 65	171229	1251	FN()	Has a paper deck
Xerox WC 65	171231	707	FN()	Has a paper deck; RADF & bypass jam; reports are unavailable
Xerox WC 65	171232	583	FN()	Has paper deck; scratched front door; RADF will not feed- inop; shows "network unavailale- unable to run reports; bypass will not feed
Xerox WC 65	171233	1949	FN()	Has paper deck; keeps showing fuser module not installed- reinstall fuser but message keeps returning (probably a bad sensor)
Xerox WC 65	171234	2993	FN()	Has paper deck
Xerox WC 65	178993	3126	FN()	Has LCT w/ bypass, false jam in finisher - not tested
Xerox WC 7132	188045	N/A	RADF() PED()	Error code 116-353 - hard-drive failed - not tested

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 7232	192737	172	SCAN() RADF() PS() PED() FN() FAX()	Black meter = 113k, color meter = 59k
Xerox WC 7242	191249	382	SCAN() RADF() PS() PED() FN() FAX()	Black meter = 223k, color meter = 159k
Xerox WC 7328	190037	353	SCAN() PED() FAX()	Black meter = 166k, color meter = 188k, Bypass not feeding paper - not tested
Xerox WC 7328	190081	227	SCAN() PED() FN(YFN1) FAX()	Ground in dirt, black meter = 175k, color meter = 52k
Xerox WC 7328	190264	637	SCAN() PED() FAX()	Squeaking in machine, black meter = 139k, color meter = 498k
Xerox WC 7328	190265	349	SCAN() PED() FAX()	Black meter = 90k, color meter = 260k
Xerox WC 7328	190855	N/A	PED() FN(YFN1)	Control panel screen shattered - not tested
Xerox WC 7328	191349	86	SCAN() PED() FN(YFN1) FAX()	Black meter = 68k, color meter = 19k
Xerox WC 7335	190020	129	SCAN() PED() FN(YFN1)	Finisher will not latch to machine correctly - machine not tested, black meter - 82k, color meter = 48k
Xerox WC 7335	190021	261	SCAN() PED() FN(YFN1)	Missing bridge unit, does not recognize finisher attached to machine - not tested, black meter = 165k, color meter = 96k
Xerox WC 7335	190025	284	SCAN() PED() FN(YFN1)	Bypass hinge cover out of position, black meter = 100k, color meter = 184k
Xerox WC 7335	190139	288	PED() FN(SFN1) FAX()	Black meter = 147k, color meter = 141k
Xerox WC 7335	190532	407	SCAN() PED() FN(YFN1) FAX()	Black meter = 403k, color meter = 5k
Xerox WC 7335	190976	603	SCAN() PED() FN(YFN1) FAX()	Black meter = 359k, color meter = 244k
Xerox WC 7335	190977	565	SCAN() PED() FN(YFN1) FAX()	Black meter = 241k, color meter = 325k
Xerox WC 7335	190980	261	SCAN() PED() FN(SFN1) FAX()	Paper not jogging in stapler - not stapling correctly, black meter = 59k, color meter = 203k
Xerox WC 7335	190981	321	SCAN() PED() FN(YFN1) FAX()	Black meter = 104k, color meter = 218k
Xerox WC 7335	190993	172	SCAN() PED() FN(SFN1) FAX()	Black meter = 95k, color meter = 78k
Xerox WC 7335	191044	307	SCAN() PED() FN(YFN1) FAX()	Black meter = 233k, color meter = 75k
Xerox WC 7335	191598	325	PED() FN(SFN1) FAX()	Black meter = 259k, color meter = 66k

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
Xerox WC 7335	192198	341	SCAN() PED()	Yellow panels, black meter = 309k, color meter = 32k
Xerox WC 7335	192288	215	SCAN() PED() FN(YFN1) FAX()	Black meter = 173k, color meter = 43k
Xerox WC 7335	192296	440	SCAN() PED() FN(YFN1) FAX()	Black meter = 143k, color meter = 298k
Xerox WC 7335	192297	446	SCAN() PED() FN(YFN1) FAX()	Missing finisher exit tray, yellow and dirty panels; color = 100k; B/W = 346k
Xerox WC 7345	183989	261	SCAN() PED() FN(SFN1) FAX()	Black meter = 121k, color meter = 141k
Xerox WC 7345	183990	353	SCAN() PED() FN(SFN1) FAX()	Duplexer interlock switch broken, black meter = 184k, color meter = 169k
Xerox WC 7345	183991	360	SCAN() PED() FN(YFN1) FAX()	Bridge unit top cover broken, has password - not fully tested
Xerox WC 7345	184085	N/A	PED()	Error code 116-388 not tested, hard-drive missing - not tested
Xerox WC 7345	187506	521	SCAN() PED() FN(YFN1) FAX()	Black meter = 470k, color meter = 51k
Xerox WC 7345	187628	173	SCAN() PED() FN(SFN1)	Black meter = 142k, color meter = 31k
Xerox WC 7345	187629	163	SCAN() PED() FN(YFN1)	Black meter = 142k, color meter = 22k
Xerox WC 7345	187639	244	SCAN() PED() FN(SFN1) FAX()	Duplexer interlock pin broken, black meter = 238k, color meter = 6k
Xerox WC 7345	188244	84	PED() FN(SFN1) FAX()	Jamming out of cassette #4 - not tested, black meter = 26k, color meter = 59k
Xerox WC 7345	188245	133	SCAN() PED() FN(SFN1) FAX()	Black meter = 47k, color meter = 87k
Xerox WC 7345	188246	139	SCAN() PED() FN(SFN1) FAX()	Black meter = 31k, color meter = 109k
Xerox WC 7345	188247	46	SCAN() PED() FN(YFN1) FAX()	bridge unit mount broken, lower finisher trim panel scraped, black meter = 21k, color meter = 26k
Xerox WC 7345	188248	175	SCAN() PED() FN(SFN1) FAX()	Black meter = 54k, color meter = 122k
Xerox WC 7345	188249	193	PED() FN(SFN1) FAX()	Black meter = 61k, color meter = 133k
Xerox WC 7345	188250	131	SCAN() PED() FAX()	Wires pulled from bypass - not tested, jamming in bridge unit; missing finisher, black meter = 55k, color meter = 126k, duplexer actuator broken
Xerox WC 7345	188251	131	SCAN() PED() FN(SFN1) FAX()	Duplexer interlock switch missing - borrowed to test, black meter = 48k, color meter = 85k
Xerox WC 7345	190915	79	SCAN() PED() FN(SFN1)	Power plug socket broken on

Manufacturer/Model#	CTRL #	Meter	Accessories	Comments
			FAX()	machine, error code 012-261 - finisher error - disconnected to test, black meter = 26k, color meter = 53k
Xerox WC 7345	191047	347	SCAN() PED() FN(SFN1)	Error code 012-212 - finisher error - not tested, missing finisher trays, black meter = 158k, color meter = 189k
Xerox WC 7345	191350	437	SCAN() PED() FN(SFN1) FAX()	Black meter = 230k, color meter = 207k
Xerox WC 7345	192736	255	SCAN() PED()	Black meter = 431k, color meter = 225k
Xerox WC 7665	192151	1588	PC() FN()	Missing booklet maker extension
Xerox WC 7665	192152	2144	PC() FN()	Black meter = 945k, color meter = 1200k

We maintain a constantly changing inventory of over 4000 used copiers, faxes and duplicators.
While we make every effort to keep this list as current as possible, the list you are viewing may have already changed.
Please call our sales team for current availability.